APPENDIX D:
CONTAMINATION OVERVIEW STUDY

Stantec

Contamination Overview Study Highway 401 Planning Study, Brockville Planning, Preliminary Design and Class Environmental Assessment

MTO Project Reference:
G.W.P. 4003-19-00

February 8, 2021

Prepared for:

Ontario Ministry of Transportation
Eastern Region (Program Delivery East)
1355 John Counter Blvd
Kingston ON K7L 5A3

Prepared by:

Stantec Consulting Ltd.
100-300 Hagey Boulevard
Waterloo ON N2L 0A4

Project No.: 165001160

Table of Contents

EXECUTIVE SUMMARY I

1.0 INTRODUCTION 1.1
1.1 OBJECTIVE 1.2
1.2 SCOPE OF WORK 1.2

2.0 METHODOLOGY 2.1
2.1 HISTORICAL RECORDS REVIEW 2.1
2.2 SITE RECONNAISSANCE 2.2

3.0 RESULTS 3.1
3.1 HISTORICAL RECORDS REVIEW 3.1
3.1.1 Aerial Photographs and Satellite Imagery 3.1
3.1.2 Physiographic Setting 3.2
3.1.3 Topography and Hydrogeological Setting 3.2
3.1.4 ERIS Historical Database Review 3.2
3.2 SITE RECONNAISSANCE 3.6
3.2.1 General Site Layout and Observations 3.7
3.2.2 Storage Tanks 3.8
3.2.3 Building Materials 3.8
3.2.4 PCBs 3.8
3.3 CHEMICAL STORAGE 3.9
3.3.1 Waste Generation and Disposal 3.9
3.3.2 Surficial Staining, Fill, Debris, and Vegetation Observations 3.9

4.0 ENVIRONMENTAL CONCERNS 4.1
4.1 POTENTIAL SOURCES OF CONTAMINATION 4.1
4.2 RECOMMENDATIONS 4.5

5.0 LIMITATIONS 5.1

6.0 REFERENCES 6.1

LIST OF TABLES

Table E-1: Summary of Potential Sources of Contamination i
Table 1: Summary of Aerial Photography and Satellite Imagery 3.1
Table 2: Summary of Potential Sources of Contamination Observed During Site Reconnaissance 3.9
Table 3: Summary of Potential Sources of Contamination 4.1

LIST OF FIGURES (APPENDIX A)

Figures 1 to 4: Contamination Overview Study Site Plans

LIST OF APPENDICES

APPENDIX A: FIGURES A.1

APPENDIX B: ERIS REPORT B.1

APPENDIX C: PHOTOGRAPHIC LOG C.1

APPENDIX D: QUALIFICATIONS OF COS PROJECT TEAM D.1

CONTAMINATION OVERVIEW STUDY HIGHWAY 401 PLANNING STUDY, BROCKVILLE
PLANNING, PRELIMINARY DESIGN AND CLASS ENVIRONMENTAL ASSESSMENT

Executive Summary

The Ontario Ministry of Transportation (MTO) retained Stantec Consulting Ltd. to undertake a Planning, Preliminary Design, and Class Environmental Assessment (Class EA) Study for Highway 401 from 2 km west of Stewart Boulevard to 750 m east of Augusta Road, a length of approximately 4.5 km, within the City of Brockville. The study will develop a plan for the rehabilitation and/or replacement of five (5) structures; determine the long-term plans for the Stewart Boulevard and North Augusta Road interchanges, and will establish the future footprint for the interim six and ultimate eight lanes of Highway 401.

The location of the proposed improvements will hereinafter be referred to as the "Site" (**Figure 1 to 4**, **Appendix A**). As part of this study, Stantec has completed a Contamination Overview Study (COS) in accordance with the MTO document, *Environmental Reference for Highway Design*, dated June 2013. The specific purpose of the COS was to assess if evidence of potential and actual environmental contamination exists at the Site as a result of current and past activities on the Site or adjacent/ neighbouring properties. Stantec has considered the "Site" to be an approximate area involving physical work (i.e., excavation, material handling) associated with the project and the "Study area" to be a 250 m buffer around the Site.

To fulfill the objective of the COS, historical records and documentation available for the Site and the surrounding areas were reviewed via desktop review of available resources. In addition, a site reconnaissance was completed via a windshield survey of the Site and surrounding areas on September 30, 2020. Following the review of historical records and the site reconnaissance, potential sources of contamination (PSOC) to the Site were identified, as summarized below. PSOC were ranked as either high, moderate, or low depending on the distance of the PSOC from the Site and the activity associated with the PSOC as defined in **Table 3**.

Table E-1: Summary of Potential Sources of Contamination

PSOC ID No.	Description of Potential Source	Location	Approximate Distance from the Site	Contaminant of Concern	Potential for Concern	Explanation of Potential for Concern
1	Underground storage tanks (USTs) and waste generation	1917 Parkedale Avenue	Adjacent to the Site	Polycyclic aromatic hydrocarbons (PAH), petroleum hydrocarbons (PHC), volatile organic compounds (VOC), metals, inorganics	High	Presence of former USTs including one 13,638 L private fuel tank on site and numbered company 1207931 Ontario Limited was registered for the generation of various wastes; heavy mobile equipment observed in the southern portion of this property in an unpaved parking lot, adjacent to Highway 401; property inferred to be upgradient from the Site

PSOC ID No.	Description of Potential Source	Location	Approximate Distance from the Site	Contaminant of Concern	Potential for Concern	Explanation of Potential for Concern
2	Vehicle maintenance	2399 Parkedale Avenue	20 m north of the Site	PAH, PHC, VOC	Moderate	Sears Canada Inc. was historically registered for waste generation consistent with vehicle maintenance; property inferred to be upgradient from the Site
3	USTs and waste generation	325 Stewart Boulevard	Adjacent to the Site	PAH, PHC, VOC	High	Suncor Energy Product was listed at this address for multiple USTs including three 50,000 L tanks and two 25,000 L tanks; a numbered company was listed for waste generation from 2013 to 2020; property inferred to be upgradient from the Site
4	USTs and waste generation	154 Stewart Boulevard	Adjacent to the Site	PAH, PHC, VOC	High	Hilltop Esso and Imperial Oil were listed for the generation of waste from 1999 to 2012; Hill Top Esso was listed for USTs between 1989 to 1994; property inferred to be downgradient from the Site
5	Dry cleaning and vehicle maintenance	125 Stewart Boulevard	Adjacent to the Site	PAH, PHC, VOC, inorganics	High	Durant's One Hour Cleaners Limited was listed as a dry cleaner with solvent waste generation; various vehicle service and maintenance companies were listed for USTs and automotive waste generation; totes of unknown quantities and materials were observed; property inferred to be downgradient from a portion of the Site, and upgradient from another portion of the Site
6	Waste generation, manufacturing	1879 Parkedale Avenue	50 m north of the Site	PAH, PHC, VOC, metals, inorganics	Moderate	Motor Cells MFG was listed for generation of various wastes and the manufacturing of railroad stock and railroad equipment; property inferred to be upgradient from the Site

CONTAMINATION OVERVIEW STUDY HIGHWAY 401 PLANNING STUDY, BROCKVILLE PLANNING, PRELIMINARY DESIGN AND CLASS ENVIRONMENTAL ASSESSMENT

PSOC ID No.	Description of Potential Source	Location	Approximate Distance from the Site	Contaminant of Concern	Potential for Concern	Explanation of Potential for Concern
7	USTs and waste generation	2089 Parkedale Avenue	50 m north of the Site	PAH, PHC, VOC, metals, inorganics	Moderate	Various companies were listed for the generation of various wastes, and William Cartage was listed for a 50,000 L single-wall UST in 1990, exact location of UST is unknown; property inferred to be upgradient from the Site
8	Manufacturing and waste generation	2157 Parkedale Avenue	70 m north of the Site	PAH, PHC, VOC, metals, inorganics	Moderate	Canarm Limited was listed between 1960 and 2020 for manufacturing fabricated metal products and generation of various wastes; property inferred to be upgradient from the Site
9	Spills, waste generation, USTs	2183 Parkedale Avenue	70 m north of the Site	PAH, PHC, VOC, metals, inorganics	Moderate	CP Express & Transport was listed for multiple spills; various companies were listed for fuel tanks including a 13,638 L tank; various companies were listed for generation of various wastes; property inferred to be upgradient from the Site
10	USTs, spills, waste generation	260 Central Avenue West	70 m south of the Site	PAH, PHC, VOC	Moderate	Various companies were listed for fuel tanks on site including a 231,846 L fuel tank in 1995, and waste generation; Reynolds Central Fuel was listed for a 45 L spill in 1996; property inferred to be downgradient from the Site
11	Waste generation	329 Stewart Boulevard	75 m north of Site	PAH, PHC, VOC, polychlorinated biphenyls (PCB), metals, inorganics	Moderate	Canadian Tire Corporation was listed for the generation of various wastes from 2016 to 2020; property inferred to be upgradient from the Site
12	Spills	Municipal roadways within the Site	N/A, roadways comprising the Site	PAH, PHC, VOC	Moderate	Numerous historical spills of fuel and hydraulic oil were identified for various roadways within the Study Area and on unplottable lands. Although the exact location of all these spills could not be determined, residual impacts to soil and/or water may be present

PSOC ID No.	Description of Potential Source	Location	Approximate Distance from the Site	Contaminant of Concern	Potential for Concern	Explanation of Potential for Concern
13	Waste generation, spills, PCB storage, manufacturing	100 Central Avenue West	50 m west of the Site	PAH, PHC, VOC, PCBs, metals, inorganics	Moderate	Various commercial and light industrial companies were listed for the generation of various wastes, manufacturing various materials, storage of PCBs, and multiple spills; property inferred to be downgradient from the Site
14	Vehicle maintenance	1000 Oxford Avenue	50 m north of the Site	PAH, PHC, VOC, and metals and inorganics	Moderate	Vehicle maintenance and repair located adjacent to the northern boundary of the Site; large quantities of totes of unknown quantities and material were observed during the site reconnaissance; property inferred to be upgradient from the Site
15	USTs	1861 Parkedale Avenue	100 m north of the Site	PAH, PHC, VOC	Low	Historical presence of USTs, exact location of former USTs is unknown; property inferred to be upgradient from the Site
16	Manufacturing and waste generation	2117 Parkedale Avenue	120 m north of the Site	PAH, PHC, VOC, metals, inorganics	Low	Wade-Tech Limited was listed between 1978 to 1994 for undefined waste generation and manufacturing industrial process furnaces and ovens; property inferred to be upgradient from the Site
17	Spills	2337 Parkedale Avenue	100 m north of the Site	PAH, PHC, VOC	Low	Multiple spills occurred in 1991 and 1997; property inferred to be upgradient from the Site
18	Spills and vehicle maintenance	3049 Jefferson Street/Drive	25 m north of the Site	PAH, PHC, VOC, PCB, metals, inorganics	Low	Two spills occurred in the parking lot area; totes of unknown quantities and materials were observed at time of site reconnaissance; property inferred to be upgradient from the Site
19	Vehicle maintenance	1942 Parkedale Avenue	100 m north of the Site	PAH, PHC, VOC, PCB, metals, inorganics	Low	Walmart Canada Corp. was listed for generation of various waste from 2005 to 2010 consistent with that of automobile servicing (Tire & Lube Express); property inferred to be upgradient from the Site

PSOC ID No.	Description of Potential Source	Location	Approximate Distance from the Site	Contaminant of Concern	Potential for Concern	Explanation of Potential for Concern
20	Waste generation, USTs	2211 Parkedale Avenue	100 m north of the Site	PAH, PHC, VOC, metals, inorganics	Low	UPI Energy Lp. was listed for two expired fuel tanks; property inferred to be upgradient from the Site
21	Waste generation and USTs	220 Central Avenue West	100 m south of the Site	PAH, PHC, VOC	Low	Various companies were listed for fuel storage tanks; Esso Petroleum Canada was listed for waste generation; property inferred to be downgradient from the Site
22	Gasoline service station	355 Stewart Boulevard	100 m north of the Site	PAH, PHC, VOC	Low	Canadian Tire gasoline service station observed during site reconnaissance, inferred fuel storage; property inferred to be upgradient from the Site

Notes:
PAH – polycyclic aromatic hydrocarbons
PCB – polychlorinated biphenyls
PHC – petroleum hydrocarbons
VOC – volatile organic compounds

Based on the above, the following recommendations are provided:

- A Preliminary Site Screening (PSS), Phase I ESA and Phase II ESA (if recommended as part of the PSS or Phase I ESA) should be completed for any property that will be acquired by MTO in accordance with the requirements of the MTO documents *Environmental Guide for Contaminated Property Identification and Management* (MTO, 2006) and *Environmental Reference for Highway Design* (MTO, 2013). If building demolition will be required, designated substance surveys should be completed for buildings or structures prior to demolition.

- Soil and groundwater that will be disturbed during construction should be sampled and analyzed for metals and inorganics (including electrical conductivity and sodium adsorption ratio [SAR]), PAH, and PHC. In addition, areas within or adjacent to PSOC should be analyzed for the specific contaminants of concern as described in **Table 3**. The selection of soil for analysis should take into consideration the presence of anthropogenic substances such as debris/waste, evidence of PHCs, solvents, or unusual odours or staining.

- Ontario Regulation (O.Reg.) 406/19 (*On-Site and Excess Soil Management*) and the associated document *Rules for Soil Management and Excess Soil Quality Standard*s referenced by O.Reg. 406/19 should be followed for soil that is excavated and managed on-site or off-site during construction. In addition, it is understood that salt-related parameters, such as electrical conductivity and SAR may not be considered to be contaminants when related to the application of a substance to surfaces for the safety of vehicular or pedestrian traffic under snow or ice conditions (O.Reg. 153/04 s.49.1.1); however, soil or water impacted by salt should be managed according to O.Reg. 406/19 if it is to be removed from the right-of-way.
- Should excess water be generated at the Site during future construction activities, water quality analyses should be conducted to determine appropriate management methods. This work should be done in coordination with a QP_{ESA} as defined by O.Reg. 153/04, to maintain data quality and provide an appropriate assessment of water quality.
- Should evidence of soil or water impacts be identified during construction (e.g., staining, odours, PHC sheen) samples should be collected for laboratory analyses to confirm concentrations of potential contaminants so as to appropriate manage the material in accordance with O.Reg. 406/19, and protect workers according to health and safety guidelines.

The statements made in this Executive Summary text are subject to the limitations included in **Section 5.0**, and are to be read in conjunction with the remainder of this report.

Introduction
February 8, 2021

1.0 INTRODUCTION

The Ontario Ministry of Transportation (MTO) retained Stantec Consulting Ltd. to undertake a Planning, Preliminary Design, and Class Environmental Assessment (Class EA) Study for Highway 401 from 2 km west of Stewart Boulevard to 750 m east of Augusta Road, a length of approximately 4.5 km within the City of Brockville. The study will develop a plan for the rehabilitation and/or replacement of five (5) structures; determine the long-term plans for the Stewart Boulevard and North Augusta Road interchanges, and will establish the future footprint for the interim six and ultimate eight lanes of Highway 401. The locations of the proposed improvements are shown below.



The location of the proposed improvements will hereinafter be referred to as the “Site” (**Figures 1 to 4**, **Appendix A**). As part of this study, Stantec has completed a Contamination Overview Study (COS). The specific purpose of the COS was to assess if evidence of potential and actual environmental contamination exists at the Site as a result of current and past activities on the Site or adjacent/neighbouring properties. Stantec has considered the “Site” to be an approximate area involving physical work (i.e., excavation, material handling) associated with the project and the “Study area” to be a 250 m buffer around the Site.

1.1 OBJECTIVE

The objective of the COS was to identify properties or areas that represented the potential for Site contamination at the time of the investigation. The Canadian Standards Association (CSA) Standard Z768-01 for Phase I Environmental Site Assessment (ESA) defines contamination as the presence of a substance of concern, or a condition, in concentrations above appropriate pre-established criteria in soil, water, groundwater, air, or structures (CSA, R2016). Potential sources of contamination (PSOC) were qualitatively ranked as either a high, moderate, or low concern. **Section 2.0** provides a definition of each qualitative ranking.

1.2 SCOPE OF WORK

The scope of work completed to fulfill the objective of the COS in accordance with the MTO document, Environmental Reference for Highway Design, dated June 2013, which consists of:

- Review of historical records and documentation available for the Site and study area (a 250 m buffer from the Site). This review included a database search and a review of historical aerial photographs.
- Completion of a site reconnaissance of the Site and study area where accessible by public roadways.

The COS used the following documents as guidance to conduct the investigation:

- CSA 2001 Standard Z768-01: Phase I Environmental Site Assessment. November 2001, reaffirmed 2016.
- MTO, 2013. Environmental Reference for Highway Design.
- MTO, 2006. Environmental Guide for Contaminated Property Identification and Management.

The COS is considered to be a modified Phase I ESA, which differs from the requirements of CSA Z768-01 in that site interviews were not completed with individual landowners, fire insurance plans were not ordered, city directory searches and title searches were not completed for the road alignment, well records were not reviewed, and requests were not directly made to the Ontario Ministry of the Environment, Conservation and Parks (MECP) for information they have on file for the Site and adjacent properties. Much of the information that could be obtained from MECP files was instead obtained through a database search completed by Environmental Risk Information Services (ERIS). A buffer of 250 m around the Site was defined for the database search, which was consistent with a typical COS that focuses on the identification of PSOC directly adjacent to the areas that form the Site.

The site reconnaissance comprised a windshield survey that was conducted only in areas accessible by public roadways.

Note that an excess materials management plan is not considered part of the scope of a COS.

2.0 METHODOLOGY

This section describes the methods used to complete the historical records review and the Site reconnaissance activities. A list of PSOCs contributing to potential environmental concerns at the Site was developed using the information obtained from the activities carried out as part of this COS (refer to **Table 3**).

High, Moderate, and Low potential concerns identified within the study area were generally defined as follows:

- High: Current or former potentially contaminating activity at which soil and/or groundwater contamination is typically found (e.g., gasoline service station, dry cleaning operation, known soil and/or groundwater contamination, heavy industrial operations) adjacent to the Site or within 50 m of the Site in the inferred upgradient direction.
- Moderate: Current or former potentially contaminating activity at which soil and/or groundwater contamination is typically found (e.g., gasoline service station, dry cleaning operation, known soil and/or groundwater contamination, heavy industrial operations, reported spills) within 50 m of the Site in the inferred downgradient direction or within 75 m of the Site in the inferred upgradient direction.
- Low: Current or former potentially contaminating activity between 75 m and 100 m from the Site in the inferred downgradient direction OR between 75 m and 100 m from the Site in the inferred upgradient direction, or a source of potential contamination where the source has likely been remediated or the contamination has likely attenuated (e.g., the potential for concern associated with a spill of a limited quantity of fuel (<50 L) to a roadway).

Section 4.0 summarizes PSOCs that represent environmental concerns at the Site, while **Table 3** provides the justification for ranking the PSOC as High, Moderate, or Low.

2.1 HISTORICAL RECORDS REVIEW

The historical records review consisted of a review of information available from government, public, and other agencies or parties, and information on file at Stantec. In addition, topographic mapping and geological reference maps were reviewed to develop a conceptual understanding of site physiography and hydrogeology. Information was reviewed from the following sources:

- Aerial/Satellite Imagery:
    - Google Earth Pro imagery (1984, 1994, 2005, 2006, 2007, 2008, 2009, 2012, 2013, 2015, and 2018)

- ERIS – The ERIS report documented the database search for the Site and properties within a 250 m buffer of the Site. The ERIS report, including full references for each database searched, is provided in **Appendix B**, and included searches of the following:
    - Federal Databases, including but not limited to: federal tank, spills, polychlorinated biphenyl (PCB) storage sites, and waste disposal site databases
    - Private Databases, including but not limited to: private tank listings, waste disposal site databases, and manufacturing directories
    - Provincial Databases, including but not limited to: provincial tank, certificates of approval/environmental compliance approvals, waste generation, waste disposal, and spill databases
- Topographic/Geologic/Physiographic Mapping:
    - Ontario Geological Survey, 1991. Quaternary Geology of Ontario, Southern Sheet; Map 2556, Scale 1: 1,000,000
    - Ontario Geological Survey, 1991. Bedrock Geology of Ontario, Southern Sheet; Map 2544, Scale 1: 1,000,000
    - Ontario Ministry of Natural Resources and Forestry, 2018. Make a Topographic Map

A search of MECP Freedom of Information (FOI) files and the Technical Standards and Safety Authority (TSSA) was not completed. Information typically available through the FOI and TSSA offices was accessed by the ERIS database search.

2.2 SITE RECONNAISSANCE

Site reconnaissance activities included:

- A windshield survey (i.e., observations and photographic documentation) of the Study Area from publicly accessible roadways (i.e., Parkedale Avenue, Stewart Boulevard, Kent Boulevard, Jefferson Drive, Ormond Street, North Augusta Road, Broome Road, Central Avenue West, Decker Drive, Ferguson Drive, Balmoral Place, Brookview Crescent and several other residential streets within the study area south of Highway 401). Due to safety concerns, the Site was not observed from Highway 401.
- Observation of properties adjacent to the Site to determine land use, where visible from public roadways.

Mr. Romeet Gonsalves, B.Sc., of Stantec carried out the site reconnaissance on September 30, 2020.

3.0 RESULTS

3.1 HISTORICAL RECORDS REVIEW

This section presents the findings of the historical records review. The site location is presented on **Figures 1** to **4** (**Appendix A**). The ERIS report prepared for the Site is included in **Appendix B**.

3.1.1 Aerial Photographs and Satellite Imagery

Table 1 below provides a summary of pertinent information obtained from the aerial photographs and satellite imagery sources listed above. Aerial photographs were not ordered as the National Air Photo Library was experiencing significant delays due to the COVID-19 closures, and sufficient historical information was obtained from the ERIS report.

Table 1: Summary of Aerial Photography and Satellite Imagery

Year	Summary
1984	Highway 401 was present. Both overpasses, North Augusta Road and Stewart Boulevard were present. The Site and Study Area appeared to be developed with commercial and light industrial properties north of Highway 401 and residential properties south of Highway 401.
1994	The Site and Study Area were generally consistent with the layout as shown on the 1984 satellite imagery. Greater resolution is available in the 1994 image, showing that gasoline service stations are present at 325 and 355 Stewart Boulevard, as well as commercial shopping centers including the 1000 Island Mall north of Highway 401 and the Brockville Shopping Center south of Highway 401. Other major roads including Parkedale Avenue and Central Avenue West are present.
2004	The Site and Study Area were generally consistent with the layout as shown on the 1994 satellite imagery, with some further development occurring north of Highway 401, including a Loblaws and Walmart shopping centers between Crocker Crescent and Broome Road. Construction had begun for a Home Depot at 2120 Parkedale Avenue and some buildings at the intersection of Parkedale Avenue and North Augusta Road have been torn down.
2006	The Site and Study Area were generally consistent with the layout as shown on the 2004 satellite imagery, with some further development occurring north of Highway 401, and some additional development to the south of Highway 401, at the western end of Central Avenue West.
2007- 2020	The Site and Study area were generally consistent with the layout as shown in the 2006 aerial photograph and observed during site reconnaissance. Redevelopment of commercial properties has taken place at the intersection of Parkedale Avenue and North Augusta Road.

3.1.2 Physiographic Setting

According to the Quaternary Geology of Ontario map published by the Ontario Geologic Survey (Map 2556), the surficial soil in the vicinity of the Site, where present, generally consists of bedrock at surface; glaciomarine and marine deposits composed of silt and clay; and till composed of undifferentiated, predominantly sandy silt to silt matric, commonly rich in clasts, often high in total matrix carbonate content. Borehole and water well records within the Study Area were provided by ERIS and indicated that overburden within the Study Area generally consisted of black topsoil and gravel overlying grey-brown clay and/or loose medium-grained sand.

According to the Bedrock Geology of Ontario map published by the Ontario Geologic Survey (Map 2544), bedrock in the vicinity of the Site consists of Beekmantown Group sandstone and dolostone; Potsdam Group conglomerate, sandstone, shale, dolostone; and Flinton Group conglomerate, wacke, quartz arenite, arkose, limestone, siltstone, chert, minor iron formation, and metavolcanics rocks. Depth to bedrock was not indicated on the map. Boreholes and water well records included in the ERIS report identified bedrock within the Study Area at depths ranging from ground surface to 19.8 m below ground surface (BGS).

3.1.3 Topography and Hydrogeological Setting

The Site is a portion of Highway 401 which extends approximately 4,500 m northeast – southwest though Brockville, Ontario. The North Augusta Road overpass and the Stewart Boulevard overpass pass above the highway at an elevation of approximately 5.5 m greater than the surrounding area. The remainder of the Study Area was observed to be generally flat in the accessible areas, with a gentle slope towards the south.

Based on a review of available maps and the topography observed in the vicinity of the Site, the inferred regional groundwater flow appears to be to the south towards the Saint Lawrence River, approximately 2.75 km south of the Study Area. No local tributaries were observed in the Study Area. The elevation of the local groundwater table can generally mimic the local topography and may not reflect the regional trend in drainage. Static groundwater levels encountered within water records provided as part of the ERIS report were reported to range from 0.6 m to 3.0 m BGS. The local shallow groundwater flow pattern also can be influenced by subsurface structures in the vicinity, such as building foundations, weeping tiles, and utility trenches.

3.1.4 ERIS Historical Database Review

This section summarizes relevant information provided by the ERIS database review. The addresses referenced below can be observed on **Figures 1** to **4, Appendix A**. The complete ERIS report is included in **Appendix B** and additional details regarding identified PSOCs are included in **Table 3**.

CONTAMINATION OVERVIEW STUDY HIGHWAY 401 PLANNING STUDY, BROCKVILLE PLANNING, PRELIMINARY DESIGN AND CLASS ENVIRONMENTAL ASSESSMENT

Results
February 8, 2021

3.1.4.1 100 Central Avenue West

Various businesses were listed at this location between 1990 to 2012 for hazardous waste generation including metals, paints, petroleum, and halogenated solvents, PCB storage and transfer, and the manufacturing of industrial and commercial machinery, miscellaneous fabricated metal products, plastic products, and paint per the *Scott's Manufacturing Directory*. Hazardous waste generation, presence of PCBs and industrial manufacturing were considered to represent a PSOC **(PSOC-13)**.

3.1.4.2 220 Central Avenue West

Esso Petroleum Canada was listed at this address for the generation of petroleum wastes from 1988 to 1997, and various companies were listed at this address for expired fuel tanks. Hazardous waste generation and the presence of underground storage tanks (USTs) at this property were considered to represent a PSOC **(PSOC-21).**

3.1.4.3 260 Central Avenue West

Various companies were listed at this address for fuel tanks, including Doug Summers listed at this address for a 231,846 L fuel tank in 1995. The records did not specify whether the tanks were above ground or below ground. Various companies were also listed at this address for the generation of petroleum and aliphatic solvents from 1986 to 2013. Hazardous waste generation, the presence of fuel storage, and a historical 45 L oil spill at this property were considered to represent a PSOC **(PSOC-10)**.

3.1.4.4 125 Stewart Boulevard

125 Stewart Boulevard is the Brockville Shopping Center with numerous tenants associated with the same civic address. As a result, various businesses were listed at this property in the *Pesticide Register*, the *Scott's Manufacturing Directory*, the *Ontario Regulation 347 Waste Generators Summary*, and the *National Pollutant Release Inventory*. These were generally not considered to be an environmental concern with respect to the Site, given the retail nature of these occupants and expected small volumes generated, with the following exceptions:

- Durant's One Hour Cleaners Limited was listed at this address as a Power Launderer and Dry Cleaning service. The company was listed for the generation of halogenated solvents from 1992 to 2001.
- Various vehicle service companies were also listed at this address for the generation of various wastes, USTs, and spills of oil and other automotive fluids.

Historical dry cleaning and auto servicing operations at this property were considered to represent a PSOC **(PSOC-5)**.

3.1.4.5 154 Stewart Boulevard

Imperial Oil and Hilltop Esso Hutt's Auto Service were listed at this address for the hazardous generation of light fuels, waste oils and lubricants, oil skimmings and sludges from 1999 to 2012, and Hilltop Esso was listed for the registration of USTs. Hazardous waste generation and the presence of USTs at this property were considered to represent a PSOC **(PSOC-4)**. This address was also listed for a spill of 5 L of gasoline to ground in 1988 at the Esso Station due to container overflow; however, based on the volume and age of the spill, still is not considered to be a concern to the site.

3.1.4.6 325 Stewart Boulevard

Various companies were listed at this address for multiple USTs including three 50,000 L double-walled USTs and two 25,000 L single-walled USTs, and for the generation of petroleum and organic wastes from 2013 to 2020. Hazardous waste generation and the presence of USTs at this property were considered to represent a PSOC **(PSOC-3).**

3.1.4.7 329 Stewart Boulevard

Canadian Tire Corporation was listed at this address for the generation of organic, alkaline, resin and organic wastes in 2016 to 2020. Hazardous waste generation at this property were considered to represent a PSOC **(PSOC-11).**

3.1.4.8 1861 Parkedale Avenue

Canada Transport Group Ltd was listed at this address for expired fuel tanks in 1991. The presence of former USTs at this property were considered to present a PSOC **(PSOC-15)**.

3.1.4.9 1879 Parkedale Avenue

Motor Coils MFG was listed at this address in the *Scott's Manufacturing Directory* for motor and generator manufacturing, railroad stock manufacturing, and industrial supplies and railroad equipment manufacturing in 1960, and for the hazardous waste generation of alkaline, acid, solvent, petroleum, paint, and resin wastes from 1986 to 2020. Hazardous waste generation and manufacturing at this property was considered to represent a PSOC **(PSOC-6)**.

3.1.4.10 1917 Parkedale Avenue

David Eaton S&D Equipment Rentals was listed at this address for a 13,638 L private fuel tank installed in 1984, and numbered company 1207931 Ontario Limited was listed at this address for the generation of petroleum, solvent, and paint wastes from 2006 to 1016. Hazardous waste generation and the presence of USTs at this property were considered to represent a PSOC **(PSOC-1)**.

CONTAMINATION OVERVIEW STUDY HIGHWAY 401 PLANNING STUDY, BROCKVILLE PLANNING, PRELIMINARY DESIGN AND CLASS ENVIRONMENTAL ASSESSMENT

Results
February 8, 2021

3.1.4.11 1942 Parkedale Avenue

Walmart Canada Corp. was listed at this address for the generation of petroleum, pesticide, solvent, alkaline and acid wastes in 2005 to 2010. These are generally not considered to be an environmental concern with respect to the Site, given the retail nature of the occupant and the expected small volumes generated. However, petroleum, alkaline and acid waste generated suggest that vehicle servicing may also have been conducted at this property, which is considered to represent a PSOC **(PSOC-19)**.

3.1.4.12 2089 Parkedale Avenue

Various businesses were listed at this address for the generation of waste oils and lubricants, and petroleum wastes for 1986 to 2001. William Cartage was listed at this address for a 50,000 L single-walled UST in 1990. Hazardous waste generation and the presence of a UST at this property were considered to represent a PSOC **(PSOC-7)**.

3.1.4.13 2117 Parkedale Avenue

Wade-Tech Limited was listed at this address in the *Scott's Manufacturing Directory* for industrial process furnaces and ovens manufacturing in 1978, and for undefined waste generation in 1986 to 1994. The associated waste generator number was ON767700. The limited details of waste generation and the industrial manufacturing at this property were considered to represent a PSOC **(PSOC-16)**.

3.1.4.14 2157 Parkedale Avenue

Canarm Limited was listed at this address for the generation of halogenated and other solvents, paint, and petroleum wastes from 1986 to 2020 and for miscellaneous fabricated metal product manufacturing in 1960, per the *Scott's Manufacturing Directory*. Hazardous waste generation and manufacturing at this property were considered to represent a PSOC **(PSOC-8)**.

3.1.4.15 2183 Parkedale Avenue

Various companies were listed at this address for the generation of inorganic laboratory chemicals, organic laboratory chemicals, alkaline waste, and acid waste in 1993 to 2008. CP Express & Transport was listed at this address for a 13,638 L private fuel tank, and various companies were listed at this address for expired fuel tanks. Hazardous waste generation and the presence of USTs at this property were considered to represent a PSOC **(PSOC-9)**.

3.1.4.16 2211 Parkedale Avenue

UPI Energy Lp. was listed at this address for two expired fuel tanks. The presence of historical storage tanks at this property were considered to represent a PSOC **(PSOC-20)**.

3.1.4.17 2337 Parkedale Avenue

Various businesses were listed at this address for the waste generation of halogenated solvents, petroleum distillates, waste oils and lubricants, aliphatic solvents, inorganic laboratory chemicals, alkaline

wastes and other chemicals. Parke-Davis Canada was listed at this address for a 225 L spill of diesel fuel to the ground in 1991 and a 500 L spill of mineral oil to the ground in 1997. Hazardous waste generation and the presence of spills at this property were considered to represent a PSOC **(PSOC-17).**

3.1.4.18 2399 Parkedale Avenue

2399 Parkedale Avenue is the 1000 Islands shopping center with numerous tenants associated with the same civic address. As a result, various businesses were listed at this property in the *Pesticide Register*, the *Scott's Manufacturing Directory*, the *Ontario Regulation 347 Waste Generators Summary*, and the *National Pollutant Release Inventory*. These are generally not considered to be an environmental concern with respect to the Site, given the retail nature of these occupants and expected small volumes generated, with the exception of Sears Canada Inc., which was listed at this address for various hazardous waste generation consistent with auto servicing at this property, and it is therefore considered to represent a PSOC **(PSOC-2).**

3.1.4.19 3049 Jefferson Street/Drive

This address (referenced interchangeably as both Jefferson Street and Jefferson Drive) was listed for a 675 L spill of diesel fuel in the parking lot from a transport truck to pavement and ditch via storm sewer in 1993 due to equipment failure. Another spill of 20 L of diesel to ground was reported in 2003 in the same parking lot. The presence of multiple spills at this property was considered to represent a PSOC **(PSOC-18).**

3.1.4.20 Historical Spills

In addition to the spills discussed in the above sections, unplottable spills of fuel and hydraulic oil were identified in the ERIS report for various roadways within the Study Area. Although the exact locations of these spills could not be determined based on the information provided, residual impacts to soil and/or water that may remain following the above releases represent a PSOC (**PSOC-12**).

3.1.4.21 Other Records

The remaining listings in the ERIS report included minor spills, small quantities of pesticide storage, manufacturing of nonhazardous good, and generation of nonhazardous wastes. These listings were determined to not represent a PSOC to the Site based on the distance from the Site, inferred direction of groundwater flow and/or the nature of the records.

ERIS provided several unplottable records that may be associated with the study area. The unplottable records were determined to not represent a PSOC to the Site based on their location (i.e., determined to not be within the Study Area) or nature of the records.

3.2 SITE RECONNAISSANCE

The results of the site reconnaissance conducted on September 30, 2020 are summarized in the following sections.

CONTAMINATION OVERVIEW STUDY HIGHWAY 401 PLANNING STUDY, BROCKVILLE PLANNING, PRELIMINARY DESIGN AND CLASS ENVIRONMENTAL ASSESSMENT

Results
February 8, 2021

Pertinent photographs of the Site are provided in **Appendix C**, and the site details are indicated on **Figures 1** to **4**, **Appendix A**. Additional details regarding identified PSOCs are included in **Table 3**.

3.2.1 General Site Layout and Observations

The Site included portions of Highway 401, Stewart Boulevard including the Stewart Boulevard underpass, North Augusta Road including the North Augusta Road underpass, the exits/ramps connecting the two underpasses to Highway 401, and the Canadian National Railway passing under Highway 401, in Brockville, ON (**Figures 1** to **4**, **Appendix A**). The observed surface features included asphalt, concrete, and gravel, as well as low-lying vegetation on the roadsides. Adjacent surface features included fields, wooded areas, low-lying vegetation, surface water drainage, and residential, commercial, and industrial properties.

Given the site use as a highway, it is possible that road de-icing materials have impacted the soil and/or groundwater quality along much of the Site. Salt-related parameters are not considered to be contaminants for on-site soils when substances have been applied for the safety of vehicular or pedestrian traffic under snow or ice conditions (O.Reg. 153/04 s.49.1.1); however, salt-impacted soil or water would require special management measures if being removed off-site.

A Petro-Canada gasoline service station (Suncor Energy Products Partnership) located at 325 Stewart Boulevard, adjacent to the northern site boundary, and a Canadian Tire gasoline service station located at 355 Stewart Boulevard, approximately 200 m north of the Site were observed during the site visit. No above ground storage tanks (ASTs) were observed; however, the ERIS report registers the Petro-Canada property for multiple USTs and the hazardous waste generation of petroleum and other wastes. The Canadian Tire gasoline service station is not listed in the ERIS report, but it is expected that fuel storage is present at this property. The presence of fuel storage and dispensing at these adjacent properties is considered to represent a PSOC **(PSOC-3 and PSOC-22).**

KD Construction, Equipment Rental & Float Service was observed at 1917 Parkedale Avenue East, adjacent to the northern boundary of the Site. Heavy mobile equipment that was observed at this property appeared to be maintained and clean. The nature of site operations, together with fuel storage and hazardous waste generation records referenced above and in the ERIS report (**Appendix B**), indicate that this property is considered to represent a PSOC (**PSOC-1)**.

Several automobile service and repair shops were located within the Study Area, at the following locations: Oil Changers at 125 Stewart Boulevard (**PSOC-5**), Dave Pipe's Auto Service at 3049 Jefferson Drive (**PSOC-18**), and Benson Tire at 1000 Oxford Avenue (**PSOC-14**). Given the nature of site operations, together with waste generation and other records as summarized above and in the ERIS report (**Appendix B**), these properties are considered to represent PSOCs. Brockville Towing Service and Townview Auto Body at 340 Central Avenue West, and Brockville Oil and Tires at 103 Broome Road were observed within the study area; however, based on the distance from the Site, these properties are not considered to represent PSOCs.

Light industrial and commercial properties were observed adjacent to the north side of Highway 401, including the 1000 Island Mall and nearby retailers at 2399 Parkedale Avenue. These are generally not considered to be an environmental concern with respect to the Site, given the absence of waste generation, fuel storage and other listings in the ERIS report.

Residential properties and several schools were observed on the south side of Highway 401 during the site visit. Some vacant fields and parks were also present in the area. To the south of Highway 401, industrial and commercial activity was mostly observed west of Stewart Boulevard.

The remainder of the Site and Study Area were occupied by roadways, wooded and vacant areas, and the Highland Golf Course, situated to the north of Highway 401 within the western portion of the Study Area.

3.2.1.1 Site Services

Overhead electrical lines, roadside ditches and culverts were observed within the Study Area. Various underground telecommunication or other services and their associated support structures are also expected to be present at the Site. Natural gas pipeline markers were observed across the Study Area.

3.2.2 Storage Tanks

No ASTs were observed on the Site, and no evidence of USTs was observed during the site reconnaissance. ASTs were observed within the Study Area at 2210 and 2120 Parkedale Avenue, and at the property situated between 340 Central Avenue West and 700 Central Avenue West (refer to photographs in **Appendix C**). Given the distances of approximately 100 - 250 m from the Site, the ASTs were not considered to be PSOCs. Fuel storage tanks were identified in the ERIS report (**Appendix B**) for numerous properties within the Study Area, as discussed in **Section 3.1.4.**

3.2.3 Building Materials

Numerous buildings were observed within the boundaries of the Study Area; however, as the Study Area was observed at a windshield level only, the buildings' materials and contents were not known. It is possible that buildings and/or structures within the Site may contain asbestos, lead, urea formaldehyde foam insulation (UFFI), PCBs, ozone depleting substances, or other special attention items; however, detailed observation of structures was not undertaken as part of the COS.

3.2.4 PCBs

Pole-mounted transformers were identified along the roadway of the Site and along most roads in the Study Area. Transformers may contain PCBs; however, it is anticipated that the transformers would have been upgraded and no longer contain PCBs. For this reason, the presence of pole-mounted transformers at the Site was not considered to represent a significant environmental concern. No evidence of large transformers or significant electrical equipment were observed at the properties listed in the ERIS report including 329 Stewart Boulevard, 100 Central Avenue West, 3049 Jefferson Street or 1942 Parkedale Avenue.

CONTAMINATION OVERVIEW STUDY HIGHWAY 401 PLANNING STUDY, BROCKVILLE PLANNING, PRELIMINARY DESIGN AND CLASS ENVIRONMENTAL ASSESSMENT

Results
February 8, 2021

3.3 CHEMICAL STORAGE

Storage of fuels or other automotive substances observed at the following automotive shops represent PSOCs: 1000 Oxford Road (**PSOC-14**), 3049 Jefferson Drive (**PSOC-18**), 125 Stewart Boulevard (**PSOC-5**).

Storage of fuels or other automotive substances were also observed at 103 Broome Road and at 340 Central Avenue West; however, based on the distance of approximately 250 and 220 m from the Site, respectively, these properties are not considered to represent PSOCs.

3.3.1 Waste Generation and Disposal

No evidence of waste generation or disposal was observed on the Site. Waste generation records were identified in the ERIS report for numerous properties within the Study Area, as discussed in **Section 3.1.4**.

3.3.2 Surficial Staining, Fill, Debris, and Vegetation Observations

Surficial staining, fill, debris, and stressed vegetation was not observed at the Site or within the surrounding Study Area; however, the Site was observed at a windshield level only so detailed ground observations were not completed. Rainy conditions during the site visit also made ground conditions difficult to observe.

Table 2 below summarizes relevant findings from the site reconnaissance. The addresses referenced below can be observed on **Figures 1 to 4** in **Appendix A**.

Table 2: Summary of Potential Sources of Contamination Observed During Site Reconnaissance

PSOC ID No.	Description of Potential Source	Location	Approximate Distance from the Site	Contaminant of Concern	Potential for Concern	Explanation of Potential for Concern
5	Vehicle maintenance	125 Stewart Boulevard	Adjacent to the Site	Polycyclic aromatic hydrocarbons (PAH), petroleum hydrocarbons (PHC), volatile organic compounds (VOC), and metals and inorganics	High	Oil changing and other vehicle maintenance activities observed approximately 30 m southeast of the Site; totes observed of unknown quantities and material; property inferred to be downgradient from one portion of the Site and upgradient from another potion of the Site

PSOC ID No.	Description of Potential Source	Location	Approximate Distance from the Site	Contaminant of Concern	Potential for Concern	Explanation of Potential for Concern
14	Vehicle maintenance	1000 Oxford Avenue	60 m north of the Site	PAH, PHC, VOC, and metals and inorganics	High	Vehicle maintenance and repair located adjacent to the northern boundary of the Site; totes observed of unknown quantities and material; property inferred to be upgradient from the Site
18	Vehicle maintenance	3049 Jefferson Drive	25 m north of the Site	PAH, PHC, VOC, and metals and inorganics	Low	Vehicle maintenance and repair located 100 m northwest of the Site; totes observed of unknown quantities and material; property inferred to be upgradient from the Site
22	Gasoline service station	355 Stewart Boulevard	100 m north of the site	PAH, PHC, VOC	Low	Canadian Tire gasoline service station observed during site recon, possible USTs; property inferred to be upgradient from the Site

Notes:
PAH – polycyclic aromatic hydrocarbons
PHC – petroleum hydrocarbons
VOC – volatile organic compounds

4.0 ENVIRONMENTAL CONCERNS

PSOCs were identified that may contribute to environmental concerns at the Site. The PSOC are summarized in **Table 3** below, along with a ranking of the likelihood (i.e., high, moderate, or low) that the soil and/or groundwater quality at the Site has been impacted.

4.1 POTENTIAL SOURCES OF CONTAMINATION

Properties or features identified as being PSOCs to the Site are summarized in **Table 3** below and shown on **Figures 1** to **4**, **Appendix A**:

Table 3: Summary of Potential Sources of Contamination

PSOC ID No.	Description of Potential Source	Location	Approximate Distance from the Site	Contaminant of Concern	Potential for Concern	Explanation of Potential for Concern
1	USTs and waste generation	1917 Parkedale Avenue	Adjacent to the Site	PAH, PHC, VOC, metals, inorganics	High	Presence of former USTs including one 13638 L private fuel tank on site and numbered company 1207931 Ontario Limited was registered for the generation of various wastes; heavy mobile equipment observed in the southern portion of this property in an unpaved parking lot, adjacent to Highway 401; property inferred to be upgradient from the Site
2	Vehicle maintenance	2399 Parkedale Avenue	20 m north of the Site	PAH, PHC, VOC	Moderate	Sears Canada Inc. was historically registered for waste generation consistent with vehicle maintenance; property inferred to be upgradient from the Site
3	USTs and waste generation	325 Stewart Boulevard	Adjacent to the Site	PAH, PHC, VOC	High	Suncor Energy Product was listed at this address for multiple USTs including three 50000 L tanks and two 25000 L tanks; a numbered company was listed for waste generation from 2013 to 2020; property inferred to be upgradient from the Site

PSOC ID No.	Description of Potential Source	Location	Approximate Distance from the Site	Contaminant of Concern	Potential for Concern	Explanation of Potential for Concern
4	USTs and Waste generation,	154 Stewart Boulevard	Adjacent to the Site	PAH, PHC, VOC	High	Hill Top Esso and Imperial Oil were listed for the generation of waste from 1999 to 2012; Hill Top Esso was listed for USTs between 1989 to 1994; property inferred to be downgradient from the Site
5	Dry cleaning and vehicle maintenance	125 Stewart Boulevard	Adjacent to the Site	PAH, PHC, VOC, inorganics	High	Durant's One Hour Cleaners Limited was listed as a dry cleaner with solvent waste generation; various vehicle service and maintenance companies were listed for USTs and automotive waste generation; totes of unknown quantities and materials were observed; property inferred to be downgradient from a portion of the Site, and upgradient from another portion of the Site
6	Waste generation, manufacturing	1879 Parkedale Avenue	50 m north of the Site	PAH, PHC, VOC, metals, inorganics	Moderate	Motor Cells MFG was listed for the generation of various waste and the manufacturing of railroad stock and railroad equipment; property inferred to be upgradient from the Site
7	USTs and waste generation	2089 Parkedale Avenue	50 m north of the Site	PAH, PHC, VOC, metals, inorganics	Moderate	Various companies were listed for the generation of various wastes, and William Cartage was listed for a 50,000 L single-wall UST in 1990, exact location of UST is unknown; property inferred to be upgradient from the Site
8	Manufacturing and waste generation	2157 Parkedale Avenue	70 m north of the Site	PAH, PHC, VOC, metals, inorganics	Moderate	Canarm Limited was listed between 1960 and 2020 for manufacturing fabricated metal products and the generation of various waste; property inferred to be upgradient from the Site

CONTAMINATION OVERVIEW STUDY HIGHWAY 401 PLANNING STUDY, BROCKVILLE PLANNING, PRELIMINARY DESIGN AND CLASS ENVIRONMENTAL ASSESSMENT

Environmental Concerns
February 8, 2021

PSOC ID No.	Description of Potential Source	Location	Approximate Distance from the Site	Contaminant of Concern	Potential for Concern	Explanation of Potential for Concern
9	Spills, waste generation, USTs	2183 Parkedale Avenue	70 m north of the Site	PAH, PHC, VOC, metals, inorganics	Moderate	CP Express & Transport was listed for multiple spills; various companies were listed for fuel tanks including a 13,638 L tank; various companies were listed for the generation of various waste; property inferred to be upgradient from the Site
10	USTs, spills, waste generation	260 Central Avenue West	70 m south of the Site	PAH, PHC, VOC	Moderate	Various companies were listed for fuel tanks on site including a 231,846 L fuel tank in 1995, and waste generation; Reynolds Central Fuel was listed for a 45 L spill in 1996; property inferred to be downgradient from the Site
11	Waste generation	329 Stewart Boulevard	75 m north of Site	PAH, PHC, VOC, PCB, metals, inorganics	Moderate	Canadian Tire Corporation was listed for waste generation from 2016 to 2020; property inferred to be upgradient from the Site
12	Spills	Roadways within the Site	Various roadways	PAH, PHC, VOC	Moderate	Numerous historical spills of fuel and hydraulic oil were identified for various roadways within the Study Area and on unplottable lands. Although the exact location of all these spills could not be determined, residual impacts to soil and/or water may remain
13	Waste generation, spills, PCB storage, manufacturing	100 Central Avenue West	50 m west of the Site	PAH, PHC, VOC, PCBs, metals, inorganics	Moderate	Various companies were listed for the generation of various wastes, for manufacturing various materials, for the storage of PCBs, and for multiple spills; property inferred to be downgradient from the Site
14	Vehicle maintenance	1000 Oxford Avenue	50 m north of the Site	PAH, PHC, VOC, and metals and inorganics	Moderate	Vehicle maintenance and repair located adjacent to the northern boundary of the Site; totes observed of unknown quantities and material; property inferred to be upgradient from the Site

PSOC ID No.	Description of Potential Source	Location	Approximate Distance from the Site	Contaminant of Concern	Potential for Concern	Explanation of Potential for Concern
15	USTs	1861 Parkedale Avenue	100 m north of the Site	PAH, PHC, VOC	Low	Presence of former USTs, exact location of former USTs is unknown; property inferred to be upgradient from the Site
16	Manufacturing and waste generation	2117 Parkedale Avenue	120 m north of the Site	PAH, PHC, VOC, metals, inorganics	Low	Wade-Tech Limited was listed between 1978 to 1994 for undefined waste generation and manufacturing industrial process furnaces and ovens; property inferred to be upgradient from the Site
17	Spills	2337 Parkedale Avenue	100 m north of the Site	PAH, PHC, VOC	Low	Multiple spills occurred in 1991 and 1997; property inferred to be upgradient from the Site
18	Spills and vehicle maintenance	3049 Jefferson Street/Drive	25 m north of the Site	PAH, PHC, VOC, PCB, metals, inorganics	Low	Two spills occurred in the parking lot area; totes of unknown quantities and materials were observed; property inferred to be upgradient from the Site
19	Vehicle maintenance	1942 Parkedale Avenue	100 m north of the Site	PAH, PHC, VOC, PCB, metals, inorganics	Low	Walmart Canada Corp. was listed for generation of waste from 2005 to 2010 consistent with that of automobile servicing (Tire & Lube Express); property inferred to be upgradient from the Site
20	Waste generation, USTs	2211 Parkedale Avenue	100 m north of the Site	PAH, PHC, VOC, metals, inorganics	Low	UPI Energy Lp. was listed for two expired fuel tanks; property inferred to be upgradient from the Site
21	Waste generation and USTs	220 Central Avenue West	100 m south of the Site	PAH, PHC, VOC	Low	Various companies were listed for fuel tanks; Esso Petroleum Canada was listed for waste generation; property inferred to be downgradient from the Site
22	Gasoline service station	355 Stewart Boulevard	100 m north of the Site	PAH, PHC, VOC	Low	Canadian Tire gasoline service station observed during site recon, possible USTs; property inferred to be upgradient from the Site

CONTAMINATION OVERVIEW STUDY HIGHWAY 401 PLANNING STUDY, BROCKVILLE PLANNING, PRELIMINARY DESIGN AND CLASS ENVIRONMENTAL ASSESSMENT

Environmental Concerns
February 8, 2021

4.2 RECOMMENDATIONS

Based on the PSOCs identified in **Section 4.1**, the following recommendations are provided:

- A Preliminary Site Screening (PSS), Phase I ESA and Phase II ESA (if recommended as part of the PSS or Phase I ESA) should be completed for any property that will be acquired by MTO in accordance with the requirements of the MTO documents *Environmental Guide for Contaminated Property Identification and Management* (MTO, 2006) and *Environmental Reference for Highway Design* (MTO, 2013). If building demolition will be required, designated substance surveys should be completed for buildings or structures prior to demolition.

- Soil and groundwater that will be disturbed during construction should be sampled and analyzed for metals and inorganics (including electrical conductivity (EC) and sodium adsorption ratio (SAR)), polycyclic aromatic hydrocarbons (PAH) and petroleum hydrocarbons (PHC). In addition, areas within or adjacent to PSOC should be analyzed for the specific contaminants of concern as described in **Table 3**. The selection of soil for analysis should take into consideration the presence of anthropogenic substances such as debris/waste and PHC, solvent, or other unusual odours or staining.

- Ontario Regulation (O.Reg.) 406/19 (*On-Site and Excess Soil Management*) and the associated document *Rules for Soil Management and Excess Soil Quality Standard*s referenced by O.Reg. 406/19 should be followed for soil that is excavated and managed on-site or off-site during construction. In addition, it is understood that salt-related parameters, such as EC and SAR may not be considered to be contaminants when related to the application of a substance to surfaces for the safety of vehicular or pedestrian traffic under snow or ice conditions (O.Reg. 153/04 s.49.1.1); however, soil or water impacted by salt should be managed according to O.Reg. 406/19 if it is to be removed from the right-of-way.

- Should excess water be generated at the Site during future construction activities, water quality analyses should be conducted to determine appropriate management methods. This work should be done in coordination with a QP_{ESA} as defined by O.Reg. 153/04, to maintain data quality and provide an appropriate assessment of water quality.

- Should evidence of soil or water impacts be identified during construction (e.g., staining, odours, petroleum hydrocarbon sheen) samples should be collected for laboratory analyses to confirm concentrations of potential contaminants so as to appropriate manage the material in accordance with O.Reg. 406/19, and protect workers according to health and safety guidelines.

5.0 LIMITATIONS

This report documents work that was performed in accordance with generally accepted professional standards at the time and location in which the services were provided. No other representations, warranties or guarantees are made concerning the accuracy or completeness of the data or conclusions contained within this report, including no assurance that this work has uncovered all potential liabilities associated with the identified property.

This report provides an evaluation of selected environmental conditions associated with the identified portion of the property that was assessed at the time the work was conducted and is based on information obtained by and/or provided to Stantec at that time. There are no assurances regarding the accuracy and completeness of this information. All information received from the client or third parties in the preparation of this report has been assumed by Stantec to be correct. Stantec assumes no responsibility for any deficiency or inaccuracy in information received from others.

The opinions in this report can only be relied upon as they relate to the condition of the portion of the identified property that was assessed at the time the work was conducted. Activities at the property subsequent to Stantec's assessment may have significantly altered the property's condition. Stantec cannot comment on other areas of the property that were not assessed.

Conclusions made within this report consist of Stantec's professional opinion as of the time of the writing of this report and are based solely on the scope of work described in the report, the limited data available and the results of the work. They are not a certification of the property's environmental condition. This report should not be construed as legal advice.

This report has been prepared for the exclusive use of the client identified herein and any use by any third party is prohibited. Stantec assumes no responsibility for losses, damages, liabilities or claims, howsoever arising, from third party use of this report.

This report is limited by the following:

- Review of the specific databases and information sources listed.
- Site visit was conducted at a "windshield level" and included observations from publicly accessible areas only.

The locations of any utilities, buildings and structures, and property boundaries illustrated in or described within this report, if any, including pole lines, conduits, water mains, sewers and other surface or sub-surface utilities and structures are not guaranteed. Before starting work, the exact location of all such utilities and structures should be confirmed and Stantec assumes no liability for damage to them.

CONTAMINATION OVERVIEW STUDY HIGHWAY 401 PLANNING STUDY, BROCKVILLE PLANNING, PRELIMINARY DESIGN AND CLASS ENVIRONMENTAL ASSESSMENT

Limitations
February 8, 2021

The conclusions are based on the site conditions encountered by Stantec at the time the work was performed at the specific testing and/or sampling locations, and conditions may vary among sampling locations. Factors such as areas of potential concern identified in previous studies, site conditions (e.g., utilities) and cost may have constrained the sampling locations used in this assessment.

In addition, analysis has been carried out for only a limited number of chemical parameters, and it should not be inferred that other chemical species are not present. Due to the nature of the investigation and the limited data available, Stantec does not warrant against undiscovered environmental liabilities nor that the sampling results are indicative of the condition of the entire site. As the purpose of this report is to identify site conditions which may pose an environmental risk; the identification of non-environmental risks to structures or people on the site is beyond the scope of this assessment.

Should additional information become available which differs significantly from our understanding of conditions presented in this report, Stantec specifically disclaims any responsibility to update the conclusions in this report.

This report was prepared by Romeet Gonsalves, B.Sc., and reviewed by Grace Ferguson, M.Sc., P.Eng. Qualifications are provided in **Appendix E**.

All of which is respectfully submitted,

STANTEC CONSULTING LTD.

Gonsalves, Romeet
Digitally signed by Gonsalves, Romeet
Date: 2021.02.08 16:38:11 -05'00'

Digitally signed by Grace Ferguson
Date: 2021.02.08 17:12:05 -05'00'

Romeet Gonsalves, B.Sc.
Junior Environmental Site Assessor
Tel: 613 301 6782
Romeet.Gonsalves@stantec.com

Grace Ferguson, M.Sc., P.Eng.
Senior Hydrogeologist
Tel: 519 585 7456
Grace.Ferguson@stantec.com

RG/GF/jt

6.0 REFERENCES

Canadian Standard Association (CSA). 2016. CSA Standard Z768-01, Phase I Environmental Site Assessment.

Environmental Risk Information Services (ERIS). 2020. Phase I ESA. Hwy 401, Lyn ON, 165001160.306.103.

Google Earth. 1994, 2005, 2006, 2007, 2008, 2009, 2012, 2013, 2015, and 2018. Accessed September 30, 2020.

Ontario Geological Survey. 1991. Bedrock Geology of Ontario, Southern Sheet; Map 2544, Scale 1: 1,000,000.

Ontario Geological Survey, 1991. Quaternary Geology of Ontario, Southern Sheet; Map 2556, Scale 1: 1,000,000.

Ontario Ministry of Natural Resources and Forestry (MNR). 2018. Make a Topographic Map. Accessed on September 30, 2020 from https://www.gisapplication.lrc.gov.on.ca/matm/Index.html?site=Make_A_Topographic_Map&viewer=MATM&locale=en-US.

Ontario Ministry of Transportation (MTO). 2006. Environmental Guide for Contaminated Property Identification and Management, October 2006.

Ontario Ministry of Transportation (MTO). 2013. Environmental Reference for Highway Design, June 2013.

APPENDICES

CONTAMINATION OVERVIEW STUDY HIGHWAY 401 PLANNING STUDY, BROCKVILLE PLANNING, PRELIMINARY DESIGN AND CLASS ENVIRONMENTAL ASSESSMENT

Appendix A Figures
February 8, 2021

Appendix A FIGURES


Stantec
Legend
Inferred Direction of Groundwater Flow
Lot Boundary
Remediation Study Area
Lot Boundary
0
100
200
Meters
1:5,000 (At original document size of 11 x 17)
Notes
1. Coordinate System: NAD 1983 UTM Zone 18N
2. Base features produced under license with the Ontario Ministry of Natural Resources and Forestry © Queen's Printer for Ontario, 2020-2021.
3. Imagery obtained from © First Base Solutions, 2020. City of Brockville 2018.
401
Elizabethtown-Kitley
Augusta
Project Location
City of Brockville
16300116G REVA
Prepared by JW on 2020-01-28
Client/Project
ONTARIO MINISTRY OF TRANSPORTATION
HIGHWAY 401 PLANNING STUDY, BROCKVILLE PLANNING
PRELIMINARY DESIGN AND CLASS ENVIRONMENTAL ASSESSMENT
Figure No.
1
Title
Contamination Overview Study
Former Golf Course (Closed in 2019)
ASTs Observed
Former Golf Course (Closed in 2019)
Patricia Rd Avenue
Lot 6 Con 2 Elizabethtown
Lot 6 Con 1 Elizabethtown
Lot 7 Con 2 Elizabethtown
Lot 7 Con 1 Elizabethtown
Lot 8 Con 2 Elizabethtown
Lot 8 Con 1 Elizabethtown
Lot 9 Con 2 Elizabethtown
Lot 9 Con 1 Elizabethtown
Lot

Stantec

Legend
- Inferred Direction of Groundwater Flow
- Project Structure
- Lot Boundary
- Remediation Study Area
- Lot Boundary

Potential Sources of Contamination (Potential for Concern)
- High
- Moderate
- Low

0 100 200 Meters

1:5,000 (At original document size of 11x17)

Notes
1. Coordinate System: NAD 1983 UTM Zone 18N
2. Base features produced under license with the Ontario Ministry of Natural Resources and Forestry © Queen's Printer for Ontario, 2019.
3. Imagery obtained from © First Base Solutions, 2020, City of Brockville 2018.



Project Location
City of Brockville

160501160 REVA
Prepared by JW on 2021-01-25

Client/Project
ONTARIO MINISTRY OF TRANSPORTATION
HIGHWAY 401 PLANNING STUDY, BROCKVILLE PLANNING, PRELIMINARY DESIGN AND CLASS ENVIRONMENTAL ASSESSMENT

Figure No.
2

Title
Contamination Overview Study

Stantec

Legend
- Inferred Direction of Groundwater Flow
- Project Structure
- Lot Boundary
- Remediation Study Area
- Lot Boundary

Potential Sources of Contamination (Potential for Concern)
- High
- Moderate
- Low

0 100 200 Meters

1:5,000 (At original document size of 11x17)

Notes
1. Coordinate System: NAD 1983 UTM Zone 18N
2. Base features produced under license with the Ontario Ministry of Natural Resources and Forestry © Queen's Printer for Ontario, 2019.
3. Imagery obtained from © First Base Solutions, 2020, City of Brockville 2018.



Project Location
City of Brockville

160501160 REVA
Prepared by JW on 2021-01-25

Client/Project
ONTARIO MINISTRY OF TRANSPORTATION
HIGHWAY 401 PLANNING STUDY, BROCKVILLE PLANNING, PRELIMINARY DESIGN AND CLASS ENVIRONMENTAL ASSESSMENT

Figure No.
3

Title
Contamination Overview Study



CONTAMINATION OVERVIEW STUDY HIGHWAY 401 PLANNING STUDY, BROCKVILLE PLANNING, PRELIMINARY DESIGN AND CLASS ENVIRONMENTAL ASSESSMENT

Appendix B Eris Report
February 8, 2021

Appendix B ERIS REPORT

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

DATABASE REPORT

Project Property: *Phase I ESA*
Hwy 401
Lyn ON

Project No: *165001160.306.103*

Report Type: *Quote - Custom-Build Your Own Report*

Order No: *20200504109*

Requested by: *Stantec Consulting Ltd.*

Date Completed: *August 10, 2020*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents....2
Executive Summary....3
Executive Summary: Report Summary....4
Executive Summary: Site Report Summary - Project Property....6
Executive Summary: Site Report Summary - Surrounding Properties....7
Executive Summary: Summary By Data Source....65
Map....134
Aerial....135
Topographic Map....136
Detail Report....137
Unplottable Summary....618
Unplottable Report....625
Appendix: Database Descriptions....695
Definitions....704

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property: *Phase I ESA*
Hwy 401 Lyn ON

Project No: *165001160.306.103*

Order Information:

Order No: *20200504109*
Date Requested: *May 4, 2020*
Requested by: *Stantec Consulting Ltd.*
Report Type: *Quote - Custom-Build Your Own Report*

Historical/Products:

Excel Add-On *Excel Add-On*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Boundary to 0.25km	Total
AAGR	Abandoned Aggregate Inventory	Y	0	0	0
AGR	Aggregate Inventory	Y	0	0	0
AMIS	Abandoned Mine Information System	Y	0	1	1
ANDR	Anderson's Waste Disposal Sites	Y	0	3	3
AST	Aboveground Storage Tanks	Y	0	3	3
AUWR	Automobile Wrecking & Supplies	Y	0	2	2
BORE	Borehole	Y	0	12	12
CA	Certificates of Approval	Y	0	51	51
CDRY	Dry Cleaning Facilities	Y	0	0	0
CFOT	Commercial Fuel Oil Tanks	Y	0	0	0
CHEM	Chemical Register	Y	0	0	0
CNG	Compressed Natural Gas Stations	Y	0	0	0
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Y	0	0	0
CONV	Compliance and Convictions	Y	0	0	0
CPU	Certificates of Property Use	Y	0	3	3
DRL	Drill Hole Database	Y	0	0	0
EASR	Environmental Activity and Sector Registry	Y	0	4	4
EBR	Environmental Registry	Y	0	18	18
ECA	Environmental Compliance Approval	Y	0	18	18
EEM	Environmental Effects Monitoring	Y	0	0	0
EHS	ERIS Historical Searches	Y	0	48	48
EIIS	Environmental Issues Inventory System	Y	0	0	0
EMHE	Emergency Management Historical Event	Y	0	0	0
EPAR	Environmental Penalty Annual Report	Y	0	0	0
EXP	List of Expired Fuels Safety Facilities	Y	0	63	63
FCON	Federal Convictions	Y	0	0	0
FCS	Contaminated Sites on Federal Land	Y	0	0	0
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FRST	Federal Identification Registry for Storage Tank Systems (FIRSTS)	Y	0	0	0
FST	Fuel Storage Tank	Y	0	6	6
FSTH	Fuel Storage Tank - Historic	Y	0	3	3
GEN	Ontario Regulation 347 Waste Generators Summary	Y	0	246	246
GHG	Greenhouse Gas Emissions from Large Facilities	Y	0	0	0
HINC	TSSA Historic Incidents	Y	0	6	6
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0
INC	Fuel Oil Spills and Leaks	Y	0	3	3

Database	Name	Searched	Project Property	Boundary to 0.25km	Total
LIMO	Landfill Inventory Management Ontario	Y	0	0	0
MINE	Canadian Mine Locations	Y	0	0	0
MNR	Mineral Occurrences	Y	0	1	1
NATE	National Analysis of Trends in Emergencies System (NATES)	Y	0	0	0
NCPL	Non-Compliance Reports	Y	0	0	0
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	Y	0	0	0
NEBI	National Energy Board Pipeline Incidents	Y	0	0	0
NEBP	National Energy Board Wells	Y	0	0	0
NEES	National Environmental Emergencies System (NEES)	Y	0	0	0
NPCB	National PCB Inventory	Y	0	5	5
NPRI	National Pollutant Release Inventory	Y	0	19	19
OGWE	Oil and Gas Wells	Y	0	0	0
OOGW	Ontario Oil and Gas Wells	Y	0	0	0
OPCB	Inventory of PCB Storage Sites	Y	0	10	10
ORD	Orders	Y	0	0	0
PAP	Canadian Pulp and Paper	Y	0	0	0
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	Y	0	44	44
PINC	Pipeline Incidents	Y	0	2	2
PRT	Private and Retail Fuel Storage Tanks	Y	0	7	7
PTTW	Permit to Take Water	Y	0	0	0
REC	Ontario Regulation 347 Waste Receivers Summary	Y	0	1	1
RSC	Record of Site Condition	Y	0	4	4
RST	Retail Fuel Storage Tanks	Y	0	8	8
SCT	Scott's Manufacturing Directory	Y	0	22	22
SPL	Ontario Spills	Y	1	51	52
SRDS	Wastewater Discharger Registration Database	Y	0	0	0
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0
VAR	Variances for Abandonment of Underground Storage Tanks	Y	0	0	0
WDS	Waste Disposal Sites - MOE CA Inventory	Y	0	0	0
WDSH	Waste Disposal Sites - MOE 1991 Historical Approval Inventory	Y	0	0	0
WWIS	Water Well Information System	Y	0	80	80
	Total:		1	744	745

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
116	SPL	TRANSPORT TRUCK	NORTH AUGUSTA ROAD AT THE 401 MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON	ENE/0.2	1.91	13

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
1	SPL	Musket Transport Ltd. <UNOFFICIAL>	Highway 401 WB @ Highway 29 (Exit 696) Brockville ON	ESE/18.3	-0.21	137
2	WWIS		lot 12 con 1 ON ***Well ID:*** 3600647	W/189.1	2.12	138
3	EHS		2399 Parkedale Ave Brockville ON K6V3G9	NNE/171.4	0.02	140
4	EHS		2399 Parkedale Avenue Brockville ON K6V 3G9	N/179.1	0.06	140
5	WWIS		lot 13 con 2 ON ***Well ID:*** 3600949	W/207.5	2.98	141
6	WWIS		lot 12 con 1 ON ***Well ID:*** 3600646	W/211.9	2.98	143
7	WWIS		ON ***Well ID:*** 3607065	WNW/231.6	3.56	146
8	SPL		REAR OF 2399 PARDALE AVE,1,000 ISLANDS \ BROCKVILLE CITY ON	N/205.8	0.45	148
8	PES	WHEELER'S YOUR INDEPENDENT GROCER/702320 ONT. LTD.	2399 PARKEDALE AVE W BROCKVILLE ON K6V3G9	N/205.8	0.45	149
8	PES	LOBLAWS INC. O/A BROCKVILLE YOUR INDEPENDENT GROCER	2399 PARKDALE AVE BROCKVILLE ON K6V3G9	N/205.8	0.45	149
8	GEN	SEARS CANADA INC.	2399 PARKDALE AVE. BROCKVILLE ON K6V 3G9	N/205.8	0.45	149

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
8	GEN	SEARS CANADA INC.	2399 PARKDALE AVENUE BROCKVILLE ON K6V 3G9	N/205.8	0.45	150
8	GEN	TAWCO CLEANING CENTRE	1000 ISLANDS MALL 2399 PARKDALE AVE. BROCKVILLE ON K0E 1T0	N/205.8	0.45	150
8	GEN	TAWCO CLEANING CENTRE 04-084	1000 ISLANDS MALL 2399 PARKDALE AVE. BROCKVILLE ON K0E 1T0	N/205.8	0.45	150
8	GEN	TAWCO CLEANING CENTRE	1000 ISLANDS MALL 2399 PARKDALE AVENUE BROCKVILLE ON K6V 3G9	N/205.8	0.45	150
8	GEN	WAL-MART INC.	STORE #3006 - 1000 ISLANDS MALL 535 PARKDALE AVENUE BROCKVILLE ON K6V 3G9	N/205.8	0.45	151
8	GEN	WAL-MART CANADA INC.	STORE #3006 - 1000 ISLANDS MALL 535 PARKDALE AVENUE BROCKVILLE ON K6V 3G9	N/205.8	0.45	151
8	GEN	SHOPPERS DRUG MART	1000 ISLANDS MALL 2399 PARKDALE BOULEVARD BROCKVILLE ON K6V 3G9	N/205.8	0.45	152
8	GEN	WAL-MART CANADA CORP.	535 PARKDALE AVENUE STORE #3006 BROCKVILLE ON K6V 3G9	N/205.8	0.45	152
8	GEN	RBC Financial Group	1000 Islands Mall Brockville ON K6V 3G9	N/205.8	0.45	152
8	PES	SHOPPERS DRUG MART #0935 (1000 ISLANDS MALL)	2399 PARKEDALE AVENUE BROCKVILLE ON K6V 3G9	N/205.8	0.45	153
8	PES	MARK S. LESLIE APOTHECARY LTD.O/A SHOPPERS DRUG MART	2399 PARKEDALE AVE, 1000 ISLAND MALL BROCKVILLE ON K6V 3G9	N/205.8	0.45	153
8	PES	SHOPPERS DRUG MART #0935 (1000 ISLANDS MALL)	2399 PARKEDALE AVENUE BROCKVILLE ON K6V 3G9	N/205.8	0.45	153
8	GEN	SEARS CANADA INC.	2399 PARKDALE AVENUE BROCKVILLE ON	N/205.8	0.45	154

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
8	GEN	Altima 1000 Islands Dental Centre	2399 Parkdale Ave, Unit 15 Brockville ON K6V 3G9	N/205.8	0.45	154
8	GEN	Altima 1000 Islands Dental Centre	2399 Parkdale Ave, Unit 15 Brockville ON K6V 3G9	N/205.8	0.45	154
8	PES	SHOPPERS DRUG MART #0935 (1000 ISLANDS MALL)	2399 PARKEDALE AVENUE BROCKVILLE ON K6V3G9	N/205.8	0.45	155
8	PES	MARK S. LESLIE APOTHECARY LTD.O/A SHOPPERS DRUG MART	2399 PARKEDALE AVE, 1000 ISLAND MALL BROCKVILLE ON K6V 3G9	N/205.8	0.45	155
8	GEN	Altima 1000 Islands Dental Centre	2399 Parkdale Ave, Unit 15 Brockville ON K6V 3G9	N/205.8	0.45	156
8	GEN	Mark S. Leslie Apothecary Ltd.	2399 PARKEDALE AVE, UNIT 27 Brockville ON K6V 3G9	N/205.8	0.45	156
8	GEN	Mark S. Leslie Apothecary Ltd.	2399 PARKEDALE AVE, UNIT 27 Brockville ON K6V 3G9	N/205.8	0.45	156
8	GEN	Mark S. Leslie Apothecary Ltd.	2399 PARKEDALE AVE, UNIT 27 Brockville ON K6V 3G9	N/205.8	0.45	157
8	GEN	Sears Canada Inc.	2399 Parkedale Avenue Brockville ON K6V 3G9	N/205.8	0.45	157
8	PES	MARK S. LESLIE APOTHECARY LTD.O/A SHOPPERS DRUG MART	2399 PARKEDALE AVE, 1000 ISLAND MALL BROCKVILLE ON K6V3G9	N/205.8	0.45	158
8	PES	702320 ONT. LTD./WHEELER'S YOUR INDEPENDENT GROCER	2399 PARKEDALE AVENUE BROCKVILLE ON K6V3G9	N/205.8	0.45	158
8	PES	NATIONAL GROCERS CO. LTD.	2399 PARKEDALE AVENUE BROCKVILLE ON K6V3G9	N/205.8	0.45	158

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
8	PES	WHEELER'S YOUR INDEPENDENT GROCER/702320 ONT. LTD.	2399 PARKEDALE AVE W BROCKVILLE ON K6V3G9	N/205.8	0.45	159
8	GEN	Caroly Burpee Professional serv. LTD	2399 PARKEDALE AVE, UNIT 27 Brockville ON K6V 3G9	N/205.8	0.45	159
8	PES	CAROLYN BURPEE PROFESSIONAL PHARMACY SERVICES INC	2399 Parkedale AV Brockville ON K6V 3G9	N/205.8	0.45	159
8	SPL	Enbridge Gas Distribution Inc.	2399 Parkdale Ave Brockville ON	N/205.8	0.45	160
9	PES	ECONOMY VALU-MART/702320 ONTARIO LIMITED	2465 PARKDALE AVENUE BROCKVILLE ON K6V 5X9	WNW/249.9	3.90	160
9	HINC		2465 PARKDALE AVENUE BROCKVILLE ON	WNW/249.9	3.90	161
10	EHS		2399 Parkedale Avenue Brockville ON K6V 3G9	ENE/102.0	0.02	161
11	SCT	EMPLOYMENT & BUSINESS JOURNAL	125 STEWART BLVD SUITE 211B BROCKVILLE ON K6V 4W4	SE/63.8	-0.08	162
11	PES	ZELLERS LTD	125 STEWART BLVD BROCKVILLE ON	SE/63.8	-0.08	162
11	PES	771485 ONTARIO LIMITED RON'S NO FRILLS	125 STEWART BLVD. BROCKVILLE ON K0E 1R0	SE/63.8	-0.08	162
11	SCT	EMPLOYMENT & BUSINESS JOURNAL	125 STEWART BLVD SUITE 211B BROCKVILLE ON K6V 4W4	SE/63.8	-0.08	163
11	SCT	6 G INDUSTRIES INC	125 STEWART BLVD UNIT 201 BROCKVILLE ON K6V	SE/63.8	-0.08	163

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
11	RST	ZIPPY LUBE & CAR CLEAN-UP	125 STEWART BLVD BROCKVILLE ON K6V 4W4	SE/63.8	-0.08	163
11	SCT	EBJ PUBLISHING INC.	125 Stewart Blvd Suite 211B Brockville ON K6V 4W4	SE/63.8	-0.08	163
11	SPL	ZELLERS	125 STEWART BLVD., BEHIND THE ZELLERS STORE RETAIL STORE BROCKVILLE CITY ON	SE/63.8	-0.08	163
11	EHS		125 Stewart Blvd. Brockville ON	SE/63.8	-0.08	164
11	PES	771485 ONTARIO LIMITED/JACK & FAITH'S NO FRILLS	125 STEWART BLVD BROCKVILLE ON K6V6X9	SE/63.8	-0.08	164
11	GEN	DURANT'S ONE HOUR CLEANERS LIMITED	125 STEWART BLVD. (BROCKVILLE CENTRE) BROCKVILLE ON K6V 3P6	SE/63.8	-0.08	165
11	GEN	PHARMA PLUS DRUGS LTD	125 STEWART BOULEVARD BROCKVILLE ON K6V 4W4	SE/63.8	-0.08	165
11	GEN	BROCK (OUT OF BUS) 05-844	125 STEWART BLVD. BROCKVILLE ON K6V 4W4	SE/63.8	-0.08	165
11	GEN	DURANT'S ONE HOUR CLEANERS LIMITED12-443	125 STEWART BLVD. (BROCKVILLE CENTRE) BROCKVILLE ON K6V 3P6	SE/63.8	-0.08	165
11	GEN	PHARMA PLUS DRUGS LTD. 31-655	125 STEWART BLVD., BROCKVILLE C/O 5935 AIRPORT ROAD STEI 500 MISSISSAUGA ON L4V 1W5	SE/63.8	-0.08	166
11	GEN	BROCK PHOTO CENTER 05-844	125 STEWART BLVD. BROCKVILLE ON K6V 4W4	SE/63.8	-0.08	166
11	GEN	MAXWELLS DRYCLEANING SERVICE	125 STEWART BLVD. BROCKVILLE ON K6V 4W4	SE/63.8	-0.08	166

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
11	GEN	PHARMA PLUS DRUGS LTD.	125 STEWART BOULEVARD BROCKVILLE ON K6V 4W4	SE/63.8	-0.08	167
11	GEN	DURANT'S ONE HOUR CLEANERS LIMITED	BROCKVILLE CENTRE 125 STEWART BOULEVARD BROCKVILLE ON K6V 3P6	SE/63.8	-0.08	167
11	GEN	MAXWELLS DRYCLEANING SERVICE	125 STEWART BOULEVARD BROCKVILLE ON K6V 4W4	SE/63.8	-0.08	167
11	GEN	Eastern Enginering Group Inc	125 Stewart Blvd Suite 212 Brockville ON K6V 4W4	SE/63.8	-0.08	168
11	GEN	Zellers Inc.	125 Steward Blvd. Brockville ON K6V 4W4	SE/63.8	-0.08	168
11	EHS		125 Stewart Boulevard Brockville ON K6V 4W4	SE/63.8	-0.08	168
11	PES	ZELLERS STORE #107 - BROCKVILLE S.C.	125 STEWART BLVD BROCKVILLE ON K6V 4W4	SE/63.8	-0.08	168
11	PES	2062072 ONTARIO LIMITED O/A BRETT'S VALU-MART	125 STEWART BLVD BROCKVILLE ON K6V 4W4	SE/63.8	-0.08	169
11	CPU	239142 Investments Limited	125 Stewart Blvd Brockville ON K6V 4W4	SE/63.8	-0.08	169
11	GEN	Brockville Shopping Centre	125 Stewart Blvd. Brockville ON	SE/63.8	-0.08	170
11	SPL	Valu-Mart (Gary-Owner) <UNOFFICIAL>	125 Stewart Street Brockville ON	SE/63.8	-0.08	170
11	CPU	239142 Investments Limited	125 Stewart Blvd., Brockville, United Counties of Leeds and Grenville Part of Lot 12, Concession 1, Plan 238, Part Lot 5, Part 6 CITY OF BROCKVILLE ON	SE/63.8	-0.08	170
11	PES	2062072 ONTARIO LIMITED O/A BRETT'S VALU-MART	125 STEWART BLVD BROCKVILLE ON K6V 4W4	SE/63.8	-0.08	171

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
11	RSC	239142 Investments Limited	125 Stewart Blvd., Brockville, Ontario, K6V 4W4 ON K6V 4W4	SE/63.8	-0.08	171
11	PES	ZELLERS INC O/A ZELLERS STORE #107	125 STEWART BLVD BROCKVILLE ON K6V4W4	SE/63.8	-0.08	172
11	SPL	unknown<UNOFFICIAL>	125 Stewart Boulevard Brockville ON	SE/63.8	-0.08	172
11	PES	ZELLERS INC O/A ZELLERS STORE #107	125 STEWART BLVD BROCKVILLE ON K6V 4W4	SE/63.8	-0.08	173
11	PES	2062072 ONTARIO LIMITED O/A BRETT'S VALU-MART	125 STEWART BLVD BROCKVILLE ON K6V4W4	SE/63.8	-0.08	173
11	NPRI	ZELLERS	125 STEWART Boulevard BROCKVILLE ON K6V4W5	SE/63.8	-0.08	173
11	RST	OIL CHANGERS	125 STEWART BLVD BROCKVILLE ON K6V4W4	SE/63.8	-0.08	176
11	CPU	239142 Investments Limited	Brockville Shopping Centre Address: 125 Stewart Blvd Part Lot 12, Concession 1, Plan 238, Part Lot 5, Part 6 City of Brockville, United Counties of Leeds and Grenville CITY OF BROCKVILLE ON	SE/63.8	-0.08	176
11	RST	1000 ISLAND LUBE CENTER LTD	125 STEWART BLVD BROCKVILLE ON K6V4W4	SE/63.8	-0.08	176
11	SPL		125 Stewart Blvd Part Lot 12 Concession 1 Plan 238 Part Lot 5 Part 6 Brockville ON NA	SE/63.8	-0.08	177
11	GEN	First National Management Corporation	125 Stewart Blvd Brockville ON K6V 4W4	SE/63.8	-0.08	177
11	PES	ZELLERS INC O/A ZELLERS STORE #107	125 STEWART BLVD BROCKVILLE ON K6V4W4	SE/63.8	-0.08	177

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
11	PES	2125795 ONTARIO LIMITED O/A GEMMELL'S GARDEN CENTRE	18 - 125 STEWART BLVD BROCKVILLE ON K6V4W5	SE/63.8	-0.08	178
11	PES	771485 ONTARIO LIMITED/JACK & FAITH'S NO FRILLS	125 STEWART BLVD BROCKVILLE ON K6V6X9	SE/63.8	-0.08	178
11	PES	ZELLERS STORE #107 - BROCKVILLE S.C.	125 STEWART BLVD BROCKVILLE ON K6V4W4	SE/63.8	-0.08	179
11	GEN	First National Management Corporation	125 Stewart Blvd Brockville ON K6V 4W4	SE/63.8	-0.08	179
12	GEN	MINISTRY OF REVENUE	BROCKVILLE REGIONAL ASSESSMENT OFFICE 2479 PARKDALE AVE. BROCKVILLE ON K6V 3H2	W/249.9	5.02	179
12	GEN	MINISTRY OF REVENUE 27-397	BROCKVILLE REGIONAL ASSESSMENT OFFICE 2479 PARKDALE AVE. BROCKVILLE ON K6V 3H2	W/249.9	5.02	180
12	GEN	Rideau Community Health Services	2-2479 Parkedale Rd Brockville ON K6V 3H2	W/249.9	5.02	180
12	GEN	Rideau Community Health Services	2-2479 Parkedale Rd Brockville ON K6V 3H2	W/249.9	5.02	180
13	WWIS		ON ***Well ID:*** 3600487	ENE/68.6	0.02	180
14	GEN	Northern Property New LP2	1-4 Balmoral Brockville ON K6V 6K1	E/92.5	-3.17	183
14	GEN	Northern Property New LP2	1-4 Balmoral Brockville ON K6V 6K1	E/92.5	-3.17	183
15	EHS		1 Balmoral Pl Brockville ON K6V6J9	ESE/107.5	-3.68	183

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
16	EHS		2511, 2523, 2539 & 2545 Parkdale Ave & 325 Stewart Blvd, Brockville Brockville ON K6V 4W8	WSW/217.6	5.02	183
17	GEN	1195149 Ontario Ltd	325 Stewart Blvd. Brockville ON K6V4W8	W/247.2	5.02	184
18	EHS		Parkedale Ave Stewart Blvd Brockville ON	WSW/182.8	5.02	184
19	WWIS		BROCKVILLE ON ***Well ID:*** 7302213	NNE/223.7	-0.17	184
20	MNR	Section A-4	ON	SW/37.1	4.92	187
21	SPL	TRANSPORT TRUCK	HWY 401 JUST WEST OF HWY 29 MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON	SW/12.5	5.02	188
21	SPL	PUROLATOR COURIER LTD.	HWY #401 WESTBOUND, STEWART BLVD NORTH, PARKEDALE AVE EAST & NORTH AUGUSTA RD. MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON	SW/12.5	5.02	188
21	SPL	HYDRO ONE	HWY 29 & 401 OVERPASS TRANSFORMER BROCKVILLE CITY ON	SW/12.5	5.02	189
22	SPL		329 Stewart Blvd. Brockville ON K6V 4W8	WSW/249.9	5.02	189
22	EHS		329 Stewart Boulevard Brockville ON K6V 4W8	WSW/249.9	5.02	190
22	GEN	Canadian Tire Corporation, limited	329 Stewart St. Brockville ON K6V 4W8	WSW/249.9	5.02	190
22	GEN	Canadian Tire Corporation, limited	329 Stewart St. Brockville ON K6V 4W8	WSW/249.9	5.02	190

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
22	GEN	Canadian Tire Corporation, limited	329 Stewart St. Brockville ON K6V 4W8	WSW/249.9	5.02	191
23	HINC		121 BROOKVIEW CRESCENT BROCKVILLE ON K6V 4P4	E/148.2	-4.16	191
24	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	325 STEWART BLVD BROCKVILLE ON K6V 4W8	WSW/207.7	5.02	192
24	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	325 STEWART BLVD BROCKVILLE ON K6V 4W8	WSW/207.7	5.02	192
24	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	325 STEWART BLVD BROCKVILLE ON K6V 4W8	WSW/207.7	5.02	192
24	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	325 STEWART BLVD BROCKVILLE ON K6V 4W8	WSW/207.7	5.02	193
24	FST	SUNCOR ENERGY PRODUCTS PARTNERSHIP	325 STEWART BLVD BROCKVILLE ON K6V 4W8	WSW/207.7	5.02	193
24	RST	PETROCAN CARWASH	325 STEWART BLVD BROCKVILLE ON K6V4W8	WSW/207.7	5.02	193
24	GEN	1195149 Ontario Ltd	325 Stewart Blvd. Brockville ON	WSW/207.7	5.02	193
24	GEN	1195149 Ontario Ltd	325 Stewart Blvd. Brockville ON K6V4W8	WSW/207.7	5.02	194
24	GEN	1195149 Ontario Ltd	325 Stewart Blvd. Brockville ON K6V4W8	WSW/207.7	5.02	194
24	GEN	1195149 Ontario Ltd	325 Stewart Blvd. Brockville ON K6V4W8	WSW/207.7	5.02	194
24	GEN	1195149 Ontario Ltd	325 Stewart Blvd. Brockville ON K6V4W8	WSW/207.7	5.02	195

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
25	SPL	TRANSPORT TRUCK	ON RAMP TO HWY 401 WESTBOUND AT HWY 401 AND HWY 29. MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON	SW/55.9	5.02	195
25	SPL	TRANSPORT TRUCK	401 1.5 MILES WEST OF HWY. 29 MOTOR VEHICLE (OPERATING FLUID) ELIZABETHTOWN TWP. ON	SW/55.9	5.02	195
26	WWIS		Leeds and Grenville ON ***Well ID:*** 7104241	WSW/224.0	5.02	196
26	WWIS		Brockville ON ***Well ID:*** 7106557	WSW/224.0	5.02	199
27	WWIS		lot 12 con 1 ON ***Well ID:*** 3600642	WSW/179.7	5.02	200
28	AST		ON	NE/199.1	-1.01	202
29	OPCB	St. Mary's School,	40 Central Avenue LOT 6, REG. PLAN 238 BROCKVILLE ON K6V 4N5	ESE/237.7	-5.09	202
29	OPCB	St. Mary's School,	40 Central Avenue LOT 6, REG. PLAN 238 BROCKVILLE ON K6V 4N5	ESE/237.7	-5.09	203
29	OPCB	St. Mary's School,	40 Central Avenue LOT 6, REG. PLAN 238 BROCKVILLE ON K6V 4N5	ESE/237.7	-5.09	203
29	GEN	CATHOLIC DISTRICT SBE ONTARIO	ST. MARY CATHOLIC HIGH SCHOOL 40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	ESE/237.7	-5.09	203
29	GEN	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	ESE/237.7	-5.09	204
29	OPCB	St. Mary's School,	40 Central Avenue LOT 6, REG. PLAN 238 BROCKVILLE ON K6V 4N5	ESE/237.7	-5.09	204
29	NPCB	ST. MARY CATHOLIC HIGH SCHOOL	40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	ESE/237.7	-5.09	205

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
29	NPCB	ST. MARY'S SCHOOL	LOT 6, REG. PLAN 238 40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	ESE/237.7	-5.09	205
29	GEN	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON	ESE/237.7	-5.09	205
29	GEN	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON	ESE/237.7	-5.09	206
29	GEN	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON	ESE/237.7	-5.09	206
29	GEN	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	ESE/237.7	-5.09	207
29	GEN	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON	ESE/237.7	-5.09	208
29	GEN	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	ESE/237.7	-5.09	208
29	GEN	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	ESE/237.7	-5.09	209
29	GEN	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	ESE/237.7	-5.09	210
29	GEN	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	ESE/237.7	-5.09	210
29	GEN	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	ESE/237.7	-5.09	211
30	AST		ON	NE/203.7	-1.01	211

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
31	WWIS		BROCKVILLE ON **Well ID:** 7264500	S/131.8	5.08	212
32	WWIS		lot 12 con 1 ON **Well ID:** 3600643	SSE/184.3	2.02	215
33	WWIS		Brockville ON **Well ID:** 7215265	S/144.6	4.60	218
34	WWIS		BROCKVILLE ON **Well ID:** 7264499	S/134.0	5.08	221
35	WWIS		Brockville ON **Well ID:** 7048684	SSE/216.3	0.41	224
36	WWIS		BRAKVILLE ON **Well ID:** 3616923	S/188.6	2.53	227
37	EHS		154 Stewart Boulevard Brockville ON	S/162.0	4.17	228
38	WWIS		ON **Well ID:** 7255814	S/175.0	3.22	228
39	SPL	IMPERIAL OIL	ESSO STATION 154 STEWART ST ESSO SERVICE STATION BROCKVILLE CITY ON K6V 4W6	S/153.0	4.99	229
39	PRT	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V4W6	S/153.0	4.99	230
39	PRT	HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V4W6	S/153.0	4.99	230
39	EHS		154 Stewart Blvd Brockville ON K6V 4W6	S/153.0	4.99	230
39	GEN	IMPERIAL OIL LIMITED	154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	S/153.0	4.99	230

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
39	GEN	IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON	S/153.0	4.99	230
39	EXP	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	231
39	EXP	HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	231
39	EXP	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	231
39	EXP	HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	231
39	EXP	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	232
39	EXP	HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	232
39	EXP	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	232
39	EXP	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	233
39	EXP	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON	S/153.0	4.99	233
39	EXP	HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	233
39	EXP	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON	S/153.0	4.99	233

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
39	EXP	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON	S/153.0	4.99	234
39	EXP	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON	S/153.0	4.99	234
39	EXP	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON	S/153.0	4.99	234
39	EXP	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON	S/153.0	4.99	234
39	GEN	IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON	S/153.0	4.99	235
39	EHS		154 Stewart Blvd Brockville ON	S/153.0	4.99	235
39	GEN	IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON	S/153.0	4.99	235
39	GEN	IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON	S/153.0	4.99	235
39	GEN	IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	S/153.0	4.99	236
39	GEN	IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON	S/153.0	4.99	236
39	EXP	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	236
39	EXP	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	237
39	EXP	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	237

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
39	EXP	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	237
39	EXP	HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	237
39	EXP	HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	238
39	EXP	HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	238
39	EXP	HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	238
39	EXP	HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	S/153.0	4.99	238
39	GEN	IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	S/153.0	4.99	239
39	GEN	IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	S/153.0	4.99	239
39	GEN	IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	S/153.0	4.99	240
39	GEN	IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	S/153.0	4.99	240
40	CA	PARKE-DAVIS DIV. WARNER LAMB. OF CANADA	2337 PARKEDALE AVENUE BROCKVILLE CITY ON	NE/185.8	-0.97	241
40	CA	PARKE DAVIS CANADA INC.	LOT 11 CONC. 1 BROCKVILLE CITY ON	NE/185.8	-0.97	241

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
40	CA	PARKE-DAVIS CANADA, INC.	LOT 11 CONC. 1 BROCKVILLE CITY ON	NE/185.8	-0.97	241
40	CA	WARNER-LAMBERT CANADA	2337 PARKEDALE AVE. BROCKVILLE CITY ON	NE/185.8	-0.97	241
40	CA	WARNER-LAMBERT CANADA INC.	2337 PARKEDALE AVENUE BROCKVILLE CITY ON	NE/185.8	-0.97	242
40	CA	PARKE-DAVIS DIV. WARNER LAMB. OF CANADA	2337 PARKEDALE AVENUE BROCKVILLE CITY ON	NE/185.8	-0.97	242
40	CA	PARKE-DAVIS, DIV. OF WARNER LAMBERT CANA	2337 PARKEDALE AVENUE BROCKVILLE ON	NE/185.8	-0.97	242
40	SPL	PARKE-DAVIS CANADA INC.	BROCKVILLE PLANT 2337 PARKDALE AVENUE BROCKVILLE CITY ON	NE/185.8	-0.97	243
40	SCT	WARNER-LAMBERT PARKE-DAVIS	2337 PARKEDALE AVE W BROCKVILLE ON K6V	NE/185.8	-0.97	243
40	CA	PARKE-DAVIS DIV. WARNER LAMB. OF CANADA	2337 PARKEDALE AVENUE BROCKVILLE CITY ON	NE/185.8	-0.97	243
40	CA	PARKE-DAVIS DIV. WARNER LAMB. OF CANADA	2337 PARKEDALE AVENUE BROCKVILLE CITY ON	NE/185.8	-0.97	244
40	CA	PARKE-DAVIS DIV. WARNER LAMB. OF CANADA	2337 PARKEDALE AVENUE BROCKVILLE CITY ON	NE/185.8	-0.97	244
40	CA	PARKE-DAVIS DIV. WARNER LAMB. OF CANADA	2337 PARKEDALE AVENUE BROCKVILLE CITY ON	NE/185.8	-0.97	244
40	CA	PARKE-DAVIS DIV. WARNER LAMB. OF CANADA	2337 PARKEDALE AVENUE BROCKVILLE CITY ON	NE/185.8	-0.97	245
40	SPL	PARKE-DAVIS CANADA INC.	2337 PARKEDALE AVENUE BROCKVILLE PLANT 2337 PARKDALE AVENUE	NE/185.8	-0.97	245

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			BROCKVILLE CITY ON			
40	SPL	PARKE-DAVIS CANADA INC.	BROCKVILLE PLANT 2337 PARKDALE AVENUE BROCKVILLE CITY ON	NE/185.8	-0.97	246
40	SPL	TRILLIUM HEALTH CARE MANUFACTU	LOCAL CREEK. 2337 PARKDALE AVE. BROCKVILLE CITY ON	NE/185.8	-0.97	246
40	NPRI	WARNER-LAMBERT CANADA INC	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NE/185.8	-0.97	247
40	NPRI	WARNER-LAMBERT CANADA INC	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NE/185.8	-0.97	247
40	NPRI	WARNER-LAMBERT CANADA INC.	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NE/185.8	-0.97	248
40	NPRI	TRILLIUM HEALTH CARE MANUFACTURING	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NE/185.8	-0.97	249
40	SCT	Trillium Health Care Manufacturing Inc.	2337 Parkdale Ave W Brockville ON	NE/185.8	-0.97	249
40	CA	WARNER-LAMBERT CANADA	2337 PARKDALE AVE. BROCKVILLE ON	NE/185.8	-0.97	250
40	CA		2337 Parkedale Avenue Brockville ON	NE/185.8	-0.97	250
40	CA		2337 Parkedale Avenue Brockville ON	NE/185.8	-0.97	250
40	CA		2337 Parkedale Avenue Brockville ON	NE/185.8	-0.97	251
40	EBR	Parke-Davis Div. Warner Lambert of Canada Inc.	2337 Parkedale Avenue CITY OF BROCKVILLE ON	NE/185.8	-0.97	251

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
40	EBR	Parke-Davis Div. Warner Lambert of Canada Inc.	2337 Parkedale Avenue CITY OF BROCKVILLE ON	NE/185.8	-0.97	251
40	EBR	Parke-Davis Div. Warner Lambert of Canada Inc.	2337 Parkedale Avenue CITY OF BROCKVILLE ON	NE/185.8	-0.97	252
40	EBR	Parke-Davis Div. Warner Lambert of Canada Inc.	2337Parkedale Avenue, Brockville City CITY OF BROCKVILLE ON	NE/185.8	-0.97	252
40	EBR	Trillium Health Care Manufacturing Inc.	2337 Parkedale Avenue Brockville Ontario K6V 5W5 CITY OF BROCKVILLE ON	NE/185.8	-0.97	253
40	EBR	Trillium Health Care Manufacturing Inc.	2337 Parkedale Avenue Brockville Ontario K6V 5W5 CITY OF BROCKVILLE ON	NE/185.8	-0.97	253
40	NPRI	TRILLIUM HEALTH CARE MANUFACTURING	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NE/185.8	-0.97	254
40	EBR	Trillium Health Care Products Inc.	2337 Parkedale Avenue Brockville Ontario K6V 5W5 CITY OF BROCKVILLE ON	NE/185.8	-0.97	255
40	EBR	Trillium Health Care Products Inc.	2337 Parkedale Avenue Brockville Ontario K6V 5W5 CITY OF BROCKVILLE ON	NE/185.8	-0.97	255
40	GEN	PARKE-DAVIS CANADA INC	2337 PARKEDALE AVE. BROCKVILLE ON K6V 5W5	NE/185.8	-0.97	256
40	GEN	PARKE-DAVIS CANADA INC.	DIV. OF WARNER-LAMBERT CANADA INC. 2337 PARKDALE AVE. BROCKVILLE ON K6V 5W5	NE/185.8	-0.97	256
40	GEN	PARKE-DAVIS, DIV. OF	2337 PARKEDALE AVENUE BROCKVILLE ON K6V 5W5	NE/185.8	-0.97	257
40	GEN	PARKE-DAVIS CANADA INC. 30-002	DIV. OF WARNER-LAMBERT CANADA INC. 2337 PARKDALE AVE. BROCKVILLE ON K6V 5W5	NE/185.8	-0.97	258

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
40	GEN	PARKE-DAVIS, DIV. (SEE & USE ON2369500)	2337 PARKEDALE AVENUE BROCKVILLE ON K6V 5W5	NE/185.8	-0.97	258
40	GEN	TRILLIUM HEALTH CARE MANUFACTURING	2337 PARKDALE AVENUE BROCKVILLE ON K6V 5W5	NE/185.8	-0.97	259
40	GEN	TRILLIUM HEALTH CARE MANUFACTURING	2337 PARKEDALE AVENUE BROCKVILLE ON K6V 5W5	NE/185.8	-0.97	260
40	NPRI	TRILLIUM HEALTH CARE PRODUCTS	2337 PARKEDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V 5W5	NE/185.8	-0.97	261
40	SCT	Trillium Health Care Products Inc.	2337 Parkdale Ave W Brockville ON K6V 5W5	NE/185.8	-0.97	262
40	NPRI	TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NE/185.8	-0.97	262
40	SCT	Trillium Health Care Products	2337 Parkedale Ave Brockville ON K6V 5W5	NE/185.8	-0.97	263
40	NPRI	TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NE/185.8	-0.97	263
40	NPRI	TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NE/185.8	-0.97	265
40	NPRI	TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NE/185.8	-0.97	266
40	SPL		TRILLIUM HEALTH CARE PRODUCTS 2337 PARKDALE AVENUE<UNOFFICIAL> Brockville ON	NE/185.8	-0.97	268
40	EHS		2337 Parkdale Avenue Brockville ON K6V 5W5	NE/185.8	-0.97	268

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
40	NPRI	TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NE/185.8	-0.97	269
40	NPRI	TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NE/185.8	-0.97	270
40	CA	Trillium Health Care Products Inc.	2337 Parkedale Avenue Brockville ON	NE/185.8	-0.97	272
40	NPRI	TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NE/185.8	-0.97	272
40	EBR	Trillium Health Care Products Inc.	2337 Parkedale Avenue Brockville, United Counties Of Leeds & Grenville CITY OF BROCKVILLE ON	NE/185.8	-0.97	273
40	NPRI	TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NE/185.8	-0.97	274
40	GEN	TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON	NE/185.8	-0.97	275
40	NPRI	TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NE/185.8	-0.97	276
40	GEN	TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON	NE/185.8	-0.97	277
40	GEN	TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON	NE/185.8	-0.97	278
40	GEN	TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON	NE/185.8	-0.97	279
40	NPRI	TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NE/185.8	-0.97	279

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
40	EHS		2337 Parkedale Ave Brockville ON K6V3G9	NE/185.8	-0.97	280
40	GEN	TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON	NE/185.8	-0.97	280
40	ECA	Trillium Health Care Products Inc.	2337 Parkedale Ave Brockville ON	NE/185.8	-0.97	281
40	ECA	Trillium Health Care Manufacturing Inc.	2337 Parkedale Avenue Brockville ON K6V 5W5	NE/185.8	-0.97	282
40	ECA	Trillium Health Care Products Inc.	2337 Parkedale Avenue Brockville ON K6V 5W5	NE/185.8	-0.97	282
40	ECA	Trillium Health Care Manufacturing Inc.	2337 Parkedale Avenue Brockville ON K6V 5W5	NE/185.8	-0.97	282
40	ECA	Trillium Health Care Products Inc.	2337 Parkedale Ave Brockville ON K6V 5W5	NE/185.8	-0.97	282
40	ECA	Trillium Health Care Products Inc.	2337 Parkedale Avenue Brockville ON K6V 5W5	NE/185.8	-0.97	283
40	GEN	TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON K6V 5W5	NE/185.8	-0.97	283
40	GEN	TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON K6V 5W5	NE/185.8	-0.97	284
40	GEN	TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON K6V 5W5	NE/185.8	-0.97	285
40	GEN	TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON K6V 5W5	NE/185.8	-0.97	286
40	EHS		2337 Parkedale Avenue Brockville ON K6V 3G9	NE/185.8	-0.97	288

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
40	EHS		2337 Parkedale Ave Brockville ON K6V3G9	NE/185.8	-0.97	288
40	EHS		2337 Parkedale Avenue Brockville ON K6V 3G9	NE/185.8	-0.97	288
40	GEN	TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON K6V 5W5	NE/185.8	-0.97	288
40	EHS		2337 Parkedale Avenue Brockville ON K6V 3G9	NE/185.8	-0.97	290
40	EHS		Portion of 2337 Parkedale Ave Brockville ON K6V 3G9	NE/185.8	-0.97	290
40	EHS		Portion of 2337 Parkedale Ave Brockville ON K6V 3G9	NE/185.8	-0.97	290
41	EHS		160 Stewart Blvd Brockville ON K6V4W6	SSW/124.1	5.02	291
42	WWIS		BROCKVILLE ON ***Well ID:*** 3616423	S/207.4	2.87	291
43	WWIS		lot 12 con 1 ON ***Well ID:*** 3600645	S/210.1	2.87	294
44	WWIS		ON ***Well ID:*** 3600482	WSW/209.9	6.86	296
45	WWIS		BROCKVILLE ON ***Well ID:*** 7266770	S/154.1	5.02	298
46	WWIS		lot 11 con 1 BROCKVILLE ON ***Well ID:*** 3616332	NE/212.3	-0.94	301
47	WWIS		lot 13 con 1 ON ***Well ID:*** 3600648	WSW/239.6	7.03	303

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
48	WWIS		lot 12 con 1 ON ***Well ID:*** 3600641	SW/56.0	5.14	305
49	EHS		3050 Jefferson Drive Brockville ON K6V 6N3	WSW/244.0	8.14	308
49	EHS		3050 Jefferson Drive Brockville ON K6V 6N3	WSW/244.0	8.14	308
49	EHS		3050 Jefferson Dr Brockville ON K6V6N3	WSW/244.0	8.14	308
50	CA	TACO BELL OF CANADA	3049 JEFFERSON DRIVE BROCKVILLE CITY ON K6V 6N7	SW/99.8	6.00	308
50	SPL	TRANSPORT TRUCK	3049 JEFFERSON DRIVE SAVE-A-CENTRE PARKING LOT MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON K6V 6N7	SW/99.8	6.00	309
50	GEN	GREAT ATLANTIC & PACIFIC CO. OF CDA.LTD.	SAVE-A-CENTRE #903 3049 JEFFERSON STREET BROCKVILLE ON K6V 6N3	SW/99.8	6.00	309
50	GEN	PHARMACY, THE	3049 TEFFERSON STREET BROCKVILLE ON KV6 6N3	SW/99.8	6.00	309
50	GEN	PHARMACY, THE	3049 JEFFERSON STREET BROCKVILLE ON K6V 6N3	SW/99.8	6.00	310
50	GEN	PHARMACY, (SEE & USE ON2371813)	3049 TEFFERSON STREET BROCKVILLE ON KV6 6N3	SW/99.8	6.00	310
50	GEN	THE GREAT ATLANTIC & PACIFIC CO. OF CANADA, LTD.	3049 JEFFERSON STREET BROCKVILLE ON K6V 6N3	SW/99.8	6.00	310
50	SPL	Save-A-Center parking lot<UNOFFICIAL>	3049 Jefferson Drive Brockville ON K6V 6N7	SW/99.8	6.00	311
50	SPL	Hydro One Networks Inc.	3049 Jefferson Dr Brockville ON K6V 6N7	SW/99.8	6.00	311

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
50	PES	METRO ONTARIO INC O/A METRO/FOOD BASICS # 921	3049 JEFFERSON STREET BROCKVILLE ON K6V6N3	SW/99.8	6.00	312
50	PES	METRO ONTARIO INC O/A METRO/FOOD BASICS # 921	3049 Jefferson Street Brockville ON K6V 6N3	SW/99.8	6.00	312
50	NPRI	THE GREAT ATLANTIC & PACIFIC COMPANY OF CANAD	3049 JEFFERSON Drive BROCKVILLE ON K6V6N7	SW/99.8	6.00	312
50	PES	METRO ONTARIO INC O/A METRO/FOOD BASICS # 921	3049 JEFFERSON STREET BROCKVILLE ON K6V6N3	SW/99.8	6.00	315
51	AST		ON	NE/219.3	-2.95	315
52	WWIS		lot 14 con 1 BROCKVILLE ON ***Well ID:*** 3616334	WSW/218.8	9.70	316
52	WWIS		BROCKVILLE ON ***Well ID:*** 3616068	WSW/218.8	9.70	317
53	GEN	glidden paint, store 835	7748 kent blvd, #8 brockville ON K6V 7J9	WSW/199.7	9.01	319
54	SPL	GLIDDEN PAINTS	KENT BLVD. RETAIL OUTLET BROCKVILLE CITY ON	WSW/199.6	9.01	320
54	GEN	GLIDDEN PAINTS & WALL PAPER	7748 KENT ROAD BLVD., UNIT 8 BROCKVILLE ON K6V 7J9	WSW/199.6	9.01	320
55	SPL		mile marker 704 Hwy 401 westbound Augusta ON	SW/16.0	5.02	321
56	EHS		7777 Kent Boulevard Brockville ON K6V 6N7	WSW/151.0	7.97	321
57	CA	P.U.C. BROCKVILLE	MAPLE AVE./PARK ST. BROCKVILLE CITY ON	E/213.0	-5.71	321

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
58	CA	BLACK & DECKER CANADA INC.	100 CENTRAL AVE. BROCKVILLE CITY ON	SSW/243.3	3.45	322
58	CA	BLACK & DECKER CANADA INC.	100 CENTRAL AVE. *** BROCKVILLE CITY ON	SSW/243.3	3.45	322
58	CA	BLACK & DECKER CANADA INC.	100 CENTRAL AVENUE BROCKVILLE CITY ON	SSW/243.3	3.45	322
58	CA	BLACK & DECKER CANADA INC.	100 CENTRAL AVE. BROCKVILLE CITY ON	SSW/243.3	3.45	322
58	CA	BLACK & DECKER CANADA INC.	100 CENTRAL AVENUE BROCKVILLE CITY ON	SSW/243.3	3.45	323
58	CA	BLACK & DECKER CANADA INC.	100 CENTRAL AVE. BROCKVILLE CITY ON	SSW/243.3	3.45	323
58	CA	BLACK & DECKER CANADA INC.	100 CENTRAL AVENUE BROCKVILLE CITY ON	SSW/243.3	3.45	323
58	NPCB	BLACK AND DECKER CANADA INC	100 CENTRAL AVE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	324
58	SCT	BLACK & DECKER CANADA INC.	100 CENTRAL AVE W BROCKVILLE ON K6V 4N8	SSW/243.3	3.45	324
58	CA	BLACK & DECKER CANADA (1989) INC.	100 CENTRAL AVENUE BROCKVILLE CITY ON	SSW/243.3	3.45	324
58	SPL	BLACK AND DECKER	100 CENTRAL AVENUE BROCKVILLE PLANT 100 CENTRAL AVENUE BROCKVILLE CITY ON	SSW/243.3	3.45	324
58	CA	BLACK & DECKER CANADA (1989) INC.	100 CENTRAL AVENUE BROCKVILLE CITY ON	SSW/243.3	3.45	325
58	NPCB	BLACK AND DECKER CANADA INC	100 CENTRAL AVE CENTRAL AVE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	325

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
58	SPL	CAMOLOR	100 CENTRAL AVENUE BROCKVILLE CITY ON	SSW/243.3	3.45	326
58	CA	BLACK & DECKER CAN. INC.	100 CENTRAL AVE. BROCKVILLE CITY ON	SSW/243.3	3.45	326
58	CA	BLACK AND DECKER CANADA INC.	100 CENTRAL AVE. BROCKVILLE CITY ON	SSW/243.3	3.45	326
58	CA	BLACK & DECKER	100 CENTRAL AVE. BROCKVILLE CITY ON	SSW/243.3	3.45	327
58	CA	BLACK & DECKER	100 CENTRAL AVE. BROCKVILLE CITY ON	SSW/243.3	3.45	327
58	CA		100 Central Avenue, P.O. Box 126 Brockville ON	SSW/243.3	3.45	327
58	EBR	Black & Decker Canada (1989) Inc.	100 CENTRAL AVENUE, BROCKVILLE CITY CITY OF BROCKVILLE ON	SSW/243.3	3.45	328
58	EBR	Camalor Mfg. Inc.	100 Central Avenue, P.O. Box 126 Brockville Ontario N6V 5V2 CITY OF BROCKVILLE ON	SSW/243.3	3.45	328
58	REC	BLACK AND DECKER CANADA INC.	100 CENTRAL AVE. BROCKVILLE ON	SSW/243.3	3.45	328
58	OPCB	BLACK AND DECKER CANADA INC	100 CENTRAL AVE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	329
58	OPCB	BLACK AND DECKER CANADA INC	100 CENTRAL AVE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	329
58	OPCB	BLACK AND DECKER CANADA INC	100 CENTRAL AVE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	329

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
58	OPCB	BLACK AND DECKER CANADA INC	100 CENTRAL AVE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	329
58	OPCB	BLACK AND DECKER CANADA INC	100 CENTRAL AVE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	330
58	GEN	BLACK & DECKER CANADA INC.	100 CENTRAL AVE. W. BROCKVILLE ON K6V 4N8	SSW/243.3	3.45	330
58	GEN	BLACK & DECKER CANADA INC. 05-043	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	331
58	GEN	BLACK & DECKER CANADA INC	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	332
58	GEN	BLACK & DECKER CANADA INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	333
58	GEN	CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	334
58	EHS		100 Central Avenue Brockville ON	SSW/243.3	3.45	335
58	OPCB	BLACK AND DECKER CANADA INC	100 CENTRAL AVE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	335
58	SCT	Camalor Mfg. Inc.	100 Central Ave W Brockville ON K6V 4N8	SSW/243.3	3.45	335
58	NPCB	BLACK AND DECKER CANADA INC	100 CENTRAL AVE W BROCKVILLE ON K6V 4N8	SSW/243.3	3.45	335
58	EBR	Black & Decker Canada Inc.	100 Central Avenue Brockville, United Counties of Leeds and Grenville K6V 5W6 CITY OF BROCKVILLE ON	SSW/243.3	3.45	336
58	EHS		100 Central Ave W Brockville ON K6V 4N8	SSW/243.3	3.45	336

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
58	CA	Black & Decker Canada Inc.	100 Central Ave Brockville ON	SSW/243.3	3.45	336
58	GEN	BLACK & DECKER CANADA INC.	100 CENTRAL AVENUE BROCKVILLE ON	SSW/243.3	3.45	337
58	GEN	CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON	SSW/243.3	3.45	337
58	EHS		100 Central Avenue Brockville ON	SSW/243.3	3.45	338
58	GEN	BLACK & DECKER CANADA INC.	100 CENTRAL AVENUE BROCKVILLE ON	SSW/243.3	3.45	338
58	GEN	CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON	SSW/243.3	3.45	339
58	GEN	CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON	SSW/243.3	3.45	339
58	GEN	BLACK & DECKER CANADA INC.	100 CENTRAL AVENUE BROCKVILLE ON	SSW/243.3	3.45	339
58	GEN	CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	340
58	GEN	BLACK & DECKER CANADA INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	340
58	EHS		100 Central Ave W Brockville ON K6V4N8	SSW/243.3	3.45	341
58	GEN	CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON	SSW/243.3	3.45	341
58	ECA	Black & Decker Canada Inc.	100 Central Ave Brockville ON K6V 5W6	SSW/243.3	3.45	342

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
58	ECA	Camalor Mfg. Inc.	100 Central Avenue, P.O. Box 126 Brockville ON N6V 5V2	SSW/243.3	3.45	342
58	GEN	CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	342
58	GEN	CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	343
58	GEN	CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	343
58	GEN	CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	343
58	GEN	CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	SSW/243.3	3.45	344
59	BORE		ON	ENE/4.2	2.90	344
60	CA	YMCA-YWCA OF BROCKVILLE	345 PARK ST./MAPLE AVE. (SWM) BROCKVILLE CITY ON K6V 5Y7	E/249.9	-4.93	345
61	EHS		7789 Kent Boulevard Brockville ON K6V 6N7	SW/91.8	6.95	345
62	SPL	W.A. MACKEY FUELS	7789 KENT BLVD. TANK TRUCK (CARGO) BROCKVILLE CITY ON K6V 6N7	SW/91.8	6.95	345
63	BORE		ON	ENE/4.7	2.44	346
64	WWIS		ON ***Well ID:*** 7101789	ENE/63.1	-7.24	347
65	WWIS		Brockville ON	SSW/248.3	2.88	350

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7112299			
66	EHS		30 Dewick Drive Brockville ON K6V 1Y4	ENE/82.3	-5.88	352
67	WWIS		Brockville ON ***Well ID:*** 7111990	SSW/233.9	2.69	352
67	WWIS		Brockville ON ***Well ID:*** 7123681	SSW/233.9	2.69	362
68	WWIS		Brockville ON ***Well ID:*** 7123820	NE/137.9	-5.08	366
69	EHS		7815 Kent Blvd. Brockville ON	SW/125.8	10.09	368
70	EHS		Parkdale Ave And Park Street Brockville ON	NE/108.4	-6.02	369
71	RSC	COMMUNITY & PRIMARY HEALTH CARE - LANARK, LEEDS & GRENVILLE	2235 PARKEDALE AVENUE, BROCKVILLE, ON K6V 6B2 Brockville ON	NE/146.1	-5.82	369
71	GEN	Leeds & Grenville Community Family Health Team	2235 Parkedale Avenue Brockville ON K6V 6B2	NE/146.1	-5.82	370
71	GEN	Community & Primary Health Care -	2235 Parkedale Avenue Brockville ON K6V 6B2	NE/146.1	-5.82	370
71	GEN	Leeds & Grenville Community Family Health Team Community Family Health Team	2235 Parkedale Avenue Brockville ON K6V 6B2	NE/146.1	-5.82	371
71	GEN	Leeds & Grenville Community Family Health Team Community Family Health Team	2235 Parkedale Avenue Brockville ON K6V 6B2	NE/146.1	-5.82	371
72	CA	P.U.C. BROCKVILLE	ELM AVE./MAPLE AVE./ORMOND ST. BROCKVILLE CITY ON	ENE/241.6	-4.98	371

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
73	WWIS		Brockville ON ***Well ID:*** 7177786	NE/185.9	-4.98	371
74	HINC		19 BRAMSHOT STREET BROCKVILLE ON	ENE/122.4	-3.84	374
75	BORE		ON	ENE/10.2	-1.65	375
76	BORE		ON	ENE/10.3	-2.17	376
77	BORE		ON	ENE/20.9	-1.20	377
77	BORE		ON	ENE/20.9	-1.20	377
78	BORE		ON	ENE/54.8	-6.02	378
79	BORE		ON	ENE/18.6	-0.72	380
80	BORE		ON	ENE/65.3	-5.44	381
81	CA	TRIPLE B BAGEL INC.	2211 PARKEDALE AVENUE BROCKVILLE CITY ON	NE/211.5	-4.98	382
81	SCT	ZIPPY PRINT	2211 PARKEDALE AVE W BROCKVILLE ON K6V 6B2	NE/211.5	-4.98	382
81	GEN	UAP INC.	2211 PARKDALE AVENUE BROCKVILLE ON K6V 6V2	NE/211.5	-4.98	382
81	GEN	JAMES ROSS LTD.	2211 PARKDALE AVE. R.R.# 4, ELIZABETH TOWN IND.PARK, BROCKVILLE ON K6V 5T4	NE/211.5	-4.98	382

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
81	GEN	ZIPPY PRINT	2211 PARKEDALE AVENUE, UNIT #2 COMMERCE COURT BROCKVILLE ON K6V 1A8	NE/211.5	-4.98	383
81	GEN	ZIPPY PRINT	2211 PARKEDALE AVENUE, UNIT 2 COMMERCE COURT BROCKVILLE ON K6V 1A8	NE/211.5	-4.98	383
81	EHS		2211 PARKEDALE AVENUE BROCKVILLE ON K6V 6B2	NE/211.5	-4.98	383
81	GEN	LifeLabs LP	2211 Parkedale Ave. Brockville ON K6V 6B2	NE/211.5	-4.98	383
81	EXP	UPI ENERGY LP*	2211 PARKEDALE AVE W BROCKVILLE ON	NE/211.5	-4.98	384
81	EXP	UPI ENERGY LP*	2211 PARKEDALE AVE W BROCKVILLE ON	NE/211.5	-4.98	384
81	GEN	LifeLabs LP	2211 Parkedale Ave. Brockville ON K6V 6B2	NE/211.5	-4.98	384
81	GEN	LifeLabs LP	2211 Parkedale Ave. Brockville ON K6V 6B2	NE/211.5	-4.98	384
81	GEN	Dentistry @ Brockville	2211 Parkedale Ave Brockville ON	NE/211.5	-4.98	385
81	GEN	Dentistry @ Brockville	2211 Parkedale Ave Brockville ON	NE/211.5	-4.98	385
81	GEN	Drs. K and G Dentistry Professional Corporation	2211 Parkedale Ave Brockville ON K6V 6B2	NE/211.5	-4.98	385
81	GEN	Drs. K and G Dentistry Professional Corporation	2211 Parkedale Ave Brockville ON K6V 6B2	NE/211.5	-4.98	385
81	GEN	Dentistry @ Brockville	2211 Parkedale Ave Brockville ON K6V 6B2	NE/211.5	-4.98	386

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
81	GEN	Drs. K and G Dentistry Professional Corporation	2211 Parkedale Ave Brockville ON K6V 6B2	NE/211.5	-4.98	386
81	GEN	LifeLabs LP	2211 Parkedale Ave, Unit 5B Brockville ON K6V 6B2	NE/211.5	-4.98	386
81	EHS		2211 Parkedale Avenue Brockville ON K6V 6M2	NE/211.5	-4.98	387
81	EHS		2211 Parkedale Ave Brockville On Brockville ON K6V6B2	NE/211.5	-4.98	387
81	GEN	Drs. K and G Dentistry Professional Corporation	2211 Parkedale Ave Brockville ON K6V 6B2	NE/211.5	-4.98	387
81	GEN	LifeLabs LP	2211 Parkedale Ave, Unit 5B Brockville ON K6V 6B2	NE/211.5	-4.98	387
82	BORE		ON	ENE/9.6	-2.09	388
83	BORE		ON	ENE/20.1	-1.46	389
84	SPL		44.607487, -75.691013 Brockville ON	ENE/45.4	-3.81	390
85	HINC		95 BRIGHTON CRESCENT BROCKVILLE ON K6V 2P4	ENE/249.0	-3.98	391
86	SPL	CP EXPRESS & TRANSPORT	2183 PARKDALE AVE. MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON	NE/150.5	-4.98	391
86	PRT	C P EXPRESS & TRANSPORT LTD	2183 PARKDALE AV BROCKVILLE ON	NE/150.5	-4.98	392

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
86	SPL	TRANSPORT TRUCK	2183 PARKDALE RD. AT MYERS TRANSPORT LOADING DOCK. TRANSPORT TRUCK (CARGO) BROCKVILLE CITY ON	NE/150.5	-4.98	392
86	GEN	CP EXPRESS (SEE & USE ON1890804)	2183 PARKDALE AVENUE BROCKVILLE ON K6V 5V8	NE/150.5	-4.98	392
86	GEN	CANADIAN PACIFIC (SEE & USE ON1890804)	2183 PARKDALE AVENUE BROCKVILLE ON K6V 5V8	NE/150.5	-4.98	393
86	GEN	3028241 CANADA LIMITED	2183 PARKDALE AVEUNE BROCKVILLE ON	NE/150.5	-4.98	393
86	GEN	INTERLINK FREIGHT SYSTEMS	2183 PARKDALE AVENUE BROCKVILLE ON	NE/150.5	-4.98	393
86	GEN	Meyers Transport	2183 Parkedale Ave. Brockville ON K6V 5W1	NE/150.5	-4.98	394
86	SPL		2183 Parkedale Ave, Brockville ON	NE/150.5	-4.98	394
86	EXP	INTERLINK FREIGHT SYSTEMS INC	2183 PARKEDALE AV BROCKVILLE ON	NE/150.5	-4.98	395
86	EXP	C P EXPRESS & TRANSPORT LTD	2183 PARKEDALE AV BROCKVILLE ON	NE/150.5	-4.98	395
86	EXP	INTERLINK FREIGHT SYSTEMS INC	2183 PARKEDALE AV BROCKVILLE ON	NE/150.5	-4.98	395
86	EXP	C P EXPRESS & TRANSPORT LTD	2183 PARKEDALE AV BROCKVILLE ON K6V 5V8	NE/150.5	-4.98	395
86	EXP	INTERLINK FREIGHT SYSTEMS INC	2183 PARKEDALE AV BROCKVILLE ON	NE/150.5	-4.98	396

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
86	EXP	C P EXPRESS & TRANSPORT LTD	2183 PARKEDALE AV BROCKVILLE ON	NE/150.5	-4.98	396
86	GEN	Meyers Transport	2183 Parkedale Ave. Brockville ON	NE/150.5	-4.98	396
86	EXP	INTERLINK FREIGHT SYSTEMS INC	2183 PARKEDALE AV BROCKVILLE ON K6V 5V8	NE/150.5	-4.98	397
86	EXP	C P EXPRESS & TRANSPORT LTD	2183 PARKEDALE AV BROCKVILLE ON K6V 5V8	NE/150.5	-4.98	397
86	SPL	Meyers Transport Limited	2183 Parkedale Ave Brockville ON	NE/150.5	-4.98	397
86	GEN	1310463 Ontario Ltd	2183 Parkdale Ave Brockville ON K6V 5W1	NE/150.5	-4.98	398
87	EHS		2183 Parkedale Avenue Brockville ON	NE/179.7	-4.98	398
88	SPL	ESSO PETROLEUM CANADA	220 CENTRAL AVE. STORAGE TANK BROCKVILLE CITY ON	SW/151.1	5.79	398
88	SPL	QUEENSWAY TANK LINES	220 CENTRAL AVE TANK TRUCK (CARGO) BROCKVILLE CITY ON	SW/151.1	5.79	399
88	EBR	Imperial Oil Inc.	220 Central Avenue West Brockville Ontario K6V 5T7 CITY OF BROCKVILLE ON	SW/151.1	5.79	399
88	EHS		220 Central Ave. W. Brockville ON	SW/151.1	5.79	400
88	GEN	ESSO PETROLEUM CANADA	220 CENTRAL AVENUE, BROCKVILLE C/O 1 DUNCAN MILL ROAD DON MILLS ON M3B 1Z2	SW/151.1	5.79	400
88	GEN	ESSO PETROLEUM CANADA	220 CENTRAL AVENUE BROCKVILLE ON K6V 5T7	SW/151.1	5.79	400

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
88	GEN	ESSO PETROLEUM CANADA 14-645	220 CENTRAL AVENUE, BROCKVILLE C/O 1 DUNCAN MILL ROAD DON MILLS ON M3B 1Z2	SW/151.1	5.79	401
88	GEN	IMPERIAL OIL LIMITED	220 CENTRAL AVENUE WEST BROCKVILLE ON K6V 5T7	SW/151.1	5.79	401
88	GEN	IMPERIAL OIL	220 CENTRAL AVENUE WEST BROCKVILLE ON K6V 5T7	SW/151.1	5.79	401
88	EHS		220 Central Avenue West Brockville ON K6V 4N8	SW/151.1	5.79	402
88	RSC	Imperial Oil Limited	220 CENTRAL AVE W, BROCKVILLE, ON, K6V 4N8 BROCKVILLE ON K6V 4N8	SW/151.1	5.79	402
88	EXP	IMPERIAL OIL LIMITED C/O AUDREY STURGE	220 CENTRAL AV W BROCKVILLE ON	SW/151.1	5.79	403
88	EXP	DAVID R BANGS FUELS LTD	220 CENTRAL AV W BROCKVILLE ON	SW/151.1	5.79	403
88	EXP	IMPERIAL OIL LIMITED C/O AUDREY STURGE	220 CENTRAL AV W BROCKVILLE ON K6V 5T7	SW/151.1	5.79	403
88	EXP	IMPERIAL OIL LIMITED C/O AUDREY STURGE	220 CENTRAL AV W BROCKVILLE ON	SW/151.1	5.79	403
88	EXP	IMPERIAL OIL LIMITED C/O AUDREY STURGE	220 CENTRAL AVE W BROCKVILLE ON K6V 5T7	SW/151.1	5.79	404
89	WWIS		ON ***Well ID:*** 7242292	NE/213.3	-4.98	404

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
90	WWIS		lot 10 con 1 BROCKVILLE ON ***Well ID:*** 7299908	NE/140.5	-4.98	405
91	WWIS		lot 10 con 1 BROCKVILLE ON ***Well ID:*** 7299907	NE/103.0	-4.98	408
92	WWIS		lot 10 con 1 BROCKVILLE ON ***Well ID:*** 7299909	NE/225.3	-4.98	411
93	SCT	Sands Medical Inc.	300 Central Ave W Brockville ON K6V 5V2	SW/190.1	5.35	415
94	ECA	Canarm Limited	Canarm Limited ON K6V5V6	NE/134.1	-4.98	415
95	PRT	DOUG SUMMERS FUELS A DIV OF UNIVERSAL TERMINALS	260 CENTRAL AV W BROCKVILLE ON	SW/117.0	6.57	415
95	SPL	REYNOLDS CENTRAL FUELS	260 CENTRAL AVE. TANK TRUCK (CARGO) BROCKVILLE CITY ON	SW/117.0	6.57	416
95	GEN	REYNOLDS-CENTRAL FUELS	260 CENTRAL AVE. W. P.O. BOX 789 BROCKVILLE ON K6V 5W1	SW/117.0	6.57	416
95	GEN	REYNOLDS-CENTRAL FUELS	260 CENTRAL AVE. W. BROCKVILLE ON K6V 5W1	SW/117.0	6.57	416
95	GEN	REYNOLDS-CENTRAL FUELS 33-162	260 CENTRAL AVE. W. P.O. BOX 789 BROCKVILLE ON K6V 5W1	SW/117.0	6.57	417
95	GEN	REYNOLDS-CENTRAL FUELS	260 CENTRAL AVENUE WEST BROCKVILLE ON K6V 5W1	SW/117.0	6.57	417
95	GEN	Burnbrae Farms	260 Central Avenue Brockville ON	SW/117.0	6.57	418
95	EXP	ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	SW/117.0	6.57	418

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
95	EXP	REYNOLDS CENTRAL FUELS DIV OF ULTRAMAR LTD ATTN RENE TREMBLAY	260 CENTRAL AV W BROCKVILLE ON	SW/117.0	6.57	418
95	EXP	DOUG SUMMERS FUELS DIV OF UNIVERSAL TERMINALS INC	260 CENTRAL AV W BROCKVILLE ON	SW/117.0	6.57	418
95	EXP	ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	SW/117.0	6.57	419
95	EXP	ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	SW/117.0	6.57	419
95	EXP	ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	SW/117.0	6.57	419
95	EXP	ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	SW/117.0	6.57	419
95	EXP	ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	SW/117.0	6.57	420
95	GEN	Burnbrae Farms	260 Central Avenue Brockville ON K6V 4N8	SW/117.0	6.57	420
95	GEN	Burnbrae Farms	260 Central Avenue Brockville ON K6V 4N8	SW/117.0	6.57	420
95	GEN	Burnbrae Farms	260 Central Avenue Brockville ON K6V 4N8	SW/117.0	6.57	420
95	EXP	ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	SW/117.0	6.57	421
95	EXP	ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	SW/117.0	6.57	421
95	EXP	ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	SW/117.0	6.57	421

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
95	EXP	ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	SW/117.0	6.57	421
95	EXP	ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	SW/117.0	6.57	422
95	GEN	Burnbrae Farms Ltd	260 Cetral Ave West Brockville ON K6V 5V7	SW/117.0	6.57	422
95	GEN	Burnbrae Farms Ltd.	260 Central Avenue Brockville ON K6V 4N8	SW/117.0	6.57	422
96	CA	BROCKVILLE CITY	PARKEDALE AVE./CALIFORNIA AVE. BROCKVILLE CITY ON	NE/247.9	-4.98	422
96	CA	P.U.C. BROCKVILLE	PARKEDALE AVE./CALIFORNIA AVE. BROCKVILLE CITY ON	NE/247.9	-4.98	423
96	EHS		NE Corner of California Ave and Parkedale Ave Brockville ON	NE/247.9	-4.98	423
97	CA	CANARM LTD.	2157 PARKEDALE AVE. BROCKVILLE CITY ON	NE/124.0	-4.98	423
97	SCT	Canarm Ltd.	2157 Parkedale Ave W Brockville ON K6V 5V6	NE/124.0	-4.98	424
97	CA	CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE CITY ON	NE/124.0	-4.98	424
97	EBR	Canarm Limited	2157 Parkdale Avenue Brockville Ontario K6V 5V6 CITY OF BROCKVILLE ON	NE/124.0	-4.98	424
97	GEN	CANARM LTD.	2157 PARKEDALE AVE. W. BROCKVILLE ON K6V 5V6	NE/124.0	-4.98	425

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
97	GEN	CANARM LTD. 08-027	2157 PARKEDALE AVE. W. BROCKVILLE ON K6V 5V6	NE/124.0	-4.98	425
97	GEN	CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON K6V 5V6	NE/124.0	-4.98	426
97	NPRI	CANARM	2157 PARKEDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5V6	NE/124.0	-4.98	426
97	SCT	Canarm Ltd.	2157 Parkedale Ave Brockville ON K6V 5V6	NE/124.0	-4.98	427
97	CA	Canarm Limited	2157 Parkdale Avenue Brockville ON	NE/124.0	-4.98	427
97	EBR	Canarm Limited	2157 Parkedale Avenue Brockville United Counties of Leeds and Grenville K6V 5V6 CITY OF BROCKVILLE ON	NE/124.0	-4.98	428
97	GEN	CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON	NE/124.0	-4.98	428
97	GEN	CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON	NE/124.0	-4.98	429
97	SPL	Canarm Limited	2157 Parkedale Ave Brockville ON	NE/124.0	-4.98	430
97	GEN	CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON K6V 5V6	NE/124.0	-4.98	430
97	EASR	CANARM LTD.	2157 Parkedale AVE Brockville ON K6V 5V6	NE/124.0	-4.98	431
97	GEN	CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON	NE/124.0	-4.98	431

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
97	INC		2157 PARKEDALE AVENUE, BROCKVILLE ON	NE/124.0	-4.98	431
97	ECA	Canarm Limited	2157 Parkedale Ave Brockville ON K6V 5V6	NE/124.0	-4.98	432
97	ECA	Canarm Limited	2157 Parkdale Avenue Brockville ON K6V 5V6	NE/124.0	-4.98	433
97	GEN	CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON K6V 5V6	NE/124.0	-4.98	433
97	GEN	CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON K6V 5V6	NE/124.0	-4.98	433
97	GEN	CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON K6V 5V6	NE/124.0	-4.98	434
97	GEN	CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON K6V 5V6	NE/124.0	-4.98	435
98	RST	TOM CARR'S SERVICE CENTRE	340 CENTRAL W BROCKVILLE ON K6V 5T3	SW/232.8	1.58	436
98	GEN	TOWNVIEW AUTO BODY	340 CENTRAL AVENUE W C/O PO BOX 884 BROCKVILLE ON K6V 5W1	SW/232.8	1.58	436
98	RST	R & R SERVICE CENTRE	340 CENTRAL W BROCKVILLE ON K6V5V2	SW/232.8	1.58	436
98	RST	R & R SERVICE CENTRE	340 CENTRAL W BROCKVILLE ON K6V5V2	SW/232.8	1.58	437

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
99	HINC		92 SALISBURY AVENUE BROCKVILLE ON K6V 2T7	ENE/131.3	-2.98	437
100	WWIS		Brockville ON ***Well ID:*** 7234038	ENE/102.9	-3.09	437
101	SCT	WADE-TECH LIMITED	2117 PARKEDALE AVE W BROCKVILLE ON K6V 5V8	NE/204.5	-4.98	440
101	GEN	WADE TECH LTD.(SEE&USE ON0733800 H	2117 PARKDALE C/O P.O. BOX 730 BROCKVILLE ON K6V 5V8	NE/204.5	-4.98	440
101	GEN	WADE TECH LTD.(SEE&USE ON0733800 HEWITT)	2117 PARKDALE C/O P.O. BOX 730 BROCKVILLE ON K6V 5V8	NE/204.5	-4.98	440
101	SCT	Hands At Work Stitching Servs	2117 Parkedale Ave Brockville ON K6V 5Y6	NE/204.5	-4.98	441
102	SCT	Daltco Electric & Supply	1 Kesco Ave Brockville ON K6V 5V5	NE/143.1	-4.78	441
103	PINC		101 SALISBURY AVE, BROCKVILLE ON	ENE/149.2	-1.98	441
103	SPL	Enbridge Gas Distribution Inc.	101 Salisbury Ave, Brockville Brockville ON K6V 2T6	ENE/149.2	-1.98	442
104	SPL	Enbridge Energy Distribution Inc.	94 Bisely Crst Brockville ON	ENE/205.3	-1.98	442
105	EXP	CENTRAL AVE AUTO SERVICE AND BROCKVILLE TOWING	380 CENTRAL AV W BROCKVILLE ON	SW/232.4	-0.50	443
106	EHS		380 Central Ave W Brockville ON K6V5J9	SW/226.5	0.75	443
107	PRT	WILLIAM CARTAGE LTD	2089 PARKDALE AV BROCKVILLE ON	NE/218.7	-3.98	443

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
107	GEN	COONEY HAULAGE LTD.	2089 PARKDALE AVE., BROCKVILLE ON K8V 5R2	NE/218.7	-3.98	443
107	GEN	COONEY HAULAGE LTD. 42-284	2089 PARKDALE AVE., BROCKVILLE C/O PO BOX 186 TRENTON ON K8V 5R2	NE/218.7	-3.98	444
107	GEN	COONEY HAULAGE LTD.	2089 PARKDALE AVENUE BROCKVILLE ON K8V 5V7	NE/218.7	-3.98	444
107	GEN	COONEY BULK SALES LIMITED	2089 PARKDALE AVENUE BROCKVILLE ON K8V 5V7	NE/218.7	-3.98	445
107	EHS		2089 Parkdale Ave. Brockville ON	NE/218.7	-3.98	445
107	RSC	Hilliard Cooney Limited	2089 Parkdale Avenue West, Brockville, Ontario BROCKVILLE ON	NE/218.7	-3.98	445
107	FSTH	WILLIAM CARTAGE LTD	2089 PARKDALE AV BROCKVILLE ON	NE/218.7	-3.98	446
107	SPL		2089 Parkdale Ave. Brockville ON	NE/218.7	-3.98	446
107	FST	WILLIAM CARTAGE LTD	2089 PARKDALE AV BROCKVILLE ON K6V 5V7	NE/218.7	-3.98	446
107	PINC		2089 Parkdale Avenue, Brockville ON	NE/218.7	-3.98	447
108	WWIS		BROCKVILLE ON ***Well ID:*** 7101787	NE/135.3	-3.23	447
109	GEN	WILLIAM BROWNLEE CARTAGE LIMITED	BOX 520 2089 PARKEDALE AVE. BROCKVILLE ON K6V 5V7	NE/113.1	-3.02	450
109	GEN	WILLIAM (SEE & USE ON0061604) 42-284	BOX 520 2089 PARKEDALE AVE. BROCKVILLE ON K6V 5V7	NE/113.1	-3.02	451

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
109	FSTH	WILLIAM CARTAGE LTD	2089 PARKEDALE AV BROCKVILLE ON	NE/113.1	-3.02	451
110	WWIS		lot 17 con 2 ON ***Well ID:*** 3612722	WSW/199.5	9.15	451
111	INC		93 SEVENOAKS AVE, BROCKVILLE ON	ENE/133.6	-0.96	454
112	GEN	L.A. Knapp Inc.	440 Central Avenue West Brockville ON K6V 4N8	SW/234.0	-1.73	455
112	GEN	L.A. Knapp Inc.	440 Central Avenue West Brockville ON K6V 4N8	SW/234.0	-1.73	455
113	ECA	Loblaw Properties Limited	NE corner of Parkedale Avenue & Crocker Brockville ON M4T 2S5	NE/233.1	-1.98	455
114	SCT	MUTTART BUILDER'S SUPPLIES LTD	2057 PARKEDALE AVE W BROCKVILLE ON K6V 5V8	NE/200.7	-1.98	456
114	PES	MUTTART BUILDERS' SUPPLIES	2057 PARKEDALE AVENUE BROCKVILLE ON K6V5V8	NE/200.7	-1.98	456
115	SCT	Zigman Metals Ltd.	700 Central Ave W Brockville ON K6V 5W1	SW/236.6	-2.22	456
115	AUWR	ZIGMAN METALS	700 CENTRAL W BROCKVILLE ON K6V 5W1	SW/236.6	-2.22	457
115	SPL		700 Central Ave. West, Brockville Brockville ON	SW/236.6	-2.22	457
115	EASR	L. ZIGMAN & SONS LIMITED	700 CENTRAL AVENUE WEST BROCKVILLE ON K6V 5W1	SW/236.6	-2.22	457
115	AUWR	ZIGMAN METALS	700 CENTRAL W BROCKVILLE ON K6V5W1	SW/236.6	-2.22	457

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
118	GEN	Michaels Stores, Inc.	1965 Parkedale Ave Brockville ON	NE/203.2	-0.98	458
118	GEN	Michaels Stores, Inc.	1965 Parkedale Ave Brockville ON K6V 0B4	NE/203.2	-0.98	458
118	GEN	Michaels Stores, Inc.	1965 Parkedale Ave Brockville ON K6V 0B4	NE/203.2	-0.98	459
118	GEN	Michaels Stores, Inc.	1965 Parkedale Ave Brockville ON K6V 0B4	NE/203.2	-0.98	459
118	GEN	Michaels Stores, Inc.	1965 Parkedale Ave Brockville ON K6V 0B4	NE/203.2	-0.98	460
118	GEN	Michaels Stores, Inc.	1965 Parkedale Ave Brockville ON K6V 0B4	NE/203.2	-0.98	461
119	GEN	Altima Parkedale Dental Centre	1981 Parkedale avenue, Unit A Brockville ON K6V 0B4	NE/218.0	-0.98	462
119	GEN	Altima Parkedale Dental Centre	1981 Parkedale avenue, Unit A Brockville ON K6V 0B4	NE/218.0	-0.98	462
119	GEN	Altima Parkedale Dental Centre	1981 Parkedale avenue, Unit A Brockville ON	NE/218.0	-0.98	463
119	GEN	Altima Parkedale Dental Centre	1981 Parkedale avenue, Unit A Brockville ON K6V 0B4	NE/218.0	-0.98	463
119	GEN	Altima Parkedale Dental Centre	1981 Parkedale avenue, Unit A Brockville ON K6V 0B4	NE/218.0	-0.98	463
119	GEN	Altima Parkedale Dental Centre	1981 Parkedale avenue, Unit A Brockville ON K6V 0B4	NE/218.0	-0.98	464

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
119	GEN	Altima Dental Services Ontario Inc.	1981 Parkedale avenue, Unit A Brockville ON K6V 0B4	NE/218.0	-0.98	464
119	GEN	Altima Dental Services Ontario Inc.	1981 Parkedale avenue, Unit A Brockville ON K6V 0B4	NE/218.0	-0.98	465
120	CA	The Corporation of the City of Brockville	Parkedale Avenue & North Augusta Road Brockville ON	NE/228.5	-0.42	465
121	WWIS		ON ***Well ID:*** 3600488	NE/187.1	0.50	465
122	SPL	TRANSPORT TRUCK	401 WEST TO BROKVILLE EXIT TO PARKDALE AVE. MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON	NE/104.3	-0.71	468
122	SPL		401 & Parkdale (North Augusta Rd.) Brockville ON K6V 5T1	NE/104.3	-0.71	469
123	WWIS		ON ***Well ID:*** 3600522	NE/183.7	-0.98	469
124	SPL		Highway 401 Eastbound Brockville ON	ENE/11.5	0.02	471
125	PES	WAL-MART CANADA CORP #3006	1942 PARKEDALE AVE BROCKVILLE ON K6V 7N4	NE/249.9	-0.98	472
125	GEN	Wal-Mart Canada Corp.	1942 Parkdale Ave. Brockville ON K6V 9Z1	NE/249.9	-0.98	472
125	SPL	McDonalds Restaurant<UNOFFICIAL>	1942 Parkdale Avenue MCDONALDS RESTAURANT<UNOFFICIAL> Brockville ON	NE/249.9	-0.98	473
125	SPL		WALMART, 1942 PARKDALE AVE<UNOFFICIAL> Brockville ON	NE/249.9	-0.98	473

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
125	PES	WAL-MART CANADA CORP #3006	1942 PARKEDALE AVE BROCKVILLE ON K6V 7N4	NE/249.9	-0.98	474
125	GEN	Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON	NE/249.9	-0.98	474
125	GEN	Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON	NE/249.9	-0.98	475
125	GEN	Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON	NE/249.9	-0.98	476
125	GEN	Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON K6V 9Z1	NE/249.9	-0.98	476
125	GEN	Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON	NE/249.9	-0.98	477
125	INC		1942 PARKDALE AVENUE, BROCKVILLE ON	NE/249.9	-0.98	478
125	SPL	Enbridge Gas Distribution Inc.	1942 Parkdale Ave Brockville ON	NE/249.9	-0.98	479
125	EASR	WAL-MART CANADA CORP/LA COMPAGNIE WAL-MART DU CANADA	1942 PARKEDALE AVE BROCKVILLE ON K6V 7N4	NE/249.9	-0.98	479
125	GEN	Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON K6V 9Z1	NE/249.9	-0.98	479
125	GEN	Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON K6V 9Z1	NE/249.9	-0.98	480
125	GEN	Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON K6V 9Z1	NE/249.9	-0.98	481
125	GEN	Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON K6V 9Z1	NE/249.9	-0.98	482

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
125	PES	WAL-MART CANADA CORP #3006	1942 PARKEDALE AVE BROCKVILLE ON K6V9Z1	NE/249.9	-0.98	482
125	EHS		1942 Parkedale Ave Brockville ON K6V 5T2	NE/249.9	-0.98	483
125	PES	WAL-MART CANADA CORP #3006	1942 PARKEDALE AVE BROCKVILLE ON K6V9Z1	NE/249.9	-0.98	483
125	GEN	Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON K6V 9Z1	NE/249.9	-0.98	483
125	PES	WAL-MART CANADA CORP/LA COMPAGNIE WAL-MART DU CANADA	1942 PARKEDALE AVE BROCKVILLE ON K6V 7N4	NE/249.9	-0.98	484
125	EHS		1942 Parkdale Avenue East Brockville ON K6V 5T2	NE/249.9	-0.98	485
126	WWIS		lot 8 con 2 ON ***Well ID:*** 3600914	NE/222.4	-0.98	485
127	WWIS		lot 17 con 1 ON ***Well ID:*** 3611804	WSW/193.6	5.06	487
128	WWIS		lot 7 con 2 ON ***Well ID:*** 3608838	NE/232.7	-0.98	490
129	CA	P.U.C. BROCKVILLE	WAVERLY DR./FIRST AVE. BROCKVILLE CITY ON	ENE/43.3	0.02	493
130	SPL	HARMAC TRANSPORTATION	IN FRONT OF 1951 PARKDALE RD. @ BROOM RD. TANK TRUCK (CARGO) BROCKVILLE CITY ON	NE/198.7	0.02	494
131	CA	P.U.C. BROCKVILLE	PARKEDALE AVE./BROOME RD. BROCKVILLE CITY ON	NE/213.0	0.02	494
131	EHS		First Ave & Parkedale Ave Brockville ON	NE/213.0	0.02	494

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
131	GEN	MACGREGOR CRANE SERVICE LIMITED	FIRST AVE. & PARKDALE AVE. BROCKVILLE P.O.BOX 261 BROCKVILLE ON K6H 5S7	NE/213.0	0.02	495
131	GEN	MACGREGOR CRANE SERVICE LIMITED 26-326	FIRST AVE. & PARKDALE AVE. BROCKVILLE P.O.BOX 261 BROCKVILLE ON K6H 5S7	NE/213.0	0.02	495
131	ECA	Motor Coils Mfg. Ltd.	Broome Road Parkedale Ave Brockville ON K6V 5T2	NE/213.0	0.02	495
132	SPL	Trans Plus <UNOFFICIAL>	North Augusta Rd & Pakedale Ave, Brockville ON	NE/213.6	0.02	495
133	WWIS		lot 17 con 1 ON ***Well ID:*** 3611808	WSW/131.0	4.74	496
134	PES	ALEX JOANNIDES HOLDINGS INC.	2360 Parkdale AVE Brockville ON K6V 7J5	NE/226.9	0.02	498
135	WWIS		lot 17 con 1 ON ***Well ID:*** 3600483	ENE/122.6	0.02	499
136	PRT	DAVID EATON S & D EQUIPMENT RENTALS	1917 PARKEDALE AV BROCKVILLE ON K6V 5T2	NE/171.9	1.22	501
136	FSTH	DAVID EATON S & D EQUIPMENT RENTALS	1917 PARKEDALE AVE E BROCKVILLE ON K6V 5T2	NE/171.9	1.22	501
136	GEN	1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON	NE/171.9	1.22	502
136	CA	1207931 Ontario Limited	1917 Parkedale Avenue Brockville ON	NE/171.9	1.22	502
136	CA	1207931 Ontario Limited	1917 Parkedale Avenue Brockville ON	NE/171.9	1.22	502

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
136	EXP	DAVID EATON S & D EQUIPMENT RENTALS	1917 PARKEDALE AVE E BROCKVILLE ON	NE/171.9	1.22	502
136	EXP	DAVID EATON S & D EQUIPMENT RENTALS	1917 PARKEDALE AVE E BROCKVILLE ON K6V 5T2	NE/171.9	1.22	503
136	EXP	DAVID EATON S & D EQUIPMENT RENTALS	1917 PARKEDALE AVE E BROCKVILLE ON	NE/171.9	1.22	503
136	GEN	1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON	NE/171.9	1.22	503
136	GEN	1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON	NE/171.9	1.22	503
136	GEN	1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON	NE/171.9	1.22	504
136	GEN	1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON	NE/171.9	1.22	504
136	EXP	DAVID EATON S & D EQUIPMENT RENTALS	1917 PARKEDALE AVE E BROCKVILLE ON K6V 5T2	NE/171.9	1.22	505
136	ECA	1207931 Ontario Limited	1917 Parkedale Avenue Brockville ON K6V 5T2	NE/171.9	1.22	505
136	ECA	1207931 Ontario Limited	1917 Parkedale Avenue Brockville ON K6V 5T2	NE/171.9	1.22	505
136	GEN	1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON K6V 5T2	NE/171.9	1.22	506
136	GEN	1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON K6V 5T2	NE/171.9	1.22	506

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
136	GEN	1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON K6V 5T2	NE/171.9	1.22	507
136	GEN	1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON K6V 5T2	NE/171.9	1.22	507
136	GEN	1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON K6V 5T2	NE/171.9	1.22	508
137	WWIS		lot 7 con 2 ON **Well ID:** 3600913	NE/214.5	1.19	508
138	WWIS		lot 7 con 1 ON **Well ID:** 3600636	NE/182.7	2.01	510
139	WWIS		ON **Well ID:** 3600493	NE/209.5	2.04	513
140	ANDR	Chemical Rd junkyard	Brockville ON K6V 5T3	WSW/209.6	14.10	515
141	AMIS	ELIZABETHTOWN NEW SITE 1	ELIZABETHTOWN ON	WSW/229.3	15.30	516
142	RST	FRANK'S AUTO REPAIR	1909 PARKEDALE AVE E BROCKVILLE ON K6V 5T2	NE/188.3	4.00	516
143	WWIS		lot 19 con 2 ON **Well ID:** 3614462	WSW/164.9	13.14	517
144	WWIS		ON **Well ID:** 3604633	NE/132.1	5.02	523
145	CA	MOTOR COILS MFG	1879 PARKDALE AVE. BROCKVILLE CITY ON	NE/121.0	5.02	525
145	SCT	MOTOR COILS MFG. LTD.	1879 PARKDALE AVE E RR 2 BROCKVILLE ON K6V 5T2	NE/121.0	5.02	525

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
145	CA	MOTOR COILS MFG. LTD.	1879 PARKEDALE AVENUE BROCKVILLE CITY ON	NE/121.0	5.02	526
145	SCT	MOTOR COILS MFG. LTD.	1879 PARKEDALE AVE W BROCKVILLE ON K6V 5T2	NE/121.0	5.02	526
145	EBR	Motor Coils Mfg. Co. (1981) Ltd.	1879 Parkdale Avenue Brockville Ontario K6V 5T2 CITY OF BROCKVILLE ON	NE/121.0	5.02	526
145	SCT	Motor Coils Mfg. Ltd.	1879 Parkedale Ave E RR 2 Brockville ON K6V 5T2	NE/121.0	5.02	527
145	GEN	MOTOR COILS MANUFACTURING	1879 PARKDALE AVENUE, BROCKVILLE, ON K6V 5T2	NE/121.0	5.02	527
145	GEN	MOTOR COILS MANUFACTURING	1879 PARKDALE AVENUE BROCKVILLE ON K6V 5T2	NE/121.0	5.02	527
145	GEN	MOTOR COILS MANUFACTURING 27-428	1879 PARKDALE AVENUE BROCKVILLE ON K6V 5T2	NE/121.0	5.02	528
145	GEN	MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON K6V 5T2	NE/121.0	5.02	528
145	CA	Motor Coils Mfg. Co. (1981) Ltd.	1879 Parkedale Avenue Brockville ON	NE/121.0	5.02	529
145	GEN	MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON	NE/121.0	5.02	530
145	GEN	MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON	NE/121.0	5.02	531
145	GEN	MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON	NE/121.0	5.02	532
145	GEN	MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON K6V 5T2	NE/121.0	5.02	532

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
145	EHS		1879 Parkdale Avenue Brockville ON	NE/121.0	5.02	533
145	GEN	MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON	NE/121.0	5.02	533
145	ECA	Motor Coils Mfg. Co. (1981) Ltd.	1879 Parkedale Avenue Brockville ON K6V 5T2	NE/121.0	5.02	534
145	GEN	MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON K6V 5T2	NE/121.0	5.02	535
145	GEN	MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON K6V 5T2	NE/121.0	5.02	536
145	GEN	MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON K6V 5T2	NE/121.0	5.02	536
145	GEN	MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON K6V 5T2	NE/121.0	5.02	537
145	EBR	Motor Coils Mfg. Ltd.	1879 Parkedale Avenue Brockville CITY OF BROCKVILLE ON	NE/121.0	5.02	538
145	SPL	Motor Coils Mfg. Co. (1981) Ltd.	1879 Parkedale Ave Brockville ON K6V 5T2	NE/121.0	5.02	539
145	GEN	MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON K6V 5T2	NE/121.0	5.02	539
145	EBR	Motor Coils Mfg. Ltd.	1879 Parkedale Avenue Brockville, ON Canada ON	NE/121.0	5.02	540
145	ECA	Motor Coils Mfg. Ltd.	1879 Parkedale Ave Brockville ON K6V 5T2	NE/121.0	5.02	541
146	WWIS		lot 7 con 1 ON	NE/68.8	5.02	541

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 3600635			
147	WWIS		ON ***Well ID:*** 3600534	NE/188.3	5.02	544
148	WWIS		lot 7 con 1 ON ***Well ID:*** 3600631	ENE/149.7	1.42	546
149	WWIS		ON ***Well ID:*** 3600498	ENE/197.9	1.09	549
150	ANDR	Chemical Rd Dump 1968	Brockville ON K6V 5T3	WSW/207.6	11.15	551
151	WWIS		lot 7 con 11 ON ***Well ID:*** 3608778	NE/234.6	5.03	552
152	SPL	CANADA TRANSPORT	1861 PARKDALE TRANSPORT TRUCK (CARGO) BROCKVILLE CITY ON	NE/181.3	5.02	555
152	PRT	CANADA TRANSPORT GROUP LTD	1861 PARKDALE AV BROCKVILLE ON K6V 5T2	NE/181.3	5.02	556
152	EXP	CANADA TRANSPORT GROUP LTD	1861 PARKEDALE AVE E BROCKVILLE ON	NE/181.3	5.02	556
152	EXP	CANADA TRANSPORT GROUP LTD	1861 PARKEDALE AVE E BROCKVILLE ON K6V 5T2	NE/181.3	5.02	556
152	EXP	CANADA TRANSPORT GROUP LTD	1861 PARKEDALE AVE E BROCKVILLE ON	NE/181.3	5.02	556
152	EXP	CANADA TRANSPORT GROUP LTD	1861 PARKEDALE AVE E BROCKVILLE ON K6V 5T2	NE/181.3	5.02	557
153	ANDR	Chemical Rd Dump 1963	Brockville ON K6V 5T3	WSW/242.2	10.02	557
154	WWIS		lot 7 con 1 ON	ENE/35.3	2.98	557

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 3600630			
155	WWIS		lot 7 con 1 ON ***Well ID:*** 3600633	NE/137.9	5.02	559
156	WWIS		lot 7 con 1 ON ***Well ID:*** 3608487	NE/141.2	5.02	562
157	WWIS		lot 7 con 1 ON ***Well ID:*** 3600629	NE/31.7	4.19	565
158	EHS		1000 Oxford Avenue Brockville ON	NE/91.7	5.02	568
159	SPL	PRIVATE RESIDENCE	AT MOBILE HOME AT 1871 OXFORD AVE. FURNACE OIL TANK BROCKVILLE CITY ON K6V 7B5	ENE/116.5	1.39	568
160	WWIS		lot 17 con 2 ON ***Well ID:*** 3613100	WSW/94.3	7.32	568
161	PES	GORD'S WEED CONTROL	1845 PARKDALE AVENUE, R.R. #2 BROCKVILLE ON L0C 1B0	NE/162.0	5.02	571
161	PES	788636 ONTARIO LIMITED/GARDEN WORLD	R.R. #2, 1845 PARKEDALE AVENUE BROCKVILLE ON K6V 6T4	NE/162.0	5.02	571
161	PES	GARDENER LANDSCAPING/GARDEN WORLD (C#91392)	R.R. #2, 1845 PARKEDALE AVENUE BROCKVILLE ON K6V 1H3	NE/162.0	5.02	572
161	GEN	GARDEN WORLD 17-502	1845 PARKEDALE AVENUE BROCKVILLE ON K6V 5T2	NE/162.0	5.02	572
161	GEN	GARDEN WORLD	1845 PARKEDALE AVENUE BROCKVILLE ON K6V 5T2	NE/162.0	5.02	572
161	GEN	AUTO PAK	1845 PARKDALE AVE EAST BROCKVILLE ON K6V 5T2	NE/162.0	5.02	573

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
161	PES	788636 ONTARIO LIMITED/GARDEN WORLD	C/O 1845 PARKEDALE AVENUE BROCKVILLE ON K6V5T1	NE/162.0	5.02	573
161	PES	GARDENER LANDSCAPING/GARDEN WORLD (C#91392)	R. R. #2, 1845 PARKEDALE AVENUE BROCKVILLE ON K6V5T2	NE/162.0	5.02	573
162	WWIS		lot 6 con 1 ON ***Well ID:*** 3605369	ENE/48.2	3.08	574
163	GEN	INFRASTRUCTURE ONTARIO	1804 OXFORD AVE BROCKVILLE ON	NE/174.1	5.02	576
164	WWIS		lot 6 con 1 ON ***Well ID:*** 3600618	NE/28.9	4.01	576
165	WWIS		lot 6 con 1 ON ***Well ID:*** 3604921	ENE/152.4	0.59	579
166	ECA	The Corporation of the City of Brockville	Parkedale Avenue & North Augusta Rd Brockville ON K6V 5V1	NE/193.5	5.02	581
167	WWIS		lot 6 con 1 ON ***Well ID:*** 3600617	NE/125.6	5.02	582
168	CA		Parkdale & Oxford Avenues Brockville ON	NE/187.4	5.02	584
169	WWIS		ON ***Well ID:*** 3600510	NE/158.7	5.02	584
170	WWIS		lot 6 con 1 ON ***Well ID:*** 3600620	NE/61.2	4.83	587
171	WWIS		lot 6 con 1 Brockville ON ***Well ID:*** 7307509	ENE/150.3	0.63	589
173	WWIS		lot 6 con 1 ON ***Well ID:*** 3600615	NE/128.5	5.02	591

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
174	WWIS		lot 6 con 1 ON ***Well ID:*** 3600608	NE/194.2	5.02	593
175	WWIS		lot 6 con 1 ON ***Well ID:*** 3600904	ENE/230.2	-1.97	596
176	WWIS		ON ***Well ID:*** 3600509	NE/171.1	5.02	598
177	WWIS		lot 6 con 1 ON ***Well ID:*** 3608305	ENE/168.3	-0.55	601
178	WWIS		lot 6 con 1 BROCKVILLE ON ***Well ID:*** 3616501	NE/214.4	4.02	603
178	WWIS		lot 6 con 1 BROCKVILLE ON ***Well ID:*** 7045448	NE/214.4	4.02	605
179	WWIS		lot 6 con 1 BROCKVILLE ON ***Well ID:*** 2410238	NE/221.1	4.02	606
179	WWIS		lot 6 con 1 BROCKVILLE ON ***Well ID:*** 7045450	NE/221.1	4.02	609
180	WWIS		lot 6 con 1 BROCKVILLE ON ***Well ID:*** 3616500	NE/222.0	4.02	610
180	WWIS		lot 6 con 1 BROCKVILLE ON ***Well ID:*** 7045447	NE/222.0	4.02	612
181	GEN	General Maintenance Contractors Ltd.	2805 2nd Concession Rd. Brockville ON K6V 5T1	NE/243.0	4.02	613
182	WWIS		lot 6 con 1 BROCKVILLE ON ***Well ID:*** 3616502	NE/230.8	4.02	613
182	WWIS		lot 6 con 1 BROCKVILLE ON ***Well ID:*** 7045449	NE/230.8	4.02	616

Executive Summary: Summary By Data Source

AMIS - Abandoned Mine Information System

A search of the AMIS database, dated 1800-Oct 2018 has found that there are 1 AMIS site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
ELIZABETHTOWN NEW SITE 1	ELIZABETHTOWN ON	229.3	141

ANDR - Anderson's Waste Disposal Sites

A search of the ANDR database, dated 1860s-Present has found that there are 3 ANDR site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Chemical Rd junkyard	Brockville ON K6V 5T3	209.6	140
Chemical Rd Dump 1968	Brockville ON K6V 5T3	207.6	150
Chemical Rd Dump 1963	Brockville ON K6V 5T3	242.2	153

AST - Aboveground Storage Tanks

A search of the AST database, dated May 31, 2014 has found that there are 3 AST site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	ON	199.1	28
	ON	203.7	30

Site	Address	Distance (m)	Map Key
	ON	219.3	51

AUWR - Automobile Wrecking & Supplies

A search of the AUWR database, dated 1999-Jan 31, 2020 has found that there are 2 AUWR site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
ZIGMAN METALS	700 CENTRAL W BROCKVILLE ON K6V 5W1	236.6	115
ZIGMAN METALS	700 CENTRAL W BROCKVILLE ON K6V5W1	236.6	115

BORE - Borehole

A search of the BORE database, dated 1875-Jul 2018 has found that there are 12 BORE site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	ON	4.2	59
	ON	4.7	63
	ON	10.2	75
	ON	10.3	76
	ON	20.9	77

Site	Address	Distance (m)	Map Key
	ON	20.9	77
	ON	54.8	78
	ON	18.6	79
	ON	65.3	80
	ON	9.6	82
	ON	9.6	82
	ON	20.1	83

CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 51 CA site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Trillium Health Care Products Inc.	2337 Parkedale Avenue Brockville ON	185.8	40
	2337 Parkedale Avenue Brockville ON	185.8	40

Site	Address	Distance (m)	Map Key
	2337 Parkedale Avenue Brockville ON	185.8	40
PARKE-DAVIS DIV. WARNER LAMB. OF CANADA	2337 PARKEDALE AVENUE BROCKVILLE CITY ON	185.8	40
PARKE DAVIS CANADA INC.	LOT 11 CONC. 1 BROCKVILLE CITY ON	185.8	40
PARKE-DAVIS CANADA, INC.	LOT 11 CONC. 1 BROCKVILLE CITY ON	185.8	40
WARNER-LAMBERT CANADA	2337 PARKEDALE AVE. BROCKVILLE CITY ON	185.8	40
WARNER-LAMBERT CANADA INC.	2337 PARKEDALE AVENUE BROCKVILLE CITY ON	185.8	40
PARKE-DAVIS DIV. WARNER LAMB. OF CANADA	2337 PARKEDALE AVENUE BROCKVILLE CITY ON	185.8	40
PARKE-DAVIS, DIV. OF WARNER LAMBERT CANA	2337 PARKEDALE AVENUE BROCKVILLE ON	185.8	40
PARKE-DAVIS DIV. WARNER LAMB. OF CANADA	2337 PARKEDALE AVENUE BROCKVILLE CITY ON	185.8	40
PARKE-DAVIS DIV. WARNER LAMB. OF CANADA	2337 PARKEDALE AVENUE BROCKVILLE CITY ON	185.8	40
PARKE-DAVIS DIV. WARNER LAMB. OF CANADA	2337 PARKEDALE AVENUE BROCKVILLE CITY ON	185.8	40
PARKE-DAVIS DIV. WARNER LAMB. OF CANADA	2337 PARKEDALE AVENUE BROCKVILLE CITY ON	185.8	40

Site	Address	Distance (m)	Map Key
PARKE-DAVIS DIV. WARNER LAMB. OF CANADA	2337 PARKEDALE AVENUE BROCKVILLE CITY ON	185.8	40
WARNER-LAMBERT CANADA	2337 PARKDALE AVE. BROCKVILLE ON	185.8	40
	2337 Parkedale Avenue Brockville ON	185.8	40
TACO BELL OF CANADA	3049 JEFFERSON DRIVE BROCKVILLE CITY ON K6V 6N7	99.8	50
P.U.C. BROCKVILLE	MAPLE AVE./PARK ST. BROCKVILLE CITY ON	213.0	57
BLACK & DECKER CANADA INC.	100 CENTRAL AVE. BROCKVILLE CITY ON	243.3	58
BLACK & DECKER CANADA INC.	100 CENTRAL AVE. *** BROCKVILLE CITY ON	243.3	58
BLACK & DECKER CANADA INC.	100 CENTRAL AVENUE BROCKVILLE CITY ON	243.3	58
BLACK & DECKER CANADA INC.	100 CENTRAL AVE. BROCKVILLE CITY ON	243.3	58
BLACK & DECKER CANADA INC.	100 CENTRAL AVENUE BROCKVILLE CITY ON	243.3	58
BLACK & DECKER CANADA INC.	100 CENTRAL AVE. BROCKVILLE CITY ON	243.3	58

Site	Address	Distance (m)	Map Key
BLACK & DECKER CANADA INC.	100 CENTRAL AVENUE BROCKVILLE CITY ON	243.3	58
BLACK & DECKER CANADA (1989) INC.	100 CENTRAL AVENUE BROCKVILLE CITY ON	243.3	58
BLACK & DECKER CANADA (1989) INC.	100 CENTRAL AVENUE BROCKVILLE CITY ON	243.3	58
BLACK & DECKER CAN. INC.	100 CENTRAL AVE. BROCKVILLE CITY ON	243.3	58
BLACK AND DECKER CANADA INC.	100 CENTRAL AVE. BROCKVILLE CITY ON	243.3	58
BLACK & DECKER	100 CENTRAL AVE. BROCKVILLE CITY ON	243.3	58
BLACK & DECKER	100 CENTRAL AVE. BROCKVILLE CITY ON	243.3	58
	100 Central Avenue, P.O. Box 126 Brockville ON	243.3	58
Black & Decker Canada Inc.	100 Central Ave Brockville ON	243.3	58
YMCA-YWCA OF BROCKVILLE	345 PARK ST./MAPLE AVE. (SWM) BROCKVILLE CITY ON K6V 5Y7	249.9	60
P.U.C. BROCKVILLE	ELM AVE./MAPLE AVE./ORMOND ST. BROCKVILLE CITY ON	241.6	72
TRIPLE B BAGEL INC.	2211 PARKEDALE AVENUE BROCKVILLE CITY ON	211.5	81

Site	Address	Distance (m)	Map Key
BROCKVILLE CITY	PARKEDALE AVE./CALIFORNIA AVE. BROCKVILLE CITY ON	247.9	96
P.U.C. BROCKVILLE	PARKEDALE AVE./CALIFORNIA AVE. BROCKVILLE CITY ON	247.9	96
CANARM LTD.	2157 PARKEDALE AVE. BROCKVILLE CITY ON	124.0	97
CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE CITY ON	124.0	97
Canarm Limited	2157 Parkdale Avenue Brockville ON	124.0	97
The Corporation of the City of Brockville	Parkedale Avenue & North Augusta Road Brockville ON	228.5	120
P.U.C. BROCKVILLE	WAVERLY DR./FIRST AVE. BROCKVILLE CITY ON	43.3	129
P.U.C. BROCKVILLE	PARKEDALE AVE./BROOME RD. BROCKVILLE CITY ON	213.0	131
1207931 Ontario Limited	1917 Parkedale Avenue Brockville ON	171.9	136
1207931 Ontario Limited	1917 Parkedale Avenue Brockville ON	171.9	136
MOTOR COILS MFG	1879 PARKDALE AVE. BROCKVILLE CITY ON	121.0	145

Site	Address	Distance (m)	Map Key
MOTOR COILS MFG. LTD.	1879 PARKEDALE AVENUE BROCKVILLE CITY ON	121.0	145
Motor Coils Mfg. Co. (1981) Ltd.	1879 Parkedale Avenue Brockville ON	121.0	145
	Parkdale & Oxford Avenues Brockville ON	187.4	168

CPU - Certificates of Property Use

A search of the CPU database, dated 1994-Jun 30, 2020 has found that there are 3 CPU site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
239142 Investments Limited	Brockville Shopping Centre Address: 125 Stewart Blvd Part Lot 12, Concession 1, Plan 238, Part Lot 5, Part 6 City of Brockville, United Counties of Leeds and Grenville CITY OF BROCKVILLE ON	63.8	11
239142 Investments Limited	125 Stewart Blvd., Brockville, United Counties of Leeds and Grenville Part of Lot 12, Concession 1, Plan 238, Part Lot 5, Part 6 CITY OF BROCKVILLE ON	63.8	11
239142 Investments Limited	125 Stewart Blvd Brockville ON K6V 4W4	63.8	11

EASR - Environmental Activity and Sector Registry

A search of the EASR database, dated Oct 2011-Jun 30, 2020 has found that there are 3 EASR site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
CANARM LTD.	2157 Parkedale AVE Brockville ON K6V 5V6	124.0	97
L. ZIGMAN & SONS LIMITED	700 CENTRAL AVENUE WEST BROCKVILLE ON K6V 5W1	236.6	115

Site	Address	Distance (m)	Map Key
WAL-MART CANADA CORP/LA COMPAGNIE WAL-MART DU CANADA	1942 PARKEDALE AVE BROCKVILLE ON K6V 7N4	249.9	125

EBR - Environmental Registry

A search of the EBR database, dated 1994-Jun 30, 2020 has found that there are 18 EBR site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Trillium Health Care Products Inc.	2337 Parkedale Avenue Brockville Ontario K6V 5W5 CITY OF BROCKVILLE ON	185.8	40
Trillium Health Care Products Inc.	2337 Parkedale Avenue Brockville, United Counties Of Leeds & Grenville CITY OF BROCKVILLE ON	185.8	40
Parke-Davis Div. Warner Lambert of Canada Inc.	2337 Parkedale Avenue CITY OF BROCKVILLE ON	185.8	40
Parke-Davis Div. Warner Lambert of Canada Inc.	2337 Parkedale Avenue CITY OF BROCKVILLE ON	185.8	40
Parke-Davis Div. Warner Lambert of Canada Inc.	2337Parkedale Avenue, Brockville City CITY OF BROCKVILLE ON	185.8	40
Trillium Health Care Manufacturing Inc.	2337 Parkedale Avenue Brockville Ontario K6V 5W5 CITY OF BROCKVILLE ON	185.8	40
Trillium Health Care Manufacturing Inc.	2337 Parkedale Avenue Brockville Ontario K6V 5W5 CITY OF BROCKVILLE ON	185.8	40

Site	Address	Distance (m)	Map Key
Trillium Health Care Products Inc.	2337 Parkedale Avenue Brockville Ontario K6V 5W5 CITY OF BROCKVILLE ON	185.8	40
Black & Decker Canada (1989) Inc.	100 CENTRAL AVENUE, BROCKVILLE CITY CITY OF BROCKVILLE ON	243.3	58
Camalor Mfg. Inc.	100 Central Avenue, P.O. Box 126 Brockville Ontario N6V 5V2 CITY OF BROCKVILLE ON	243.3	58
Black & Decker Canada Inc.	100 Central Avenue Brockville, United Counties of Leeds and Grenville K6V 5W6 CITY OF BROCKVILLE ON	243.3	58
Imperial Oil Inc.	220 Central Avenue West Brockville Ontario K6V 5T7 CITY OF BROCKVILLE ON	151.1	88
Canarm Limited	2157 Parkedale Avenue Brockville United Counties of Leeds and Grenville K6V 5V6 CITY OF BROCKVILLE ON	124.0	97
Canarm Limited	2157 Parkdale Avenue Brockville Ontario K6V 5V6 CITY OF BROCKVILLE ON	124.0	97
Motor Coils Mfg. Co. (1981) Ltd.	1879 Parkdale Avenue Brockville Ontario K6V 5T2 CITY OF BROCKVILLE ON	121.0	145
Motor Coils Mfg. Ltd.	1879 Parkedale Avenue Brockville CITY OF BROCKVILLE ON	121.0	145
Motor Coils Mfg. Ltd.	1879 Parkedale Avenue Brockville, ON Canada ON	121.0	145

ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011-Jun 30, 2020 has found that there are 18 ECA site(s) within approximately 0.25

kilometers of the project property.

Site	Address	Distance (m)	Map Key
Trillium Health Care Manufacturing Inc.	2337 Parkedale Avenue Brockville ON K6V 5W5	185.8	40
Trillium Health Care Products Inc.	2337 Parkedale Avenue Brockville ON K6V 5W5	185.8	40
Trillium Health Care Manufacturing Inc.	2337 Parkedale Avenue Brockville ON K6V 5W5	185.8	40
Trillium Health Care Products Inc.	2337 Parkedale Ave Brockville ON K6V 5W5	185.8	40
Trillium Health Care Products Inc.	2337 Parkedale Avenue Brockville ON K6V 5W5	185.8	40
Trillium Health Care Products Inc.	2337 Parkedale Ave Brockville ON	185.8	40
Black & Decker Canada Inc.	100 Central Ave Brockville ON K6V 5W6	243.3	58
Camalor Mfg. Inc.	100 Central Avenue, P.O. Box 126 Brockville ON N6V 5V2	243.3	58
Canarm Limited	Canarm Limited ON K6V5V6	134.1	94
Canarm Limited	2157 Parkdale Avenue Brockville ON K6V 5V6	124.0	97
Canarm Limited	2157 Parkedale Ave Brockville ON K6V 5V6	124.0	97

Site	Address	Distance (m)	Map Key
Loblaw Properties Limited	NE corner of Parkedale Avenue & Crocker Brockville ON M4T 2S5	233.1	113
Motor Coils Mfg. Ltd.	Broome Road Parkedale Ave Brockville ON K6V 5T2	213.0	131
1207931 Ontario Limited	1917 Parkedale Avenue Brockville ON K6V 5T2	171.9	136
1207931 Ontario Limited	1917 Parkedale Avenue Brockville ON K6V 5T2	171.9	136
Motor Coils Mfg. Co. (1981) Ltd.	1879 Parkedale Avenue Brockville ON K6V 5T2	121.0	145
Motor Coils Mfg. Ltd.	1879 Parkedale Ave Brockville ON K6V 5T2	121.0	145
The Corporation of the City of Brockville	Parkedale Avenue & North Augusta Rd Brockville ON K6V 5V1	193.5	166

EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Apr 30, 2020 has found that there are 48 EHS site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	2399 Parkedale Ave Brockville ON K6V3G9	171.4	3
	2399 Parkedale Avenue Brockville ON K6V 3G9	179.1	4
	2399 Parkedale Avenue Brockville ON K6V 3G9	102.0	10

Site	Address	Distance (m)	Map Key
	2399 Parkedale Avenue Brockville ON K6V 3G9	102.0	10
	125 Stewart Blvd. Brockville ON	63.8	11
	125 Stewart Boulevard Brockville ON K6V 4W4	63.8	11
	1 Balmoral Pl Brockville ON K6V6J9	107.5	15
	2511, 2523, 2539 & 2545 Parkdale Ave & 325 Stewart Blvd, Brockville Brockville ON K6V 4W8	217.6	16
	Parkedale Ave Stewart Blvd Brockville ON	182.8	18
	329 Stewart Boulevard Brockville ON K6V 4W8	249.9	22
	154 Stewart Boulevard Brockville ON	162.0	37
	154 Stewart Blvd Brockville ON K6V 4W6	153.0	39
	154 Stewart Blvd Brockville ON	153.0	39
	2337 Parkedale Ave Brockville ON K6V3G9	185.8	40

Site	Address	Distance (m)	Map Key
	2337 Parkedale Avenue Brockville ON K6V 3G9	185.8	40
	2337 Parkedale Ave Brockville ON K6V3G9	185.8	40
	2337 Parkedale Avenue Brockville ON K6V 3G9	185.8	40
	2337 Parkedale Avenue Brockville ON K6V 3G9	185.8	40
	Portion of 2337 Parkedale Ave Brockville ON K6V 3G9	185.8	40
	Portion of 2337 Parkedale Ave Brockville ON K6V 3G9	185.8	40
	2337 Parkdale Avenue Brockville ON K6V 5W5	185.8	40
	160 Stewart Blvd Brockville ON K6V4W6	124.1	41
	3050 Jefferson Drive Brockville ON K6V 6N3	244.0	49
	3050 Jefferson Drive Brockville ON K6V 6N3	244.0	49
	3050 Jefferson Dr Brockville ON K6V6N3	244.0	49
	7777 Kent Boulevard Brockville ON K6V 6N7	151.0	56

Site	Address	Distance (m)	Map Key
	100 Central Avenue Brockville ON	243.3	58
	100 Central Ave W Brockville ON K6V 4N8	243.3	58
	100 Central Avenue Brockville ON	243.3	58
	100 Central Ave W Brockville ON K6V4N8	243.3	58
	7789 Kent Boulevard Brockville ON K6V 6N7	91.8	61
	30 Dewick Drive Brockville ON K6V 1Y4	82.3	66
	7815 Kent Blvd. Brockville ON	125.8	69
	Parkdale Ave And Park Street Brockville ON	108.4	70
	2211 PARKEDALE AVENUE BROCKVILLE ON K6V 6B2	211.5	81
	2211 Parkedale Avenue Brockville ON K6V 6M2	211.5	81
	2211 Parkedale Ave Brockville On Brockville ON K6V6B2	211.5	81

Site	Address	Distance (m)	Map Key
	2183 Parkedale Avenue Brockville ON	179.7	87
	220 Central Ave. W. Brockville ON	151.1	88
	220 Central Avenue West Brockville ON K6V 4N8	151.1	88
	NE Corner of California Ave and Parkedale Ave Brockville ON	247.9	96
	380 Central Ave W Brockville ON K6V5J9	226.5	106
	2089 Parkdale Ave. Brockville ON	218.7	107
	1942 Parkedale Ave Brockville ON K6V 5T2	249.9	125
	1942 Parkdale Avenue East Brockville ON K6V 5T2	249.9	125
	First Ave & Parkedale Ave Brockville ON	213.0	131
	1879 Parkdale Avenue Brockville ON	121.0	145
	1000 Oxford Avenue Brockville ON	91.7	158

EXP - List of Expired Fuels Safety Facilities

A search of the EXP database, dated Feb 28, 2017 has found that there are 63 EXP site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON	153.0	39
HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39

Site	Address	Distance (m)	Map Key
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON	153.0	39
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON	153.0	39
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON	153.0	39
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON	153.0	39
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON	153.0	39
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39

Site	Address	Distance (m)	Map Key
HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V 4W6	153.0	39
UPI ENERGY LP*	2211 PARKEDALE AVE W BROCKVILLE ON	211.5	81
UPI ENERGY LP*	2211 PARKEDALE AVE W BROCKVILLE ON	211.5	81
INTERLINK FREIGHT SYSTEMS INC	2183 PARKEDALE AV BROCKVILLE ON	150.5	86
C P EXPRESS & TRANSPORT LTD	2183 PARKEDALE AV BROCKVILLE ON	150.5	86
INTERLINK FREIGHT SYSTEMS INC	2183 PARKEDALE AV BROCKVILLE ON	150.5	86
C P EXPRESS & TRANSPORT LTD	2183 PARKEDALE AV BROCKVILLE ON K6V 5V8	150.5	86
INTERLINK FREIGHT SYSTEMS INC	2183 PARKEDALE AV BROCKVILLE ON	150.5	86
C P EXPRESS & TRANSPORT LTD	2183 PARKEDALE AV BROCKVILLE ON	150.5	86
INTERLINK FREIGHT SYSTEMS INC	2183 PARKEDALE AV BROCKVILLE ON K6V 5V8	150.5	86

Site	Address	Distance (m)	Map Key
C P EXPRESS & TRANSPORT LTD	2183 PARKEDALE AV BROCKVILLE ON K6V 5V8	150.5	86
IMPERIAL OIL LIMITED C/O AUDREY STURGE	220 CENTRAL AV W BROCKVILLE ON	151.1	88
DAVID R BANGS FUELS LTD	220 CENTRAL AV W BROCKVILLE ON	151.1	88
DAVID R BANGS FUELS LTD	220 CENTRAL AV W BROCKVILLE ON	151.1	88
IMPERIAL OIL LIMITED C/O AUDREY STURGE	220 CENTRAL AV W BROCKVILLE ON K6V 5T7	151.1	88
IMPERIAL OIL LIMITED C/O AUDREY STURGE	220 CENTRAL AV W BROCKVILLE ON	151.1	88
IMPERIAL OIL LIMITED C/O AUDREY STURGE	220 CENTRAL AVE W BROCKVILLE ON K6V 5T7	151.1	88
ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	117.0	95
REYNOLDS CENTRAL FUELS DIV OF ULTRAMAR LTD ATTN RENE TREMBLAY	260 CENTRAL AV W BROCKVILLE ON	117.0	95
DOUG SUMMERS FUELS DIV OF UNIVERSAL TERMINALS INC	260 CENTRAL AV W BROCKVILLE ON	117.0	95
ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	117.0	95

Site	Address	Distance (m)	Map Key
ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	117.0	95
ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	117.0	95
ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	117.0	95
ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	117.0	95
ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	117.0	95
ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	117.0	95
ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	117.0	95
ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	117.0	95
ULTRAMAR CANADA INC	260 CENTRAL AV W BROCKVILLE ON K6V 5W1	117.0	95
CENTRAL AVE AUTO SERVICE AND BROCKVILLE TOWING	380 CENTRAL AV W BROCKVILLE ON	232.4	105
DAVID EATON S & D EQUIPMENT RENTALS	1917 PARKEDALE AVE E BROCKVILLE ON	171.9	136
DAVID EATON S & D EQUIPMENT RENTALS	1917 PARKEDALE AVE E BROCKVILLE ON K6V 5T2	171.9	136

Site	Address	Distance (m)	Map Key
DAVID EATON S & D EQUIPMENT RENTALS	1917 PARKEDALE AVE E BROCKVILLE ON	171.9	136
DAVID EATON S & D EQUIPMENT RENTALS	1917 PARKEDALE AVE E BROCKVILLE ON K6V 5T2	171.9	136
CANADA TRANSPORT GROUP LTD	1861 PARKEDALE AVE E BROCKVILLE ON K6V 5T2	181.3	152
CANADA TRANSPORT GROUP LTD	1861 PARKEDALE AVE E BROCKVILLE ON	181.3	152
CANADA TRANSPORT GROUP LTD	1861 PARKEDALE AVE E BROCKVILLE ON K6V 5T2	181.3	152
CANADA TRANSPORT GROUP LTD	1861 PARKEDALE AVE E BROCKVILLE ON	181.3	152

FST - Fuel Storage Tank

A search of the FST database, dated Feb 28, 2017 has found that there are 6 FST site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
SUNCOR ENERGY PRODUCTS PARTNERSHIP	325 STEWART BLVD BROCKVILLE ON K6V 4W8	207.7	24
SUNCOR ENERGY PRODUCTS PARTNERSHIP	325 STEWART BLVD BROCKVILLE ON K6V 4W8	207.7	24
SUNCOR ENERGY PRODUCTS PARTNERSHIP	325 STEWART BLVD BROCKVILLE ON K6V 4W8	207.7	24

Site	Address	Distance (m)	Map Key
SUNCOR ENERGY PRODUCTS PARTNERSHIP	325 STEWART BLVD BROCKVILLE ON K6V 4W8	207.7	24
SUNCOR ENERGY PRODUCTS PARTNERSHIP	325 STEWART BLVD BROCKVILLE ON K6V 4W8	207.7	24
WILLIAM CARTAGE LTD	2089 PARKDALE AV BROCKVILLE ON K6V 5V7	218.7	107

FSTH - Fuel Storage Tank - Historic

A search of the FSTH database, dated Pre-Jan 2010* has found that there are 3 FSTH site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
WILLIAM CARTAGE LTD	2089 PARKDALE AV BROCKVILLE ON	218.7	107
WILLIAM CARTAGE LTD	2089 PARKEDALE AV BROCKVILLE ON	113.1	109
DAVID EATON S & D EQUIPMENT RENTALS	1917 PARKEDALE AVE E BROCKVILLE ON K6V 5T2	171.9	136

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Apr 30, 2020 has found that there are 240 GEN site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
SEARS CANADA INC.	2399 PARKDALE AVE. BROCKVILLE ON K6V 3G9	205.8	8
SEARS CANADA INC.	2399 PARKDALE AVENUE BROCKVILLE ON K6V 3G9	205.8	8

Site	Address	Distance (m)	Map Key
TAWCO CLEANING CENTRE	1000 ISLANDS MALL 2399 PARKDALE AVE. BROCKVILLE ON K0E 1T0	205.8	8
TAWCO CLEANING CENTRE 04-084	1000 ISLANDS MALL 2399 PARKDALE AVE. BROCKVILLE ON K0E 1T0	205.8	8
TAWCO CLEANING CENTRE	1000 ISLANDS MALL 2399 PARKDALE AVENUE BROCKVILLE ON K6V 3G9	205.8	8
WAL-MART INC.	STORE #3006 - 1000 ISLANDS MALL 535 PARKDALE AVENUE BROCKVILLE ON K6V 3G9	205.8	8
WAL-MART CANADA INC.	STORE #3006 - 1000 ISLANDS MALL 535 PARKDALE AVENUE BROCKVILLE ON K6V 3G9	205.8	8
SHOPPERS DRUG MART	1000 ISLANDS MALL 2399 PARKDALE BOULEVARD BROCKVILLE ON K6V 3G9	205.8	8
WAL-MART CANADA CORP.	535 PARKDALE AVENUE STORE #3006 BROCKVILLE ON K6V 3G9	205.8	8
RBC Financial Group	1000 Islands Mall Brockville ON K6V 3G9	205.8	8
SEARS CANADA INC.	2399 PARKDALE AVENUE BROCKVILLE ON	205.8	8
Altima 1000 Islands Dental Centre	2399 Parkdale Ave, Unit 15 Brockville ON K6V 3G9	205.8	8
Altima 1000 Islands Dental Centre	2399 Parkdale Ave, Unit 15 Brockville ON K6V 3G9	205.8	8
Altima 1000 Islands Dental Centre	2399 Parkdale Ave, Unit 15 Brockville ON K6V 3G9	205.8	8

Site	Address	Distance (m)	Map Key
Mark S. Leslie Apothecary Ltd.	2399 PARKEDALE AVE, UNIT 27 Brockville ON K6V 3G9	205.8	8
Mark S. Leslie Apothecary Ltd.	2399 PARKEDALE AVE, UNIT 27 Brockville ON K6V 3G9	205.8	8
Mark S. Leslie Apothecary Ltd.	2399 PARKEDALE AVE, UNIT 27 Brockville ON K6V 3G9	205.8	8
Sears Canada Inc.	2399 Parkedale Avenue Brockville ON K6V 3G9	205.8	8
Caroly Burpee Professional serv. LTD	2399 PARKEDALE AVE, UNIT 27 Brockville ON K6V 3G9	205.8	8
DURANT'S ONE HOUR CLEANERS LIMITED	125 STEWART BLVD. (BROCKVILLE CENTRE) BROCKVILLE ON K6V 3P6	63.8	11
PHARMA PLUS DRUGS LTD	125 STEWART BOULEVARD BROCKVILLE ON K6V 4W4	63.8	11
BROCK (OUT OF BUS) 05-844	125 STEWART BLVD. BROCKVILLE ON K6V 4W4	63.8	11
DURANT'S ONE HOUR CLEANERS LIMITED12-443	125 STEWART BLVD. (BROCKVILLE CENTRE) BROCKVILLE ON K6V 3P6	63.8	11
PHARMA PLUS DRUGS LTD. 31-655	125 STEWART BLVD., BROCKVILLE C/O 5935 AIRPORT ROAD STEI 500 MISSISSAUGA ON L4V 1W5	63.8	11
BROCK PHOTO CENTER 05-844	125 STEWART BLVD. BROCKVILLE ON K6V 4W4	63.8	11

Site	Address	Distance (m)	Map Key
MAXWELLS DRYCLEANING SERVICE	125 STEWART BLVD. BROCKVILLE ON K6V 4W4	63.8	11
PHARMA PLUS DRUGS LTD.	125 STEWART BOULEVARD BROCKVILLE ON K6V 4W4	63.8	11
DURANT'S ONE HOUR CLEANERS LIMITED	BROCKVILLE CENTRE 125 STEWART BOULEVARD BROCKVILLE ON K6V 3P6	63.8	11
MAXWELLS DRYCLEANING SERVICE	125 STEWART BOULEVARD BROCKVILLE ON K6V 4W4	63.8	11
Eastern Enginering Group Inc	125 Stewart Blvd Suite 212 Brockville ON K6V 4W4	63.8	11
Zellers Inc.	125 Steward Blvd. Brockville ON K6V 4W4	63.8	11
Brockville Shopping Centre	125 Stewart Blvd. Brockville ON	63.8	11
First National Management Corporation	125 Stewart Blvd Brockville ON K6V 4W4	63.8	11
First National Management Corporation	125 Stewart Blvd Brockville ON K6V 4W4	63.8	11
MINISTRY OF REVENUE 27-397	BROCKVILLE REGIONAL ASSESSMENT OFFICE 2479 PARKDALE AVE. BROCKVILLE ON K6V 3H2	249.9	12
Rideau Community Health Services	2-2479 Parkedale Rd Brockville ON K6V 3H2	249.9	12
Rideau Community Health Services	2-2479 Parkedale Rd Brockville ON K6V 3H2	249.9	12

Site	Address	Distance (m)	Map Key
MINISTRY OF REVENUE	BROCKVILLE REGIONAL ASSESSMENT OFFICE 2479 PARKDALE AVE. BROCKVILLE ON K6V 3H2	249.9	12
Northern Property New LP2	1-4 Balmoral Brockville ON K6V 6K1	92.5	14
Northern Property New LP2	1-4 Balmoral Brockville ON K6V 6K1	92.5	14
1195149 Ontario Ltd	325 Stewart Blvd. Brockville ON K6V4W8	247.2	17
Canadian Tire Corporation, limited	329 Stewart St. Brockville ON K6V 4W8	249.9	22
Canadian Tire Corporation, limited	329 Stewart St. Brockville ON K6V 4W8	249.9	22
Canadian Tire Corporation, limited	329 Stewart St. Brockville ON K6V 4W8	249.9	22
1195149 Ontario Ltd	325 Stewart Blvd. Brockville ON	207.7	24
1195149 Ontario Ltd	325 Stewart Blvd. Brockville ON K6V4W8	207.7	24
1195149 Ontario Ltd	325 Stewart Blvd. Brockville ON K6V4W8	207.7	24
1195149 Ontario Ltd	325 Stewart Blvd. Brockville ON K6V4W8	207.7	24

Site	Address	Distance (m)	Map Key
1195149 Ontario Ltd	325 Stewart Blvd. Brockville ON K6V4W8	207.7	24
CATHOLIC DISTRICT SBE ONTARIO	ST. MARY CATHOLIC HIGH SCHOOL 40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	237.7	29
CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	237.7	29
CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON	237.7	29
CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON	237.7	29
CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON	237.7	29
CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	237.7	29
CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON	237.7	29
CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	237.7	29
CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	237.7	29
CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	237.7	29
CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	237.7	29

Site	Address	Distance (m)	Map Key
CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO	40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	237.7	29
IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON	153.0	39
IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON	153.0	39
IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	153.0	39
IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON	153.0	39
IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	153.0	39
IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	153.0	39
IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	153.0	39
IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	153.0	39
IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	153.0	39
IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	153.0	39
IMPERIAL OIL LIMITED	154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	153.0	39

Site	Address	Distance (m)	Map Key
IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON	153.0	39
IMPERIAL OIL	154 STEWART BOULEVARD BROCKVILLE ON	153.0	39
PARKE-DAVIS CANADA INC	2337 PARKEDALE AVE. BROCKVILLE ON K6V 5W5	185.8	40
PARKE-DAVIS CANADA INC.	DIV. OF WARNER-LAMBERT CANADA INC. 2337 PARKDALE AVE. BROCKVILLE ON K6V 5W5	185.8	40
PARKE-DAVIS, DIV. OF	2337 PARKEDALE AVENUE BROCKVILLE ON K6V 5W5	185.8	40
PARKE-DAVIS CANADA INC. 30-002	DIV. OF WARNER-LAMBERT CANADA INC. 2337 PARKDALE AVE. BROCKVILLE ON K6V 5W5	185.8	40
PARKE-DAVIS, DIV. (SEE & USE ON2369500)	2337 PARKEDALE AVENUE BROCKVILLE ON K6V 5W5	185.8	40
TRILLIUM HEALTH CARE MANUFACTURING	2337 PARKDALE AVENUE BROCKVILLE ON K6V 5W5	185.8	40
TRILLIUM HEALTH CARE MANUFACTURING	2337 PARKEDALE AVENUE BROCKVILLE ON K6V 5W5	185.8	40
TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON	185.8	40
TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON	185.8	40
TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON	185.8	40

Site	Address	Distance (m)	Map Key
TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON	185.8	40
TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON	185.8	40
TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON K6V 5W5	185.8	40
TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON K6V 5W5	185.8	40
TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON K6V 5W5	185.8	40
TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON K6V 5W5	185.8	40
TRILLIUM HEALTH CARE MANUFACTURING	2337 Parkedale Avenue Brockville ON K6V 5W5	185.8	40
THE GREAT ATLANTIC & PACIFIC CO. OF CANADA, LTD.	3049 JEFFERSON STREET BROCKVILLE ON K6V 6N3	99.8	50
GREAT ATLANTIC & PACIFIC CO. OF CDA.LTD.	SAVE-A-CENTRE #903 3049 JEFFERSON STREET BROCKVILLE ON K6V 6N3	99.8	50
PHARMACY, THE	3049 TEFFERSON STREET BROCKVILLE ON KV6 6N3	99.8	50
PHARMACY, THE	3049 JEFFERSON STREET BROCKVILLE ON K6V 6N3	99.8	50

Site	Address	Distance (m)	Map Key
PHARMACY, (SEE & USE ON2371813)	3049 TEFFERSON STREET BROCKVILLE ON KV6 6N3	99.8	50
glidden paint, store 835	7748 kent blvd, #8 brockville ON K6V 7J9	199.7	53
GLIDDEN PAINTS & WALL PAPER	7748 KENT ROAD BLVD., UNIT 8 BROCKVILLE ON K6V 7J9	199.6	54
BLACK & DECKER CANADA INC.	100 CENTRAL AVE. W. BROCKVILLE ON K6V 4N8	243.3	58
BLACK & DECKER CANADA INC. 05-043	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	243.3	58
BLACK & DECKER CANADA INC	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	243.3	58
BLACK & DECKER CANADA INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	243.3	58
CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	243.3	58
BLACK & DECKER CANADA INC.	100 CENTRAL AVENUE BROCKVILLE ON	243.3	58
CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON	243.3	58
BLACK & DECKER CANADA INC.	100 CENTRAL AVENUE BROCKVILLE ON	243.3	58
CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON	243.3	58

Site	Address	Distance (m)	Map Key
CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON	243.3	58
BLACK & DECKER CANADA INC.	100 CENTRAL AVENUE BROCKVILLE ON	243.3	58
CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	243.3	58
BLACK & DECKER CANADA INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	243.3	58
CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON	243.3	58
CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	243.3	58
CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	243.3	58
CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	243.3	58
CAMALOR MFG. INC.	100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	243.3	58
Leeds & Grenville Community Family Health Team	2235 Parkedale Avenue Brockville ON K6V 6B2	146.1	71

Site	Address	Distance (m)	Map Key
Community & Primary Health Care -	2235 Parkedale Avenue Brockville ON K6V 6B2	146.1	71
Leeds & Grenville Community Family Health Team Community Family Health Team	2235 Parkedale Avenue Brockville ON K6V 6B2	146.1	71
Leeds & Grenville Community Family Health Team Community Family Health Team	2235 Parkedale Avenue Brockville ON K6V 6B2	146.1	71
UAP INC.	2211 PARKDALE AVENUE BROCKVILLE ON K6V 6V2	211.5	81
JAMES ROSS LTD.	2211 PARKDALE AVE. R.R.# 4,ELIZABETH TOWN IND.PARK, BROCKVILLE ON K6V 5T4	211.5	81
ZIPPY PRINT	2211 PARKEDALE AVENUE, UNIT #2 COMMERCE COURT BROCKVILLE ON K6V 1A8	211.5	81
LifeLabs LP	2211 Parkedale Ave. Brockville ON K6V 6B2	211.5	81
LifeLabs LP	2211 Parkedale Ave. Brockville ON K6V 6B2	211.5	81
LifeLabs LP	2211 Parkedale Ave. Brockville ON K6V 6B2	211.5	81
Dentistry @ Brockville	2211 Parkedale Ave Brockville ON	211.5	81

Site	Address	Distance (m)	Map Key
Dentistry @ Brockville	2211 Parkedale Ave Brockville ON	211.5	81
Drs. K and G Dentistry Professional Corporation	2211 Parkedale Ave Brockville ON K6V 6B2	211.5	81
Drs. K and G Dentistry Professional Corporation	2211 Parkedale Ave Brockville ON K6V 6B2	211.5	81
Dentistry @ Brockville	2211 Parkedale Ave Brockville ON K6V 6B2	211.5	81
Drs. K and G Dentistry Professional Corporation	2211 Parkedale Ave Brockville ON K6V 6B2	211.5	81
LifeLabs LP	2211 Parkedale Ave, Unit 5B Brockville ON K6V 6B2	211.5	81
Drs. K and G Dentistry Professional Corporation	2211 Parkedale Ave Brockville ON K6V 6B2	211.5	81
LifeLabs LP	2211 Parkedale Ave, Unit 5B Brockville ON K6V 6B2	211.5	81
CP EXPRESS (SEE & USE ON1890804)	2183 PARKDALE AVENUE BROCKVILLE ON K6V 5V8	150.5	86
CANADIAN PACIFIC (SEE & USE ON1890804)	2183 PARKDALE AVENUE BROCKVILLE ON K6V 5V8	150.5	86
3028241 CANADA LIMITED	2183 PARKDALE AVEUNE BROCKVILLE ON	150.5	86
INTERLINK FREIGHT SYSTEMS	2183 PARKDALE AVENUE BROCKVILLE ON	150.5	86

Site	Address	Distance (m)	Map Key
Meyers Transport	2183 Parkedale Ave. Brockville ON K6V 5W1	150.5	86
Meyers Transport	2183 Parkedale Ave. Brockville ON	150.5	86
1310463 Ontario Ltd	2183 Parkdale Ave Brockville ON K6V 5W1	150.5	86
ESSO PETROLEUM CANADA	220 CENTRAL AVENUE, BROCKVILLE C/O 1 DUNCAN MILL ROAD DON MILLS ON M3B 1Z2	151.1	88
ESSO PETROLEUM CANADA	220 CENTRAL AVENUE BROCKVILLE ON K6V 5T7	151.1	88
ESSO PETROLEUM CANADA 14-645	220 CENTRAL AVENUE, BROCKVILLE C/O 1 DUNCAN MILL ROAD DON MILLS ON M3B 1Z2	151.1	88
IMPERIAL OIL LIMITED	220 CENTRAL AVENUE WEST BROCKVILLE ON K6V 5T7	151.1	88
IMPERIAL OIL	220 CENTRAL AVENUE WEST BROCKVILLE ON K6V 5T7	151.1	88
Burnbrae Farms	260 Central Avenue Brockville ON K6V 4N8	117.0	95
Burnbrae Farms	260 Central Avenue Brockville ON K6V 4N8	117.0	95
Burnbrae Farms	260 Central Avenue Brockville ON K6V 4N8	117.0	95

Site	Address	Distance (m)	Map Key
Burnbrae Farms Ltd	260 Cetral Ave West Brockville ON K6V 5V7	117.0	95
Burnbrae Farms Ltd.	260 Central Avenue Brockville ON K6V 4N8	117.0	95
REYNOLDS-CENTRAL FUELS	260 CENTRAL AVE. W. P.O. BOX 789 BROCKVILLE ON K6V 5W1	117.0	95
REYNOLDS-CENTRAL FUELS	260 CENTRAL AVE. W. BROCKVILLE ON K6V 5W1	117.0	95
REYNOLDS-CENTRAL FUELS 33-162	260 CENTRAL AVE. W. P.O. BOX 789 BROCKVILLE ON K6V 5W1	117.0	95
REYNOLDS-CENTRAL FUELS	260 CENTRAL AVENUE WEST BROCKVILLE ON K6V 5W1	117.0	95
Burnbrae Farms	260 Central Avenue Brockville ON	117.0	95
CANARM LTD.	2157 PARKEDALE AVE. W. BROCKVILLE ON K6V 5V6	124.0	97
CANARM LTD. 08-027	2157 PARKEDALE AVE. W. BROCKVILLE ON K6V 5V6	124.0	97
CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON K6V 5V6	124.0	97
CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON	124.0	97
CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON	124.0	97

Site	Address	Distance (m)	Map Key
CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON	124.0	97
CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON K6V 5V6	124.0	97
CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON	124.0	97
CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON K6V 5V6	124.0	97
CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON K6V 5V6	124.0	97
CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON K6V 5V6	124.0	97
CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON K6V 5V6	124.0	97
CANARM LIMITED	2157 PARKEDALE AVENUE BROCKVILLE ON K6V 5V6	124.0	97
TOWNVIEW AUTO BODY	340 CENTRAL AVENUE W C/O PO BOX 884 BROCKVILLE ON K6V 5W1	232.8	98
WADE TECH LTD.(SEE&USE ON0733800 H	2117 PARKDALE C/O P.O. BOX 730 BROCKVILLE ON K6V 5V8	204.5	101
WADE TECH LTD.(SEE&USE ON0733800 HEWITT)	2117 PARKDALE C/O P.O. BOX 730 BROCKVILLE ON K6V 5V8	204.5	101

Site	Address	Distance (m)	Map Key
COONEY HAULAGE LTD.	2089 PARKDALE AVE., BROCKVILLE ON K8V 5R2	218.7	107
COONEY HAULAGE LTD. 42-284	2089 PARKDALE AVE., BROCKVILLE C/O PO BOX 186 TRENTON ON K8V 5R2	218.7	107
COONEY HAULAGE LTD.	2089 PARKDALE AVENUE BROCKVILLE ON K8V 5V7	218.7	107
COONEY BULK SALES LIMITED	2089 PARKDALE AVENUE BROCKVILLE ON K8V 5V7	218.7	107
WILLIAM BROWNLEE CARTAGE LIMITED	BOX 520 2089 PARKEDALE AVE. BROCKVILLE ON K6V 5V7	113.1	109
WILLIAM (SEE & USE ON0061604) 42-284	BOX 520 2089 PARKEDALE AVE. BROCKVILLE ON K6V 5V7	113.1	109
L.A. Knapp Inc.	440 Central Avenue West Brockville ON K6V 4N8	234.0	112
Michaels Stores, Inc.	1965 Parkedale Ave Brockville ON	203.2	118
Michaels Stores, Inc.	1965 Parkedale Ave Brockville ON K6V 0B4	203.2	118
Michaels Stores, Inc.	1965 Parkedale Ave Brockville ON K6V 0B4	203.2	118
Michaels Stores, Inc.	1965 Parkedale Ave Brockville ON K6V 0B4	203.2	118

Site	Address	Distance (m)	Map Key
Michaels Stores, Inc.	1965 Parkedale Ave Brockville ON K6V 0B4	203.2	118
Michaels Stores, Inc.	1965 Parkedale Ave Brockville ON K6V 0B4	203.2	118
Altima Parkedale Dental Centre	1981 Parkedale avenue, Unit A Brockville ON K6V 0B4	218.0	119
Altima Parkedale Dental Centre	1981 Parkedale avenue, Unit A Brockville ON K6V 0B4	218.0	119
Altima Parkedale Dental Centre	1981 Parkedale avenue, Unit A Brockville ON K6V 0B4	218.0	119
Altima Parkedale Dental Centre	1981 Parkedale avenue, Unit A Brockville ON	218.0	119
Altima Parkedale Dental Centre	1981 Parkedale avenue, Unit A Brockville ON K6V 0B4	218.0	119
Altima Parkedale Dental Centre	1981 Parkedale avenue, Unit A Brockville ON K6V 0B4	218.0	119
Altima Parkedale Dental Centre	1981 Parkedale avenue, Unit A Brockville ON K6V 0B4	218.0	119
Altima Dental Services Ontario Inc.	1981 Parkedale avenue, Unit A Brockville ON K6V 0B4	218.0	119
Altima Dental Services Ontario Inc.	1981 Parkedale avenue, Unit A Brockville ON K6V 0B4	218.0	119

Site	Address	Distance (m)	Map Key
Wal-Mart Canada Corp.	1942 Parkdale Ave. Brockville ON K6V 9Z1	249.9	125
Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON	249.9	125
Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON	249.9	125
Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON	249.9	125
Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON K6V 9Z1	249.9	125
Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON	249.9	125
Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON K6V 9Z1	249.9	125
Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON K6V 9Z1	249.9	125
Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON K6V 9Z1	249.9	125
Wal-Mart Canada Corp.	1942 Parkdale Ave. #3006 Brockville ON K6V 9Z1	249.9	125
MACGREGOR CRANE SERVICE LIMITED	FIRST AVE. & PARKDALE AVE. BROCKVILLE P.O.BOX 261 BROCKVILLE ON K6H 5S7	213.0	131

Site	Address	Distance (m)	Map Key
MACGREGOR CRANE SERVICE LIMITED 26-326	FIRST AVE. & PARKDALE AVE. BROCKVILLE P.O.BOX 261 BROCKVILLE ON K6H 5S7	213.0	131
1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON K6V 5T2	171.9	136
1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON K6V 5T2	171.9	136
1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON K6V 5T2	171.9	136
1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON K6V 5T2	171.9	136
1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON	171.9	136
1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON	171.9	136
1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON	171.9	136
1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON	171.9	136
1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON	171.9	136

Site	Address	Distance (m)	Map Key
1207931 Ontario Limited	1917 Parkedale Ave. Brockville ON K6V 5T2	171.9	136
MOTOR COILS MANUFACTURING	1879 PARKDALE AVENUE, BROCKVILLE, ON K6V 5T2	121.0	145
MOTOR COILS MANUFACTURING	1879 PARKDALE AVENUE BROCKVILLE ON K6V 5T2	121.0	145
MOTOR COILS MANUFACTURING 27-428	1879 PARKDALE AVENUE BROCKVILLE ON K6V 5T2	121.0	145
MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON K6V 5T2	121.0	145
MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON	121.0	145
MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON	121.0	145
MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON	121.0	145
MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON K6V 5T2	121.0	145
MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON	121.0	145
MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON K6V 5T2	121.0	145
MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON K6V 5T2	121.0	145

Site	Address	Distance (m)	Map Key
MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON K6V 5T2	121.0	145
MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON K6V 5T2	121.0	145
MOTOR COILS MANUFACTURING	1879 Parkedale Ave. Brockville ON K6V 5T2	121.0	145
GARDEN WORLD 17-502	1845 PARKEDALE AVENUE BROCKVILLE ON K6V 5T2	162.0	161
GARDEN WORLD	1845 PARKEDALE AVENUE BROCKVILLE ON K6V 5T2	162.0	161
AUTO PAK	1845 PARKDALE AVE EAST BROCKVILLE ON K6V 5T2	162.0	161
INFRASTRUCTURE ONTARIO	1804 OXFORD AVE BROCKVILLE ON	174.1	163
General Maintenance Contractors Ltd.	2805 2nd Concession Rd. Brockville ON K6V 5T1	243.0	181

HINC - TSSA Historic Incidents

A search of the HINC database, dated 2006-June 2009* has found that there are 5 HINC site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	2465 PARKDALE AVENUE BROCKVILLE ON	249.9	9

Site	Address	Distance (m)	Map Key
	121 BROOKVIEW CRESCENT BROCKVILLE ON K6V 4P4	148.2	23
	19 BRAMSHOT STREET BROCKVILLE ON	122.4	74
	95 BRIGHTON CRESCENT BROCKVILLE ON K6V 2P4	249.0	85
	92 SALISBURY AVENUE BROCKVILLE ON K6V 2T7	131.3	99

INC - Fuel Oil Spills and Leaks

A search of the INC database, dated Feb 28, 2017 has found that there are 3 INC site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	2157 PARKEDALE AVENUE, BROCKVILLE ON	124.0	97
	93 SEVENOAKS AVE, BROCKVILLE ON	133.6	111
	1942 PARKDALE AVENUE, BROCKVILLE ON	249.9	125

MNR - Mineral Occurrences

A search of the MNR database, dated 1846-Jan 2020 has found that there are 1 MNR site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Section A-4	ON	37.1	20

NPCB - National PCB Inventory

A search of the NPCB database, dated 1988-2008* has found that there are 5 NPCB site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
ST. MARY'S SCHOOL	LOT 6, REG. PLAN 238 40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	237.7	29
ST. MARY CATHOLIC HIGH SCHOOL	40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	237.7	29
BLACK AND DECKER CANADA INC	100 CENTRAL AVE BROCKVILLE ON K6V 5W6	243.3	58
BLACK AND DECKER CANADA INC	100 CENTRAL AVE W BROCKVILLE ON K6V 4N8	243.3	58
BLACK AND DECKER CANADA INC	100 CENTRAL AVE CENTRAL AVE BROCKVILLE ON K6V 5W6	243.3	58

NPRI - National Pollutant Release Inventory

A search of the NPRI database, dated 1993-May 2017 has found that there are 19 NPRI site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
ZELLERS	125 STEWART Boulevard BROCKVILLE ON K6V4W5	63.8	11
WARNER-LAMBERT CANADA INC.	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	185.8	40
TRILLIUM HEALTH CARE MANUFACTURING	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	185.8	40
TRILLIUM HEALTH CARE MANUFACTURING	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	185.8	40

Site	Address	Distance (m)	Map Key
TRILLIUM HEALTH CARE PRODUCTS	2337 PARKEDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V 5W5	185.8	40
TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	185.8	40
TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	185.8	40
TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	185.8	40
TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	185.8	40
TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	185.8	40
TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	185.8	40
TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	185.8	40
WARNER-LAMBERT CANADA INC	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	185.8	40

Site	Address	Distance (m)	Map Key
WARNER-LAMBERT CANADA INC	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	185.8	40
TRILLIUM HEALTH CARE PRODUCTS	2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	185.8	40
THE GREAT ATLANTIC & PACIFIC COMPANY OF CANAD	3049 JEFFERSON Drive BROCKVILLE ON K6V6N7	99.8	50
CANARM	2157 PARKEDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5V6	124.0	97

OPCB - Inventory of PCB Storage Sites

A search of the OPCB database, dated 1987-Oct 2004; 2012-Dec 2013 has found that there are 10 OPCB site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
St. Mary's School,	40 Central Avenue LOT 6, REG. PLAN 238 BROCKVILLE ON K6V 4N5	237.7	29
St. Mary's School,	40 Central Avenue LOT 6, REG. PLAN 238 BROCKVILLE ON K6V 4N5	237.7	29
St. Mary's School,	40 Central Avenue LOT 6, REG. PLAN 238 BROCKVILLE ON K6V 4N5	237.7	29
BLACK AND DECKER CANADA INC	100 CENTRAL AVE BROCKVILLE ON K6V 5W6	243.3	58
BLACK AND DECKER CANADA INC	100 CENTRAL AVE BROCKVILLE ON K6V 5W6	243.3	58

Site	Address	Distance (m)	Map Key
BLACK AND DECKER CANADA INC	100 CENTRAL AVE BROCKVILLE ON K6V 5W6	243.3	58
BLACK AND DECKER CANADA INC	100 CENTRAL AVE BROCKVILLE ON K6V 5W6	243.3	58
BLACK AND DECKER CANADA INC	100 CENTRAL AVE BROCKVILLE ON K6V 5W6	243.3	58
BLACK AND DECKER CANADA INC	100 CENTRAL AVE BROCKVILLE ON K6V 5W6	243.3	58

PES - Pesticide Register

A search of the PES database, dated Oct 2011-Jun 30, 2020 has found that there are 41 PES site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
WHEELER'S YOUR INDEPENDENT GROCER/702320 ONT. LTD.	2399 PARKEDALE AVE W BROCKVILLE ON K6V3G9	205.8	8
LOBLAWS INC. O/A BROCKVILLE YOUR INDEPENDENT GROCER	2399 PARKDALE AVE BROCKVILLE ON K6V3G9	205.8	8
SHOPPERS DRUG MART #0935 (1000 ISLANDS MALL)	2399 PARKEDALE AVENUE BROCKVILLE ON K6V 3G9	205.8	8
MARK S. LESLIE APOTHECARY LTD. O/A SHOPPERS DRUG MART	2399 PARKEDALE AVE, 1000 ISLAND MALL BROCKVILLE ON K6V 3G9	205.8	8
SHOPPERS DRUG MART #0935 (1000 ISLANDS MALL)	2399 PARKEDALE AVENUE BROCKVILLE ON K6V 3G9	205.8	8

Site	Address	Distance (m)	Map Key
SHOPPERS DRUG MART #0935 (1000 ISLANDS MALL)	2399 PARKEDALE AVENUE BROCKVILLE ON K6V3G9	205.8	8
MARK S. LESLIE APOTHECARY LTD. O/A SHOPPERS DRUG MART	2399 PARKEDALE AVE, 1000 ISLAND MALL BROCKVILLE ON K6V 3G9	205.8	8
MARK S. LESLIE APOTHECARY LTD. O/A SHOPPERS DRUG MART	2399 PARKEDALE AVE, 1000 ISLAND MALL BROCKVILLE ON K6V3G9	205.8	8
702320 ONT. LTD./WHEELER'S YOUR INDEPENDENT GROCER	2399 PARKEDALE AVENUE BROCKVILLE ON K6V3G9	205.8	8
NATIONAL GROCERS CO. LTD.	2399 PARKEDALE AVENUE BROCKVILLE ON K6V3G9	205.8	8
WHEELER'S YOUR INDEPENDENT GROCER/702320 ONT. LTD.	2399 PARKEDALE AVE W BROCKVILLE ON K6V3G9	205.8	8
CAROLYN BURPEE PROFESSIONAL PHARMACY SERVICES INC	2399 Parkedale AV Brockville ON K6V 3G9	205.8	8
ECONOMY VALU-MART/702320 ONTARIO LIMITED	2465 PARKDALE AVENUE BROCKVILLE ON K6V 5X9	249.9	9
ZELLERS LTD	125 STEWART BLVD BROCKVILLE ON	63.8	11
771485 ONTARIO LIMITED RON'S NO FRILLS	125 STEWART BLVD. BROCKVILLE ON K0E 1R0	63.8	11
771485 ONTARIO LIMITED/JACK & FAITH'S NO FRILLS	125 STEWART BLVD BROCKVILLE ON K6V6X9	63.8	11
ZELLERS STORE #107 - BROCKVILLE S.C.	125 STEWART BLVD BROCKVILLE ON K6V 4W4	63.8	11

Site	Address	Distance (m)	Map Key
2062072 ONTARIO LIMITED O/A BRETT'S VALU-MART	125 STEWART BLVD BROCKVILLE ON K6V 4W4	63.8	11
2062072 ONTARIO LIMITED O/A BRETT'S VALU-MART	125 STEWART BLVD BROCKVILLE ON K6V 4W4	63.8	11
ZELLERS INC O/A ZELLERS STORE #107	125 STEWART BLVD BROCKVILLE ON K6V4W4	63.8	11
ZELLERS INC O/A ZELLERS STORE #107	125 STEWART BLVD BROCKVILLE ON K6V 4W4	63.8	11
2062072 ONTARIO LIMITED O/A BRETT'S VALU-MART	125 STEWART BLVD BROCKVILLE ON K6V4W4	63.8	11
ZELLERS INC O/A ZELLERS STORE #107	125 STEWART BLVD BROCKVILLE ON K6V4W4	63.8	11
2125795 ONTARIO LIMITED O/A GEMMELL'S GARDEN CENTRE	18 - 125 STEWART BLVD BROCKVILLE ON K6V4W5	63.8	11
771485 ONTARIO LIMITED/JACK & FAITH'S NO FRILLS	125 STEWART BLVD BROCKVILLE ON K6V6X9	63.8	11
ZELLERS STORE #107 - BROCKVILLE S.C.	125 STEWART BLVD BROCKVILLE ON K6V4W4	63.8	11
METRO ONTARIO INC O/A METRO/FOOD BASICS # 921	3049 JEFFERSON STREET BROCKVILLE ON K6V6N3	99.8	50
METRO ONTARIO INC O/A METRO/FOOD BASICS # 921	3049 JEFFERSON STREET BROCKVILLE ON K6V6N3	99.8	50

Site	Address	Distance (m)	Map Key
METRO ONTARIO INC O/A METRO/FOOD BASICS # 921	3049 Jefferson Street Brockville ON K6V 6N3	99.8	50
MUTTART BUILDERS' SUPPLIES	2057 PARKEDALE AVENUE BROCKVILLE ON K6V5V8	200.7	114
WAL-MART CANADA CORP/LA COMPAGNIE WAL-MART DU CANADA	1942 PARKEDALE AVE BROCKVILLE ON K6V 7N4	249.9	125
WAL-MART CANADA CORP #3006	1942 PARKEDALE AVE BROCKVILLE ON K6V9Z1	249.9	125
WAL-MART CANADA CORP #3006	1942 PARKEDALE AVE BROCKVILLE ON K6V9Z1	249.9	125
WAL-MART CANADA CORP #3006	1942 PARKEDALE AVE BROCKVILLE ON K6V 7N4	249.9	125
WAL-MART CANADA CORP #3006	1942 PARKEDALE AVE BROCKVILLE ON K6V 7N4	249.9	125
ALEX JOANNIDES HOLDINGS INC.	2360 Parkdale AVE Brockville ON K6V 7J5	226.9	134
GARDENER LANDSCAPING/GARDEN WORLD (C#91392)	R. R. #2, 1845 PARKEDALE AVENUE BROCKVILLE ON K6V5T2	162.0	161
788636 ONTARIO LIMITED/GARDEN WORLD	C/O 1845 PARKEDALE AVENUE BROCKVILLE ON K6V5T1	162.0	161
GARDENER LANDSCAPING/GARDEN WORLD (C#91392)	R.R. #2, 1845 PARKEDALE AVENUE BROCKVILLE ON K6V 1H3	162.0	161
788636 ONTARIO LIMITED/GARDEN WORLD	R.R. #2, 1845 PARKEDALE AVENUE BROCKVILLE ON K6V 6T4	162.0	161

Site	Address	Distance (m)	Map Key
GORD'S WEED CONTROL	1845 PARKDALE AVENUE, R.R. #2 BROCKVILLE ON L0C 1B0	162.0	161

PINC - Pipeline Incidents

A search of the PINC database, dated Feb 28, 2017 has found that there are 2 PINC site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	101 SALISBURY AVE, BROCKVILLE ON	149.2	103
	2089 Parkdale Avenue, Brockville ON	218.7	107

PRT - Private and Retail Fuel Storage Tanks

A search of the PRT database, dated 1989-1996* has found that there are 7 PRT site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
HILL TOP ESSO HUTT'S AUTO SERVICE LTD	154 STEWART BLVD BROCKVILLE ON K6V4W6	153.0	39
HILLTOP ESSO	154 STEWART BLVD BROCKVILLE ON K6V4W6	153.0	39
C P EXPRESS & TRANSPORT LTD	2183 PARKDALE AV BROCKVILLE ON	150.5	86
DOUG SUMMERS FUELS A DIV OF UNIVERSAL TERMINALS	260 CENTRAL AV W BROCKVILLE ON	117.0	95
WILLIAM CARTAGE LTD	2089 PARKDALE AV BROCKVILLE ON	218.7	107

Site	Address	Distance (m)	Map Key
DAVID EATON S & D EQUIPMENT RENTALS	1917 PARKEDALE AV BROCKVILLE ON K6V 5T2	171.9	136
CANADA TRANSPORT GROUP LTD	1861 PARKDALE AV BROCKVILLE ON K6V 5T2	181.3	152

REC - Ontario Regulation 347 Waste Receivers Summary

A search of the REC database, dated 1986-2016 has found that there are 1 REC site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
BLACK AND DECKER CANADA INC.	100 CENTRAL AVE. BROCKVILLE ON	243.3	58

RSC - Record of Site Condition

A search of the RSC database, dated 1997-Sept 2001, Oct 2004-May 2020 has found that there are 4 RSC site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
239142 Investments Limited	125 Stewart Blvd., Brockville, Ontario, K6V 4W4 ON K6V 4W4	63.8	11
COMMUNITY & PRIMARY HEALTH CARE - LANARK, LEEDS & GRENVILLE	2235 PARKEDALE AVENUE, BROCKVILLE, ON K6V 6B2 Brockville ON	146.1	71
Imperial Oil Limited	220 CENTRAL AVE W, BROCKVILLE, ON, K6V 4N8 BROCKVILLE ON K6V 4N8	151.1	88
Hilliard Cooney Limited	2089 Parkdale Avenue West, Brockville, Ontario BROCKVILLE ON	218.7	107

RST - Retail Fuel Storage Tanks

A search of the RST database, dated 1999-Jan 31, 2020 has found that there are 8 RST site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
1000 ISLAND LUBE CENTER LTD	125 STEWART BLVD BROCKVILLE ON K6V4W4	63.8	11
OIL CHANGERS	125 STEWART BLVD BROCKVILLE ON K6V4W4	63.8	11
ZIPPY LUBE & CAR CLEAN-UP	125 STEWART BLVD BROCKVILLE ON K6V 4W4	63.8	11
PETROCAN CARWASH	325 STEWART BLVD BROCKVILLE ON K6V4W8	207.7	24
R & R SERVICE CENTRE	340 CENTRAL W BROCKVILLE ON K6V5V2	232.8	98
TOM CARR'S SERVICE CENTRE	340 CENTRAL W BROCKVILLE ON K6V 5T3	232.8	98
R & R SERVICE CENTRE	340 CENTRAL W BROCKVILLE ON K6V5V2	232.8	98
FRANK'S AUTO REPAIR	1909 PARKEDALE AVE E BROCKVILLE ON K6V 5T2	188.3	142

SCT - Scott's Manufacturing Directory

A search of the SCT database, dated 1992-Mar 2011* has found that there are 22 SCT site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
EMPLOYMENT & BUSINESS JOURNAL	125 STEWART BLVD SUITE 211B BROCKVILLE ON K6V 4W4	63.8	11

Site	Address	Distance (m)	Map Key
EMPLOYMENT & BUSINESS JOURNAL	125 STEWART BLVD SUITE 211B BROCKVILLE ON K6V 4W4	63.8	11
6 G INDUSTRIES INC	125 STEWART BLVD UNIT 201 BROCKVILLE ON K6V	63.8	11
EBJ PUBLISHING INC.	125 Stewart Blvd Suite 211B Brockville ON K6V 4W4	63.8	11
Trillium Health Care Manufacturing Inc.	2337 Parkdale Ave W Brockville ON	185.8	40
Trillium Health Care Products Inc.	2337 Parkdale Ave W Brockville ON K6V 5W5	185.8	40
Trillium Health Care Products	2337 Parkedale Ave Brockville ON K6V 5W5	185.8	40
WARNER-LAMBERT PARKE-DAVIS	2337 PARKEDALE AVE W BROCKVILLE ON K6V	185.8	40
BLACK & DECKER CANADA INC.	100 CENTRAL AVE W BROCKVILLE ON K6V 4N8	243.3	58
Camalor Mfg. Inc.	100 Central Ave W Brockville ON K6V 4N8	243.3	58
ZIPPY PRINT	2211 PARKEDALE AVE W BROCKVILLE ON K6V 6B2	211.5	81
Sands Medical Inc.	300 Central Ave W Brockville ON K6V 5V2	190.1	93

Site	Address	Distance (m)	Map Key
Canarm Ltd.	2157 Parkedale Ave W Brockville ON K6V 5V6	124.0	97
Canarm Ltd.	2157 Parkedale Ave Brockville ON K6V 5V6	124.0	97
WADE-TECH LIMITED	2117 PARKEDALE AVE W BROCKVILLE ON K6V 5V8	204.5	101
Hands At Work Stitching Servs	2117 Parkedale Ave Brockville ON K6V 5Y6	204.5	101
Daltco Electric & Supply	1 Kesco Ave Brockville ON K6V 5V5	143.1	102
MUTTART BUILDER'S SUPPLIES LTD	2057 PARKEDALE AVE W BROCKVILLE ON K6V 5V8	200.7	114
Zigman Metals Ltd.	700 Central Ave W Brockville ON K6V 5W1	236.6	115
MOTOR COILS MFG. LTD.	1879 PARKDALE AVE E RR 2 BROCKVILLE ON K6V 5T2	121.0	145
MOTOR COILS MFG. LTD.	1879 PARKEDALE AVE W BROCKVILLE ON K6V 5T2	121.0	145
Motor Coils Mfg. Ltd.	1879 Parkedale Ave E RR 2 Brockville ON K6V 5T2	121.0	145

SPL - Ontario Spills

A search of the SPL database, dated 1988-Nov 2019 has found that there are 52 SPL site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Musket Transport Ltd.<UNOFFICIAL>	Highway 401 WB @ Highway 29 (Exit 696) Brockville ON	18.3	1
	REAR OF 2399 PARDALE AVE,1,000 ISLANDS \ BROCKVILLE CITY ON	205.8	8
Enbridge Gas Distribution Inc.	2399 Parkdale Ave Brockville ON	205.8	8
ZELLERS	125 STEWART BLVD., BEHIND THE ZELLERS STORE RETAIL STORE BROCKVILLE CITY ON	63.8	11
Valu-Mart (Gary-Owner)<UNOFFICIAL>	125 Stewart Street Brockville ON	63.8	11
unknown<UNOFFICIAL>	125 Stewart Boulevard Brockville ON	63.8	11
	125 Stewart Blvd Part Lot 12 Concession 1 Plan 238 Part Lot 5 Part 6 Brockville ON NA	63.8	11
TRANSPORT TRUCK	HWY 401 JUST WEST OF HWY 29 MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON	12.5	21
PUROLATOR COURIER LTD.	HWY #401 WESTBOUND, STEWART BLVD NORTH, PARKEDALE AVE EAST & NORTH AUGUSTA RD. MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON	12.5	21
HYDRO ONE	HWY 29 & 401 OVERPASS TRANSFORMER BROCKVILLE CITY ON	12.5	21
	329 Stewart Blvd. Brockville ON K6V 4W8	249.9	22

Site	Address	Distance (m)	Map Key
TRANSPORT TRUCK	ON RAMP TO HWY 401 WESTBOUND AT HWY 401 AND HWY 29. MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON	55.9	25
TRANSPORT TRUCK	401 1.5 MILES WEST OF HWY. 29 MOTOR VEHICLE (OPERATING FLUID) ELIZABETHTOWN TWP. ON	55.9	25
IMPERIAL OIL	ESSO STATION 154 STEWART ST ESSO SERVICE STATION BROCKVILLE CITY ON K6V 4W6	153.0	39
PARKE-DAVIS CANADA INC.	2337 PARKEDALE AVENUE BROCKVILLE PLANT 2337 PARKDALE AVENUE BROCKVILLE CITY ON	185.8	40
PARKE-DAVIS CANADA INC.	BROCKVILLE PLANT 2337 PARKDALE AVENUE BROCKVILLE CITY ON	185.8	40
TRILLIUM HEALTH CARE MANUFACTU	LOCAL CREEK. 2337 PARKDALE AVE. BROCKVILLE CITY ON	185.8	40
	TRILLIUM HEALTH CARE PRODUCTS 2337 PARKDALE AVENUE<UNOFFICIAL> Brockville ON	185.8	40
PARKE-DAVIS CANADA INC.	BROCKVILLE PLANT 2337 PARKDALE AVENUE BROCKVILLE CITY ON	185.8	40
TRANSPORT TRUCK	3049 JEFFERSON DRIVE SAVE-A-CENTRE PARKING LOT MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON K6V 6N7	99.8	50
Save-A-Center parking lot<UNOFFICIAL>	3049 Jefferson Drive Brockville ON K6V 6N7	99.8	50
Hydro One Networks Inc.	3049 Jefferson Dr Brockville ON K6V 6N7	99.8	50

Site	Address	Distance (m)	Map Key
GLIDDEN PAINTS	KENT BLVD. RETAIL OUTLET BROCKVILLE CITY ON	199.6	54
	mile marker 704 Hwy 401 westbound Augusta ON	16.0	55
BLACK AND DECKER	100 CENTRAL AVENUE BROCKVILLE PLANT 100 CENTRAL AVENUE BROCKVILLE CITY ON	243.3	58
CAMOLOR	100 CENTRAL AVENUE BROCKVILLE CITY ON	243.3	58
W.A. MACKEY FUELS	7789 KENT BLVD. TANK TRUCK (CARGO) BROCKVILLE CITY ON K6V 6N7	91.8	62
	44.607487, -75.691013 Brockville ON	45.4	84
CP EXPRESS & TRANSPORT	2183 PARKDALE AVE. MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON	150.5	86
TRANSPORT TRUCK	2183 PARKDALE RD. AT MYERS TRANSPORT LOADING DOCK. TRANSPORT TRUCK (CARGO) BROCKVILLE CITY ON	150.5	86
	2183 Parkedale Ave, Brockville ON	150.5	86
Meyers Transport Limited	2183 Parkedale Ave Brockville ON	150.5	86
ESSO PETROLEUM CANADA	220 CENTRAL AVE. STORAGE TANK BROCKVILLE CITY ON	151.1	88
QUEENSWAY TANK LINES	220 CENTRAL AVE TANK TRUCK (CARGO) BROCKVILLE CITY ON	151.1	88

Site	Address	Distance (m)	Map Key
REYNOLDS CENTRAL FUELS	260 CENTRAL AVE. TANK TRUCK (CARGO) BROCKVILLE CITY ON	117.0	95
Canarm Limited	2157 Parkedale Ave Brockville ON	124.0	97
Enbridge Gas Distribution Inc.	101 Salisbury Ave, Brockville Brockville ON K6V 2T6	149.2	103
Enbridge Energy Distribution Inc.	94 Bisely Crst Brockville ON	205.3	104
	2089 Parkdale Ave. Brockville ON	218.7	107
	700 Central Ave. West, Brockville Brockville ON	236.6	115
TRANSPORT TRUCK	NORTH AUGUSTA ROAD AT THE 401 MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON	0.2	116
TRANSPORT TRUCK	401 WEST TO BROKVILLE EXIT TO PARKDALE AVE. MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON	104.3	122
	401 & Parkdale (North Augusta Rd.) Brockville ON K6V 5T1	104.3	122
	Highway 401 Eastbound Brockville ON	11.5	124
McDonalds Restaurant<UNOFFICIAL>	1942 Parkdale Avenue MCDONALDS RESTAURANT<UNOFFICIAL> Brockville ON	249.9	125

Site	Address	Distance (m)	Map Key
	WALMART, 1942 PARKDALE AVE<UNOFFICIAL> Brockville ON	249.9	125
Enbridge Gas Distribution Inc.	1942 Parkdale Ave Brockville ON	249.9	125
HARMAC TRANSPORTATION	IN FRONT OF 1951 PARKDALE RD. @ BROOM RD. TANK TRUCK (CARGO) BROCKVILLE CITY ON	198.7	130
Trans Plus <UNOFFICIAL>	North Augusta Rd & Pakedale Ave, Brockville ON	213.6	132
Motor Coils Mfg. Co. (1981) Ltd.	1879 Parkedale Ave Brockville ON K6V 5T2	121.0	145
CANADA TRANSPORT	1861 PARKDALE TRANSPORT TRUCK (CARGO) BROCKVILLE CITY ON	181.3	152
PRIVATE RESIDENCE	AT MOBILE HOME AT 1871 OXFORD AVE. FURNACE OIL TANK BROCKVILLE CITY ON K6V 7B5	116.5	159

WWIS - Water Well Information System

A search of the WWIS database, dated Apr 30, 2020 has found that there are 80 WWIS site(s) within approximately 0.25 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	lot 12 con 1 ON ***Well ID:*** 3600647	189.1	2
	lot 13 con 2 ON ***Well ID:*** 3600949	207.5	5
	lot 12 con 1 ON	211.9	6

Site	Address	Distance (m)	Map Key
	Well ID: 3600646		
	ON ***Well ID:*** 3607065	231.6	7
	ON ***Well ID:*** 3600487	68.6	13
	BROCKVILLE ON ***Well ID:*** 7302213	223.7	19
	Leeds and Grenville ON ***Well ID:*** 7104241	224.0	26
	Brockville ON ***Well ID:*** 7106557	224.0	26
	lot 12 con 1 ON ***Well ID:*** 3600642	179.7	27
	BROCKVILLE ON ***Well ID:*** 7264500	131.8	31
	lot 12 con 1 ON ***Well ID:*** 3600643	184.3	32
	Brockville ON ***Well ID:*** 7215265	144.6	33
	BROCKVILLE ON ***Well ID:*** 7264499	134.0	34
	Brockville ON ***Well ID:*** 7048684	216.3	35

Site	Address	Distance (m)	Map Key
	BRAKVILLE ON ***Well ID:*** 3616923	188.6	36
	ON ***Well ID:*** 7255814	175.0	38
	BROCKVILLE ON ***Well ID:*** 3616423	207.4	42
	lot 12 con 1 ON ***Well ID:*** 3600645	210.1	43
	ON ***Well ID:*** 3600482	209.9	44
	BROCKVILLE ON ***Well ID:*** 7266770	154.1	45
	lot 11 con 1 BROCKVILLE ON ***Well ID:*** 3616332	212.3	46
	lot 13 con 1 ON ***Well ID:*** 3600648	239.6	47
	lot 12 con 1 ON ***Well ID:*** 3600641	56.0	48
	lot 14 con 1 BROCKVILLE ON ***Well ID:*** 3616334	218.8	52
	BROCKVILLE ON ***Well ID:*** 3616068	218.8	52
	ON	63.1	64

Site	Address	Distance (m)	Map Key
	Well ID: 7101789		
	Brockville ON	248.3	65
	Well ID: 7112299		
	Brockville ON	233.9	67
	Well ID: 7111990		
	Brockville ON	233.9	67
	Well ID: 7123681		
	Brockville ON	137.9	68
	Well ID: 7123820		
	Brockville ON	185.9	73
	Well ID: 7177786		
	ON	213.3	89
	Well ID: 7242292		
	lot 10 con 1 BROCKVILLE ON	140.5	90
	Well ID: 7299908		
	lot 10 con 1 BROCKVILLE ON	103.0	91
	Well ID: 7299907		
	lot 10 con 1 BROCKVILLE ON	225.3	92
	Well ID: 7299909		
	Brockville ON	102.9	100
	Well ID: 7234038		
	BROCKVILLE ON	135.3	108
	Well ID: 7101787		

Site	Address	Distance (m)	Map Key
	lot 17 con 2 ON	199.5	110
	Well ID: 3612722		
	ON	187.1	121
	Well ID: 3600488		
	ON	183.7	123
	Well ID: 3600522		
	lot 8 con 2 ON	222.4	126
	Well ID: 3600914		
	lot 17 con 1 ON	193.6	127
	Well ID: 3611804		
	lot 7 con 2 ON	232.7	128
	Well ID: 3608838		
	lot 17 con 1 ON	131.0	133
	Well ID: 3611808		
	ON	122.6	135
	Well ID: 3600483		
	lot 7 con 2 ON	214.5	137
	Well ID: 3600913		
	lot 7 con 1 ON	182.7	138
	Well ID: 3600636		
	ON	209.5	139
	Well ID: 3600493		
	lot 19 con 2 ON	164.9	143

Site	Address	Distance (m)	Map Key
	Well ID: 3614462		
	ON	132.1	144
	Well ID: 3604633		
	lot 7 con 1 ON	68.8	146
	Well ID: 3600635		
	ON	188.3	147
	Well ID: 3600534		
	lot 7 con 1 ON	149.7	148
	Well ID: 3600631		
	ON	197.9	149
	Well ID: 3600498		
	lot 7 con 11 ON	234.6	151
	Well ID: 3608778		
	lot 7 con 1 ON	35.3	154
	Well ID: 3600630		
	lot 7 con 1 ON	137.9	155
	Well ID: 3600633		
	lot 7 con 1 ON	141.2	156
	Well ID: 3608487		
	lot 7 con 1 ON	31.7	157
	Well ID: 3600629		
	lot 17 con 2 ON	94.3	160
	Well ID: 3613100		

Site	Address	Distance (m)	Map Key
	lot 6 con 1 ON	48.2	162
	Well ID: 3605369		
	lot 6 con 1 ON	28.9	164
	Well ID: 3600618		
	lot 6 con 1 ON	152.4	165
	Well ID: 3604921		
	lot 6 con 1 ON	125.6	167
	Well ID: 3600617		
	ON	158.7	169
	Well ID: 3600510		
	lot 6 con 1 ON	61.2	170
	Well ID: 3600620		
	lot 6 con 1 Brockville ON	150.3	171
	Well ID: 7307509		
	lot 6 con 1 ON	128.5	173
	Well ID: 3600615		
	lot 6 con 1 ON	194.2	174
	Well ID: 3600608		
	lot 6 con 1 ON	230.2	175
	Well ID: 3600904		
	ON	171.1	176
	Well ID: 3600509		
	lot 6 con 1 ON	168.3	177

Site	Address	Distance (m)	Map Key
	Well ID: 3608305		
	lot 6 con 1 BROCKVILLE ON ***Well ID:*** 3616501	214.4	178
	lot 6 con 1 BROCKVILLE ON ***Well ID:*** 7045448	214.4	178
	lot 6 con 1 BROCKVILLE ON ***Well ID:*** 2410238	221.1	179
	lot 6 con 1 BROCKVILLE ON ***Well ID:*** 7045450	221.1	179
	lot 6 con 1 BROCKVILLE ON ***Well ID:*** 3616500	222.0	180
	lot 6 con 1 BROCKVILLE ON ***Well ID:*** 7045447	222.0	180
	lot 6 con 1 BROCKVILLE ON ***Well ID:*** 3616502	230.8	182
	lot 6 con 1 BROCKVILLE ON ***Well ID:*** 7045449	230.8	182



Map : 0.25 Kilometer Radius

Order Number: 20200504109

Address: Hwy 401, Lyn, ON

ERIS ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 1

Order Number: 20200504109
Address: Hwy 401, Lyn, ON

ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 2

Order Number: 20200504109
Address: Hwy 401, Lyn, ON

ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 3

Order Number: 20200504109
Address: Hwy 401, Lyn, ON

ENVIRONMENTAL RISK INFORMATION SERVICES

Project Property	Expressway	Industrial and Resource - Regions	National Park
Buffer Outline	Principal Highway	Main Line	Provincial or Territorial Park
Eris Sites with Higher Elevation	Secondary Highway	Sidetrack	Other Park
Eris Sites with Same Elevation	Major Road	Transit Line	Golf Course or Driving Range
Eris Sites with Lower Elevation	Local road	Abandoned Line	Park or Sports Field
Eris Sites with Unknown Elevation	Trail		Other Recreation Area
	Proposed Road		
	Ferry Route/Ice Road		

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 4

Order Number: 20200504109
Address: Hwy 401, Lyn, ON

ENVIRONMENTAL RISK INFORMATION SERVICES

Project Property	Expressway	Industrial and Resource - Regions	National Park
Buffer Outline	Principal Highway	Main Line	Provincial or Territorial Park
Eris Sites with Higher Elevation	Secondary Highway	Sidetrack	Other Park
Eris Sites with Same Elevation	Major Road	Transit Line	Golf Course or Driving Range
Eris Sites with Lower Elevation	Local road	Abandoned Line	Park or Sports Field
Eris Sites with Unknown Elevation	Trail		Other Recreation Area
	Proposed Road		
	Ferry Route/Ice Road		

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 5

Order Number: 20200504109
Address: Hwy 401, Lyn, ON



Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 6

Order Number: 20200504109
Address: Hwy 401, Lyn, ON



Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 7

Order Number: 20200504109

Address: Hwy 401, Lyn, ON

ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 8

Order Number: 20200504109

Address: Hwy 401, Lyn, ON

ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 9

Order Number: 20200504109
Address: Hwy 401, Lyn, ON

ERIS ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 10

Order Number: 20200504109
Address: Hwy 401, Lyn, ON

ERIS ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 11

Order Number: 20200504109
Address: Hwy 401, Lyn, ON

Project Property	Expressway	Industrial and Resource - Regions	National Park
Buffer Outline	Principal Highway	Main Line	Provincial or Territorial Park
Eris Sites with Higher Elevation	Secondary Highway	Sidetrack	Other Park
Eris Sites with Same Elevation	Major Road	Transit Line	Golf Course or Driving Range
Eris Sites with Lower Elevation	Local road	Abandoned Line	Park or Sports Field
Eris Sites with Unknown Elevation	Trail		Other Recreation Area
	Proposed Road		
	Ferry Route/Ice Road		

Source: © 2015 DMTI Spatial Inc.
© ERIS Information Limited Partnership



Grid : 12

Order Number: 20200504109
Address: Hwy 401, Lyn, ON

Project Property	Expressway	Industrial and Resource - Regions	National Park
Buffer Outline	Principal Highway	Main Line	Provincial or Territorial Park
Eris Sites with Higher Elevation	Secondary Highway	Sidetrack	Other Park
Eris Sites with Same Elevation	Major Road	Transit Line	Golf Course or Driving Range
Eris Sites with Lower Elevation	Local road	Abandoned Line	Park or Sports Field
Eris Sites with Unknown Elevation	Trail		Other Recreation Area
	Proposed Road		
	Ferry Route/Ice Road		

Source: © 2015 DMTI Spatial Inc.
© ERIS Information Limited Partnership



Grid : 13

Order Number: 20200504109

Address: Hwy 401, Lyn, ON

Project Property	Expressway	Industrial and Resource - Regions	National Park
Buffer Outline	Principal Highway	Main Line	Provincial or Territorial Park
Eris Sites with Higher Elevation	Secondary Highway	Sidetrack	Other Park
Eris Sites with Same Elevation	Major Road	Transit Line	Golf Course or Driving Range
Eris Sites with Lower Elevation	Local road	Abandoned Line	Park or Sports Field
Eris Sites with Unknown Elevation	Trail		Other Recreation Area
	Proposed Road		
	Ferry Route/Ice Road		

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 14

Order Number: 20200504109

Address: Hwy 401, Lyn, ON

Project Property	Expressway	Industrial and Resource - Regions	National Park
Buffer Outline	Principal Highway	Main Line	Provincial or Territorial Park
Eris Sites with Higher Elevation	Secondary Highway	Sidetrack	Other Park
Eris Sites with Same Elevation	Major Road	Transit Line	Golf Course or Driving Range
Eris Sites with Lower Elevation	Local road	Abandoned Line	Park or Sports Field
Eris Sites with Unknown Elevation	Trail		Other Recreation Area
	Proposed Road		
	Ferry Route/Ice Road		

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 15

Order Number: 20200504109

Address: Hwy 401, Lyn, ON



Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 16

Order Number: 20200504109

Address: Hwy 401, Lyn, ON



Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 17

Order Number: 20200504109

Address: Hwy 401, Lyn, ON

ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 18

Order Number: 20200504109

Address: Hwy 401, Lyn, ON

ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 19

Order Number: 20200504109
Address: Hwy 401, Lyn, ON



Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership

75°42'30"W



Grid : 20

Order Number: 20200504109
Address: Hwy 401, Lyn, ON



Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 21

Order Number: 20200504109
Address: Hwy 401, Lyn, ON

ERIS ENVIRONMENTAL RISK INFORMATION SERVICES

Project Property	Expressway	Industrial and Resource - Regions	National Park
Buffer Outline	Principal Highway	Main Line	Provincial or Territorial Park
Eris Sites with Higher Elevation	Secondary Highway	Sidetrack	Other Park
Eris Sites with Same Elevation	Major Road	Transit Line	Golf Course or Driving Range
Eris Sites with Lower Elevation	Local road	Abandoned Line	Park or Sports Field
Eris Sites with Unknown Elevation	Trail		Other Recreation Area
	Proposed Road		
	Ferry Route/Ice Road		

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 22

Order Number: 20200504109
Address: Hwy 401, Lyn, ON

ERIS ENVIRONMENTAL RISK INFORMATION SERVICES

Project Property	Expressway	Industrial and Resource - Regions	National Park
Buffer Outline	Principal Highway	Main Line	Provincial or Territorial Park
Eris Sites with Higher Elevation	Secondary Highway	Sidetrack	Other Park
Eris Sites with Same Elevation	Major Road	Transit Line	Golf Course or Driving Range
Eris Sites with Lower Elevation	Local road	Abandoned Line	Park or Sports Field
Eris Sites with Unknown Elevation	Trail		Other Recreation Area
	Proposed Road		
	Ferry Route/Ice Road		

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 23

Order Number: 20200504109

Address: Hwy 401, Lyn, ON

ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 24

Order Number: 20200504109

Address: Hwy 401, Lyn, ON

ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 25

Order Number: 20200504109
Address: Hwy 401, Lyn, ON

ERIS ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 26

Order Number: 20200504109
Address: Hwy 401, Lyn, ON

ERIS ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 27

Order Number: 20200504109
Address: Hwy 401, Lyn, ON



Source: © 2015 DMTI Spatial Inc.
© ERIS Information Limited Partnership



Grid : 28

Order Number: 20200504109
Address: Hwy 401, Lyn, ON



Source: © 2015 DMTI Spatial Inc.
© ERIS Information Limited Partnership



Grid : 29

Order Number: 20200504109
Address: Hwy 401, Lyn, ON

Project Property
Buffer Outline
Eris Sites with Higher Elevation
Eris Sites with Same Elevation
Eris Sites with Lower Elevation
Eris Sites with Unknown Elevation
Expressway
Principal Highway
Secondary Highway
Major Road
Local road
Trail
Proposed Road
Ferry Route/Ice Road
Industrial and Resource - Regions
Main Line
Sidetrack
Transit Line
Abandoned Line
National Park
Provincial or Territorial Park
Other Park
Golf Course or Driving Range
Park or Sports Field
Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 30

Order Number: 20200504109
Address: Hwy 401, Lyn, ON

Project Property
Buffer Outline
Eris Sites with Higher Elevation
Eris Sites with Same Elevation
Eris Sites with Lower Elevation
Eris Sites with Unknown Elevation
Expressway
Principal Highway
Secondary Highway
Major Road
Local road
Trail
Proposed Road
Ferry Route/Ice Road
Industrial and Resource - Regions
Main Line
Sidetrack
Transit Line
Abandoned Line
National Park
Provincial or Territorial Park
Other Park
Golf Course or Driving Range
Park or Sports Field
Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership



Grid : 31

Order Number: 20200504109

Address: Hwy 401, Lyn, ON

ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership

Aerial Year: 2018

Address: Hwy 401, Lyn, ON

Source: ESRI World Imagery

Order Number: 20200504109

ENVIRONMENTAL RISK INFORMATION SERVICES

© ERIS Information Limited Partnership



Topographic Map

Address: Hwy 401, ON

Source: ESRI World Topographic Map

Order Number: 20200504109

ERIS ENVIRONMENTAL RISK INFORMATION SERVICES

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
116	1 of 1	ENE/0.2	101.8 / 1.91	TRANSPORT TRUCK NORTH AUGUSTA ROAD AT THE 401 MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON	SPL

Ref No:	165093	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	3/1/1999	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	TRUCK/TRAILER OVERTURN	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	56101
Nature of Impact:	Soil contamination	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	PD,FD,WORKS.
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	3/1/1999	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	UNKNOWN	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	MASKI GENERAL TRANSPORT- 200L OF DIESEL FUEL TO DITCH. PD,FD,WORKS.		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 1	ESE/18.3	99.6 / -0.21	Musket Transport Ltd.<UNOFFICIAL> Highway 401 WB @ Highway 29 (Exit 696) Brockville ON	SPL

Ref No:	4843-BG84ZP	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	9/20/2019	**Health/Env Conseq:**	2 - Minor Environment
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Miscellaneous Industrial
Incident Event:	Leak/Break	**Agency Involved:**	
Contaminant Code:	13	**Nearest Watercourse:**	
Contaminant Name:	DIESEL FUEL	**Site Address:**	Highway 401 WB @ Highway 29 (Exit 696)
Contaminant Limit 1:		**Site District Office:**	Kingston - District
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:	1202	**Site Region:**	Eastern
Environment Impact:		**Site Municipality:**	Brockville
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Land	**Northing:**	4938935.31
MOE Response:	No	**Easting:**	444565.22
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	9/20/2019	**Site Map Datum:**	

Dt Document Closed:
Incident Reason: Road Conditions
Site Name: Highway 401, WB @ Highway 29 (exit 696)<UNOFFICIAL>
Site County/District: United Counties of Leeds and Grenville
Site Geo Ref Meth:
Incident Summary: Diesel SPILL - 600L Diesel from TT to Asphalt, Gravel
Contaminant Qty: 600 L
SAC Action Class: Highway Spills (usually highway accidents)
Source Type: Truck - Only Saddle Tanks

---

2 | **1 of 1** | **W/189.1** | **102.0 / 2.12** | **lot 12 con 1 ON** | **WWIS**

Well ID: 3600647
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Data Entry Status:
Data Src: 1
Date Received: 8/6/1958
Selected Flag: Yes
Abandonment Rec:
Contractor: 3607
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY (ELIZABETHTOWN)
Site Info:
Lot: 012
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600647.pdf

Bore Hole Information

Bore Hole ID: 10214606
DP2BR: 3
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 7/1/1958
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation: 103.462066
Elevrc:
Zone: 18
East83: 444378.8
North83: 4938990
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676257
Layer: 1
Color:
General Color:
Mat1: 02
Most Common Material: TOPSOIL
Mat2: 09

Mat2 Desc: MEDIUM SAND
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 3
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676259
Layer: 3
Color: 1
General Color: WHITE
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 60
Formation End Depth: 75
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676258
Layer: 2
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 3
Formation End Depth: 60
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600647
Method Construction Code: 7
Method Construction: Diamond
Other Method Construction:

Pipe Information

Pipe ID: 10763176
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930363012
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE

Depth From:
Depth To: 75
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930363011
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 9
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600647
Pump Set At:
Static Level: 18
Final Level After Pumping: 25
Recommended Pump Depth:
Pumping Rate: 5
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 2
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676556
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 75
Water Found Depth UOM: ft

---

3 | **1 of 1** | **NNE/171.4** | **99.9 / 0.02** | **2399 Parkedale Ave Brockville ON K6V3G9** | **EHS**

Order No: 20171102078
Status: C
Report Type: Custom Report
Report Date: 07-NOV-17
Date Received: 02-NOV-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.699392
Y: 44.602971

---

4 | **1 of 1** | **N/179.1** | **99.9 / 0.06** | **2399 Parkedale Avenue Brockville ON K6V 3G9** | **EHS**

Order No: 20190702064
Status: C
Report Type: Custom Report
Report Date: 08-JUL-19
Date Received: 02-JUL-19
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.699511
Y: 44.602982

---

5 | **1 of 1** | **W/207.5** | **102.8 / 2.98** | **lot 13 con 2 ON** | **WWIS**

Well ID: 3600949
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 11/1/1956
Selected Flag: Yes
Abandonment Rec:
Contractor: 3322
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY (ELIZABETHTOWN)
Site Info:
Lot: 013
Concession: 02
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600949.pdf

Bore Hole Information

Bore Hole ID: 10214906
DP2BR: 2
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 10/5/1956
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 103.475379
Elevrc:
Zone: 18
East83: 444366.8
North83: 4939004
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676954
Layer: 2
Color: 2
General Color: GREY
Mat1: 18
Most Common Material: SANDSTONE

Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 2
Formation End Depth: 57
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676953
Layer: 1
Color:
General Color:
Mat1: 02
Most Common Material: TOPSOIL
Mat2: 05
Mat2 Desc: CLAY
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 2
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600949
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763476
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930363611
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 57
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930363610
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 6
Casing Diameter: 6
Casing Diameter UOM: inch

Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600949
Pump Set At:
Static Level: 24
Final Level After Pumping: 36
Recommended Pump Depth:
Pumping Rate: 8
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 0
Pumping Duration MIN: 30
Flowing: No

Water Details

Water ID: 933676928
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 57
Water Found Depth UOM: ft

6 | **1 of 1** | **W/211.9** | **102.8 / 2.98** | **lot 12 con 1 ON** | **WWIS**

Well ID: 3600646
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 8/6/1958
Selected Flag: Yes
Abandonment Rec:
Contractor: 3607
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY (ELIZABETHTOWN)
Site Info:
Lot: 012
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600646.pdf

Bore Hole Information

Bore Hole ID: 10214605
DP2BR: 3
Spatial Status:
Code OB: r
Elevation: 103.55175
Elevrc:
Zone: 18
East83: 444361.7

Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 6/27/1958
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

North83: 4939005
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676256
Layer: 3
Color: 1
General Color: WHITE
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 35
Formation End Depth: 43
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676255
Layer: 2
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 3
Formation End Depth: 35
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676254
Layer: 1
Color:
General Color:
Mat1: 02
Most Common Material: TOPSOIL
Mat2: 09
Mat2 Desc: MEDIUM SAND
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 3
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600646
Method Construction Code: 7
Method Construction: Diamond
Other Method Construction:

Pipe Information

Pipe ID: 10763175
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930363009
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 11
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930363010
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 43
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600646
Pump Set At:
Static Level: 20
Final Level After Pumping: 25
Recommended Pump Depth:
Pumping Rate: 7
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 2
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676555

Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 43
Water Found Depth UOM: ft

---

7 **1 of 1** **WNW/231.6** **103.4 / 3.56** **ON** **WWIS**

Well ID: 3607065
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 8/31/1977
Selected Flag: Yes
Abandonment Rec:
Contractor: 2333
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3607065.pdf

Bore Hole Information

Bore Hole ID: 10220915
DP2BR: 3
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 7/16/1977
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 103.000389
Elevrc:
Zone: 18
East83: 444350.7
North83: 4939022
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5

Overburden and Bedrock Materials Interval

Formation ID: 931690696
Layer: 1
Color: 6
General Color: BROWN
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:

Formation Top Depth: 0
Formation End Depth: 3
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931690697
Layer: 2
Color: 2
General Color: GREY
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 3
Formation End Depth: 110
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963607065
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10769485
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930374406
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 25
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930374407
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 110
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993607065
Pump Set At:
Static Level: 37
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate: 8
Flowing Rate:
Recommended Pump Rate: 7
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933683920
Layer: 2
Kind Code: 1
Kind: FRESH
Water Found Depth: 104
Water Found Depth UOM: ft

Water Details

Water ID: 933683919
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 97
Water Found Depth UOM: ft

---

8 | 1 of 33 | N/205.8 | 100.3 / 0.45 | **REAR OF 2399 PARDALE AVE,1,000 ISLANDS \ BROCKVILLE CITY ON** | SPL

Ref No: 153475
Site No:
Incident Dt: 3/19/1998
Year:
Incident Cause:
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact:
Receiving Medium: LAND
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/19/1998
Dt Document Closed:
Incident Reason:
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 56101
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

Contaminant Qty:

---

8 | 2 of 33 | N/205.8 | 100.3 / 0.45 | **WHEELER'S YOUR INDEPENDENT GROCER/702320 ONT. LTD.**
2399 PARKEDALE AVE W
BROCKVILLE ON K6V3G9 | PES

Detail Licence No: 23-01-09752-0
Licence No: 09752
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class: 01
Licence Control: 0
Latitude:
Longitude:
Lot:
Concession:
Region: 4
District: 1
County: 36
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 3425133
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region: 4
Operator District: 1
Operator County: 36
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

8 | 3 of 33 | N/205.8 | 100.3 / 0.45 | **LOBLAWS INC. O/A BROCKVILLE YOUR INDEPENDENT GROCER**
2399 PARKDALE AVE
BROCKVILLE ON K6V3G9 | PES

Detail Licence No: 23-01-12434-0
Licence No: 12434
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class: 01
Licence Control: 0
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 3421219
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region: 4
Operator District:
Operator County: 36
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

8 | 4 of 33 | N/205.8 | 100.3 / 0.45 | **SEARS CANADA INC.**
2399 PARKDALE AVE.
BROCKVILLE ON K6V 3G9 | GEN

Generator No: ON0215661
Status:
Approval Years: 96,97
Contam. Facility:
MHSW Facility:
SIC Code: 6411

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: DEPARTMENT STORES

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

8 **5 of 33** **N/205.8** **100.3 / 0.45**

SEARS CANADA INC.
2399 PARKDALE AVENUE
BROCKVILLE ON K6V 3G9

GEN

Generator No: ON0215661
Status:
Approval Years: 98,99,00,01,02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 6411
SIC Description: DEPARTMENT STORES

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

8 **6 of 33** **N/205.8** **100.3 / 0.45**

TAWCO CLEANING CENTRE
1000 ISLANDS MALL 2399 PARKDALE AVE.
BROCKVILLE ON K0E 1T0

GEN

Generator No: ON0407403
Status:
Approval Years: 90,92,93,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 9721
SIC Description: POWER LAUND./CLEANER

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

---

8 **7 of 33** **N/205.8** **100.3 / 0.45**

TAWCO CLEANING CENTRE 04-084
1000 ISLANDS MALL 2399 PARKDALE AVE.
BROCKVILLE ON K0E 1T0

GEN

Generator No: ON0407403
Status:
Approval Years: 94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 9721
SIC Description: POWER LAUND./CLEANER

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

---

8 **8 of 33** **N/205.8** **100.3 / 0.45**

TAWCO CLEANING CENTRE
1000 ISLANDS MALL 2399 PARKDALE AVENUE
BROCKVILLE ON K6V 3G9

GEN

Generator No: ON0407403
Status:
Approval Years: 99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 9721
SIC Description: POWER LAUND./CLEANERS

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

---

8 **9 of 33** **N/205.8** **100.3 / 0.45**

WAL-MART INC.
STORE #3006 - 1000 ISLANDS MALL 535
PARKDALE AVENUE
BROCKVILLE ON K6V 3G9

GEN

Generator No: ON1881516
Status:
Approval Years: 94,95,96,97
Contam. Facility:
MHSW Facility:
SIC Code: 6411
SIC Description: DEPARTMENT STORES

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 243
Waste Class Desc: PCB'S

---

8 **10 of 33** **N/205.8** **100.3 / 0.45**

WAL-MART CANADA INC.
STORE #3006 - 1000 ISLANDS MALL 535
PARKDALE AVENUE
BROCKVILLE ON K6V 3G9

GEN

Generator No: ON1881516
Status:
Approval Years: 98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 6411
SIC Description: DEPARTMENT STORES

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 147
Waste Class Desc: CHEMICAL FERTILIZER WASTES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 252

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 265
Waste Class Desc: GRAPHIC ART WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

---

8 **11 of 33** **N/205.8** **100.3 / 0.45**

SHOPPERS DRUG MART
1000 ISLANDS MALL 2399 PARKDALE BOULEVARD
BROCKVILLE ON K6V 3G9

GEN

Generator No: ON2530781
Status:
Approval Years: 00,01
Contam. Facility:
MHSW Facility:
SIC Code: 6031
SIC Description: PHARMACIES

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

8 **12 of 33** **N/205.8** **100.3 / 0.45**

WAL-MART CANADA CORP.
535 PARKDALE AVENUE STORE #3006
BROCKVILLE ON K6V 3G9

GEN

Generator No: ON1881516
Status:
Approval Years: 02,03,04
Contam. Facility:
MHSW Facility:
SIC Code: 441310
SIC Description: Automotive Parts & Accessories Stores

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

8 **13 of 33** **N/205.8** **100.3 / 0.45**

RBC Financial Group
1000 Islands Mall
Brockville ON K6V 3G9

GEN

Generator No: ON1744086
Status:
Approval Years: 04
Contam. Facility:
MHSW Facility:
SIC Code: 531310

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: Real Estate Property Managers

---

8 **14 of 33** **N/205.8** **100.3 / 0.45**

SHOPPERS DRUG MART #0935 (1000 ISLANDS MALL)
2399 PARKEDALE AVENUE
BROCKVILLE ON K6V 3G9

PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

8 **15 of 33** **N/205.8** **100.3 / 0.45**

MARK S. LESLIE APOTHECARY LTD.O/A SHOPPERS DRUG MART
2399 PARKEDALE AVE, 1000 ISLAND MALL
BROCKVILLE ON K6V 3G9

PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

8 **16 of 33** **N/205.8** **100.3 / 0.45**

SHOPPERS DRUG MART #0935 (1000 ISLANDS MALL)
2399 PARKEDALE AVENUE
BROCKVILLE ON K6V 3G9

PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

8 **17 of 33** **N/205.8** **100.3 / 0.45** **SEARS CANADA INC.**
2399 PARKDALE AVENUE
BROCKVILLE ON **GEN**

Generator No: ON0215661
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 452110
SIC Description: Department Stores
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

---

8 **18 of 33** **N/205.8** **100.3 / 0.45** **Altima 1000 Islands Dental Centre**
2399 Parkdale Ave, Unit 15
Brockville ON K6V 3G9 **GEN**

Generator No: ON9527774
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 621210
SIC Description: Offices of Dentists
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

---

8 **19 of 33** **N/205.8** **100.3 / 0.45** **Altima 1000 Islands Dental Centre**
2399 Parkdale Ave, Unit 15
Brockville ON K6V 3G9 **GEN**

Generator No: ON9527774
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 621210
SIC Description: Offices of Dentists
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

8 **20 of 33** **N/205.8** **100.3 / 0.45** **SHOPPERS DRUG MART #0935 (1000 ISLANDS MALL)**
2399 PARKEDALE AVENUE
BROCKVILLE ON K6V3G9 **PES**

Detail Licence No:
Licence No: 13327
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class: 01
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:
Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 3426701
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

8 **21 of 33** **N/205.8** **100.3 / 0.45** **MARK S. LESLIE APOTHECARY LTD.O/A SHOPPERS DRUG MART**
2399 PARKEDALE AVE, 1000 ISLAND MALL
BROCKVILLE ON K6V 3G9 **PES**

Detail Licence No: 23-01-14882-0
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: LIMITED
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

County:
Trade Name:
PDF Link:
SWP Area Name:

---

8 **22 of 33** **N/205.8** **100.3 / 0.45** **Altima 1000 Islands Dental Centre** **GEN**
2399 Parkdale Ave, Unit 15
Brockville ON K6V 3G9

Generator No: ON9527774
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 621210
SIC Description: Offices of Dentists

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

---

8 **23 of 33** **N/205.8** **100.3 / 0.45** **Mark S. Leslie Apothecary Ltd.** **GEN**
2399 PARKEDALE AVE, UNIT 27
Brockville ON K6V 3G9

Generator No: ON3281326
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 446110
SIC Description: 446110

PO Box No:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Nastran Najafi-Fard
Phone No Admin: 416-493-1220 Ext.3218

Detail(s)

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

8 **24 of 33** **N/205.8** **100.3 / 0.45** **Mark S. Leslie Apothecary Ltd.** **GEN**
2399 PARKEDALE AVE, UNIT 27
Brockville ON K6V 3G9

Generator No: ON3281326
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 446110
SIC Description: 446110

PO Box No:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Nastran Najafi-Fard
Phone No Admin: 416-493-1220 Ext.3218

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

8 **25 of 33** **N/205.8** **100.3 / 0.45** **Mark S. Leslie Apothecary Ltd.** **GEN**
2399 PARKEDALE AVE, UNIT 27
Brockville ON K6V 3G9

Generator No: ON3281326
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 261 A
Waste Class Desc: Pharmaceuticals

Waste Class: 312 P
Waste Class Desc: Pathological wastes

---

8 **26 of 33** **N/205.8** **100.3 / 0.45** **Sears Canada Inc.** **GEN**
2399 Parkedale Avenue
Brockville ON K6V 3G9

Generator No: ON6155489
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 263 L
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 221 I
Waste Class Desc: Light fuels

Waste Class: 122 C
Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 148 C
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 263 C
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 145 L

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Desc: Wastes from the use of pigments, coatings and paints

---

8 **27 of 33** **N/205.8** **100.3 / 0.45** **MARK S. LESLIE APOTHECARY LTD.O/A SHOPPERS DRUG MART** **PES**
2399 PARKEDALE AVE, 1000 ISLAND MALL
BROCKVILLE ON K6V3G9

Detail Licence No:
Licence No: 14882
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class: 01
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 3426701
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

8 **28 of 33** **N/205.8** **100.3 / 0.45** **702320 ONT. LTD./WHEELER'S YOUR INDEPENDENT GROCER** **PES**
2399 PARKEDALE AVENUE
BROCKVILLE ON K6V3G9

Detail Licence No:
Licence No: 10241
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Retail Vendor Class 03
Licence Type Code: 21
Licence Class: 03
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 3421219
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

8 **29 of 33** **N/205.8** **100.3 / 0.45** **NATIONAL GROCERS CO. LTD.** **PES**
2399 PARKEDALE AVENUE
BROCKVILLE ON K6V3G9

Detail Licence No:
Licence No: 10174
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Retail Vendor Class 03
Licence Type Code: 21

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 3421219
Operator Ext:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence Class: 03
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

8 **30 of 33** **N/205.8** **100.3 / 0.45** **WHEELER'S YOUR INDEPENDENT GROCER/702320 ONT. LTD.** **PES**
2399 PARKEDALE AVE W
BROCKVILLE ON K6V3G9

Detail Licence No:
Licence No: 09752
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Retail Vendor Class 03
Licence Type Code: 21
Licence Class: 03
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 3425133
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

8 **31 of 33** **N/205.8** **100.3 / 0.45** **Caroly Burpee Professional serv. LTD** **GEN**
2399 PARKEDALE AVE, UNIT 27
Brockville ON K6V 3G9

Generator No: ON3281326
Status: Registered
Approval Years: As of Apr 2020
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312 P
Waste Class Desc: Pathological wastes

Waste Class: 261 A
Waste Class Desc: Pharmaceuticals

---

8 **32 of 33** **N/205.8** **100.3 / 0.45** **CAROLYN BURPEE PROFESSIONAL PHARMACY SERVICES INC** **PES**
2399 Parkedale AV
Brockville ON K6V 3G9

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail Licence No:		**Operator Box:**	
Licence No:	L-232-8057394762	**Operator Class:**	
Status:	Active	**Operator No:**	
Approval Date:	2019-06-05	**Operator Type:**	
Report Source:	PEST-Limited Vendor	**Oper Area Code:**	
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:	44.60472222	**Operator Region:**	
Longitude:	-75.69888889	**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	Kingston
County:		**SWP Area Name:**	Cataraqui
Trade Name:			
PDF Link:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2155940		

8 **33 of 33** **N/205.8** **100.3 / 0.45** **SPL**

Enbridge Gas Distribution Inc.
2399 Parkdale Ave
Brockville ON

Ref No:	4758-BC7T8L	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	5/15/2019	**Health/Env Conseq:**	2 - Minor Environment
Year:		**Client Type:**	Corporation
Incident Cause:		**Sector Type:**	Miscellaneous Communal
Incident Event:	Leak/Break	**Agency Involved:**	
Contaminant Code:	35	**Nearest Watercourse:**	
Contaminant Name:	NATURAL GAS (METHANE)	**Site Address:**	2399 Parkdale Ave
Contaminant Limit 1:		**Site District Office:**	Kingston - District
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:	1075	**Site Region:**	Eastern
Environment Impact:		**Site Municipality:**	Brockville
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Air	**Northing:**	
MOE Response:	No	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	5/15/2019	**Site Map Datum:**	
Dt Document Closed:	6/29/2019	**SAC Action Class:**	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Incident Reason:	Operator/Human Error	**Source Type:**	Pipeline/Components
Site Name:	commercial<UNOFFICIAL>		
Site County/District:	United Counties of Leeds and Grenville		
Site Geo Ref Meth:			
Incident Summary:	TSSA - Enbridge, 1" steel service IP line damaged, made safe		
Contaminant Qty:	0 other - see incident description		

9 **1 of 2** **WNW/249.9** **103.8 / 3.90** **PES**

ECONOMY VALU-MART/702320 ONTARIO LIMITED
2465 PARKDALE AVENUE
BROCKVILLE ON K6V 5X9

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Vendor	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF Link:			

9 **2 of 2** **WNW/249.9** **103.8 / 3.90** **HINC**

2465 PARKDALE AVENUE
BROCKVILLE ON

External File Num:	FS INC 0809-04861
Fuel Occurrence Type:	Fire
Date of Occurrence:	9/2/2008
Fuel Type Involved:	Natural Gas
Status Desc:	Completed - Causal Analysis(End)
Job Type Desc:	Incident/Near-Miss Occurrence (FS)
Oper. Type Involved:	Commercial (e.g. restaurant, business unit, etc)
Service Interruptions:	No
Property Damage:	Yes
Fuel Life Cycle Stage:	Utilization
Root Cause:	Root Cause: Equipment/Material/Component:Yes Procedures:Yes Maintenance:No Design:Yes Training: No Management:No Human Factors:No
Reported Details:	Kelsey's Restaurant
Fuel Category:	Unknown
Occurrence Type:	Incident
Affiliation:	Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
County Name:	Leeds and Grenville
Approx. Quant. Rel:	
Nearby body of water:	
Enter Drainage Syst.:	
Approx. Quant. Unit:	
Environmental Impact:	

10 **1 of 2** **ENE/102.0** **99.9 / 0.02** **EHS**

2399 Parkedale Avenue
Brockville ON K6V 3G9

Order No:	20190930182	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	03-OCT-19	**Search Radius (km):**	.25
Date Received:	30-SEP-19	**X:**	-75.698162
Previous Site Name:		**Y:**	44.602977
Lot/Building Size:			
Additional Info Ordered:	City Directory		

10 **2 of 2** **ENE/102.0** **99.9 / 0.02** **EHS**

2399 Parkedale Avenue
Brockville ON K6V 3G9

Order No:	20190930182	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	03-OCT-19	**Search Radius (km):**	.25
Date Received:	30-SEP-19	**X:**	-75.698162
Previous Site Name:		**Y:**	44.602977
Lot/Building Size:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Additional Info Ordered:		City Directory			

11 **1 of 46** **SE/63.8** **99.8 / -0.08** **EMPLOYMENT & BUSINESS JOURNAL** **SCT**
125 STEWART BLVD SUITE 211B
BROCKVILLE ON K6V 4W4

Established: 1995
Plant Size (ft²): 0
Employment: 2

--Details--
Description: Newspaper Publishers
SIC/NAICS Code: 511110

11 **2 of 46** **SE/63.8** **99.8 / -0.08** **ZELLERS LTD** **PES**
125 STEWART BLVD
BROCKVILLE ON

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

11 **3 of 46** **SE/63.8** **99.8 / -0.08** **771485 ONTARIO LIMITED RON'S NO FRILLS** **PES**
125 STEWART BLVD.
BROCKVILLE ON K0E 1R0

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

11 **4 of 46** **SE/63.8** **99.8 / -0.08** **EMPLOYMENT & BUSINESS JOURNAL** **SCT**
125 STEWART BLVD SUITE 211B
BROCKVILLE ON K6V 4W4

Established: 1995
Plant Size (ft²): 0
Employment: 2

--Details--
Description: NEWSPAPERS: PUBLISHING, OR PUBLISHING AND PRINTING
SIC/NAICS Code: 2711

11 **5 of 46** **SE/63.8** **99.8 / -0.08** **6 G INDUSTRIES INC** **SCT**
125 STEWART BLVD UNIT 201
BROCKVILLE ON K6V

Established: 1991
Plant Size (ft²): 2000
Employment: 5

--Details--
Description: FABRICATED PLATE WORK (BOILER SHOPS)
SIC/NAICS Code: 3443

Description: FABRICATED PIPE AND PIPE FITTINGS
SIC/NAICS Code: 3498

11 **6 of 46** **SE/63.8** **99.8 / -0.08** **ZIPPY LUBE & CAR CLEAN-UP** **RST**
125 STEWART BLVD
BROCKVILLE ON K6V 4W4

Headcode: 00921430
Headcode Desc: OIL CHANGES & LUBRICATION SERVICE
Phone:
List Name:
Description:

11 **7 of 46** **SE/63.8** **99.8 / -0.08** **EBJ PUBLISHING INC.** **SCT**
125 Stewart Blvd Suite 211B
Brockville ON K6V 4W4

Established: 1998
Plant Size (ft²): 0
Employment: 1

--Details--
Description: Newspaper Publishers
SIC/NAICS Code: 511110

11 **8 of 46** **SE/63.8** **99.8 / -0.08** **ZELLERS** **SPL**
125 STEWART BLVD., BEHIND THE ZELLERS
STORE RETAIL STORE
BROCKVILLE CITY ON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Ref No:	236978	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	8/24/2002	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	OTHER CONTAINER LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	FIRE DEPT. AND WORKS
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	56101
Nature of Impact:	Soil contamination	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	8/24/2002	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	VANDALISM	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ZELLERS: 50-60 L OF USED COOKING OIL TP GROUND, CONTAINED AND CLEANED		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	9 of 46	SE/63.8	99.8 / -0.08	125 Stewart Blvd. Brockville ON	EHS

Order No:	20021205004	**Nearest Intersection:**	Central Avenue West/401
Status:	C	**Municipality:**	
Report Type:	Complete Report	**Client Prov/State:**	ON
Report Date:	12/13/02	**Search Radius (km):**	0.30
Date Received:	12/5/02	**X:**	-75.697904
Previous Site Name:		**Y:**	44.599436
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	10 of 46	SE/63.8	99.8 / -0.08	771485 ONTARIO LIMITED/JACK & FAITH'S NO FRILLS 125 STEWART BLVD BROCKVILLE ON K6V6X9	PES

Detail Licence No:	23-01-11249-0	**Operator Box:**	
Licence No:	11249	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	613
Licence Type:	Limited Vendor	**Oper Phone No:**	3428868
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:	0	**Oper Concession:**	
Latitude:		**Operator Region:**	4
Longitude:		**Operator District:**	
Lot:		**Operator County:**	36
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF Link:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	11 of 46	SE/63.8	99.8 / -0.08	DURANT'S ONE HOUR CLEANERS LIMITED 125 STEWART BLVD. (BROCKVILLE CENTRE) BROCKVILLE ON K6V 3P6	GEN

Generator No:	ON1275400	**PO Box No:**	
Status:		**Country:**	
Approval Years:	92,93,97,98	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	9721		
SIC Description:	POWER LAUND./CLEANER		

Detail(s)

Waste Class:	241
Waste Class Desc:	HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	12 of 46	SE/63.8	99.8 / -0.08	PHARMA PLUS DRUGS LTD 125 STEWART BOULEVARD BROCKVILLE ON K6V 4W4	GEN

Generator No:	ON1553302	**PO Box No:**	
Status:		**Country:**	
Approval Years:	92,93,97	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	6031		
SIC Description:	PHARMACIES		

Detail(s)

Waste Class:	261
Waste Class Desc:	PHARMACEUTICALS
Waste Class:	312
Waste Class Desc:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	13 of 46	SE/63.8	99.8 / -0.08	BROCK (OUT OF BUS) 05-844 125 STEWART BLVD. BROCKVILLE ON K6V 4W4	GEN

Generator No:	ON1588800	**PO Box No:**	
Status:		**Country:**	
Approval Years:	92,93,95,96,97,98	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	6571		
SIC Description:	CAMERA/PHOTO. SUPPLY		

Detail(s)

Waste Class:	264
Waste Class Desc:	PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	14 of 46	SE/63.8	99.8 / -0.08	DURANT'S ONE HOUR CLEANERS LIMITED12-443 125 STEWART BLVD. (BROCKVILLE CENTRE) BROCKVILLE ON K6V 3P6	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON1275400
Status:
Approval Years: 94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 9721
SIC Description: POWER LAUND./CLEANER

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	15 of 46	SE/63.8	99.8 / -0.08	PHARMA PLUS DRUGS LTD. 31-655 125 STEWART BLVD., BROCKVILLE C/O 5935 AIRPORT ROAD STEI 500 MISSISSAUGA ON L4V 1W5	GEN

Generator No: ON1553302
Status:
Approval Years: 94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 6031
SIC Description: PHARMACIES

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	16 of 46	SE/63.8	99.8 / -0.08	BROCK PHOTO CENTER 05-844 125 STEWART BLVD. BROCKVILLE ON K6V 4W4	GEN

Generator No: ON1588800
Status:
Approval Years: 94
Contam. Facility:
MHSW Facility:
SIC Code: 6571
SIC Description: CAMERA/PHOTO. SUPPLY

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	17 of 46	SE/63.8	99.8 / -0.08	MAXWELLS DRYCLEANING SERVICE 125 STEWART BLVD. BROCKVILLE ON K6V 4W4	GEN

Generator No: ON1999000
Status:
Approval Years: 95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 9721

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: POWER LAUND./CLEANERS

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	18 of 46	SE/63.8	99.8 / -0.08	PHARMA PLUS DRUGS LTD. 125 STEWART BOULEVARD BROCKVILLE ON K6V 4W4	GEN

Generator No: ON1553302
Status:
Approval Years: 98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 6031
SIC Description: PHARMACIES

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	19 of 46	SE/63.8	99.8 / -0.08	DURANT'S ONE HOUR CLEANERS LIMITED BROCKVILLE CENTRE 125 STEWART BOULEVARD BROCKVILLE ON K6V 3P6	GEN

Generator No: ON1275400
Status:
Approval Years: 99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 9721
SIC Description: POWER LAUND./CLEANERS

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	20 of 46	SE/63.8	99.8 / -0.08	MAXWELLS DRYCLEANING SERVICE 125 STEWART BOULEVARD BROCKVILLE ON K6V 4W4	GEN

Generator No: ON1999000
Status:
Approval Years: 99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 9721
SIC Description: POWER LAUND./CLEANERS

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Desc: HALOGENATED SOLVENTS

---

11 **21 of 46** **SE/63.8** **99.8 / -0.08** **Eastern Enginering Group Inc** **GEN**
125 Stewart Blvd Suite 212
Brockville ON K6V 4W4

Generator No: ON6380487
Status:
Approval Years: 02,03,04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

---

11 **22 of 46** **SE/63.8** **99.8 / -0.08** **Zellers Inc.** **GEN**
125 Steward Blvd.
Brockville ON K6V 4W4

Generator No: ON9593184
Status:
Approval Years: 02,03,04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 243
Waste Class Desc: PCB'S

---

11 **23 of 46** **SE/63.8** **99.8 / -0.08** **125 Stewart Boulevard** **EHS**
Brockville ON K6V 4W4

Order No: 20051125027
Status: C
Report Type: Custom Report
Report Date: 12/5/2005
Date Received: 11/25/2005
Previous Site Name:
Lot/Building Size: 14.77 acres
Additional Info Ordered:

Nearest Intersection: The southeast corner of Stewart Boulevard and Highway 401
Municipality:
Client Prov/State: ON
Search Radius (km): 0.3
X: -75.697744
Y: 44.599394

---

11 **24 of 46** **SE/63.8** **99.8 / -0.08** **ZELLERS STORE #107 - BROCKVILLE S.C.** **PES**
125 STEWART BLVD
BROCKVILLE ON K6V 4W4

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Limited Vendor
Licence Type Code: 23

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

11 **25 of 46** **SE/63.8** **99.8 / -0.08** **2062072 ONTARIO LIMITED O/A BRETT'S VALU-MART** **PES**
125 STEWART BLVD
BROCKVILLE ON K6V 4W4

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

11 **26 of 46** **SE/63.8** **99.8 / -0.08** **239142 Investments Limited** **CPU**
125 Stewart Blvd
Brockville ON K6V 4W4

EBR Registry No: 010-2868
Ministry Ref No: 1112-778Q8B
Notice Type: Instrument Proposal
Notice Stage:
Notice Date:
Proposal Date: February 22, 2008
Year: 2008
Instrument Type: (EPA s. 168.6) - Certificate of Property Use
Off Instrument Name:
Posted By:
Company Name:
Site Address:
Location Other:
Proponent Name:
Proponent Address: 9011 Leslie Street Suite No. 302 Richmond Hill Ontario Canada L4B 3B6
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

125 Stewart Blvd Part Lot 12, Concession 1, Plan 238, Part Lot 5, Part 6 City of Brockville, United Counties of Leeds and Grenville

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	27 of 46	SE/63.8	99.8 / -0.08	Brockville Shopping Centre 125 Stewart Blvd. Brockville ON	GEN

Generator No: ON2956900
Status:
Approval Years: 06
Contam. Facility:
MHSW Facility:
SIC Code: 531190
SIC Description: Lessors of Other Real Estate Property

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	28 of 46	SE/63.8	99.8 / -0.08	Valu-Mart (Gary-Owner)<UNOFFICIAL> 125 Stewart Street Brockville ON	SPL

Ref No: 5233-7LLSYM
Site No:
Incident Dt:
Year:
Incident Cause: Pipe Or Hose Leak
Incident Event:
Contaminant Code: 38
Contaminant Name: REFRIGERANT GAS, R404
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Not Anticipated
Nature of Impact: Air Pollution
Receiving Medium:
Receiving Env:
MOE Response: No Field Response
Dt MOE Arvl on Scn:
MOE Reported Dt: 11/21/2008
Dt Document Closed:
Incident Reason: Unknown - Reason not determined
Site Name: Valu-Mart<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Valu-Mart: 90.5 kgs R404 release to atmosphere repaired
Contaminant Qty: 90.5 kg

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Other
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office: Kingston - District
Site Postal Code:
Site Region:
Site Municipality: Brockville
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Air Spills - Gases and Vapours
Source Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	29 of 46	SE/63.8	99.8 / -0.08	239142 Investments Limited 125 Stewart Blvd., Brockville, United Counties of Leeds and Grenville Part of Lot 12, Concession 1, Plan 238, Part Lot 5, Part 6 CITY OF BROCKVILLE ON	CPU

EBR Registry No: 010-8443
Ministry Ref No: CPU 0648-7UDP3
Notice Type: Instrument Decision

Decision Posted:
Exception Posted:
Section:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Notice Stage:
Notice Date: January 21, 2010
Proposal Date: November 23, 2009
Year: 2009
Instrument Type: (EPA s. 168.6) - Certificate of Property Use
Off Instrument Name:
Posted By:
Company Name: 239142 Investments Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 9011 Leslie Street , Suite 302, Richmond Hill Ontario, Canada L4B 3B6
Comment Period:
URL:

Act 1:
Act 2:
Site Location Map:

Site Location Details:

125 Stewart Blvd., Brockville, United Counties of Leeds and Grenville Part of Lot 12, Concession 1, Plan 238, Part Lot 5, Part 6 CITY OF BROCKVILLE

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	30 of 46	SE/63.8	99.8 / -0.08	2062072 ONTARIO LIMITED O/A BRETT'S VALU-MART 125 STEWART BLVD BROCKVILLE ON K6V 4W4	PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
11	31 of 46	SE/63.8	99.8 / -0.08	239142 Investments Limited 125 Stewart Blvd., Brockville, Ontario, K6V 4W4 ON K6V 4W4	RSC

RSC ID: 78713
RA No:
RSC Type:
Curr Property Use: Commercial
Ministry District: BROCKVILLE
Filing Date: 13-Aug-10
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686: Yes
Asmt Roll No: 0802 020 051 16900 0000

Cert Date: 22-Aug-07
Cert Prop Use No: 0648-7UDPY3
Intended Prop Use: Commercial
Qual Person Name: Louis Kates
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N): Yes
Accuracy Estimate: 21 to 100 meters
Telephone: 905-8821763
Fax: 905-8826568
Email: louis.kates@gmail.com

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Prop ID No (PIN):	44176-0188(R)
Property Municipal Address:	125 Stewart Blvd., Brockville, Ontario, K6V 4W4
Mailing Address:	PO BOX 32530 STN VILLAGE GATE, RICHMOND HILL, ON, L4C 1A0
Latitude & Latitude:	44.59987700N 75.69756360W (converted from UTM)
UTM Coordinates:	NAD83 18-444640-4938740
Consultant:	
Legal Desc:	Part Lot 5, Plan 238; Part Lot 6, Plan 238; Part Lot 12, Concession 1 Elizabethtown as in LR133104, LR74470, LR41159 except LR66143; Brockville
Measurement Method:	Digitized from a map
Applicable Standards:	Background Site Conditions Standard, with Nonpotable Ground Water, Coarse Textured Soil, for Industrial/Commercial/Community property use with Risk As
RSC PDF:	

11 **32 of 46** **SE/63.8** **99.8 / -0.08** **ZELLERS INC O/A ZELLERS STORE #107** **PES**
125 STEWART BLVD
BROCKVILLE ON K6V4W4

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Vendor	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF Link:			

11 **33 of 46** **SE/63.8** **99.8 / -0.08** **unknown<UNOFFICIAL>** **SPL**
125 Stewart Boulevard
Brockville ON

Ref No:	3308-8LYSMU	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	9/22/2011	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Discharge or Emission to Air	**Sector Type:**	Other
Incident Event:		**Agency Involved:**	
Contaminant Code:	38	**Nearest Watercourse:**	
Contaminant Name:	REFRIGERANT GAS, N.O.S.	**Site Address:**	125 Stewart Boulevard
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Not Anticipated	**Site Municipality:**	Brockville
Nature of Impact:	Air Pollution	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	No Field Response	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	9/23/2011	**Site Map Datum:**	
Dt Document Closed:	12/22/2011	**SAC Action Class:**	Air Spills - Gases and Vapours
Incident Reason:	Unknown - Reason not determined	**Source Type:**	
Site Name:	business Brett's Value-Mart<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Summary:	Brett's Valu Mart: R 404 to atm; ~ 335 lbs; rprd
Contaminant Qty:	335 lb

11 **34 of 46** **SE/63.8** **99.8 / -0.08** **ZELLERS INC O/A ZELLERS STORE #107** **PES**
125 STEWART BLVD
BROCKVILLE ON K6V 4W4

Detail Licence No:	23-01-15431-0	**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	LIMITED	**Oper Phone No:**	
Licence Type Code:		**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF Link:			

11 **35 of 46** **SE/63.8** **99.8 / -0.08** **2062072 ONTARIO LIMITED O/A BRETT'S VALU-MART** **PES**
125 STEWART BLVD
BROCKVILLE ON K6V4W4

Detail Licence No:		**Operator Box:**	
Licence No:	13671	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	613
Licence Type:	Limited Vendor	**Oper Phone No:**	4980622
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF Link:			

11 **36 of 46** **SE/63.8** **99.8 / -0.08** **ZELLERS** **NPRI**
125 STEWART Boulevard
BROCKVILLE ON K6V4W5

NPRI ID:	8800000408	**Org ID:**	
Other ID:		**Submit Date:**	
No Other ID:		**Last Modified:**	
Track ID:		**Contact ID:**	
Report ID:		**Cont Type:**	MED
Report Type:		**Contact Title:**	Mr.

Rpt Type ID:		**Cont First Name:**	FRED
Report Year:	2004	**Cont Last Name:**	WARE
Not-Current Rpt?:		**Contact Position:**	SENIOR MANAGER ENERGY ENVIRONMENT SOURCING INITIATIVES
Yr of Last Filed Rpt:		**Contact Fax:**	
Fac ID:		**Contact Ph.:**	
Fac Name:	ZELLERS STORE, #107 BROCKVILLE S.C.	**Cont Area Code:**	416
Fac Address1:		**Contact Tel.:**	8614938
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:		**Cont Fax Area Cde:**	
Facility Lat:		**Contact Fax:**	
Facility Long:		**Contact Email:**	fred.ware@hbc.com
DLS (Last Filed Rpt):		**Latitude:**	
Facility DLS:		**Longitude:**	
Datum:		**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	20	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	53		
NAICS 2 Description:	Real Estate and Rental and Leasing		
NAICS Code (4 digit):	5311		
NAICS 4 Description:	Lessors of Real Estate		
NAICS Code (6 digit):	531120		
NAICS 6 Description:	Lessors of Non-Residential Buildings (except Mini-Warehouses)		

Substance Release Report

CAS No:	10024-97-2
Report ID:	
Rpt Period:	2004
Subst Released:	Nitrous oxide
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	NA - M10
Report ID:	
Rpt Period:	2004
Subst Released:	PM2.5 - Particulate Matter <= 2.5 Microns
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	124-38-9
Report ID:	
Rpt Period:	2004
Subst Released:	Carbon dioxide
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes

CAS No:	7446-09-5
Report ID:	
Rpt Period:	2004
Subst Released:	Sulphur dioxide
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	630-08-0
Report ID:	
Rpt Period:	2004
Subst Released:	Carbon monoxide
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	74-82-8
Report ID:	
Rpt Period:	2004
Subst Released:	Methane
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	11104-93-1
Report ID:	
Rpt Period:	2004
Subst Released:	Nitrogen oxides (expressed as NO2)
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	811-97-2
Report ID:	
Rpt Period:	2004
Subst Released:	HFC-134a Hydrofluorocarbon
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	NA - M08
Report ID:	
Rpt Period:	2004
Subst Released:	PM - Total Particulate Matter
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	NA - M09
Report ID:	
Rpt Period:	2004
Subst Released:	PM10 - Particulate Matter <= 10 Microns
Air:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M16
Report ID:
Rpt Period: 2004
Subst Released: Volatile Organic Compounds (VOCs)
Air:
Water:
Land:
Total Releases:
Units: tonnes

---

11 **37 of 46** **SE/63.8** **99.8 / -0.08** **OIL CHANGERS**
125 STEWART BLVD
BROCKVILLE ON K6V4W4 **RST**

Headcode: 00921430
Headcode Desc: OIL CHANGES & LUBRICATION SERVICE
Phone: 6133425562
List Name:
Description:

---

11 **38 of 46** **SE/63.8** **99.8 / -0.08** **239142 Investments Limited**
Brockville Shopping Centre Address: 125 Stewart Blvd Part Lot 12, Concession 1, Plan 238, Part Lot 5, Part 6 City of Brockville, United Counties of Leeds and
Grenville CITY OF BROCKVILLE ON **CPU**

EBR Registry No: 010-2868 **Decision Posted:**
Ministry Ref No: 1112-778Q8B **Exception Posted:**
Notice Type: Instrument Decision **Section:**
Notice Stage: **Act 1:**
Notice Date: August 19, 2016 **Act 2:**
Proposal Date: February 22, 2008 **Site Location Map:**
Year: 2008
Instrument Type: (EPA s. 168.6) - Certificate of Property Use
Off Instrument Name:
Posted By:
Company Name: 239142 Investments Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 9011 Leslie Street, Suite No. 302, Richmond Hill Ontario, Canada L4B 3B6
Comment Period:
URL:

Site Location Details:

Brockville Shopping Centre Address: 125 Stewart Blvd Part Lot 12, Concession 1, Plan 238, Part Lot 5, Part 6 City of Brockville, United Counties of Leeds and Grenville CITY OF BROCKVILLE

---

11 **39 of 46** **SE/63.8** **99.8 / -0.08** **1000 ISLAND LUBE CENTER LTD**
125 STEWART BLVD
BROCKVILLE ON K6V4W4 **RST**

Headcode: 00921430
Headcode Desc: OIL CHANGES & LUBRICATION SERVICE

Phone: 6133425562
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

---

11 **40 of 46** **SE/63.8** **99.8 / -0.08** **125 Stewart Blvd Part Lot 12 Concession 1 Plan 238 Part Lot 5 Part 6**
Brockville ON NA **SPL**

Ref No: 1876-AL7JT3
Site No: NA
Incident Dt: 4/7/2017
Year:
Incident Cause:
Incident Event: Leak/Break
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: 1202
Environment Impact:
Nature of Impact:
Receiving Medium:
Receiving Env: Land
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 4/7/2017
Dt Document Closed:
Incident Reason: Unknown / N/A
Site Name: Brockville Shopping Centre
Site County/District: United Counties of Leeds and Grenville
Site Geo Ref Meth: 10-30 metres eg. Medium Quality GPS
Incident Summary: TT leaking diesel to ground, cntd, clnd
Contaminant Qty: 40 L

Discharger Report:
Material Group:
Health/Env Conseq: 2 - Minor Environment
Client Type:
Sector Type: Miscellaneous Industrial
Agency Involved:
Nearest Watercourse:
Site Address: 125 Stewart Blvd Part Lot 12 Concession 1 Plan 238 Part Lot 5 Part 6
Site District Office: Kingston - District
Site Postal Code:
Site Region: Eastern
Site Municipality: Brockville
Site Lot:
Site Conc: NA
Northing: 4938740
Easting: 444640
Site Geo Ref Accu: GPS
Site Map Datum: NAD83
SAC Action Class:
Source Type: Truck - Transport/Hauling

---

11 **41 of 46** **SE/63.8** **99.8 / -0.08** **First National Management Corporation**
125 Stewart Blvd
Brockville ON K6V 4W4 **GEN**

Generator No: ON7598785
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241 L
Waste Class Desc: Halogenated solvents and residues

---

11 **42 of 46** **SE/63.8** **99.8 / -0.08** **ZELLERS INC O/A ZELLERS STORE #107**
125 STEWART BLVD
BROCKVILLE ON K6V4W4 **PES**

Detail Licence No:
Licence No: 15431
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Licence Type:	Limited Vendor	**Oper Phone No:**	3451454
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF Link:			

11 **43 of 46** **SE/63.8** **99.8 / -0.08**

2125795 ONTARIO LIMITED O/A GEMMELL'S GARDEN CENTRE
18 - 125 STEWART BLVD
BROCKVILLE ON K6V4W5

PES

Detail Licence No:		**Operator Box:**	
Licence No:	18566	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF Link:			

11 **44 of 46** **SE/63.8** **99.8 / -0.08**

771485 ONTARIO LIMITED/JACK & FAITH'S NO FRILLS
125 STEWART BLVD
BROCKVILLE ON K6V6X9

PES

Detail Licence No:		**Operator Box:**	
Licence No:	11249	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	613
Licence Type:	Retail Vendor Class 03	**Oper Phone No:**	3428868
Licence Type Code:	21	**Operator Ext:**	
Licence Class:	03	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF Link:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

11 **45 of 46** **SE/63.8** **99.8 / -0.08**

ZELLERS STORE #107 - BROCKVILLE S.C.
125 STEWART BLVD
BROCKVILLE ON K6V4W4

PES

Detail Licence No:		**Operator Box:**	
Licence No:	12915	**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:	Legacy Licenses (Excluding TS)	**Oper Area Code:**	613
Licence Type:	Limited Vendor	**Oper Phone No:**	3451454
Licence Type Code:	23	**Operator Ext:**	
Licence Class:	01	**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF Link:			

11 **46 of 46** **SE/63.8** **99.8 / -0.08**

First National Management Corporation
125 Stewart Blvd
Brockville ON K6V 4W4

GEN

Generator No:	ON7598785	**PO Box No:**	
Status:	Registered	**Country:**	Canada
Approval Years:	As of Apr 2020	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:			
SIC Description:			

Detail(s)

Waste Class:	241 L
Waste Class Desc:	Halogenated solvents and residues

12 **1 of 4** **W/249.9** **104.9 / 5.02**

MINISTRY OF REVENUE
BROCKVILLE REGIONAL ASSESSMENT OFFICE
2479 PARKDALE AVE.
BROCKVILLE ON K6V 3H2

GEN

Generator No:	ON0958302	**PO Box No:**	
Status:		**Country:**	
Approval Years:	86,87,88,89,90	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	0000		
SIC Description:	*** NOT DEFINED ***		

Detail(s)

Waste Class:	264
Waste Class Desc:	PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	2 of 4	W/249.9	104.9 / 5.02	MINISTRY OF REVENUE 27-397 BROCKVILLE REGIONAL ASSESSMENT OFFICE 2479 PARKDALE AVE. BROCKVILLE ON K6V 3H2	GEN

Generator No: ON0958302
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 8253
SIC Description: TAXATION ADMIN.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	3 of 4	W/249.9	104.9 / 5.02	Rideau Community Health Services 2-2479 Parkedale Rd Brockville ON K6V 3H2	GEN

Generator No: ON6045634
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312 P
Waste Class Desc: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	4 of 4	W/249.9	104.9 / 5.02	Rideau Community Health Services 2-2479 Parkedale Rd Brockville ON K6V 3H2	GEN

Generator No: ON6045634
Status: Registered
Approval Years: As of Oct 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312 P
Waste Class Desc: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
13	1 of 1	ENE/68.6	99.9 / 0.02	ON	WWIS

Well ID: 3600487
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:

Data Entry Status:
Data Src: 1
Date Received: 1/18/1960
Selected Flag: Yes
Abandonment Rec:
Contractor: 3607

Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600487.pdf

Bore Hole Information

Bore Hole ID: 10214446
DP2BR: 45
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 9/30/1959
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 98.214088
Elevrc:
Zone: 18
East83: 444639.7
North83: 4939082
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931675893
Layer: 1
Color:
General Color:
Mat1: 14
Most Common Material: HARDPAN
Mat2: 13
Mat2 Desc: BOULDERS
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 45
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931675894
Layer: 2
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:

Mat3:
Mat3 Desc:
Formation Top Depth: 45
Formation End Depth: 86
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600487
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763016
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362697
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 86
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362696
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 52
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600487
Pump Set At:
Static Level: 9
Final Level After Pumping: 15
Recommended Pump Depth: 12
Pumping Rate: 12
Flowing Rate:
Recommended Pump Rate: 6
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 2
Pumping Duration MIN: 0

Flowing: No

Water Details

Water ID: 933676360
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 86
Water Found Depth UOM: ft

---

14 **1 of 2** **E/92.5** **96.7 / -3.17** **Northern Property New LP2**
1-4 Balmoral
Brockville ON K6V 6K1 **GEN**

Generator No: ON5800077
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS
PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

14 **2 of 2** **E/92.5** **96.7 / -3.17** **Northern Property New LP2**
1-4 Balmoral
Brockville ON K6V 6K1 **GEN**

Generator No: ON5800077
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS
PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

15 **1 of 1** **ESE/107.5** **96.2 / -3.68** **1 Balmoral Pl**
Brockville ON K6V6J9 **EHS**

Order No: 20140321027
Status: C
Report Type: Custom Report
Report Date: 27-MAR-14
Date Received: 21-MAR-14
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.696692
Y: 44.601352

---

16 **1 of 1** **WSW/217.6** **104.9 / 5.02** **2511, 2523, 2539 & 2545 Parkdale Ave & 325**
Stewart Blvd, Brockville **EHS**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Brockville ON K6V 4W8

Order No: 20200318003
Status: C
Report Type: Custom Report
Report Date: 23-MAR-20
Date Received: 18-MAR-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.70263358
Y: 44.6011893

---

17 | 1 of 1 | W/247.2 | 104.9 / 5.02 | 1195149 Ontario Ltd
325 Stewart Blvd.
Brockville ON K6V4W8 | GEN

Generator No: ON6366705
Status: Registered
Approval Years: As of Apr 2020
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 150 L
Waste Class Desc: Inert organic wastes

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

---

18 | 1 of 1 | WSW/182.8 | 104.9 / 5.02 | Parkedale Ave Stewart Blvd
Brockville ON | EHS

Order No: 20130926035
Status: C
Report Type: Standard Report
Report Date: 07-OCT-13
Date Received: 26-SEP-13
Previous Site Name: Unknown
Lot/Building Size: Unknown
Additional Info Ordered: City Directory

Nearest Intersection:
Municipality: Brockville
Client Prov/State: ON
Search Radius (km): .25
X: -75.702469
Y: 44.600861

---

19 | 1 of 1 | NNE/223.7 | 99.7 / -0.17 | BROCKVILLE ON | WWIS

Well ID: 7302213
Construction Date:
Primary Water Use: Test Hole
Sec. Water Use: Monitoring
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z268033
Tag: A182530
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:

Data Entry Status:
Data Src:
Date Received: 12/22/2017
Selected Flag: Yes
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
Street Name: 2399 PARKDALE AVE
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:

Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Bore Hole Information

Bore Hole ID: 1006925425
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11/24/2017
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 99.012382
Elevrc:
Zone: 18
East83: 444580
North83: 4939242
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007100550
Layer: 3
Color: 1
General Color: WHITE
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3: 73
Mat3 Desc: HARD
Formation Top Depth: .61
Formation End Depth: 4.57
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007100549
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 06
Mat2 Desc: SILT
Mat3: 85
Mat3 Desc: SOFT
Formation Top Depth: .31
Formation End Depth: .61
Formation End Depth UOM: m

Overburden and Bedrock

Materials Interval

Formation ID: 1007100548
Layer: 1
Color: 6
General Color: BROWN
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Mat2 Desc:
Mat3: 85
Mat3 Desc: SOFT
Formation Top Depth: 0
Formation End Depth: .31
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007100560
Layer: 2
Plug From: 0.31
Plug To: 1.22
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007100559
Layer: 1
Plug From: 0
Plug To: 0.31
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007100561
Layer: 3
Plug From: 1.22
Plug To: 4.57
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1007100558
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 1007100547
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007100554

Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 1.52
Casing Diameter: 4.03
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007100555
Layer: 1
Slot: 10
Screen Top Depth: 1.52
Screen End Depth: 4.57
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 9.82

Water Details

Water ID: 1007100553
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1007100552
Diameter: 7.62
Depth From: 1.52
Depth To: 4.57
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1007100551
Diameter: 11.43
Depth From: 0
Depth To: 1.52
Hole Depth UOM: m
Hole Diameter UOM: cm

20 ***1 of 1*** ***SW/37.1*** ***104.8 / 4.92*** ***Section A-4*** ***MNR***

ON

MDI No: MDI31B12SE00016
OGF ID: 205265728
Deposit Status: DISCRETIONARY OCCURRENCE
Claim Map: T-2156
Geological District: SOUTHEASTERN ONTARIO
Mining Division: SOUTHERN ONTARIO
Name: Section A-4
P Commod: SANDSTONE (SILICA)
S Commod: SILICA SAND
Class Sub Type No: 2496
Twp Area: ELIZABETHTOWN
Dep Class: INDUSTRIAL
Zone: 18
Easting: 444327.79
Northing: 4938722.81
Effective Dt/time: 28-Nov-2013
Date Last Modified:
Geo Update Dt/time:

Class Sub Type: Discretionary Mineral Occurrence
Source Map: P2495
Detail: http://www.geologyontario.mndm.gov.on.ca/mndmfiles/mdi/data/records/MDI31B12SE00016.html
All Names: Section A-4 , Section S BR-4
Access Description: In a roadcut in the N end of Brockville, at Hwy 401 and 29/42 intersection.**Note: Many records provided by the department have a truncated [Access Description] field.
Status: DISCRETIONARY OCCURRENCE

Deposit Details

Deposit Year: 1991
Deposit Character: STRATIFORM
Commodity: SANDSTONE (SILICA), SILICA SAND
Ranking: 1
Twp/Area: ELIZABETHTOWN
Con/Lot/Sec: LOT: 13 Con: 7
Legal Desc:
Township Area Ranking: 1
Mndm Township Area No: 754
Effective Date/Time: 11/28/2013 3:46:15 PM

---

21 **1 of 3** **SW/12.5** **104.9 / 5.02** **SPL**

TRANSPORT TRUCK
HWY 401 JUST WEST OF HWY 29 MOTOR
VEHICLE (OPERATING FLUID)
BROCKVILLE CITY ON

Ref No: 66924
Site No:
Incident Dt: 2/11/1992
Year:
Incident Cause: OTHER CONTAINER LEAK
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: POSSIBLE
Nature of Impact: Soil Contamination
Receiving Medium: LAND
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 2/11/1992
Dt Document Closed:
Incident Reason: DAMAGE BY MOVING EQUIPMENT
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: TRANSPORT TRUCK - 800 L. OF DIESEL FUEL TO HIGHWAYFROM SADDLE TANKS
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 56101
Site Lot:
Site Conc:
Northing:
Easting: OPP MTO
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

21 **2 of 3** **SW/12.5** **104.9 / 5.02** **SPL**

PUROLATOR COURIER LTD.
HWY #401 WESTBOUND, STEWART BLVD
NORTH, PARKEDALE AVE EAST & NORTH
AUGUSTA RD. MOTOR VEHICLE (OPERATING
FLUID)
BROCKVILLE CITY ON

Ref No: 84041
Site No:
Incident Dt: 4/13/1993

Discharger Report:
Material Group:
Health/Env Conseq:

Year:
Incident Cause: PIPE/HOSE LEAK
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: CONFIRMED
Nature of Impact: Soil contamination
Receiving Medium: LAND
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 4/13/1993
Dt Document Closed:
Incident Reason: ADVERSE ROAD CONDITION
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: PUROLATOR COURIER- 180L DIESEL FROM TRUCK TO HWY #401 & ROAD ALONG 4KM.
Contaminant Qty:

Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 56101
Site Lot:
Site Conc:
Northing:
Easting: FD, POLICE, WORKS
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

21 **3 of 3** **SW/12.5** **104.9 / 5.02** **SPL**

HYDRO ONE
HWY 29 & 401 OVERPASS TRANSFORMER
BROCKVILLE CITY ON

Ref No: 215154
Site No:
Incident Dt: 10/31/2001
Year:
Incident Cause: OTHER TRANSPORTATION ACCIDENT
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Possible
Nature of Impact: Soil contamination
Receiving Medium: Land, Water
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/31/2001
Dt Document Closed:
Incident Reason: UNKNOWN
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: HWY 29 & 401 BROCKVILLE TRANSFORMER FELL OFF TRANSPORT 80 L TO GROUND
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved: BROCKVILLE PUBLIC WORKS
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 56101
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

22 **1 of 5** **WSW/249.9** **104.9 / 5.02** **SPL**

329 Stewart Blvd.
Brockville ON K6V 4W8

Ref No: 0758-85DRGC
Site No:
Incident Dt:
Year:
Incident Cause: Unknown
Incident Event:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Unknown
Agency Involved:

Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Not Anticipated
Nature of Impact:
Receiving Medium:
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/12/2010
Dt Document Closed:
Incident Reason: Unknown - Reason not determined
Site Name: in catch basin in front of residence <UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Source unknown - <1/2 L of diesel to catch basin.
Contaminant Qty: 0.5 L
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality:
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Watercourse Spills
Source Type:

---

22 **2 of 5** **WSW/249.9** **104.9 / 5.02** **329 Stewart Boulevard Brockville ON K6V 4W8** **EHS**

Order No: 20120712022
Status: C
Report Type: Custom Report
Report Date: 19-JUL-12
Date Received: 12-JUL-12
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.704276
Y: 44.600985

---

22 **3 of 5** **WSW/249.9** **104.9 / 5.02** **Canadian Tire Corporation, limited 329 Stewart St. Brockville ON K6V 4W8** **GEN**

Generator No: ON9242678
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 415290
SIC Description: OTHER NEW MOTOR VEHICLE PARTS AND ACCESSORIES WHOLESALER-DISTRIBUTORS
PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Danny Morin
Phone No Admin: 613-342-5261 Ext.

Detail(s)

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

---

22 **4 of 5** **WSW/249.9** **104.9 / 5.02** **Canadian Tire Corporation, limited 329 Stewart St. Brockville ON K6V 4W8** **GEN**

Generator No: ON9242678
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

SIC Code:
SIC Description:

Detail(s)

Waste Class: 263 I
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

---

22 **5 of 5** **WSW/249.9** **104.9 / 5.02** **Canadian Tire Corporation, limited 329 Stewart St. Brockville ON K6V 4W8** **GEN**

Generator No: ON9242678
Status: Registered
Approval Years: As of Apr 2020
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 267 C
Waste Class Desc: Organic acids

Waste Class: 122 C
Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 232 I
Waste Class Desc: Polymeric resins

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 263 I
Waste Class Desc: Misc. waste organic chemicals

---

23 **1 of 1** **E/148.2** **95.7 / -4.16** **121 BROOKVIEW CRESCENT BROCKVILLE ON K6V 4P4** **HINC**

External File Num: FS INC 0904-02206
Fuel Occurrence Type: CO Release
Date of Occurrence: 4/29/2009
Fuel Type Involved: Natural Gas
Status Desc: Completed - Causal Analysis(End)
Job Type Desc: Incident/Near-Miss Occurrence (FS)
Oper. Type Involved: Private Dwelling
Service Interruptions: No
Property Damage: No
Fuel Life Cycle Stage: Utilization
Root Cause: Root Cause: Equipment/Material/Component:Yes Procedures:Yes Maintenance:Yes Design:No Training: Yes Management:No Human Factors:Yes
Reported Details:
Fuel Category: Gaseous Fuel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Occurrence Type: Incident
Affiliation: Emergency Services (Fire, Police,etc)
County Name: Leeds and Grenville
Approx. Quant. Rel:
Nearby body of water:
Enter Drainage Syst.:
Approx. Quant. Unit:
Environmental Impact:

---

24 **1 of 11** **WSW/207.7** **104.9 / 5.02** **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
325 STEWART BLVD
BROCKVILLE ON K6V 4W8 **FST**

Instance No: 56537576
Cont Name:
Instance Type: FS Liquid Fuel Tank
Fuel Type: Gasoline
Status: Active
Capacity: 50000
Tank Material: Fiberglass (FRP)
Corrosion Protection: Fiberglass
Tank Type: Double Wall UST
Install Year: 2008
Parent Facility Type: FS Gasoline Station - Self Serve
Facility Type: FS Liquid Fuel Tank

---

24 **2 of 11** **WSW/207.7** **104.9 / 5.02** **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
325 STEWART BLVD
BROCKVILLE ON K6V 4W8 **FST**

Instance No: 56537574
Cont Name:
Instance Type: FS Liquid Fuel Tank
Fuel Type: Diesel
Status: Active
Capacity: 25000
Tank Material: Fiberglass (FRP)
Corrosion Protection: Fiberglass
Tank Type: Single Wall UST
Install Year: 2008
Parent Facility Type: FS Gasoline Station - Self Serve
Facility Type: FS Liquid Fuel Tank

---

24 **3 of 11** **WSW/207.7** **104.9 / 5.02** **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
325 STEWART BLVD
BROCKVILLE ON K6V 4W8 **FST**

Instance No: 56537573
Cont Name:
Instance Type: FS Liquid Fuel Tank
Fuel Type: Diesel
Status: Active
Capacity: 25000
Tank Material: Fiberglass (FRP)
Corrosion Protection: Fiberglass
Tank Type: Double Wall UST
Install Year: 2008
Parent Facility Type: FS Gasoline Station - Self Serve
Facility Type: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

24 **4 of 11** **WSW/207.7** **104.9 / 5.02** **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
325 STEWART BLVD
BROCKVILLE ON K6V 4W8 **FST**

Instance No: 56537572
Cont Name:
Instance Type: FS Liquid Fuel Tank
Fuel Type: Gasoline
Status: Active
Capacity: 50000
Tank Material: Fiberglass (FRP)
Corrosion Protection: Fiberglass
Tank Type: Double Wall UST
Install Year: 2008
Parent Facility Type: FS Gasoline Station - Self Serve
Facility Type: FS Liquid Fuel Tank

---

24 **5 of 11** **WSW/207.7** **104.9 / 5.02** **SUNCOR ENERGY PRODUCTS PARTNERSHIP**
325 STEWART BLVD
BROCKVILLE ON K6V 4W8 **FST**

Instance No: 56537575
Cont Name:
Instance Type: FS Liquid Fuel Tank
Fuel Type: Gasoline
Status: Active
Capacity: 50000
Tank Material: Fiberglass (FRP)
Corrosion Protection: Fiberglass
Tank Type: Double Wall UST
Install Year: 2008
Parent Facility Type: FS Gasoline Station - Self Serve
Facility Type: FS Liquid Fuel Tank

---

24 **6 of 11** **WSW/207.7** **104.9 / 5.02** **PETROCAN CARWASH**
325 STEWART BLVD
BROCKVILLE ON K6V4W8 **RST**

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL GAS
Phone: 6133420841
List Name: INFO-DIRECT(TM) BUSINESS FILE
Description:

---

24 **7 of 11** **WSW/207.7** **104.9 / 5.02** **1195149 Ontario Ltd**
325 Stewart Blvd.
Brockville ON **GEN**

Generator No: ON6366705
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 447190
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Desc:		OIL SKIMMINGS & SLUDGES			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	8 of 11	WSW/207.7	104.9 / 5.02	1195149 Ontario Ltd 325 Stewart Blvd. Brockville ON K6V4W8	GEN

Generator No: ON6366705
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 447190
SIC Description: 447190

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 150
Waste Class Desc: INERT INORGANIC WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	9 of 11	WSW/207.7	104.9 / 5.02	1195149 Ontario Ltd 325 Stewart Blvd. Brockville ON K6V4W8	GEN

Generator No: ON6366705
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 447190
SIC Description: 447190

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 150
Waste Class Desc: INERT INORGANIC WASTES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	10 of 11	WSW/207.7	104.9 / 5.02	1195149 Ontario Ltd 325 Stewart Blvd. Brockville ON K6V4W8	GEN

Generator No: ON6366705
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 447190
SIC Description: 447190

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	11 of 11	WSW/207.7	104.9 / 5.02	1195149 Ontario Ltd 325 Stewart Blvd. Brockville ON K6V4W8	GEN

Generator No: ON6366705
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 150 L
Waste Class Desc: Inert organic wastes

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
25	1 of 2	SW/55.9	104.9 / 5.02	TRANSPORT TRUCK ON RAMP TO HWY 401 WESTBOUND AT HWY 401 AND HWY 29. MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON	SPL

Ref No: 113311
Site No:
Incident Dt: 5/18/1995
Year:
Incident Cause: OTHER TRANSPORTATION ACCIDENT
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: POSSIBLE
Nature of Impact: Soil contamination
Receiving Medium: LAND
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/18/1995
Dt Document Closed:
Incident Reason: ERROR
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: ARMBRO TRANSPORT-60 L OF DIESEL FUEL TO GROUND FROM TRUCK OVERTURN.
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 56101
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
25	2 of 2	SW/55.9	104.9 / 5.02	TRANSPORT TRUCK 401 1.5 MILES WEST OF HWY. 29 MOTOR VEHICLE (OPERATING FLUID) ELIZABETHTOWN TWP. ON	SPL

Ref No: 50485
Site No:
Incident Dt: 5/13/1991
Year:
Incident Cause: OTHER TRANSPORTATION ACCIDENT
Incident Event:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:

Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: POSSIBLE
Nature of Impact: Soil contamination
Receiving Medium: LAND
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/13/1991
Dt Document Closed:
Incident Reason: EQUIPMENT FAILURE
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: UNITED DRIVERS SERVICES - 430 L OF DIESEL FUEL TOHWY. FROM TRANSPORT.
Contaminant Qty:

Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 56606
Site Lot:
Site Conc:
Northing:
Easting: OPP, ELIZABETHTOWN TWP. FIRE DEPT.
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

26 **1 of 2** **WSW/224.0** **104.9 / 5.02** **WWIS**

Leeds and Grenville ON

Well ID: 7104241
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z76806
Tag: A060447
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 4/29/2008
Selected Flag: Yes
Abandonment Rec:
Contractor: 7085
Form Version: 4
Owner:
Street Name: 325 STEWART BLVD.
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/710\7104241.pdf

Bore Hole Information

Bore Hole ID: 1001579000
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 3/17/2008
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 106.064041
Elevrc:
Zone: 18
East83: 444184
North83: 4938843
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1001608152
Layer: 2
Color: 6
General Color: BROWN
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 1.21
Formation End Depth: 4.81
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1001608151
Layer: 1
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 28
Mat2 Desc: SAND
Mat3: 02
Mat3 Desc: TOPSOIL
Formation Top Depth: 0
Formation End Depth: 1.21
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1001608154
Layer: 1
Plug From: 0
Plug To: 1.52
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1001608155
Layer: 2
Plug From: 1.52
Plug To: 4.81
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1001608160
Method Construction Code: 7
Method Construction: Diamond
Other Method Construction: BORING

Pipe Information

Pipe ID: 1001608149
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1001608157
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 1.76
Casing Diameter: .0508
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1001608158
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM:
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1001608150
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code: 0
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing: No

Water Details

Water ID: 1001608156
Layer: 1
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1001608153

Diameter: 15.24
Depth From:
Depth To: 4.81
Hole Depth UOM: m
Hole Diameter UOM: cm

26 ***2 of 2*** ***WSW/224.0*** ***104.9 / 5.02*** ***WWIS***

Brockville ON

Well ID: 7106557
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: M00594
Tag: A060447
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 6/18/2008
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 6964
Form Version: 5
Owner:
Street Name: 325 STEWARD BLVD.
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/710\7106557.pdf

Bore Hole Information

Bore Hole ID: 1001616044
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 5/28/2008
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 106.064041
Elevrc:
Zone: 18
East83: 444184
North83: 4938843
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1002709095
Layer: 2
Color: 6
General Color: BROWN
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:

Formation Top Depth: 1.21
Formation End Depth: 4.81
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1002709094
Layer: 1
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 02
Mat2 Desc: TOPSOIL
Mat3: 81
Mat3 Desc: SANDY
Formation Top Depth: 0
Formation End Depth: 1.21
Formation End Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1002709096
Method Construction Code:
Method Construction:
Other Method Construction:

---

27 | 1 of 1 | WSW/179.7 | 104.9 / 5.02 | lot 12 con 1 ON | WWIS

Well ID: 3600642
Construction Date:
Primary Water Use: Commerical
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 4/14/1955
Selected Flag: Yes
Abandonment Rec:
Contractor: 3705
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY (ELIZABETHTOWN)
Site Info:
Lot: 012
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600642.pdf

Bore Hole Information

Bore Hole ID: 10214601
DP2BR: 7
Spatial Status:
Code OB: r
Code OB Desc: Bedrock

Elevation: 106.983482
Elevrc:
Zone: 18
East83: 444202.7
North83: 4938799

Open Hole:
Cluster Kind:
Date Completed: 12/23/1954
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676246
Layer: 1
Color:
General Color:
Mat1: 01
Most Common Material: FILL
Mat2: 02
Mat2 Desc: TOPSOIL
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 7
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676247
Layer: 2
Color:
General Color:
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 7
Formation End Depth: 56
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600642
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763171
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Casing ID: 930363002
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 20
Casing Diameter: 5
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600642
Pump Set At:
Static Level: 20
Final Level After Pumping: 30
Recommended Pump Depth:
Pumping Rate: 8
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676551
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 45
Water Found Depth UOM: ft

---

28 | 1 of 1 | NE/199.1 | 98.8 / -1.01 | ON | AST

OGF ID: 250552162
Sub Type: Petroleum Tank
Sub Type No: 1332
Location Accuracy: Within 10 metres
Sensitivity Class: Non-Sensitive
Sensitivity Date: 20070106
Sensitivity Rationale: No Restriction Needed
Verification Flag: Verified
Verification Date: 19971023
Business Effective Dt Flag: Estimated
Business Effective Dt: 19971023
Sys Calcu Area: 8.478
Sys Calcu Length: 0.0
User Calc Metric: 0.0
Effective Date/Time: 19971023

---

29 | 1 of 18 | ESE/237.7 | 94.8 / -5.09 | St. Mary's School, 40 Central Avenue LOT 6, REG. PLAN 238 BROCKVILLE ON K6V 4N5 | OPCB

Year: 2000

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Number: 40189A052
Name Owner:
Additional Site Information:

---

29 | 2 of 18 | ESE/237.7 | 94.8 / -5.09 | St. Mary's School, 40 Central Avenue LOT 6, REG. PLAN 238 BROCKVILLE ON K6V 4N5 | OPCB

Year: 2003
Site Number: 40189A052
Name Owner:
Additional Site Information:

---

29 | 3 of 18 | ESE/237.7 | 94.8 / -5.09 | St. Mary's School, 40 Central Avenue LOT 6, REG. PLAN 238 BROCKVILLE ON K6V 4N5 | OPCB

Year: 1999
Site Number: 40189A052
Name Owner:
Additional Site Information:

--Details--
Quantity: 136.00
Address Site:
Description: Weight of Bulk Liquid with High Level PCBs (>1000 ppm) kg

Quantity: 136.00
Address Site:
Description: Weight of Liquid in Transformer with High Level PCBs (>1000 ppm) kg

Quantity: 1.00
Address Site:
Description: Number of Transformers with High Level PCBs (>1000 ppm)

Quantity: 2.00
Address Site:
Description: Number of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 400.00
Address Site:
Description: Calculated Weight (Kg) of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 1.00
Address Site:
Description: Number of Drums of Other Material with High Level PCBs (>1000 ppm)

Quantity: 150.00
Address Site:
Description: Calculated Weight (Kg) of Drums of Other Material with High Level PCBs (>1000 ppm) kg

---

29 | 4 of 18 | ESE/237.7 | 94.8 / -5.09 | CATHOLIC DISTRICT SBE ONTARIO ST. MARY CATHOLIC HIGH SCHOOL 40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5 | GEN

Generator No: ON2595701
Status:
Approval Years: 01
Contam. Facility:
PO Box No:
Country:
Choice of Contact:
Co Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility: **Phone No Admin:**
SIC Code: 8511
SIC Description: ELEMT./SECON. EDUC.

Detail(s)

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

---

29 **5 of 18** **ESE/237.7** **94.8 / -5.09** **CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO 40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5** **GEN**

Generator No: ON2595701
Status:
Approval Years: 02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 611110
SIC Description: Elementary & Secondary Schools

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

---

29 **6 of 18** **ESE/237.7** **94.8 / -5.09** **St. Mary's School, 40 Central Avenue LOT 6, REG. PLAN 238 BROCKVILLE ON K6V 4N5** **OPCB**

Year: 2004
Site Number: 40189A052
Name Owner:
Additional Site Information:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

---

29 **7 of 18** **ESE/237.7** **94.8 / -5.09** **ST. MARY CATHOLIC HIGH SCHOOL 40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5** **NPCB**

Company Code: O005032
Industry: SCHOOL/CARE/FACILITY
Site Status: NO MORE PCB'S ON THIS SITE
Transaction Date:
Inspection Date:

---

29 **8 of 18** **ESE/237.7** **94.8 / -5.09** **ST. MARY'S SCHOOL LOT 6, REG. PLAN 238 40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5** **NPCB**

Company Code: F1283
Industry: UNDEFINED
Site Status:
Transaction Date:
Inspection Date:

---

29 **9 of 18** **ESE/237.7** **94.8 / -5.09** **CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO 40 CENTRAL AVENUE BROCKVILLE ON** **GEN**

Generator No: ON2595701
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 611110
SIC Description: Elementary and Secondary Schools

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 331

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Desc: WASTE COMPRESSED GASES

---

29 **10 of 18** **ESE/237.7** **94.8 / -5.09** **CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO**
40 CENTRAL AVENUE
BROCKVILLE ON **GEN**

Generator No: ON2595701
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 611110
SIC Description: Elementary and Secondary Schools

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

29 **11 of 18** **ESE/237.7** **94.8 / -5.09** **CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO**
40 CENTRAL AVENUE
BROCKVILLE ON **GEN**

Generator No: ON2595701
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 611110
SIC Description: Elementary and Secondary Schools

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 252

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

---

29 **12 of 18** **ESE/237.7** **94.8 / -5.09** **CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO**
40 CENTRAL AVENUE
BROCKVILLE ON K6V 4N5 **GEN**

Generator No: ON2595701
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 611110
SIC Description: Elementary and Secondary Schools

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
29	13 of 18	ESE/237.7	94.8 / -5.09	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO 40 CENTRAL AVENUE BROCKVILLE ON	GEN

Generator No: ON2595701
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 611110
SIC Description: ELEMENTARY AND SECONDARY SCHOOLS

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
29	14 of 18	ESE/237.7	94.8 / -5.09	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO 40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	GEN

Generator No: ON2595701
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 611110
SIC Description: ELEMENTARY AND SECONDARY SCHOOLS

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
29	15 of 18	ESE/237.7	94.8 / -5.09	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO 40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	GEN

Generator No: ON2595701
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 611110
SIC Description: ELEMENTARY AND SECONDARY SCHOOLS

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
29	16 of 18	ESE/237.7	94.8 / -5.09	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO 40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	GEN

Generator No: ON2595701
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 611110
SIC Description: ELEMENTARY AND SECONDARY SCHOOLS

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
29	17 of 18	ESE/237.7	94.8 / -5.09	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO 40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	GEN

Generator No: ON2595701
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 148 A
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 148 C
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 148 I
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 213 I
Waste Class Desc: Petroleum distillates

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 263 A
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
29	18 of 18	ESE/237.7	94.8 / -5.09	CATHOLIC DISTRICT SCHOOL BOARD OF EASTERN ONTARIO 40 CENTRAL AVENUE BROCKVILLE ON K6V 4N5	GEN

Generator No: ON2595701
Status: Registered
Approval Years: As of Apr 2020
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 148 A
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 148 C
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 148 I
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 213 I
Waste Class Desc: Petroleum distillates

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 263 A
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
30	1 of 1	NE/203.7	98.8 / -1.01	ON	AST

OGF ID: 250552161
Sub Type: Petroleum Tank

Sub Type No: 1332
Location Accuracy: Within 10 metres
Sensitivity Class: Non-Sensitive
Sensitivity Date: 20070106
Sensitivity Rationale: No Restriction Needed
Verification Flag: Verified
Verification Date: 19971023
Business Effective Dt Flag: Estimated
Business Effective Dt: 19971023
Sys Calcu Area: 6.482
Sys Calcu Length: 0.0
User Calc Metric: 0.0
Effective Date/Time: 19971023

---

31 **1 of 1** **S/131.8** **104.9 / 5.08** **BROCKVILLE ON** **WWIS**

Well ID: 7264500
Construction Date:
Primary Water Use: Test Hole
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z227782
Tag: A193429
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 6/9/2016
Selected Flag: Yes
Abandonment Rec:
Contractor: 7085
Form Version: 7
Owner:
Street Name: 160 STEWART BLVD
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/726\7264500.pdf

Bore Hole Information

Bore Hole ID: 1006042428
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 4/19/2016
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 104.664955
Elevrc:
Zone: 18
East83: 444463
North83: 4938619
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006095489

Layer: 2
Color: 2
General Color: GREY
Mat1: 21
Most Common Material: GRANITE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: .91
Formation End Depth: 4.27
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1006095488
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3: 01
Mat3 Desc: FILL
Formation Top Depth: 0
Formation End Depth: .91
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006095501
Layer: 3
Plug From: 1.52
Plug To: 4.27
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006095499
Layer: 1
Plug From: 0
Plug To: 0.31
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006095500
Layer: 2
Plug From: 0.31
Plug To: 1.52
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1006095498
Method Construction Code: 2

Method Construction: Rotary (Convent.)
Other Method Construction: BORING

Pipe Information

Pipe ID: 1006095486
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006095495
Layer: 2
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 1.83
Casing Diameter: 5.08
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Casing

Casing ID: 1006095494
Layer: 1
Material: 7
Open Hole or Material: OTHER
Depth From: 0
Depth To: .31
Casing Diameter: 17.78
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1006095496
Layer: 1
Slot: .10
Screen Top Depth: 1.83
Screen End Depth: 4.27
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.03

Results of Well Yield Testing

Pump Test ID: 1006095487
Pump Set At:
Static Level: 1.89
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code: 0
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:

Pumping Duration MIN:
Flowing: No

Water Details

Water ID: 1006095493
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 2.74
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1006095490
Diameter: 25.4
Depth From: 0
Depth To: 0.31
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1006095491
Diameter: 21.59
Depth From: 0.31
Depth To: 0.91
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1006095492
Diameter: 10.16
Depth From: 0.91
Depth To: 4.27
Hole Depth UOM: m
Hole Diameter UOM: cm

32 | **1 of 1** | **SSE/184.3** | **101.9 / 2.02** | **lot 12 con 1 ON** | **WWIS**

Well ID: 3600643
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 3/5/1956
Selected Flag: Yes
Abandonment Rec:
Contractor: 3705
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY (ELIZABETHTOWN)
Site Info:
Lot: 012
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600643.pdf

Bore Hole Information

Bore Hole ID:	10214602	**Elevation:**	102.606681
DP2BR:	5	**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:	r	**East83:**	444539.8
Code OB Desc:	Bedrock	**North83:**	4938622
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	9
Date Completed:	9/25/1955	**UTMRC Desc:**	unknown UTM
Remarks:		**Location Method:**	p9
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	931676248
Layer:	1
Color:	
General Color:	
Mat1:	02
Most Common Material:	TOPSOIL
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0
Formation End Depth:	5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931676249
Layer:	2
Color:	
General Color:	
Mat1:	18
Most Common Material:	SANDSTONE
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	5
Formation End Depth:	57
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	963600643
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10763172
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930363003
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	8
Casing Diameter:	6
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930363004
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	57
Casing Diameter:	6
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pump Test ID:	993600643
Pump Set At:	
Static Level:	18
Final Level After Pumping:	28
Recommended Pump Depth:	
Pumping Rate:	5
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933676552
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	55
Water Found Depth UOM:	ft

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	1 of 1	S/144.6	104.5 / 4.60	Brockville ON	WWIS

Well ID: 7215265
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z171265
Tag: A153931
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

PDF URL (Map):

Data Entry Status:
Data Src:
Date Received: 1/22/2014
Selected Flag: Yes
Abandonment Rec:
Contractor: 1844
Form Version: 7
Owner:
Street Name: 154 STEWART BOULEVARD
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004695291
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11/8/2013
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 104.492912
Elevrc:
Zone: 18
East83: 444479
North83: 4938617
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1005043411
Layer: 1
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: .05
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005043412
Layer: 2
Color:
General Color:
Mat1: 11
Most Common Material: GRAVEL
Mat2: 01
Mat2 Desc: FILL
Mat3: 81
Mat3 Desc: SANDY
Formation Top Depth: .05
Formation End Depth: .5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005043413
Layer: 3
Color:
General Color:
Mat1: 28
Most Common Material: SAND
Mat2:
Mat2 Desc:
Mat3: 84
Mat3 Desc: SILTY
Formation Top Depth: .5
Formation End Depth: 1.1
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1005043414
Layer: 4
Color:
General Color:
Mat1: 26
Most Common Material: ROCK
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 1.1
Formation End Depth: 4.9
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1005043422
Layer: 1
Plug From: 0.2
Plug To: 1.6
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1005043421

Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 1005043410
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005043418
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 1.9
Casing Diameter: 5.08
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1005043419
Layer: 1
Slot: 10
Screen Top Depth: 1.9
Screen End Depth: 4.9
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 5.86

Water Details

Water ID: 1005043417
Layer: 1
Kind Code:
Kind:
Water Found Depth: 2
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1005043415
Diameter: 30
Depth From: 0
Depth To: 1.1
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1005043416
Diameter: 10.16
Depth From: 1.1
Depth To: 4.9
Hole Depth UOM: m
Hole Diameter UOM: cm

34 **1 of 1** **S/134.0** **104.9 / 5.08** **BROCKVILLE ON** **WWIS**

Well ID: 7264499
Construction Date:
Primary Water Use: Test Hole
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z227783
Tag: A193430
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 6/9/2016
Selected Flag: Yes
Abandonment Rec:
Contractor: 7085
Form Version: 7
Owner:
Street Name: 160 STEWART BLVD.
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/726\7264499.pdf

Bore Hole Information

Bore Hole ID: 1006042425
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 4/19/2016
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 104.584701
Elevrc:
Zone: 18
East83: 444464
North83: 4938617
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006095448
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3: 01
Mat3 Desc: FILL
Formation Top Depth: 0
Formation End Depth: .76
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1006095449
Layer: 2
Color: 2
General Color: GREY
Mat1: 21
Most Common Material: GRANITE
Mat2:
Mat2 Desc:
Mat3: 73
Mat3 Desc: HARD
Formation Top Depth: .76
Formation End Depth: 3.35
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006095459
Layer: 1
Plug From: 0
Plug To: 0.31
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006095461
Layer: 3
Plug From: 1.52
Plug To: 3.35
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006095460
Layer: 2
Plug From: 0.31
Plug To: 1.52
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1006095458
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction: BORING

Pipe Information

Pipe ID: 1006095446
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006095455
Layer: 2
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 1.83
Casing Diameter: 5.08
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Casing

Casing ID: 1006095454
Layer: 1
Material: 7
Open Hole or Material: OTHER
Depth From: 0
Depth To: .31
Casing Diameter: 12.78
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1006095456
Layer: 1
Slot: .10
Screen Top Depth: 1.83
Screen End Depth: 3.35
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.03

Results of Well Yield Testing

Pump Test ID: 1006095447
Pump Set At:
Static Level: 1.89
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code: 0
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing: No

Water Details

Water ID: 1006095453
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 2.74
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1006095452
Diameter: 10.16
Depth From: 0.76
Depth To: 3.35
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1006095451
Diameter: 21.59
Depth From: 0.31
Depth To: 0.76
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1006095450
Diameter: 25.4
Depth From: 0
Depth To: 0.31
Hole Depth UOM: m
Hole Diameter UOM: cm

---

35 ***1 of 1*** ***SSE/216.3*** ***100.3 / 0.41*** ***Brockville ON*** ***WWIS***

Well ID:	7048684	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Monitoring	***Date Received:***	8/28/2007
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Observation Wells	***Abandonment Rec:***	
Water Type:		***Contractor:***	6809
Casing Material:		***Form Version:***	4
Audit No:	Z63317	***Owner:***	
Tag:	A057006	***Street Name:***	
Construction Method:		***County:***	36
Elevation (m):		***Municipality:***	BROCKVILLE CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/704\7048684.pdf

Bore Hole Information

Bore Hole ID:	23048684	***Elevation:***	101.005935
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	444580
Code OB Desc:		***North83:***	4938617
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3

Date Completed:	7/10/2007	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1000031079
Layer:	2
Color:	2
General Color:	GREY
Mat1:	15
Most Common Material:	LIMESTONE
Mat2:	26
Mat2 Desc:	ROCK
Mat3:	
Mat3 Desc:	
Formation Top Depth:	4
Formation End Depth:	40
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1000031078
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	12
Most Common Material:	STONES
Mat2:	28
Mat2 Desc:	SAND
Mat3:	01
Mat3 Desc:	FILL
Formation Top Depth:	0
Formation End Depth:	4
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1000031083
Layer:	3
Plug From:	33
Plug To:	40
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1000031081
Layer:	1
Plug From:	0
Plug To:	1
Plug Depth UOM:	ft

Annular Space/Abandonment

Sealing Record

Plug ID: 1000031082
Layer: 2
Plug From: 1
Plug To: 33
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1000031088
Method Construction Code: 7
Method Construction: Diamond
Other Method Construction:

Pipe Information

Pipe ID: 1000031076
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1000031085
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 35
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1000031086
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM:
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1000031077
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 0
Water State After Test:
Pumping Test Method: 0

Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1000031084
Layer: 1
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1000031080
Diameter: 4
Depth From:
Depth To: 40
Hole Depth UOM: ft
Hole Diameter UOM: inch

36 ***1 of 1*** ***S/188.6*** ***102.4 / 2.53*** ***BRAKVILLE ON*** ***WWIS***

Well ID: 3616923
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z50501
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 11/7/2006
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 1844
Form Version: 3
Owner:
Street Name: 146 & 154 STEWART BLVD
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/361\3616923.pdf

Bore Hole Information

Bore Hole ID: 11693397
DP2BR:
Spatial Status:
Code OB: _
Code OB Desc: No formation data
Open Hole:
Cluster Kind:
Date Completed: 9/14/2006
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:

Elevation: 103.267814
Elevrc:
Zone: 18
East83: 444530
North83: 4938606
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 933304336
Layer: 1
Plug From: 0
Plug To: 4.11
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 963616923
Method Construction Code: A
Method Construction: Digging
Other Method Construction:

Pipe Information

Pipe ID: 11698263
Casing No: 1
Comment:
Alt Name:

Hole Diameter

Hole ID: 11757201
Diameter: 20
Depth From: 0
Depth To: 4.11
Hole Depth UOM: m
Hole Diameter UOM: cm

---

37 | **1 of 1** | **S/162.0** | **104.0 / 4.17** | **154 Stewart Boulevard Brockville ON** | **EHS**

Order No: 20170824132
Status: C
Report Type: Standard Report
Report Date: 31-AUG-17
Date Received: 24-AUG-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.699468
Y: 44.598614

---

38 | **1 of 1** | **S/175.0** | **103.1 / 3.22** | **ON** | **WWIS**

Well ID: 7255814
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status:
Water Type:
Casing Material:
Audit No: C31845

Data Entry Status: Yes
Data Src:
Date Received: 1/14/2016
Selected Flag: Yes
Abandonment Rec:
Contractor: 7215
Form Version: 8
Owner:

Tag: A189581
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

PDF URL (Map):

Bore Hole Information

Bore Hole ID: 1005864344
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/28/2015
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Street Name:
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Elevation: 103.481842
Elevrc:
Zone: 18
East83: 444502
North83: 4938597
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

---

39 | **1 of 42** | **S/153.0** | **104.8 / 4.99** | **IMPERIAL OIL ESSO STATION 154 STEWART ST ESSO SERVICE STATION BROCKVILLE CITY ON K6V 4W6** | **SPL**

Ref No: 9319
Site No:
Incident Dt: 9/13/1988
Year:
Incident Cause: CONTAINER OVERFLOW
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact:
Receiving Medium: LAND
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/14/1988
Dt Document Closed:
Incident Reason: EQUIPMENT FAILURE
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: ESSO PETROLEUM - 5 L GASOLINE TO GRD AT SERVICE STATION.
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 56101
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	2 of 42	S/153.0	104.8 / 4.99	HILL TOP ESSO HUTT'S AUTO SERVICE LTD 154 STEWART BLVD BROCKVILLE ON K6V4W6	PRT

Location ID: 2267
Type: retail
Expiry Date: 1992-08-31
Capacity (L): 24967
Licence #: 0056145001

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	3 of 42	S/153.0	104.8 / 4.99	HILLTOP ESSO 154 STEWART BLVD BROCKVILLE ON K6V4W6	PRT

Location ID: 2267
Type: retail
Expiry Date: 1994-04-30
Capacity (L): 126800
Licence #: 0076383470

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	4 of 42	S/153.0	104.8 / 4.99	154 Stewart Blvd Brockville ON K6V 4W6	EHS

Order No: 20010425002
Status: C
Report Type: Basic Report
Report Date: 5/9/01
Date Received: 4/25/01
Previous Site Name: 75420
Lot/Building Size: 443540
Additional Info Ordered:

Nearest Intersection: of Hwy 10
Municipality:
Client Prov/State: ON
Search Radius (km): 0.35
X: -75.698929
Y: 44.598522

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	5 of 42	S/153.0	104.8 / 4.99	IMPERIAL OIL LIMITED 154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	GEN

Generator No: ON1586222
Status:
Approval Years: 99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 4219
SIC Description: OTHER SITE WORK

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	6 of 42	S/153.0	104.8 / 4.99	IMPERIAL OIL 154 STEWART BOULEVARD BROCKVILLE ON	GEN

Generator No: ON1586222
Status:
Approval Years: 03,04,05,06,07,08
Contam. Facility:

PO Box No:
Country:
Choice of Contact:
Co Admin:

MHSW Facility:
SIC Code:
SIC Description:

Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	7 of 42	S/153.0	104.8 / 4.99	HILL TOP ESSO HUTT'S AUTO SERVICE LTD 154 STEWART BLVD BROCKVILLE ON K6V 4W6	EXP

Instance No: 9829402
Instance ID:
Instance Type: FS Facility
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 9/1/1991

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	8 of 42	S/153.0	104.8 / 4.99	HILLTOP ESSO 154 STEWART BLVD BROCKVILLE ON K6V 4W6	EXP

Instance No: 9987569
Instance ID:
Instance Type: FS Facility
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 2/17/1993

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	9 of 42	S/153.0	104.8 / 4.99	HILL TOP ESSO HUTT'S AUTO SERVICE LTD 154 STEWART BLVD BROCKVILLE ON K6V 4W6	EXP

Instance No: 10619259
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 9/1/1991

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	10 of 42	S/153.0	104.8 / 4.99	HILLTOP ESSO 154 STEWART BLVD BROCKVILLE ON K6V 4W6	EXP

Instance No: 11133153

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Instance ID:					
Instance Type:		FS Liquid Fuel Tank			
Description:					
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:		10/3/1989			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	11 of 42	S/153.0	104.8 / 4.99	HILL TOP ESSO HUTT'S AUTO SERVICE LTD 154 STEWART BLVD BROCKVILLE ON K6V 4W6	EXP
Instance No:		10619139			
Instance ID:					
Instance Type:		FS Liquid Fuel Tank			
Description:					
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:		9/1/1991			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	12 of 42	S/153.0	104.8 / 4.99	HILLTOP ESSO 154 STEWART BLVD BROCKVILLE ON K6V 4W6	EXP
Instance No:		11133120			
Instance ID:					
Instance Type:		FS Liquid Fuel Tank			
Description:					
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:		10/3/1989			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	13 of 42	S/153.0	104.8 / 4.99	HILLTOP ESSO 154 STEWART BLVD BROCKVILLE ON K6V 4W6	EXP
Instance No:		11133134			
Instance ID:					
Instance Type:		FS Liquid Fuel Tank			
Description:					
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:		10/3/1989			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	14 of 42	S/153.0	104.8 / 4.99	HILL TOP ESSO HUTT'S AUTO SERVICE LTD 154 STEWART BLVD BROCKVILLE ON K6V 4W6	EXP
Instance No:		10619304			
Instance ID:					
Instance Type:		FS Liquid Fuel Tank			
Description:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:		9/1/1991			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	15 of 42	S/153.0	104.8 / 4.99	HILL TOP ESSO HUTT'S AUTO SERVICE LTD 154 STEWART BLVD BROCKVILLE ON K6V 4W6	EXP
Instance No:		10619190			
Instance ID:					
Instance Type:		FS Liquid Fuel Tank			
Description:					
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:		9/1/1991			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	16 of 42	S/153.0	104.8 / 4.99	HILL TOP ESSO HUTT'S AUTO SERVICE LTD 154 STEWART BLVD BROCKVILLE ON	EXP
Instance No:		10619235			
Instance ID:		31267			
Instance Type:		FS Liquid Fuel Tank			
Description:		FS Liquid Fuel Tank			
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	17 of 42	S/153.0	104.8 / 4.99	HILLTOP ESSO 154 STEWART BLVD BROCKVILLE ON K6V 4W6	EXP
Instance No:		11133143			
Instance ID:					
Instance Type:		FS Liquid Fuel Tank			
Description:					
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:					
Expired Date:		10/3/1989			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	18 of 42	S/153.0	104.8 / 4.99	HILL TOP ESSO HUTT'S AUTO SERVICE LTD 154 STEWART BLVD BROCKVILLE ON	EXP
Instance No:		10619245			
Instance ID:		30063			
Instance Type:		FS Piping			
Description:		FS Piping			
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Facility Type:
Expired Date:

---

39 **19 of 42** **S/153.0** **104.8 / 4.99** **HILL TOP ESSO HUTT'S AUTO SERVICE LTD** **EXP**
154 STEWART BLVD
BROCKVILLE ON

Instance No: 10619214
Instance ID: 29808
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

39 **20 of 42** **S/153.0** **104.8 / 4.99** **HILL TOP ESSO HUTT'S AUTO SERVICE LTD** **EXP**
154 STEWART BLVD
BROCKVILLE ON

Instance No: 10619166
Instance ID: 30818
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

39 **21 of 42** **S/153.0** **104.8 / 4.99** **HILL TOP ESSO HUTT'S AUTO SERVICE LTD** **EXP**
154 STEWART BLVD
BROCKVILLE ON

Instance No: 10619325
Instance ID: 31033
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

39 **22 of 42** **S/153.0** **104.8 / 4.99** **HILL TOP ESSO HUTT'S AUTO SERVICE LTD** **EXP**
154 STEWART BLVD
BROCKVILLE ON

Instance No: 10619283
Instance ID: 31382
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

39 **23 of 42** **S/153.0** **104.8 / 4.99** **IMPERIAL OIL** **GEN**
154 STEWART BOULEVARD
BROCKVILLE ON

Generator No: ON1586222
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 447190
SIC Description: Other Gasoline Stations

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

39 **24 of 42** **S/153.0** **104.8 / 4.99** **154 Stewart Blvd** **EHS**
Brockville ON

Order No: 20111115005
Status: C
Report Type: Standard Select Report
Report Date: 11/16/2011
Date Received: 11/15/2011 10:00:40 AM
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -75.699596
Y: 44.598556

---

39 **25 of 42** **S/153.0** **104.8 / 4.99** **IMPERIAL OIL** **GEN**
154 STEWART BOULEVARD
BROCKVILLE ON

Generator No: ON1586222
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 447190
SIC Description: Other Gasoline Stations

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

39 **26 of 42** **S/153.0** **104.8 / 4.99** **IMPERIAL OIL** **GEN**
154 STEWART BOULEVARD
BROCKVILLE ON

Generator No: ON1586222
Status:
Approval Years: 2011

PO Box No:
Country:
Choice of Contact:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contam. Facility:
MHSW Facility:
SIC Code: 447190
SIC Description: Other Gasoline Stations
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

---

39 **27 of 42** **S/153.0** **104.8 / 4.99** **GEN**

IMPERIAL OIL
154 STEWART BOULEVARD
BROCKVILLE ON K6V 4W6

Generator No: ON1586222
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 447190
SIC Description: Other Gasoline Stations
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

---

39 **28 of 42** **S/153.0** **104.8 / 4.99** **GEN**

IMPERIAL OIL
154 STEWART BOULEVARD
BROCKVILLE ON

Generator No: ON1586222
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 447190
SIC Description:
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

39 **29 of 42** **S/153.0** **104.8 / 4.99** **EXP**

HILL TOP ESSO HUTT'S AUTO SERVICE LTD
154 STEWART BLVD
BROCKVILLE ON K6V 4W6

Instance No: 10619259

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Gasoline Station - Full Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 9/1/1991

---

39 **30 of 42** **S/153.0** **104.8 / 4.99** **EXP**

HILL TOP ESSO HUTT'S AUTO SERVICE LTD
154 STEWART BLVD
BROCKVILLE ON K6V 4W6

Instance No: 10619139
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Gasoline Station - Full Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 9/1/1991

---

39 **31 of 42** **S/153.0** **104.8 / 4.99** **EXP**

HILL TOP ESSO HUTT'S AUTO SERVICE LTD
154 STEWART BLVD
BROCKVILLE ON K6V 4W6

Instance No: 10619304
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Gasoline Station - Full Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 9/1/1991

---

39 **32 of 42** **S/153.0** **104.8 / 4.99** **EXP**

HILL TOP ESSO HUTT'S AUTO SERVICE LTD
154 STEWART BLVD
BROCKVILLE ON K6V 4W6

Instance No: 10619190
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Gasoline Station - Full Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 9/1/1991

---

39 **33 of 42** **S/153.0** **104.8 / 4.99** **EXP**

HILL TOP ESSO HUTT'S AUTO SERVICE LTD
154 STEWART BLVD
BROCKVILLE ON K6V 4W6

Instance No: 10619235
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Gasoline Station - Full Serve

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:		FS Liquid Fuel Tank			
Expired Date:		9/1/1991			
39	34 of 42	S/153.0	104.8 / 4.99	HILLTOP ESSO 154 STEWART BLVD BROCKVILLE ON K6V 4W6	EXP
Instance No:		11133153			
Instance ID:					
Instance Type:		FS Liquid Fuel Tank			
Description:		FS Gasoline Station - Full Serve			
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:		FS Liquid Fuel Tank			
Expired Date:		10/3/1989			
39	35 of 42	S/153.0	104.8 / 4.99	HILLTOP ESSO 154 STEWART BLVD BROCKVILLE ON K6V 4W6	EXP
Instance No:		11133120			
Instance ID:					
Instance Type:		FS Liquid Fuel Tank			
Description:		FS Gasoline Station - Full Serve			
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:		FS Liquid Fuel Tank			
Expired Date:		10/3/1989			
39	36 of 42	S/153.0	104.8 / 4.99	HILLTOP ESSO 154 STEWART BLVD BROCKVILLE ON K6V 4W6	EXP
Instance No:		11133134			
Instance ID:					
Instance Type:		FS Liquid Fuel Tank			
Description:		FS Gasoline Station - Full Serve			
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					
Facility Type:		FS Liquid Fuel Tank			
Expired Date:		10/3/1989			
39	37 of 42	S/153.0	104.8 / 4.99	HILLTOP ESSO 154 STEWART BLVD BROCKVILLE ON K6V 4W6	EXP
Instance No:		11133143			
Instance ID:					
Instance Type:		FS Liquid Fuel Tank			
Description:		FS Gasoline Station - Full Serve			
Status:		EXPIRED			
TSSA Program Area:					
Maximum Hazard Rank:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Facility Type:		FS Liquid Fuel Tank			
Expired Date:		10/3/1989			
39	38 of 42	S/153.0	104.8 / 4.99	IMPERIAL OIL 154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	GEN
Generator No:	ON1586222			**PO Box No:**	
Status:				**Country:**	Canada
Approval Years:	2016			**Choice of Contact:**	CO_ADMIN
Contam. Facility:	Yes			**Co Admin:**	Laura MacIsaac
MHSW Facility:	No			**Phone No Admin:**	902-595-2001 Ext.
SIC Code:	447190				
SIC Description:		447190			
Detail(s)					
Waste Class:		221			
Waste Class Desc:		LIGHT FUELS			
Waste Class:		252			
Waste Class Desc:		WASTE OILS & LUBRICANTS			
Waste Class:		251			
Waste Class Desc:		OIL SKIMMINGS & SLUDGES			
39	39 of 42	S/153.0	104.8 / 4.99	IMPERIAL OIL 154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	GEN
Generator No:	ON1586222			**PO Box No:**	
Status:				**Country:**	Canada
Approval Years:	2015			**Choice of Contact:**	CO_ADMIN
Contam. Facility:	Yes			**Co Admin:**	Kelly Ali
MHSW Facility:	No			**Phone No Admin:**	905-747-7660 Ext.
SIC Code:	447190				
SIC Description:		447190			
Detail(s)					
Waste Class:		221			
Waste Class Desc:		LIGHT FUELS			
Waste Class:		252			
Waste Class Desc:		WASTE OILS & LUBRICANTS			
Waste Class:		251			
Waste Class Desc:		OIL SKIMMINGS & SLUDGES			
39	40 of 42	S/153.0	104.8 / 4.99	IMPERIAL OIL 154 STEWART BOULEVARD BROCKVILLE ON K6V 4W6	GEN
Generator No:	ON1586222			**PO Box No:**	
Status:				**Country:**	Canada
Approval Years:	2014			**Choice of Contact:**	CO_ADMIN
Contam. Facility:	Yes			**Co Admin:**	Eric Kelly
MHSW Facility:	No			**Phone No Admin:**	613-226-2456 Ext.333
SIC Code:	447190				
SIC Description:		447190			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

39 ***41 of 42*** ***S/153.0*** ***104.8 / 4.99*** ***IMPERIAL OIL***
154 STEWART BOULEVARD
BROCKVILLE ON K6V 4W6 ***GEN***

Generator No: ON1586222
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 221 I
Waste Class Desc: Light fuels

Waste Class: 221 L
Waste Class Desc: Light fuels

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

---

39 ***42 of 42*** ***S/153.0*** ***104.8 / 4.99*** ***IMPERIAL OIL***
154 STEWART BOULEVARD
BROCKVILLE ON K6V 4W6 ***GEN***

Generator No: ON1586222
Status: Registered
Approval Years: As of Apr 2020
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 221 I
Waste Class Desc: Light fuels

Waste Class: 221 L
Waste Class Desc: Light fuels

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

---

40 ***1 of 82*** ***NE/185.8*** ***98.9 / -0.97*** ***PARKE-DAVIS DIV. WARNER LAMB. OF CANADA***
2337 PARKEDALE AVENUE
BROCKVILLE CITY ON ***CA***

Certificate #: 8-4020-94-
Application Year: 94
Issue Date: 3/29/1994
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: REL. (2) & INST.(1) FUME HOOD VENTILATOR
Contaminants:
Emission Control:

---

40 ***2 of 82*** ***NE/185.8*** ***98.9 / -0.97*** ***PARKE DAVIS CANADA INC.***
LOT 11 CONC. 1
BROCKVILLE CITY ON ***CA***

Certificate #: 8-4054-87-
Application Year: 87
Issue Date: 7/7/1987
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: VENTILATION
Contaminants: Ethyl Alcohol,Denat,D
Emission Control: No Controls

---

40 ***3 of 82*** ***NE/185.8*** ***98.9 / -0.97*** ***PARKE-DAVIS CANADA, INC.***
LOT 11 CONC. 1
BROCKVILLE CITY ON ***CA***

Certificate #: 8-4118-87-
Application Year: 87
Issue Date: 9/8/1987
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: DUST COLLECTOR
Contaminants: Suspended Particulate Matter
Emission Control: Baghouse (Incl Vent Fil.), Absolute Filters,

---

40 ***4 of 82*** ***NE/185.8*** ***98.9 / -0.97*** ***WARNER-LAMBERT CANADA***
2337 PARKEDALE AVE.
BROCKVILLE CITY ON ***CA***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Certificate #: 8-4146-92-
Application Year: 92
Issue Date: 10/14/1992
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: INSTALL BOTTLE SPRAY SYSTEM
Contaminants: Ethylene Oxide
Emission Control: No Controls

---

40 **5 of 82** **NE/185.8** **98.9 / -0.97** **WARNER-LAMBERT CANADA INC.**
2337 PARKEDALE AVENUE
BROCKVILLE CITY ON **CA**

Certificate #: 8-4057-93-
Application Year: 93
Issue Date: 7/21/1993
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: (1) 400 H.P. THERMOCOIL STEAM BOILER
Contaminants: Nitrogen Oxides, Sulphur Dioxide, Carbon Monoxide, Suspended Particulate Matter
Emission Control: No Controls

---

40 **6 of 82** **NE/185.8** **98.9 / -0.97** **PARKE-DAVIS DIV. WARNER LAMB. OF CANADA**
2337 PARKEDALE AVENUE
BROCKVILLE CITY ON **CA**

Certificate #: 8-4082-93-
Application Year: 93
Issue Date: 9/16/1993
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: (1) ROTOCLONE WET SCRUBBER
Contaminants: Suspended Particulate Matter
Emission Control: Centri. And/Or Cycl. Scr.,

---

40 **7 of 82** **NE/185.8** **98.9 / -0.97** **PARKE-DAVIS, DIV. OF WARNER LAMBERT CANA**
2337 PARKEDALE AVENUE
BROCKVILLE ON **CA**

Certificate #: 8-4133-98-
Application Year: 98
Issue Date: 8/26/1998
Approval Type: Industrial air

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: EMERGENCY SPRINKLER SYS. WATER PUMP
Contaminants:
Emission Control:

---

40 **8 of 82** **NE/185.8** **98.9 / -0.97** **PARKE-DAVIS CANADA INC.**
BROCKVILLE PLANT 2337 PARKDALE AVENUE
BROCKVILLE CITY ON **SPL**

Ref No: 50488
Site No:
Incident Dt: 5/13/1991
Year:
Incident Cause: CONTAINER OVERFLOW
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: POSSIBLE
Nature of Impact: Soil contamination
Receiving Medium: LAND
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/13/1991
Dt Document Closed:
Incident Reason: OVERSTRESS/OVERPRESSURE
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: PARKE-DAVIS - 225 L OF DIESEL FUEL TO GROUND AND PARKING LOT.
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 56101
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

40 **9 of 82** **NE/185.8** **98.9 / -0.97** **WARNER-LAMBERT PARKE-DAVIS**
2337 PARKEDALE AVE W
BROCKVILLE ON K6V **SCT**

Established: 1956
Plant Size (ft²): 200000
Employment: 288

--Details--
Description: PHARMACEUTICAL PREPARATIONS
SIC/NAICS Code: 2834

Description: MEDICAL, DENTAL, AND HOSPITAL EQUIPMENT AND SUPPLIES
SIC/NAICS Code: 5047

Description: DRUGS, DRUG PROPRIETARIES, AND DRUGGISTS' SUNDRIES
SIC/NAICS Code: 5122

---

40 **10 of 82** **NE/185.8** **98.9 / -0.97** **PARKE-DAVIS DIV. WARNER LAMB. OF** **CA**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				CANADA 2337 PARKEDALE AVENUE BROCKVILLE CITY ON	

Certificate #:	8-4131-96-
Application Year:	96
Issue Date:	7/31/1996
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	VENT FOR WATER PURIF. SYS., 10 FUMEHOODS
Contaminants:	Suspended Particulate Matter, Ozone, Sodium Hydroxide, Chlorine, Sodium Bisulphite
Emission Control:	Centri. And/Or Cycl. Scr., Catalytic Incineration, No Controls,

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	11 of 82	NE/185.8	98.9 / -0.97	PARKE-DAVIS DIV. WARNER LAMB. OF CANADA 2337 PARKEDALE AVENUE BROCKVILLE CITY ON	CA

Certificate #:	8-4131-96-
Application Year:	96
Issue Date:	11/14/1996
Approval Type:	Industrial air
Status:	Revised
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	INCREASE AIRFLOW THRU' TYPE W ROTOCLONE
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	12 of 82	NE/185.8	98.9 / -0.97	PARKE-DAVIS DIV. WARNER LAMB. OF CANADA 2337 PARKEDALE AVENUE BROCKVILLE CITY ON	CA

Certificate #:	8-4147-97-
Application Year:	97
Issue Date:	3/6/1998
Approval Type:	Industrial air
Status:	
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	EXHAUST FROM MAINT. OF INK JET PRINTERS
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	13 of 82	NE/185.8	98.9 / -0.97	PARKE-DAVIS DIV. WARNER LAMB. OF CANADA 2337 PARKEDALE AVENUE BROCKVILLE CITY ON	CA

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Certificate #:	8-4203-96-
Application Year:	96
Issue Date:	11/18/1996
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	DUST COLL. FOR TABLET COMPRESSING PROC.
Contaminants:	Suspended Particulate Matter
Emission Control:	Baghouse (Incl Vent Fil.)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	14 of 82	NE/185.8	98.9 / -0.97	PARKE-DAVIS DIV. WARNER LAMB. OF CANADA 2337 PARKEDALE AVENUE BROCKVILLE CITY ON	CA

Certificate #:	8-4214-97-
Application Year:	97
Issue Date:	3/6/1998
Approval Type:	Industrial air
Status:	
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	VENT FOR MOLDING MACH.,INSTALL 2 BOILERS
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	15 of 82	NE/185.8	98.9 / -0.97	PARKE-DAVIS CANADA INC. 2337 PARKEDALE AVENUE BROCKVILLE PLANT 2337 PARKDALE AVENUE BROCKVILLE CITY ON	SPL

Ref No:	134198	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	10/11/1996	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	OTHER CONTAINER LEAK	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	POSSIBLE	Site Municipality:	56101
Nature of Impact:	Air Pollution	Site Lot:	
Receiving Medium:	AIR	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	11/7/1996	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	MATERIAL FAILURE	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	BACKENTRY: PARKE-DAVIS: 52 KG ANTIACID POWDER TO PLANT ROOF: CLEANED UP		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminant Qty:

---

40 **16 of 82** **NE/185.8** **98.9 / -0.97** **PARKE-DAVIS CANADA INC.**
BROCKVILLE PLANT 2337 PARKDALE AVENUE
BROCKVILLE CITY ON **SPL**

Ref No:	140722	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	5/13/1997	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	CONTAINER OVERFLOW	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	CONFIRMED	**Site Municipality:**	56101
Nature of Impact:	Soil contamination	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	5/13/1997	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	ERROR	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: PARKE-DAVIS - 500 L OF MINERAL OIL TO ASPHALT & GROUND DURING DELIVERY.
Contaminant Qty:

---

40 **17 of 82** **NE/185.8** **98.9 / -0.97** **TRILLIUM HEALTH CARE MANUFACTU**
LOCAL CREEK. 2337 PARKDALE AVE.
BROCKVILLE CITY ON **SPL**

Ref No:	176943	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	//	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	56101
Nature of Impact:	Water course or lake	**Site Lot:**	
Receiving Medium:	WATER	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	1/24/2000	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	ERROR	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: TRILLIUM HEALTH CARE-20 LMOUTH WASH TO SUMP PIT, STORM SEWER THEN CREEK.
Contaminant Qty:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

---

40 **18 of 82** **NE/185.8** **98.9 / -0.97** **WARNER-LAMBERT CANADA INC**
2337 PARKDALE AVENUE NOT AVAILABLE
BROCKVILLE ON K6V5W5 **NPRI**

NPRI ID:	3091	**Org ID:**	21575
Other ID:		**Submit Date:**	
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	8440	**Contact ID:**	
Report ID:		**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	1993	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	44781	**Contact Ph.:**	
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	
Fac Address1:	2337 PARKDALE AVENUE	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	K6V5W5	**Cont Fax Area Cde:**	
Facility Lat:	44.6051	**Contact Fax:**	
Facility Long:	-75.6966	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	44.6051
Facility DLS:		**Longitude:**	-75.6966
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:		**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3254		
NAICS 4 Description:	Pharmaceutical and medicine manufacturing		
NAICS Code (6 digit):	325410		
NAICS 6 Description:	Pharmaceutical and medicine manufacturing		

---

40 **19 of 82** **NE/185.8** **98.9 / -0.97** **WARNER-LAMBERT CANADA INC**
2337 PARKDALE AVENUE NOT AVAILABLE
BROCKVILLE ON K6V5W5 **NPRI**

NPRI ID:	3091	**Org ID:**	21575
Other ID:	FALSE	**Submit Date:**	
No Other ID:	0	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	8441	**Contact ID:**	
Report ID:		**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	1994	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	44781	**Contact Ph.:**	
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	
Fac Address1:	2337 PARKDALE AVENUE	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	K6V5W5	**Cont Fax Area Cde:**	
Facility Lat:	44.6051	**Contact Fax:**	

Facility Long:	-75.6966	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	44.6051
Facility DLS:		**Longitude:**	-75.6966
Datum:	1983	**UTM Zone:**	18
Facility Cmnts:	FALSE	**UTM Northing:**	4939800
URL:		**UTM Easting:**	445200
No of Empl.:	300	**Waste Streams:**	FALSE
Parent Co.:	TRUE	**No Streams:**	0
No Parent Co.:	2	**Waste Off Sites:**	FALSE
Pollut Prev Cmnts:		**No Off Sites:**	0
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3254		
NAICS 4 Description:	Pharmaceutical and medicine manufacturing		
NAICS Code (6 digit):	325410		
NAICS 6 Description:	Pharmaceutical and medicine manufacturing		

Substance Release Report

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	Hydrochloric acid
Chem (fr):	Chlorure d'hydrogène
Quantity:	0
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

40 | ***20 of 82*** | ***NE/185.8*** | ***98.9 / -0.97*** | ***WARNER-LAMBERT CANADA INC. 2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5*** | ***NPRI***

NPRI ID:	3091	**Org ID:**	21576
Other ID:	*	**Submit Date:**	9/26/2001
No Other ID:	0	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	8442	**Contact ID:**	
Report ID:		**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	1995	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	44781	**Contact Ph.:**	
Fac Name:	NOT AVAILABLE	**Cont Area Code:**	
Fac Address1:	2337 PARKDALE AVENUE	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	K6V5W5	**Cont Fax Area Cde:**	
Facility Lat:	44.6051	**Contact Fax:**	
Facility Long:	-75.6966	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	44.6051
Facility DLS:		**Longitude:**	-75.6966
Datum:	1983	**UTM Zone:**	18
Facility Cmnts:	FALSE	**UTM Northing:**	4939800
URL:		**UTM Easting:**	445200
No of Empl.:	300	**Waste Streams:**	FALSE

Parent Co.:	Y	**No Streams:**	0
No Parent Co.:	2	**Waste Off Sites:**	FALSE
Pollut Prev Cmnts:	FALSE	**No Off Sites:**	0
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3254		
NAICS 4 Description:	Pharmaceutical and medicine manufacturing		
NAICS Code (6 digit):	325410		
NAICS 6 Description:	Pharmaceutical and medicine manufacturing		

40 | ***21 of 82*** | ***NE/185.8*** | ***98.9 / -0.97*** | ***TRILLIUM HEALTH CARE MANUFACTURING 2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5*** | ***NPRI***

NPRI ID:	3091	**Org ID:**	20891
Other ID:	*	**Submit Date:**	9/13/2001
No Other ID:	0.00	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	8444	**Contact ID:**	
Report ID:		**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2000	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	44783	**Contact Ph.:**	
Fac Name:	TRILLIUM HEALTH CARE	**Cont Area Code:**	
Fac Address1:	2337 PARKDALE AVENUE	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	K6V5W5	**Cont Fax Area Cde:**	
Facility Lat:	44.6051	**Contact Fax:**	
Facility Long:	-75.6966	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	44.6051
Facility DLS:		**Longitude:**	-75.6966
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	285	**Waste Streams:**	No
Parent Co.:	*	**No Streams:**	0
No Parent Co.:	1.00	**Waste Off Sites:**	No
Pollut Prev Cmnts:	False	**No Off Sites:**	0.00
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3254		
NAICS 4 Description:	Pharmaceutical and medicine manufacturing		
NAICS Code (6 digit):	325410		
NAICS 6 Description:	Pharmaceutical and medicine manufacturing		

40 | ***22 of 82*** | ***NE/185.8*** | ***98.9 / -0.97*** | ***Trillium Health Care Manufacturing Inc. 2337 Parkdale Ave W Brockville ON*** | ***SCT***

Established:	1998

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Plant Size (ft²): 200000
Employment: 200

--Details--
Description: Toilet Preparation Manufacturing
SIC/NAICS Code: 325620

---

40 **23 of 82** **NE/185.8** **98.9 / -0.97** **WARNER-LAMBERT CANADA**
2337 PARKDALE AVE.
BROCKVILLE ON **CA**

Certificate #: 8-4006-85-006
Application Year: 85
Issue Date: 7/17/85
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants: Odour/Fumes, Hydrogen Chloride, Water Vapour, Ethyl Alcohol,Denat,D, Other Organic Compounds
Emission Control: No Controls

---

40 **24 of 82** **NE/185.8** **98.9 / -0.97** **2337 Parkedale Avenue**
Brockville ON **CA**

Certificate #: 7626-4U4QMW
Application Year: 01
Issue Date: 2/20/01
Approval Type: Industrial air
Status: Approved
Application Type: New Certificate of Approval
Client Name: Trillium Health Care Manufacturing Inc.
Client Address: 2337 Parkedale Avenue
Client City: Brockville
Client Postal Code: K6V 5W5
Project Description: This application is for an amendment to their current Air Certificate of Approval. the new process involves entails application of two coatings to tablets. The first is an enteric coating to prevent dissolution of the tablet in the stomach, followed by a clear coat for the protection of the enteric coating. Methylene chloride and methanol will be used as solvent transfer agents. This request is from a company that manufactures and packages liquid, ointment, and dry form consumer health care products and pharmaceuticals.
Contaminants:
Emission Control:

---

40 **25 of 82** **NE/185.8** **98.9 / -0.97** **2337 Parkedale Avenue**
Brockville ON **CA**

Certificate #: 8394-5BGRBW
Application Year: 02
Issue Date: 7/2/02
Approval Type: Industrial air
Status: Approved
Application Type: New Certificate of Approval
Client Name: Trillium Health Care Manufacturing Inc.
Client Address: 2337 Parkedale Avenue
Client City: Brockville
Client Postal Code: K6V 5W5
Project Description: This application is for an air Certificate of Approval. The company is seeking approval for a dust collector,

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

discharging to the atmosphere, to control dust emissions from a tablet-coating process. The company manufactures pharmaceutical products.

Contaminants:
Emission Control: Baghouse (Incl Vent Fil.)

---

40 **26 of 82** **NE/185.8** **98.9 / -0.97** **2337 Parkedale Avenue**
Brockville ON **CA**

Certificate #: 4120-5DHKCV
Application Year: 02
Issue Date: 9/6/02
Approval Type: Industrial air
Status: Approved
Application Type: New Certificate of Approval
Client Name: Trillium Health Care Products Inc.
Client Address: 2337 Parkedale Avenue
Client City: Brockville
Client Postal Code: K6V 5W5
Project Description: This application is to re-submit the emission source data and ensure the emission records for the four (4) Stokes ovens used during the drying stage of manufacturing consumer health care products and pharmaceuticals are up to date. These four (4) points of emission have been previously approved and continue to be used in the manufacture of the same types of products as per the original Certificate of Approval.
Contaminants:
Emission Control:

---

40 **27 of 82** **NE/185.8** **98.9 / -0.97** **Parke-Davis Div. Warner Lambert of Canada Inc.**
2337 Parkedale Avenue CITY OF BROCKVILLE
ON **EBR**

EBR Registry No: IA7E1850
Ministry Ref No: 8421497 19971212
Notice Type: Instrument Decision
Notice Stage: 800470145
Notice Date: March 09, 1998
Proposal Date: December 22, 1997
Year: 1997
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Parke-Davis Div. Warner Lambert of Canada Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 2337 Parkedale Avenue, Brockville Ontario, K6V 5W5
Comment Period:
URL:
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

2337 Parkedale Avenue CITY OF BROCKVILLE

---

40 **28 of 82** **NE/185.8** **98.9 / -0.97** **Parke-Davis Div. Warner Lambert of Canada Inc.**
2337 Parkedale Avenue CITY OF BROCKVILLE
ON **EBR**

EBR Registry No: IA7E1435
Ministry Ref No: 8414797 19970826
Notice Type: Instrument Decision
Notice Stage: 800470467
Notice Date: October 23, 1997
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Proposal Date: September 17, 1997 **Site Location Map:**
Year: 1997
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Parke-Davis Div. Warner Lambert of Canada Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 2337 Parkedale Avenue, Brockville Ontario, K6V 5W5
Comment Period:
URL:

Site Location Details:

2337 Parkedale Avenue CITY OF BROCKVILLE

---

40 **29 of 82** **NE/185.8** **98.9 / -0.97** ***Parke-Davis Div. Warner Lambert of Canada Inc. 2337 Parkedale Avenue CITY OF BROCKVILLE ON*** **EBR**

EBR Registry No: IA8E0822 **Decision Posted:**
Ministry Ref No: 8405487RE1 **Exception Posted:**
Notice Type: Instrument Decision **Section:**
Notice Stage: 800471606 **Act 1:**
Notice Date: July 14, 1998 **Act 2:**
Proposal Date: June 11, 1998 **Site Location Map:**
Year: 1998
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Parke-Davis Div. Warner Lambert of Canada Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 2337 Parkedale Avenue, Brockville Ontario, K6V 5W5
Comment Period:
URL:

Site Location Details:

2337 Parkedale Avenue CITY OF BROCKVILLE

---

40 **30 of 82** **NE/185.8** **98.9 / -0.97** ***Parke-Davis Div. Warner Lambert of Canada Inc. 2337Parkedale Avenue, Brockville City CITY OF BROCKVILLE ON*** **EBR**

EBR Registry No: IA6E1506 **Decision Posted:**
Ministry Ref No: 8420396 19961003 **Exception Posted:**
Notice Type: Instrument Decision **Section:**
Notice Stage: 800473129 **Act 1:**
Notice Date: November 22, 1996 **Act 2:**
Proposal Date: October 09, 1996 **Site Location Map:**
Year: 1996
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Parke-Davis Div. Warner Lambert of Canada Inc.
Site Address:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Location Other:
Proponent Name:
Proponent Address: 2337 Parkedale Avenue, Brockville Ontario, K6V 5W5
Comment Period:
URL:

Site Location Details:

2337Parkedale Avenue, Brockville City CITY OF BROCKVILLE

---

40 **31 of 82** **NE/185.8** **98.9 / -0.97** ***Trillium Health Care Manufacturing Inc. 2337 Parkedale Avenue Brockville Ontario K6V 5W5 CITY OF BROCKVILLE ON*** **EBR**

EBR Registry No: IA00E1832 **Decision Posted:**
Ministry Ref No: 2552-4RLPJ9 **Exception Posted:**
Notice Type: Instrument Decision **Section:**
Notice Stage: 800478203 **Act 1:**
Notice Date: February 21, 2001 **Act 2:**
Proposal Date: December 01, 2000 **Site Location Map:**
Year: 2000
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Trillium Health Care Manufacturing Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 2337 Parkedale Avenue, Brockville Ontario, K6V 5W5
Comment Period:
URL:

Site Location Details:

2337 Parkedale Avenue Brockville Ontario K6V 5W5 CITY OF BROCKVILLE

---

40 **32 of 82** **NE/185.8** **98.9 / -0.97** ***Trillium Health Care Manufacturing Inc. 2337 Parkedale Avenue Brockville Ontario K6V 5W5 CITY OF BROCKVILLE ON*** **EBR**

EBR Registry No: IA01E0678 **Decision Posted:**
Ministry Ref No: 2437-4WMKQ3 **Exception Posted:**
Notice Type: Instrument Decision **Section:**
Notice Stage: 800478994 **Act 1:**
Notice Date: July 03, 2002 **Act 2:**
Proposal Date: May 15, 2001 **Site Location Map:**
Year: 2001
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Trillium Health Care Manufacturing Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 2337 Parkedale Avenue, Brockville Ontario, K6V 5W5
Comment Period:
URL:

Site Location Details:

2337 Parkedale Avenue Brockville Ontario K6V 5W5 CITY OF BROCKVILLE

40 | 33 of 82 | NE/185.8 | 98.9 / -0.97 | **TRILLIUM HEALTH CARE MANUFACTURING**
2337 PARKDALE AVENUE NOT AVAILABLE
BROCKVILLE ON K6V5W5 | NPRI

NPRI ID:	3091	**Org ID:**	20891
Other ID:	*	**Submit Date:**	5/27/2002
No Other ID:	0.00	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	8443	**Contact ID:**	202165
Report ID:		**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	REBECCA
Report Year:	2001	**Cont Last Name:**	MEIER
Not-Current Rpt?:	No	**Contact Position:**	OPERATIONS ENGINEERING
Yr of Last Filed Rpt:	2012	**Contact Fax:**	6133422765
Fac ID:	44782	**Contact Ph.:**	6133424436
Fac Name:	SAME	**Cont Area Code:**	613
Fac Address1:	2337 PARKDALE AVENUE	**Contact Tel.:**	33424436
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	2335
Fac Postal Zip:	K6V5W5	**Cont Fax Area Cde:**	613
Facility Lat:	44.6051	**Contact Fax:**	33422765
Facility Long:	-75.6966	**Contact Email:**	RMEIER@TRILLIUM.CC
DLS (Last Filed Rpt):		**Latitude:**	44.6051
Facility DLS:		**Longitude:**	-75.6966
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	Yes	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	250	**Waste Streams:**	No
Parent Co.:	*	**No Streams:**	0.00
No Parent Co.:	1.00	**Waste Off Sites:**	No
Pollut Prev Cmnts:	No	**No Off Sites:**	0.00
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3254		
NAICS 4 Description:	Pharmaceutical and medicine manufacturing		
NAICS Code (6 digit):	325410		
NAICS 6 Description:	Pharmaceutical and medicine manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Zinc (and its compounds)
Chem (fr):	Zinc (et ses composés)
Quantity:	0
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates
Category Type ID:	12

Category Type Desc:	Other
Category Type Desc (fr):	Autres
Grouping:	Total Land
Trans Code:	LanO
Chem:	Zinc (and its compounds)
Chem (fr):	Zinc (et ses composés)
Quantity:	0
Unit:	tonnes
Basis of Estimate Cd:	O
Basis of Estimate Desc:	O- Engineering Estimates

40 | 34 of 82 | NE/185.8 | 98.9 / -0.97 | **Trillium Health Care Products Inc.**
2337 Parkedale Avenue Brockville Ontario K6V 5W5 CITY OF BROCKVILLE
ON | EBR

EBR Registry No:	IA03E0417	**Decision Posted:**	
Ministry Ref No:	2603-5KHRNY	**Exception Posted:**	
Notice Type:	Instrument Decision	**Section:**	
Notice Stage:	800719402	**Act 1:**	
Notice Date:	January 03, 2007	**Act 2:**	
Proposal Date:	March 26, 2003	**Site Location Map:**	
Year:	2003		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Off Instrument Name:			
Posted By:			
Company Name:	Trillium Health Care Products Inc.		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	2337 Parkedale Avenue, Brockville Ontario, K6V 5W5		
Comment Period:			
URL:			

Site Location Details:

2337 Parkedale Avenue Brockville Ontario K6V 5W5 CITY OF BROCKVILLE

40 | 35 of 82 | NE/185.8 | 98.9 / -0.97 | **Trillium Health Care Products Inc.**
2337 Parkedale Avenue Brockville Ontario K6V 5W5 CITY OF BROCKVILLE
ON | EBR

EBR Registry No:	IA02E0361	**Decision Posted:**	
Ministry Ref No:	0082-58NNJD	**Exception Posted:**	
Notice Type:	Instrument Decision	**Section:**	
Notice Stage:	800720879	**Act 1:**	
Notice Date:	April 25, 2003	**Act 2:**	
Proposal Date:	May 15, 2002	**Site Location Map:**	
Year:	2002		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Off Instrument Name:			
Posted By:			
Company Name:	Trillium Health Care Products Inc.		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	2337 Parkedale Avenue, Brockville Ontario, K6V 5W5		
Comment Period:			
URL:			

Site Location Details:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

2337 Parkedale Avenue Brockville Ontario K6V 5W5 CITY OF BROCKVILLE

40 **36 of 82** **NE/185.8** **98.9 / -0.97** **PARKE-DAVIS CANADA INC**
2337 PARKEDALE AVE.
BROCKVILLE ON K6V 5W5 **GEN**

Generator No: ON0200200
Status:
Approval Years: 86,87,88
Contam. Facility:
MHSW Facility:
SIC Code: 3741
SIC Description: PHARM./MEDICAL IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

40 **37 of 82** **NE/185.8** **98.9 / -0.97** **PARKE-DAVIS CANADA INC.**
DIV. OF WARNER-LAMBERT CANADA INC. 2337
PARKDALE AVE.
BROCKVILLE ON K6V 5W5 **GEN**

Generator No: ON0200200
Status:
Approval Years: 89,90
Contam. Facility:
MHSW Facility:
SIC Code: 3741
SIC Description: PHARM./MEDICAL IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

40 **38 of 82** **NE/185.8** **98.9 / -0.97** **PARKE-DAVIS, DIV. OF**
2337 PARKEDALE AVENUE
BROCKVILLE ON K6V 5W5 **GEN**

Generator No: ON0200200
Status:
Approval Years: 92,93,95,96,97
Contam. Facility:
MHSW Facility:
SIC Code: 3741
SIC Description: PHARM./MEDICAL IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 331

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Desc:		WASTE COMPRESSED GASES			

40	39 of 82	NE/185.8	98.9 / -0.97	PARKE-DAVIS CANADA INC. 30-002 DIV. OF WARNER-LAMBERT CANADA INC. 2337 PARKDALE AVE. BROCKVILLE ON K6V 5W5	GEN

Generator No: ON0200200
Status:
Approval Years: 94
Contam. Facility:
MHSW Facility:
SIC Code: 3741
SIC Description: PHARM./MEDICAL IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

40	40 of 82	NE/185.8	98.9 / -0.97	PARKE-DAVIS, DIV. (SEE & USE ON2369500) 2337 PARKEDALE AVENUE BROCKVILLE ON K6V 5W5	GEN

Generator No: ON0200200
Status:
Approval Years: 98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 3741
SIC Description: PHARM./MEDICAL IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		213			
Waste Class Desc:		PETROLEUM DISTILLATES			
Waste Class:		241			
Waste Class Desc:		HALOGENATED SOLVENTS			
Waste Class:		252			
Waste Class Desc:		WASTE OILS & LUBRICANTS			
Waste Class:		261			
Waste Class Desc:		PHARMACEUTICALS			
Waste Class:		263			
Waste Class Desc:		ORGANIC LABORATORY CHEMICALS			
Waste Class:		331			
Waste Class Desc:		WASTE COMPRESSED GASES			
Waste Class:		122			
Waste Class Desc:		ALKALINE WASTES - OTHER METALS			

40	41 of 82	NE/185.8	98.9 / -0.97	TRILLIUM HEALTH CARE MANUFACTURING 2337 PARKDALE AVENUE BROCKVILLE ON K6V 5W5	GEN

Generator No: ON2369500
Status:
Approval Years: 98,99,00
Contam. Facility:
MHSW Facility:
SIC Code: 3741
SIC Description: PHARM./MEDICAL IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 263

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

---

40 **42 of 82** **NE/185.8** **98.9 / -0.97** **TRILLIUM HEALTH CARE MANUFACTURING**
2337 PARKEDALE AVENUE
BROCKVILLE ON K6V 5W5 **GEN**

Generator No: ON2369500
Status:
Approval Years: 01,02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 3741
SIC Description: PHARM./MEDICAL IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 268
Waste Class Desc: AMINES

Waste Class: 268
Waste Class Desc: AMINES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 114
Waste Class Desc: OTHER INORGANIC ACID WASTES

---

40 **43 of 82** **NE/185.8** **98.9 / -0.97** **TRILLIUM HEALTH CARE PRODUCTS**
2337 PARKEDALE AVENUE NOT AVAILABLE
BROCKVILLE ON K6V 5W5 **NPRI**

NPRI ID: 3091
Other ID: *
No Other ID: 0
Track ID: 76320
Report ID: 160768
Report Type: NPRI
Rpt Type ID: 1
Report Year: 2002
Not-Current Rpt?: No
Yr of Last Filed Rpt: 2012
Fac ID: 113700
Fac Name: TRILLIUM HEALTH CARE MANUFACTURING
Fac Address1: 2337 PARKEDALE AVENUE
Fac Address2: NOT AVAILABLE
Fac Postal Zip: K6V 5W5
Facility Lat:
Facility Long:
DLS (Last Filed Rpt):
Facility DLS:
Datum: 1983
Facility Cmnts: False
URL:
No of Empl.: 250
Parent Co.: *
No Parent Co.: 1
Pollut Prev Cmnts: False
Stacks: False
No of Stacks:
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 32
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3254
NAICS 4 Description: Pharmaceutical and medicine manufacturing
NAICS Code (6 digit): 325410
NAICS 6 Description: Pharmaceutical and medicine manufacturing

Org ID: 70596
Submit Date: 5/30/2003
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 202165
Cont Type: MED
Contact Title:
Cont First Name: REBECCA
Cont Last Name: MEIER
Contact Position: OPERATIONS ENGINEERING
Contact Fax: 6133422765
Contact Ph.: 6133424436
Cont Area Code: 613
Contact Tel.: 33424436
Contact Ext.: 2335
Cont Fax Area Cde: 613
Contact Fax: 33422765
Contact Email: RMEIER@TRILLIUM.CC
Latitude: 44.6051
Longitude: -75.6966
UTM Zone:
UTM Northing:
UTM Easting:
Waste Streams: False
No Streams: 0
Waste Off Sites: Fals
No Off Sites: 1
Shutdown: False
No of Shutdown: 0

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Dichloromethane
Chem (fr): Dichlorométhane
Quantity: 23
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Trans Code: ASta
Chem: Methanol
Chem (fr): Méthanol
Quantity: 21.4
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

---

40 **44 of 82** **NE/185.8** **98.9 / -0.97** **Trillium Health Care Products Inc.** **SCT**
2337 Parkdale Ave W
Brockville ON K6V 5W5

Established: 1998
Plant Size (ft²): 200000
Employment: 350

--Details--
Description: Pharmaceutical and Medicine Manufacturing
SIC/NAICS Code: 325410

Description: Toilet Preparation Manufacturing
SIC/NAICS Code: 325620

---

40 **45 of 82** **NE/185.8** **98.9 / -0.97** **TRILLIUM HEALTH CARE PRODUCTS** **NPRI**
2337 PARKDALE AVENUE NOT AVAILABLE
BROCKVILLE ON K6V5W5

NPRI ID: 3091
Other ID: N
No Other ID:
Track ID: 72945
Report ID: 152353
Report Type: NPRI
Rpt Type ID: 1
Report Year: 2003
Not-Current Rpt?: No
Yr of Last Filed Rpt: 2012
Fac ID: 113699
Fac Name: TRILLIUM HEALTH CARE MANUFACTURING
Fac Address1: 2337 PARKDALE AVENUE
Fac Address2: NOT AVAILABLE
Fac Postal Zip: K6V5W5
Facility Lat: 44.6051
Facility Long: -75.6966
DLS (Last Filed Rpt):
Facility DLS:
Datum: 1983
Facility Cmnts: False
URL:
No of Empl.: 250
Parent Co.: *
No Parent Co.: 1
Pollut Prev Cmnts: False
Stacks: True
No of Stacks:
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 32
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3254

Org ID: 70606
Submit Date: 5/31/2004
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 117363
Cont Type: MED
Contact Title:
Cont First Name: ANDY
Cont Last Name: JOZEFOWICZ
Contact Position: OPERATIONS ENGINEERING
Contact Fax: 6133422765
Contact Ph.: 6133424436
Cont Area Code: 613
Contact Tel.: 33424436
Contact Ext.: 2316
Cont Fax Area Cde: 613
Contact Fax: 33422765
Contact Email: AJOZEFOWICZ@TRILLIUM.CC
Latitude: 44.6051
Longitude: -75.6966
UTM Zone:
UTM Northing:
UTM Easting:
Waste Streams: True¿
No Streams:
Waste Off Sites: Fals
No Off Sites: 1
Shutdown: True
No of Shutdown:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

NAICS 4 Description: Pharmaceutical and medicine manufacturing
NAICS Code (6 digit): 325410
NAICS 6 Description: Pharmaceutical and medicine manufacturing

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Methanol
Chem (fr): Méthanol
Quantity: 23.853
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Volatile Organic Compounds (VOCs)
Chem (fr): Composés organiques volatils (COV)
Quantity: 23.853
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Category Type ID: 1
Category Type Desc: Stack / Point
Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Dichloromethane
Chem (fr): Dichlorométhane
Quantity: 22.409
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

---

40 **46 of 82** **NE/185.8** **98.9 / -0.97** **Trillium Health Care Products** **SCT**
2337 Parkedale Ave
Brockville ON K6V 5W5

Established: 01-JAN-98
Plant Size (ft²): 210000
Employment:

--Details--
Description: Pharmaceutical and Medicine Manufacturing
SIC/NAICS Code: 325410

Description: Pharmaceutical and Medicine Manufacturing
SIC/NAICS Code: 325410

---

40 **47 of 82** **NE/185.8** **98.9 / -0.97** **TRILLIUM HEALTH CARE PRODUCTS** **NPRI**
2337 PARKDALE AVENUE NOT AVAILABLE
BROCKVILLE ON K6V5W5

NPRI ID: 3091 **Org ID:** 70606

Other ID:	N	**Submit Date:**	6/28/2005
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	30397	**Contact ID:**	137371
Report ID:	90060	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	DAVE
Report Year:	2004	**Cont Last Name:**	LEONARD
Not-Current Rpt?:	No	**Contact Position:**	ENG. MAINTENANCE MANAGER
Yr of Last Filed Rpt:	2012	**Contact Fax:**	6133422765
Fac ID:	113699	**Contact Ph.:**	6133424436
Fac Name:	TRILLIUM HEALTH CARE MANUFACTURING	**Cont Area Code:**	613
Fac Address1:	2337 PARKDALE AVENUE	**Contact Tel.:**	33424436
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	3271
Fac Postal Zip:	K6V5W5	**Cont Fax Area Cde:**	613
Facility Lat:	44.6051	**Contact Fax:**	33422765
Facility Long:	-75.6966	**Contact Email:**	D.LEONARD@TRILLIUM.CC
DLS (Last Filed Rpt):		**Latitude:**	44.6051
Facility DLS:		**Longitude:**	-75.6966
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	True	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	250	**Waste Streams:**	False
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	True	**No Off Sites:**	1
Stacks:	No	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3254		
NAICS 4 Description:	Pharmaceutical and medicine manufacturing		
NAICS Code (6 digit):	325410		
NAICS 6 Description:	Pharmaceutical and medicine manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Volatile Organic Compounds (VOCs)
Chem (fr):	Composés organiques volatils (COV)
Quantity:	30.663
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Methanol
Chem (fr):	Méthanol
Quantity:	30.663
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1

Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Dichloromethane
Chem (fr):	Dichlorométhane
Quantity:	37.548
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

40 ***48 of 82*** ***NE/185.8*** ***98.9 / -0.97*** ***TRILLIUM HEALTH CARE PRODUCTS 2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5*** ***NPRI***

NPRI ID:	3091	**Org ID:**	70606
Other ID:	*	**Submit Date:**	5/25/2006
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	35622	**Contact ID:**	137371
Report ID:	95868	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	DAVE
Report Year:	2005	**Cont Last Name:**	LEONARD
Not-Current Rpt?:	No	**Contact Position:**	ENG. MAINTENANCE MANAGER
Yr of Last Filed Rpt:	2012	**Contact Fax:**	6133422765
Fac ID:	113699	**Contact Ph.:**	6133424436
Fac Name:	TRILLIUM HEALTH CARE MANUFACTURING	**Cont Area Code:**	613
Fac Address1:	2337 PARKDALE AVENUE	**Contact Tel.:**	33424436
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	3271
Fac Postal Zip:	K6V5W5	**Cont Fax Area Cde:**	613
Facility Lat:	44.6051	**Contact Fax:**	33422765
Facility Long:	-75.6966	**Contact Email:**	D.LEONARD@TRILLIUM.CC
DLS (Last Filed Rpt):		**Latitude:**	44.6051
Facility DLS:		**Longitude:**	-75.6966
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	280	**Waste Streams:**	False
Parent Co.:	Y	**No Streams:**	
No Parent Co.:	1	**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	1.00
Stacks:	False	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3254		
NAICS 4 Description:	Pharmaceutical and medicine manufacturing		
NAICS Code (6 digit):	325410		
NAICS 6 Description:	Pharmaceutical and medicine manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	2.6

Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	2.6
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Volatile Organic Compounds (VOCs)
Chem (fr):	Composés organiques volatils (COV)
Quantity:	38.6
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Methanol
Chem (fr):	Méthanol
Quantity:	31.2
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Dichloromethane
Chem (fr):	Dichlorométhane
Quantity:	28.2
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

40 | **49 of 82** | **NE/185.8** | **98.9 / -0.97** | **TRILLIUM HEALTH CARE PRODUCTS**
2337 PARKDALE AVENUE NOT AVAILABLE
BROCKVILLE ON K6V5W5 | **NPRI**

NPRI ID:	3091	**Org ID:**	70606
Other ID:	*	**Submit Date:**	5/10/2007
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	43036	**Contact ID:**	137371
Report ID:	103477	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	DAVE
Report Year:	2006	**Cont Last Name:**	LEONARD
Not-Current Rpt?:	No	**Contact Position:**	ENG. MAINTENANCE MANAGER

Yr of Last Filed Rpt:	2012	**Contact Fax:**	6133422765
Fac ID:	113699	**Contact Ph.:**	6133424436
Fac Name:	TRILLIUM HEALTH CARE MANUFACTURING	**Cont Area Code:**	613
Fac Address1:	2337 PARKDALE AVENUE	**Contact Tel.:**	33424436
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	3271
Fac Postal Zip:	K6V5W5	**Cont Fax Area Cde:**	613
Facility Lat:	44.6051	**Contact Fax:**	33422765
Facility Long:	-75.6966	**Contact Email:**	D.LEONARD@TRILLIUM.CC
DLS (Last Filed Rpt):		**Latitude:**	44.6051
Facility DLS:		**Longitude:**	-75.6966
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	280	**Waste Streams:**	True¿
Parent Co.:	Y	**No Streams:**	
No Parent Co.:	1	**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	1.00
Stacks:	True	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3254		
NAICS 4 Description:	Pharmaceutical and medicine manufacturing		
NAICS Code (6 digit):	325410		
NAICS 6 Description:	Pharmaceutical and medicine manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Dichloromethane
Chem (fr):	Dichlorométhane
Quantity:	15.9
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Methanol
Chem (fr):	Méthanol
Quantity:	16.3
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	2.3
Unit:	tonnes

Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Volatile Organic Compounds (VOCs)
Chem (fr):	Composés organiques volatils (COV)
Quantity:	19.8
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance
Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	2.3
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

40 | ***50 of 82*** | ***NE/185.8*** | ***98.9 / -0.97*** | ***TRILLIUM HEALTH CARE PRODUCTS 2337 PARKDALE AVENUE<UNOFFICIAL> Brockville ON*** | ***SPL***

Ref No:	2500-63Q8D2	**Discharger Report:**	
Site No:		**Material Group:**	Gases/Particulate
Incident Dt:	8/9/2004	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:	36	**Nearest Watercourse:**	
Contaminant Name:	OXYGEN (COMPRESSED GAS)	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Kingston
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	Eastern
Environment Impact:		**Site Municipality:**	Brockville
Nature of Impact:		**Site Lot:**	
Receiving Medium:	Air	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	8/10/2004	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:		**Source Type:**	
Site Name:	TRILLIUM HEALTH CARE PRODUCTS 2337 PARKDALE AVENUE<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Trillium Health-O2 Released During Reaction,FD		
Contaminant Qty:			

40 | ***51 of 82*** | ***NE/185.8*** | ***98.9 / -0.97*** | ***2337 Parkdale Avenue Brockville ON K6V 5W5*** | ***EHS***

Order No:	20080416010	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Complete Report	**Client Prov/State:**	ON

Report Date:	4/24/2008	**Search Radius (km):**	0.25
Date Received:	4/16/2008	**X:**	-75.696948
Previous Site Name:		**Y:**	44.605656
Lot/Building Size:			
Additional Info Ordered:			

40 | ***52 of 82*** | ***NE/185.8*** | ***98.9 / -0.97*** | ***TRILLIUM HEALTH CARE PRODUCTS 2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5*** | ***NPRI***

NPRI ID:	3091	**Org ID:**	70606
Other ID:	*	**Submit Date:**	5/20/2008
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	53052	**Contact ID:**	227767
Report ID:	114476	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	YVONNE
Report Year:	2007	**Cont Last Name:**	ZAWADA
Not-Current Rpt?:	No	**Contact Position:**	ENG. MAINTENANCE MANAGER
Yr of Last Filed Rpt:	2012	**Contact Fax:**	6133422765
Fac ID:	113699	**Contact Ph.:**	6133424436
Fac Name:	TRILLIUM HEALTH CARE MANUFACTURING	**Cont Area Code:**	613
Fac Address1:	2337 PARKDALE AVENUE	**Contact Tel.:**	33424436
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	2233
Fac Postal Zip:	K6V5W5	**Cont Fax Area Cde:**	613
Facility Lat:	44.6051	**Contact Fax:**	33422765
Facility Long:	-75.6966	**Contact Email:**	YZAWADA@TRILLIUM.CC
DLS (Last Filed Rpt):		**Latitude:**	44.6051
Facility DLS:		**Longitude:**	-75.6966
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	250	**Waste Streams:**	True¿
Parent Co.:	Y	**No Streams:**	
No Parent Co.:	1.00	**Waste Off Sites:**	True
Pollut Prev Cmnts:	False	**No Off Sites:**	1.00
Stacks:	True	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3254		
NAICS 4 Description:	Pharmaceutical and medicine manufacturing		
NAICS Code (6 digit):	325410		
NAICS 6 Description:	Pharmaceutical and medicine manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	Volatile Organic Compounds (VOCs)
Chem (fr):	Composés organiques volatils (COV)
Quantity:	3.5
Unit:	tonnes
Basis of Estimate Cd:	C
Basis of Estimate Desc:	C- Mass Balance

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	1.9
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Category Type ID:	6
Category Type Desc:	Road dust
Category Type Desc (fr):	Poussières de routes
Grouping:	Total Air
Trans Code:	
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	.003
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Category Type ID:	6
Category Type Desc:	Road dust
Category Type Desc (fr):	Poussières de routes
Grouping:	Total Air
Trans Code:	
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	.003
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	1.9
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

40 | ***53 of 82*** | ***NE/185.8*** | ***98.9 / -0.97*** | ***TRILLIUM HEALTH CARE PRODUCTS 2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5*** | ***NPRI***

NPRI ID:	3091	**Org ID:**	70606
Other ID:	*	**Submit Date:**	5/29/2009
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	67901	**Contact ID:**	227767
Report ID:	127203	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	YVONNE
Report Year:	2008	**Cont Last Name:**	ZAWADA
Not-Current Rpt?:	No	**Contact Position:**	ENG. MAINTENANCE MANAGER
Yr of Last Filed Rpt:	2012	**Contact Fax:**	6133422765
Fac ID:	113699	**Contact Ph.:**	6133424436
Fac Name:	TRILLIUM HEALTH CARE MANUFACTURING	**Cont Area Code:**	613
Fac Address1:	2337 PARKDALE AVENUE	**Contact Tel.:**	33424436

Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	2233
Fac Postal Zip:	K6V5W5	**Cont Fax Area Cde:**	613
Facility Lat:	44.6051	**Contact Fax:**	33422765
Facility Long:	-75.6966	**Contact Email:**	YZAWADA@TRILLIUM.CC
DLS (Last Filed Rpt):		**Latitude:**	44.6051
Facility DLS:		**Longitude:**	-75.6966
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	250	**Waste Streams:**	No
Parent Co.:	Y	**No Streams:**	
No Parent Co.:	1	**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	No	**No Off Sites:**	1
Stacks:	No	**Shutdown:**	No
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3254		
NAICS 4 Description:	Pharmaceutical and medicine manufacturing		
NAICS Code (6 digit):	325410		
NAICS 6 Description:	Pharmaceutical and medicine manufacturing		

Substance Release Report

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	1.7
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Category Type ID:	6
Category Type Desc:	Road dust
Category Type Desc (fr):	Poussières de routes
Grouping:	Total Air
Trans Code:	
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	.003
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	1.7
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 6

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Category Type Desc:	Road dust
Category Type Desc (fr):	Poussières de routes
Grouping:	Total Air
Trans Code:	
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	.003
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	54 of 82	NE/185.8	98.9 / -0.97	**Trillium Health Care Products Inc.** **2337 Parkedale Avenue** **Brockville ON**	CA

Certificate #:	6003-6VYRWK
Application Year:	2006
Issue Date:	12/31/2006
Approval Type:	Air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	55 of 82	NE/185.8	98.9 / -0.97	**TRILLIUM HEALTH CARE PRODUCTS** **2337 PARKDALE AVENUE NOT AVAILABLE** **BROCKVILLE ON K6V5W5**	NPRI

NPRI ID:	3091	**Org ID:**	70606
Other ID:	*	**Submit Date:**	5/27/2010
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	87959	**Contact ID:**	227769
Report ID:	141963	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	YVONNE
Report Year:	2009	**Cont Last Name:**	ZAWADA
Not-Current Rpt?:	No	**Contact Position:**	ENGINEERING AND MAINTENANCE MANAGER
Yr of Last Filed Rpt:	2012	**Contact Fax:**	6133422765
Fac ID:	113699	**Contact Ph.:**	6133424436
Fac Name:	TRILLIUM HEALTH CARE MANUFACTURING	**Cont Area Code:**	613
Fac Address1:	2337 PARKDALE AVENUE	**Contact Tel.:**	33424436
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	2233
Fac Postal Zip:	K6V5W5	**Cont Fax Area Cde:**	613
Facility Lat:	44.6051	**Contact Fax:**	33422765
Facility Long:	-75.6966	**Contact Email:**	YVONNE.ZAWADA@TRILLIUMHCP.COM
DLS (Last Filed Rpt):		**Latitude:**	44.6051
Facility DLS:		**Longitude:**	-75.6966
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	250	**Waste Streams:**	No
Parent Co.:	Y	**No Streams:**	
No Parent Co.:	1	**Waste Off Sites:**	Yes
Pollut Prev Cmnts:	No	**No Off Sites:**	1
Stacks:	No	**Shutdown:**	No
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			

Canadian SIC Code:	
SIC Code Description:	
American SIC Code:	
NAICS Code (2 digit):	32
NAICS 2 Description:	Manufacturing
NAICS Code (4 digit):	3254
NAICS 4 Description:	Pharmaceutical and medicine manufacturing
NAICS Code (6 digit):	325410
NAICS 6 Description:	Pharmaceutical and medicine manufacturing

Substance Release Report

Category Type ID:	6
Category Type Desc:	Road dust
Category Type Desc (fr):	Poussières de routes
Grouping:	Total Air
Trans Code:	
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	.003
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Category Type ID:	6
Category Type Desc:	Road dust
Category Type Desc (fr):	Poussières de routes
Grouping:	Total Air
Trans Code:	
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	.003
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	1.7
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Category Type ID:	1
Category Type Desc:	Stack / Point
Category Type Desc (fr):	Rejets de cheminée ou ponctuels
Grouping:	Total Air
Trans Code:	ASta
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	1.7
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	56 of 82	NE/185.8	98.9 / -0.97	**Trillium Health Care Products Inc.** **2337 Parkedale Avenue Brockville, United Counties Of Leeds & Grenville CITY OF BROCKVILLE**	EBR

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				ON	

EBR Registry No: 011-3591
Ministry Ref No: 2209-8GSLE2
Notice Type: Instrument Decision
Notice Stage: 803857923
Notice Date: February 04, 2015
Proposal Date: May 19, 2011
Year: 2011
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Off Instrument Name:
Posted By:
Company Name: Trillium Health Care Products Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 2337 Parkedale avenue, Brockville Ontario, Canada K6V 5W5
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

2337 Parkedale Avenue Brockville, United Counties Of Leeds & Grenville CITY OF BROCKVILLE

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	57 of 82	NE/185.8	98.9 / -0.97	TRILLIUM HEALTH CARE PRODUCTS 2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NPRI

NPRI ID: 3091
Other ID: Y
No Other ID: 2
Track ID: 93933
Report ID: 147984
Report Type: NPRI
Rpt Type ID: 1
Report Year: 2010
Not-Current Rpt?: No

Yr of Last Filed Rpt: 2012
Fac ID: 113699
Fac Name: TRILLIUM HEALTH CARE MANUFACTURING
Fac Address1: 2337 PARKDALE AVENUE
Fac Address2: NOT AVAILABLE
Fac Postal Zip: K6V5W5
Facility Lat: 44.6051
Facility Long: -75.6966
DLS (Last Filed Rpt):
Facility DLS:
Datum: 1983
Facility Cmnts: No
URL:
No of Empl.: 250
Parent Co.: Y
No Parent Co.: 1
Pollut Prev Cmnts: No
Stacks: No
No of Stacks:
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 32

Org ID: 70606
Submit Date: 6/16/2011
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 227769
Cont Type: MED
Contact Title:
Cont First Name: YVONNE
Cont Last Name: ZAWADA
Contact Position: ENGINEERING AND MAINTENANCE MANAGER
Contact Fax: 6133422765
Contact Ph.: 6133424436
Cont Area Code: 613
Contact Tel.: 33424436
Contact Ext.: 2233
Cont Fax Area Cde: 613
Contact Fax: 33422765
Contact Email: YVONNE.ZAWADA@TRILLIUMHCP.COM
Latitude: 44.6051
Longitude: -75.6966
UTM Zone:
UTM Northing:
UTM Easting:
Waste Streams: No
No Streams:
Waste Off Sites: Yes
No Off Sites: 2
Shutdown: No
No of Shutdown:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3254
NAICS 4 Description: Pharmaceutical and medicine manufacturing
NAICS Code (6 digit): 325410
NAICS 6 Description: Pharmaceutical and medicine manufacturing

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Zinc (and its compounds)
Chem (fr): Zinc (et ses composés)
Quantity: .001
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	58 of 82	NE/185.8	98.9 / -0.97	TRILLIUM HEALTH CARE MANUFACTURING 2337 Parkedale Avenue Brockville ON	GEN

Generator No: ON2369500
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 325410
SIC Description: Pharmaceutical and Medicine Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 114
Waste Class Desc: OTHER INORGANIC ACID WASTES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Waste Class: 268
Waste Class Desc: AMINES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

---

40 | **59 of 82** | **NE/185.8** | **98.9 / -0.97** | **TRILLIUM HEALTH CARE PRODUCTS**
2337 PARKDALE AVENUE NOT AVAILABLE
BROCKVILLE ON K6V5W5 | **NPRI**

NPRI ID: 3091
Other ID:
No Other ID:
Track ID: 100300
Report ID: 4241
Report Type: NPRI
Rpt Type ID: 1
Report Year: 2011
Not-Current Rpt?: No

Yr of Last Filed Rpt: 2012
Fac ID: 113699
Fac Name: TRILLIUM HEALTH CARE MANUFACTURING
Fac Address1: 2337 PARKDALE AVENUE
Fac Address2: NOT AVAILABLE
Fac Postal Zip: K6V5W5
Facility Lat: 44.6051
Facility Long: -75.6966
DLS (Last Filed Rpt):
Facility DLS:
Datum: 1983
Facility Cmnts:
URL:
No of Empl.: 250
Parent Co.:
No Parent Co.:
Pollut Prev Cmnts:
Stacks:
No of Stacks:
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 32
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3254
NAICS 4 Description: Pharmaceutical and medicine manufacturing
NAICS Code (6 digit): 325410
NAICS 6 Description: Pharmaceutical and medicine manufacturing

Org ID: 70606
Submit Date: 12/20/2012
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 227769
Cont Type: MED
Contact Title:
Cont First Name: YVONNE
Cont Last Name: ZAWADA
Contact Position: ENGINEERING AND MAINTENANCE MANAGER
Contact Fax: 6133422765
Contact Ph.: 6133424436
Cont Area Code: 613
Contact Tel.: 33424436
Contact Ext.: 2233
Cont Fax Area Cde: 613
Contact Fax: 33422765
Contact Email: YVONNE.ZAWADA@TRILLIUMHCP.COM
Latitude: 44.6051
Longitude: -75.6966
UTM Zone:
UTM Northing:
UTM Easting:
Waste Streams:
No Streams:
Waste Off Sites:
No Off Sites:
Shutdown:
No of Shutdown:

Substance Release Report

Category Type ID: 1
Category Type Desc: Stack / Point

Category Type Desc (fr): Rejets de cheminée ou ponctuels
Grouping: Total Air
Trans Code: ASta
Chem: Zinc (and its compounds)
Chem (fr): Zinc (et ses composés)
Quantity: .001
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

---

40 | **60 of 82** | **NE/185.8** | **98.9 / -0.97** | **TRILLIUM HEALTH CARE MANUFACTURING**
2337 Parkedale Avenue
Brockville ON | **GEN**

Generator No: ON2369500
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 325410
SIC Description: Pharmaceutical and Medicine Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 268
Waste Class Desc: AMINES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Waste Class: 114
Waste Class Desc: OTHER INORGANIC ACID WASTES

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 263

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	61 of 82	NE/185.8	98.9 / -0.97	TRILLIUM HEALTH CARE MANUFACTURING 2337 Parkedale Avenue Brockville ON	GEN

Generator No: ON2369500
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 325410
SIC Description: Pharmaceutical and Medicine Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 268
Waste Class Desc: AMINES

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 114
Waste Class Desc: OTHER INORGANIC ACID WASTES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	62 of 82	NE/185.8	98.9 / -0.97	TRILLIUM HEALTH CARE MANUFACTURING 2337 Parkedale Avenue Brockville ON	GEN

Generator No: ON2369500
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 325410
SIC Description: Pharmaceutical and Medicine Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 114
Waste Class Desc: OTHER INORGANIC ACID WASTES

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 268
Waste Class Desc: AMINES

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	63 of 82	NE/185.8	98.9 / -0.97	TRILLIUM HEALTH CARE PRODUCTS 2337 PARKDALE AVENUE NOT AVAILABLE BROCKVILLE ON K6V5W5	NPRI

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

NPRI ID:	3091	**Org ID:**	70606
Other ID:		**Submit Date:**	5/30/2013
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	110376	**Contact ID:**	
Report ID:	20281	**Cont Type:**	
Report Type:	DNMC	**Contact Title:**	
Rpt Type ID:	2	**Cont First Name:**	
Report Year:	2012	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2012	**Contact Fax:**	
Fac ID:	113699	**Contact Ph.:**	
Fac Name:	TRILLIUM HEALTH CARE MANUFACTURING	**Cont Area Code:**	
Fac Address1:	2337 PARKDALE AVENUE	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	K6V5W5	**Cont Fax Area Cde:**	
Facility Lat:	44.6051	**Contact Fax:**	
Facility Long:	-75.6966	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	44.6051
Facility DLS:		**Longitude:**	-75.6966
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:		**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	32		
NAICS 2 Description:	Manufacturing		
NAICS Code (4 digit):	3254		
NAICS 4 Description:	Pharmaceutical and medicine manufacturing		
NAICS Code (6 digit):	325410		
NAICS 6 Description:	Pharmaceutical and medicine manufacturing		

---

40 | ***64 of 82*** | ***NE/185.8*** | ***98.9 / -0.97*** | ***2337 Parkedale Ave, Brockville ON K6V3G9*** | ***EHS***

Order No:	20140611080	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	CA
Report Date:	20-JUN-14	**Search Radius (km):**	.25
Date Received:	11-JUN-14	**X:**	-75.696868
Previous Site Name:		**Y:**	44.605007
Lot/Building Size:	20 AC		
Additional Info Ordered:			

---

40 | ***65 of 82*** | ***NE/185.8*** | ***98.9 / -0.97*** | ***TRILLIUM HEALTH CARE MANUFACTURING, 2337 Parkedale Avenue, Brockville ON*** | ***GEN***

Generator No:	ON2369500	**PO Box No:**	
Status:		**Country:**	
Approval Years:	2013	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	325410		
SIC Description:	PHARMACEUTICAL AND MEDICINE MANUFACTURING		

Detail(s)

Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS
Waste Class:	212
Waste Class Desc:	ALIPHATIC SOLVENTS
Waste Class:	262
Waste Class Desc:	DETERGENTS/SOAPS
Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	261
Waste Class Desc:	PHARMACEUTICALS
Waste Class:	331
Waste Class Desc:	WASTE COMPRESSED GASES
Waste Class:	267
Waste Class Desc:	ORGANIC ACIDS
Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	112
Waste Class Desc:	ACID WASTE - HEAVY METALS
Waste Class:	114
Waste Class Desc:	OTHER INORGANIC ACID WASTES
Waste Class:	241
Waste Class Desc:	HALOGENATED SOLVENTS
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS
Waste Class:	213
Waste Class Desc:	PETROLEUM DISTILLATES
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	122
Waste Class Desc:	ALKALINE WASTES - OTHER METALS
Waste Class:	268
Waste Class Desc:	AMINES

---

40 | ***66 of 82*** | ***NE/185.8*** | ***98.9 / -0.97*** | ***Trillium Health Care Products Inc., 2337 Parkedale Ave, Brockville ON*** | ***ECA***

Approval No:	8877-9MXQXC	**MOE District:**	
Approval Date:	1/27/15	**City:**	Brockville
Status:	Approved	**Longitude:**	-75.69583333333339965065533760935068130493164062 5
Record Type:		**Latitude:**	44.60527777777779135703895008191466331481933593 75
Link Source:		**Geometry X:**	
SWP Area Name:		**Geometry Y:**	
Approval Type:			
Project Type:	Air/Noise		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Address:
Full Address: 2337 Parkedale Ave Brockville City,nited Counties Of Leeds & Grenville
Full PDF Link:

---

40 **67 of 82** **NE/185.8** **98.9 / -0.97** **Trillium Health Care Manufacturing Inc.** **ECA**
2337 Parkedale Avenue
Brockville ON K6V 5W5

Approval No: 8394-5BGRBW
Approval Date: 2002-07-02
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Cataraqui
Approval Type: ECA-AIR
Project Type: AIR
Address: 2337 Parkedale Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2437-4WMKQ3-14.pdf

MOE District: Kingston
City:
Longitude: -75.69594599999999
Latitude: 44.60523
Geometry X:
Geometry Y:

---

40 **68 of 82** **NE/185.8** **98.9 / -0.97** **Trillium Health Care Products Inc.** **ECA**
2337 Parkedale Avenue
Brockville ON K6V 5W5

Approval No: 4120-5DHKCV
Approval Date: 2002-09-06
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Cataraqui
Approval Type: ECA-AIR
Project Type: AIR
Address: 2337 Parkedale Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/0082-58NNJD-14.pdf

MOE District: Kingston
City:
Longitude: -75.69594599999999
Latitude: 44.60523
Geometry X:
Geometry Y:

---

40 **69 of 82** **NE/185.8** **98.9 / -0.97** **Trillium Health Care Manufacturing Inc.** **ECA**
2337 Parkedale Avenue
Brockville ON K6V 5W5

Approval No: 7626-4U4QMW
Approval Date: 2001-02-20
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Cataraqui
Approval Type: ECA-AIR
Project Type: AIR
Address: 2337 Parkedale Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2552-4RLPJ9-14.pdf

MOE District: Kingston
City:
Longitude: -75.69594599999999
Latitude: 44.60523
Geometry X:
Geometry Y:

---

40 **70 of 82** **NE/185.8** **98.9 / -0.97** **Trillium Health Care Products Inc.** **ECA**
2337 Parkedale Ave
Brockville ON K6V 5W5

Approval No: 8877-9MXQXC
Approval Date: 2015-01-27
Status: Approved

MOE District: Kingston
City:
Longitude: -75.69594599999999

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Record Type: ECA
Link Source: IDS
SWP Area Name: Cataraqui
Approval Type: ECA-AIR
Project Type: AIR
Address: 2337 Parkedale Ave
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2209-8GSLE2-14.pdf

Latitude: 44.60523
Geometry X:
Geometry Y:

---

40 **71 of 82** **NE/185.8** **98.9 / -0.97** **Trillium Health Care Products Inc.** **ECA**
2337 Parkedale Avenue
Brockville ON K6V 5W5

Approval No: 6003-6VYRWK
Approval Date: 2006-12-31
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Cataraqui
Approval Type: ECA-AIR
Project Type: AIR
Address: 2337 Parkedale Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2603-5KHRNY-14.pdf

MOE District: Kingston
City:
Longitude: -75.69594599999999
Latitude: 44.60523
Geometry X:
Geometry Y:

---

40 **72 of 82** **NE/185.8** **98.9 / -0.97** **TRILLIUM HEALTH CARE MANUFACTURING** **GEN**
2337 Parkedale Avenue
Brockville ON K6V 5W5

Generator No: ON2369500
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 325410
SIC Description: PHARMACEUTICAL AND MEDICINE MANUFACTURING

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Philippe Moussette
Phone No Admin: 450-447-1212 Ext.209

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 122

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 114
Waste Class Desc: OTHER INORGANIC ACID WASTES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Waste Class: 268
Waste Class Desc: AMINES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

40	73 of 82	NE/185.8	98.9 / -0.97	**TRILLIUM HEALTH CARE MANUFACTURING** **2337 Parkedale Avenue** **Brockville ON K6V 5W5**	GEN

Generator No: ON2369500
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 325410
SIC Description: PHARMACEUTICAL AND MEDICINE MANUFACTURING

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 268
Waste Class Desc: AMINES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 114
Waste Class Desc: OTHER INORGANIC ACID WASTES

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

40	74 of 82	NE/185.8	98.9 / -0.97	**TRILLIUM HEALTH CARE MANUFACTURING** **2337 Parkedale Avenue** **Brockville ON K6V 5W5**	GEN

Generator No: ON2369500
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 325410
SIC Description: PHARMACEUTICAL AND MEDICINE MANUFACTURING

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 114
Waste Class Desc: OTHER INORGANIC ACID WASTES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 268
Waste Class Desc: AMINES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

40 | **75 of 82** | **NE/185.8** | **98.9 / -0.97** | **TRILLIUM HEALTH CARE MANUFACTURING**
2337 Parkedale Avenue
Brockville ON K6V 5W5 | **GEN**

Generator No: ON2369500
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112 C
Waste Class Desc: Acid solutions - containing heavy metals

Waste Class: 114 C
Waste Class Desc: Other inorganic acid wastes

Waste Class: 121 C
Waste Class Desc: Alkaline slutions - containing heavy metals

Waste Class: 122 C

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 133 L
Waste Class Desc: Brine, chlor-alkali sludges

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 146 T
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 148 A
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 148 C
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 148 I
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 148 L
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 212 H
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 212 I
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 212 L
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 213 I
Waste Class Desc: Petroleum distillates

Waste Class: 263 A
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 241 B
Waste Class Desc: Halogenated solvents and residues

Waste Class: 241 H
Waste Class Desc: Halogenated solvents and residues

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 261 A
Waste Class Desc: Pharmaceuticals

Waste Class: 261 I
Waste Class Desc: Pharmaceuticals

Waste Class: 263 B
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 263 I
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 263 L
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 268 C

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Desc: Amines

Waste Class: 312 P
Waste Class Desc: Pathological wastes

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 261 L
Waste Class Desc: Pharmaceuticals

Waste Class: 261 T
Waste Class Desc: Pharmaceuticals

Waste Class: 262 L
Waste Class Desc: Detergents and soaps

---

40 | **76 of 82** | **NE/185.8** | **98.9 / -0.97** | **2337 Parkedale Avenue**
Brockville ON K6V 3G9 | **EHS**

Order No: 20180911318
Status: C
Report Type: Custom Report
Report Date: 13-SEP-18
Date Received: 11-SEP-18
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.696251
Y: 44.605078

---

40 | **77 of 82** | **NE/185.8** | **98.9 / -0.97** | **2337 Parkedale Ave**
Brockville ON K6V3G9 | **EHS**

Order No: 20161111115
Status: C
Report Type: Standard Report
Report Date: 14-NOV-16
Date Received: 11-NOV-16
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .045
X: -75.6966
Y: 44.6051

---

40 | **78 of 82** | **NE/185.8** | **98.9 / -0.97** | **2337 Parkedale Avenue**
Brockville ON K6V 3G9 | **EHS**

Order No: 20180620197
Status: C
Report Type: Custom Report
Report Date: 27-JUN-18
Date Received: 20-JUN-18
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Topographic Maps

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.696267
Y: 44.605092

---

40 | **79 of 82** | **NE/185.8** | **98.9 / -0.97** | **TRILLIUM HEALTH CARE MANUFACTURING**
2337 Parkedale Avenue
Brockville ON K6V 5W5 | **GEN**

Generator No: ON2369500
Status: Registered
Approval Years: As of Apr 2020

PO Box No:
Country: Canada
Choice of Contact:

Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 263 A
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 263 L
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 261 T
Waste Class Desc: Pharmaceuticals

Waste Class: 268 C
Waste Class Desc: Amines

Waste Class: 112 C
Waste Class Desc: Acid solutions - containing heavy metals

Waste Class: 212 I
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 261 I
Waste Class Desc: Pharmaceuticals

Waste Class: 133 L
Waste Class Desc: Brine, chlor-alkali sludges

Waste Class: 212 L
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 312 P
Waste Class Desc: Pathological wastes

Waste Class: 241 B
Waste Class Desc: Halogenated solvents and residues

Waste Class: 241 H
Waste Class Desc: Halogenated solvents and residues

Waste Class: 114 C
Waste Class Desc: Other inorganic acid wastes

Waste Class: 213 I
Waste Class Desc: Petroleum distillates

Waste Class: 263 I
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 263 B
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 148 A
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 212 H

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Desc: Aliphatic solvents and residues

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 261 A
Waste Class Desc: Pharmaceuticals

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 262 L
Waste Class Desc: Detergents and soaps

Waste Class: 261 L
Waste Class Desc: Pharmaceuticals

Waste Class: 148 I
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 148 L
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 122 C
Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 146 T
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 121 C
Waste Class Desc: Alkaline slutions - containing heavy metals

Waste Class: 148 C
Waste Class Desc: Misc. wastes and inorganic chemicals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	80 of 82	NE/185.8	98.9 / -0.97	2337 Parkedale Avenue Brockville ON K6V 3G9	EHS

Order No: 20190531043
Status: C
Report Type: Custom Report
Report Date: 06-JUN-19
Date Received: 31-MAY-19
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.696188
Y: 44.605097

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	81 of 82	NE/185.8	98.9 / -0.97	Portion of 2337 Parkedale Ave Brockville ON K6V 3G9	EHS

Order No: 20200203116
Status: C
Report Type: Standard Report
Report Date: 06-FEB-20
Date Received: 03-FEB-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.6958526
Y: 44.60598

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	82 of 82	NE/185.8	98.9 / -0.97	Portion of 2337 Parkedale Ave Brockville ON K6V 3G9	EHS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Order No: 20200203116
Status: C
Report Type: Standard Report
Report Date: 06-FEB-20
Date Received: 03-FEB-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.6958526
Y: 44.60598

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
41	1 of 1	SSW/124.1	104.9 / 5.02	160 Stewart Blvd Brockville ON K6V4W6	EHS

Order No: 20160310023
Status: C
Report Type: Custom Report
Report Date: 15-MAR-16
Date Received: 10-MAR-16
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km):
X: -75.700374
Y: 44.598439

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	1 of 1	S/207.4	102.7 / 2.87	BROCKVILLE ON	WWIS

Well ID: 3616423
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z27135
Tag: A020635
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

PDF URL (Map):

Data Entry Status:
Data Src:
Date Received: 5/28/2005
Selected Flag: Yes
Abandonment Rec:
Contractor: 1844
Form Version: 3
Owner:
Street Name: 146-150 STEWART BOULEVARD
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 11320858
DP2BR: 14
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 4/13/2005
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:

Elevation: 102.453559
Elevrc:
Zone: 18
East83: 444505
North83: 4938554
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 933012814
Layer: 3
Color:
General Color:
Mat1: 15
Most Common Material: LIMESTONE
Mat2: 05
Mat2 Desc: CLAY
Mat3: 28
Mat3 Desc: SAND
Formation Top Depth:
Formation End Depth:
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933012813
Layer: 2
Color:
General Color:
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 4.3
Formation End Depth:
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933012812
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 12
Mat2 Desc: STONES
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 4.3
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933269523
Layer: 1
Plug From: 0
Plug To: 1

Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 963616423
Method Construction Code: 7
Method Construction: Diamond
Other Method Construction:

Pipe Information

Pipe ID: 11335713
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930862692
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 1.5
Casing Diameter: 5
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933412866
Layer: 1
Slot: 10
Screen Top Depth: 1.5
Screen End Depth: 4.3
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.5

Hole Diameter

Hole ID: 11539822
Diameter: 2
Depth From: 0
Depth To: 2.5
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 11539823
Diameter: 10
Depth From: 2.5
Depth To: 4.3
Hole Depth UOM: m
Hole Diameter UOM: cm

43 | 1 of 1 | S/210.1 | 102.7 / 2.87 | lot 12 con 1 ON | WWIS

Well ID: 3600645
Construction Date:
Primary Water Use: Commerical
Sec. Water Use: Domestic
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 1/8/1958
Selected Flag: Yes
Abandonment Rec:
Contractor: 1707
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY (ELIZABETHTOWN)
Site Info:
Lot: 012
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600645.pdf

Bore Hole Information

Bore Hole ID: 10214604
DP2BR: 3
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 11/15/1957
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 102.343261
Elevrc:
Zone: 18
East83: 444508.8
North83: 4938554
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676252
Layer: 1
Color:
General Color:
Mat1: 09
Most Common Material: MEDIUM SAND
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 3
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676253
Layer: 2
Color:
General Color:
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 3
Formation End Depth: 73
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600645
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763174
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930363008
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 73
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930363007
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 11
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600645
Pump Set At:
Static Level: 30
Final Level After Pumping: 35
Recommended Pump Depth:
Pumping Rate: 5

Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 2
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676554
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 71
Water Found Depth UOM: ft

---

44 **1 of 1** **WSW/209.9** **106.7 / 6.86** **ON** **WWIS**

Well ID: 3600482
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 2/28/1955
Selected Flag: Yes
Abandonment Rec:
Contractor: 3110
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600482.pdf

Bore Hole Information

Bore Hole ID: 10214441
DP2BR: 5
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 2/2/1955
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 107.152748
Elevrc:
Zone: 18
East83: 444114.7
North83: 4938753
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931675883
Layer: 2
Color:
General Color:
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 5
Formation End Depth: 51
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931675882
Layer: 1
Color:
General Color:
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 5
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600482
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763011
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362687
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 51
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362686
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 5
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600482
Pump Set At:
Static Level: 3
Final Level After Pumping: 3
Recommended Pump Depth:
Pumping Rate: 17
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 0
Pumping Duration MIN: 30
Flowing: No

Water Details

Water ID: 933676355
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 48
Water Found Depth UOM: ft

---

45 ***1 of 1*** ***S/154.1*** ***104.9 / 5.02*** ***BROCKVILLE ON*** ***WWIS***

Well ID: 7266770
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z207685
Tag: A194618
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:

Data Entry Status:
Data Src:
Date Received: 7/15/2016
Selected Flag: Yes
Abandonment Rec:
Contractor: 7529
Form Version: 7
Owner:
Street Name: 160 STEWART BLVD
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Clear/Cloudy:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/726\7266770.pdf

Bore Hole Information

Bore Hole ID: 1006143633
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 6/14/2016
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 105.270195
Elevrc:
Zone: 18
East83: 444424
North83: 4938548
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006162098
Layer: 1
Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL
Mat2:
Mat2 Desc:
Mat3: 77
Mat3 Desc: LOOSE
Formation Top Depth: 0
Formation End Depth: 4
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006162099
Layer: 2
Color: 2
General Color: GREY
Mat1: 16
Most Common Material: DOLOMITE
Mat2: 18
Mat2 Desc: SANDSTONE
Mat3: 73
Mat3 Desc: HARD
Formation Top Depth: 4
Formation End Depth: 20
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006162106
Layer: 1
Plug From: 0

Plug To: 9
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1006162105
Method Construction Code:
Method Construction:
Other Method Construction:

Pipe Information

Pipe ID: 1006162096
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006162103
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 10
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1006162104
Layer: 1
Slot: 10
Screen Top Depth: 10
Screen End Depth: 20
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.376

Results of Well Yield Testing

Pump Test ID: 1006162097
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 0
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing: No

Water Details

Water ID: 1006162102
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 16
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1006162101
Diameter: 5
Depth From: 4
Depth To: 20
Hole Depth UOM: ft
Hole Diameter UOM: inch

Hole Diameter

Hole ID: 1006162100
Diameter: 9
Depth From: 0
Depth To: 4
Hole Depth UOM: ft
Hole Diameter UOM: inch

46 | **1 of 1** | **NE/212.3** | **98.9 / -0.94** | **lot 11 con 1 BROCKVILLE ON** | **WWIS**

Well ID: 3616332
Construction Date:
Primary Water Use: Not Used
Sec. Water Use:
Final Well Status: Abandoned-Supply
Water Type:
Casing Material:
Audit No: Z19410
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 11/5/2004
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 7085
Form Version: 3
Owner:
Street Name: 2337 PARKDAFE RD
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 011
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/361\3616332.pdf

Bore Hole Information

Bore Hole ID: 11175678
DP2BR:
Spatial Status:
Code OB: _
Code OB Desc: No formation data
Open Hole:
Cluster Kind:

Elevation: 97.519828
Elevrc:
Zone: 18
East83: 444712
North83: 4939359
Org CS: UTM83
UTMRC: 3

Date Completed: 10/15/2004
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 933257320
Layer: 1
Plug From: 0
Plug To: 0.3
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933257321
Layer: 2
Plug From: 0.3
Plug To: 1.52
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933257322
Layer: 3
Plug From: 1.52
Plug To: 3.96
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 963616332
Method Construction Code:
Method Construction:
Other Method Construction:

Pipe Information

Pipe ID: 11184197
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930847441
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 3.96
Casing Diameter: 5.08
Casing Diameter UOM: cm

Casing Depth UOM: m

47 **1 of 1** **WSW/239.6** **106.9 / 7.03** **lot 13 con 1 ON** **WWIS**

Well ID: 3600648
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 6/13/1951
Selected Flag: Yes
Abandonment Rec:
Contractor: 3322
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY (ELIZABETHTOWN)
Site Info:
Lot: 013
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600648.pdf

Bore Hole Information

Bore Hole ID: 10214607
DP2BR: 5
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 5/2/1951
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 106.917877
Elevrc:
Zone: 18
East83: 444091.7
North83: 4938772
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676262
Layer: 3
Color: 2
General Color: GREY
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 15
Formation End Depth: 35
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676260
Layer: 1
Color:
General Color:
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676261
Layer: 2
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 5
Formation End Depth: 15
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600648
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763177
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930363014
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 35
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930363013
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 6
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600648
Pump Set At:
Static Level: 11
Final Level After Pumping: 20
Recommended Pump Depth:
Pumping Rate: 8
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 0
Pumping Duration MIN: 30
Flowing: No

Water Details

Water ID: 933676557
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 12
Water Found Depth UOM: ft

Water Details

Water ID: 933676558
Layer: 2
Kind Code: 1
Kind: FRESH
Water Found Depth: 33
Water Found Depth UOM: ft

48 ***1 of 1*** ***SW/56.0*** ***105.0 / 5.14*** ***lot 12 con 1 ON*** ***WWIS***

Well ID: 3600641
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:

Data Entry Status:
Data Src: 1
Date Received: 6/13/1951
Selected Flag: Yes
Abandonment Rec:
Contractor: 3322
Form Version: 1
Owner:
Street Name:
County: 36

Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Municipality: BROCKVILLE CITY (ELIZABETHTOWN)
Site Info:
Lot: 012
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600641.pdf

Bore Hole Information

Bore Hole ID: 10214600
DP2BR: 1
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 5/18/1951
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 105.779853
Elevrc:
Zone: 18
East83: 444176.7
North83: 4938597
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676244
Layer: 1
Color:
General Color:
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 1
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676245
Layer: 2
Color: 2
General Color: GREY
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 1
Formation End Depth: 52

Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600641
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763170
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930363001
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 52
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930363000
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 2
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600641
Pump Set At:
Static Level: 12
Final Level After Pumping: 20
Recommended Pump Depth:
Pumping Rate: 12
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 0
Pumping Duration MIN: 30
Flowing: No

Water Details

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Water ID: 933676550
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth:
Water Found Depth UOM: ft

---

49 *1 of 3* — *WSW/244.0* — *108.0 / 8.14* — *3050 Jefferson Drive, Brockville ON K6V 6N3* — *EHS*

Order No: 20051229033
Status: C
Report Type: Complete Report
Report Date: 1/11/2006
Date Received: 12/29/2005
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -75.705338
Y: 44.599117

---

49 *2 of 3* — *WSW/244.0* — *108.0 / 8.14* — *3050 Jefferson Drive, Brockville ON K6V 6N3* — *EHS*

Order No: 20080521018
Status: C
Report Type: Basic Report
Report Date: 5/29/2008
Date Received: 5/21/2008
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection: Jefferson Dr and Stewart Blvd
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -75.705014
Y: 44.59974

---

49 *3 of 3* — *WSW/244.0* — *108.0 / 8.14* — *3050 Jefferson Dr, Brockville ON K6V6N3* — *EHS*

Order No: 20150416006
Status: C
Report Type: Custom Report
Report Date: 21-APR-15
Date Received: 16-APR-15
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.705054
Y: 44.599756

---

50 *1 of 13* — *SW/99.8* — *105.9 / 6.00* — *TACO BELL OF CANADA, 3049 JEFFERSON DRIVE, BROCKVILLE CITY ON K6V 6N7* — *CA*

Certificate #: 8-4094-94-
Application Year: 94
Issue Date: 7/15/1994
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: CONDENSATE & FRYER EXHAUST HOODS
Contaminants: Odour/Fumes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Emission Control:

---

50 *2 of 13* — *SW/99.8* — *105.9 / 6.00* — *TRANSPORT TRUCK, 3049 JEFFERSON DRIVE SAVE-A-CENTRE PARKING LOT MOTOR VEHICLE (OPERATING FLUID), BROCKVILLE CITY ON K6V 6N7* — *SPL*

Ref No: 92608
Site No:
Incident Dt: 10/21/1993
Year:
Incident Cause: PIPE/HOSE LEAK
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: POSSIBLE
Nature of Impact: Soil contamination
Receiving Medium: LAND / WATER
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/21/1993
Dt Document Closed:
Incident Reason: EQUIPMENT FAILURE
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: NORTH-EAST TRANSPORT: 675L DIESEL FUEL TO PVMT & DITCH VIA STORM SEWER.
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 56101
Site Lot:
Site Conc:
Northing:
Easting: F.D. WORKS
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

50 *3 of 13* — *SW/99.8* — *105.9 / 6.00* — *GREAT ATLANTIC & PACIFIC CO. OF CDA.LTD., SAVE-A-CENTRE #903 3049 JEFFERSON STREET, BROCKVILLE ON K6V 6N3* — *GEN*

Generator No: ON0928742
Status:
Approval Years: 98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 6571
SIC Description: CAMERA/PHOTO. SUPPLY

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

---

50 *4 of 13* — *SW/99.8* — *105.9 / 6.00* — *PHARMACY, THE, 3049 TEFFERSON STREET, BROCKVILLE ON KV6 6N3* — *GEN*

Generator No: ON2427300
Status:
Approval Years: 98
Contam. Facility:
MHSW Facility:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Code: 6031
SIC Description: PHARMACIES

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

50 **5 of 13** **SW/99.8** **105.9 / 6.00** **PHARMACY, THE** **GEN**
3049 JEFFERSON STREET
BROCKVILLE ON K6V 6N3

Generator No: ON2371815
Status:
Approval Years: 99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 6031
SIC Description: PHARMACIES

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

50 **6 of 13** **SW/99.8** **105.9 / 6.00** **PHARMACY, (SEE & USE ON2371813)** **GEN**
3049 TEFFERSON STREET
BROCKVILLE ON KV6 6N3

Generator No: ON2427300
Status:
Approval Years: 99,00
Contam. Facility:
MHSW Facility:
SIC Code: 6031
SIC Description: PHARMACIES

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

50 **7 of 13** **SW/99.8** **105.9 / 6.00** **THE GREAT ATLANTIC & PACIFIC CO. OF CANADA, LTD.** **GEN**
3049 JEFFERSON STREET
BROCKVILLE ON K6V 6N3

Generator No: ON2371815
Status:
Approval Years: 02,03,04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

50 **8 of 13** **SW/99.8** **105.9 / 6.00** **Save-A-Center parking lot<UNOFFICIAL>** **SPL**
3049 Jefferson Drive
Brockville ON K6V 6N7

Ref No: 8011-5TSTQ3
Site No:
Incident Dt: 11/30/2003
Year:
Incident Cause: Discharge Or Bypass To A Watercourse
Incident Event:
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Possible
Nature of Impact: Soil Contamination; Surface Water Pollution
Receiving Medium: Land & Water
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 11/30/2003
Dt Document Closed:
Incident Reason: Unknown - Reason not determined
Site Name: SAVE-A-CENTER<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Brockville, 20-L diesel to gnd and catchbasin
Contaminant Qty: 20 L

Discharger Report:
Material Group: Oil
Health/Env Conseq:
Client Type:
Sector Type: Other
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office: Kingston
Site Postal Code:
Site Region: Eastern
Site Municipality: Brockville
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Spills
Source Type:

---

50 **9 of 13** **SW/99.8** **105.9 / 6.00** **Hydro One Networks Inc.** **SPL**
3049 Jefferson Dr
Brockville ON K6V 6N7

Ref No: 2783-7EWJAH
Site No:
Incident Dt:
Year:
Incident Cause: Other Discharges
Incident Event:
Contaminant Code: 15
Contaminant Name: TRANSFORMER OIL (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Confirmed
Nature of Impact: Soil Contamination
Receiving Medium:
Receiving Env:
MOE Response: No Field Response
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/23/2008
Dt Document Closed: 3/17/2009
Incident Reason: Equipment Failure - Malfunction of system components
Site Name: Transformer<UNOFFICIAL>
Site County/District:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office: Kingston - District
Site Postal Code:
Site Region:
Site Municipality: Brockville
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Land Spills
Source Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Geo Ref Meth:
Incident Summary: Hydro One: 6 L non-PCB transformer oil to ground
Contaminant Qty: 6 L

---

50 **10 of 13** **SW/99.8** **105.9 / 6.00** **METRO ONTARIO INC O/A METRO/FOOD** **PES**
BASICS # 921
3049 JEFFERSON STREET
BROCKVILLE ON K6V6N3

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

50 **11 of 13** **SW/99.8** **105.9 / 6.00** **METRO ONTARIO INC O/A METRO/FOOD** **PES**
BASICS # 921
3049 Jefferson Street
Brockville ON K6V 6N3

Detail Licence No: 23-01-15185-0
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: LIMITED
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

50 **12 of 13** **SW/99.8** **105.9 / 6.00** **THE GREAT ATLANTIC & PACIFIC COMPANY OF CANAD** **NPRI**
3049 JEFFERSON Drive
BROCKVILLE ON K6V6N7

NPRI ID: 8800001726
Other ID:
No Other ID:

Org ID:
Submit Date:
Last Modified:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Track ID:
Report ID:
Report Type:
Rpt Type ID:
Report Year: 2004
Not-Current Rpt?:
Yr of Last Filed Rpt:
Fac ID:
Fac Name: A & P - 3049 JEFFERSON DR.
Fac Address1:
Fac Address2:
Fac Postal Zip:
Facility Lat:
Facility Long:
DLS (Last Filed Rpt):
Facility DLS:
Datum:
Facility Cmnts:
URL:
No of Empl.: 20
Parent Co.:
No Parent Co.:
Pollut Prev Cmnts:
Stacks:
No of Stacks:
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 53
NAICS 2 Description: Real Estate and Rental and Leasing
NAICS Code (4 digit): 5311
NAICS 4 Description: Lessors of Real Estate
NAICS Code (6 digit): 531120
NAICS 6 Description: Lessors of Non-Residential Buildings (except Mini-Warehouses)

Contact ID:
Cont Type: MED
Contact Title: Mr.
Cont First Name: KIRK
Cont Last Name: SHIPLO
Contact Position: Director Maintenence
Contact Fax:
Contact Ph.:
Cont Area Code: 416
Contact Tel.: 2346979
Contact Ext.:
Cont Fax Area Cde:
Contact Fax:
Contact Email: kshiplo@aptea.com
Latitude:
Longitude:
UTM Zone:
UTM Northing:
UTM Easting:
Waste Streams:
No Streams:
Waste Off Sites:
No Off Sites:
Shutdown:
No of Shutdown:

Substance Release Report

CAS No: 7446-09-5
Report ID:
Rpt Period: 2004
Subst Released: Sulphur dioxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M08
Report ID:
Rpt Period: 2004
Subst Released: PM - Total Particulate Matter
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 10024-97-2
Report ID:
Rpt Period: 2004
Subst Released: Nitrous oxide
Air:
Water:
Land:

Total Releases:
Units: tonnes

CAS No: 630-08-0
Report ID:
Rpt Period: 2004
Subst Released: Carbon monoxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 74-82-8
Report ID:
Rpt Period: 2004
Subst Released: Methane
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M10
Report ID:
Rpt Period: 2004
Subst Released: PM2.5 - Particulate Matter <= 2.5 Microns
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 11104-93-1
Report ID:
Rpt Period: 2004
Subst Released: Nitrogen oxides (expressed as NO2)
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M16
Report ID:
Rpt Period: 2004
Subst Released: Volatile Organic Compounds (VOCs)
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 124-38-9
Report ID:
Rpt Period: 2004
Subst Released: Carbon dioxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 811-97-2
Report ID:
Rpt Period: 2004

Subst Released: HFC-134a Hydrofluorocarbon
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M09
Report ID:
Rpt Period: 2004
Subst Released: PM10 - Particulate Matter <= 10 Microns
Air:
Water:
Land:
Total Releases:
Units: tonnes

---

50 | **13 of 13** | **SW/99.8** | **105.9 / 6.00** | **METRO ONTARIO INC O/A METRO/FOOD BASICS # 921 3049 JEFFERSON STREET BROCKVILLE ON K6V6N3** | **PES**

Detail Licence No:
Licence No: 15185
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class: 01
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

51 | **1 of 1** | **NE/219.3** | **96.9 / -2.95** | **ON** | **AST**

OGF ID: 250552160
Sub Type: Petroleum Tank
Sub Type No: 1332
Location Accuracy: Within 10 metres
Sensitivity Class: Non-Sensitive
Sensitivity Date: 20070106
Sensitivity Rationale: No Restriction Needed
Verification Flag: Verified
Verification Date: 19971023
Business Effective Dt Flag: Estimated
Business Effective Dt: 19971023
Sys Calcu Area: 125.665
Sys Calcu Length: 0.0
User Calc Metric: 0.0
Effective Date/Time: 19971023

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	1 of 2	WSW/218.8	109.6 / 9.70	lot 14 con 1 BROCKVILLE ON	WWIS

Well ID: 3616334
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z20806
Tag: A001600
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

PDF URL (Map):

Data Entry Status:
Data Src: 1
Date Received: 11/16/2004
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 1844
Form Version: 3
Owner:
Street Name: STEWART ST
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 014
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 11175680
DP2BR:
Spatial Status:
Code OB: _
Code OB Desc: No formation data
Open Hole:
Cluster Kind:
Date Completed: 9/30/2004
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 109.671241
Elevrc:
Zone: 18
East83: 444000
North83: 4938650
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 933257324
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 963616334
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Pipe ID: 11184199
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930847444
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 1.2
Casing Diameter: 50
Casing Diameter UOM: mm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933409735
Layer: 1
Slot: 10
Screen Top Depth: 1.2
Screen End Depth: 4.3
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: mm
Screen Diameter: 50

Water Details

Water ID: 934053558
Layer: 1
Kind Code:
Kind:
Water Found Depth: 3
Water Found Depth UOM: m

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
52	2 of 2	WSW/218.8	109.6 / 9.70	BROCKVILLE ON	WWIS

Well ID: 3616068
Construction Date:
Primary Water Use: Not Used
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z05683
Tag: A001600
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 1/26/2004
Selected Flag: Yes
Abandonment Rec:
Contractor: 1844
Form Version: 3
Owner:
Street Name: STEWART STREET
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/361\3616068.pdf

Bore Hole Information

Bore Hole ID:	11106265	***Elevation:***	109.671241
DP2BR:	8	***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:	r	***East83:***	444000
Code OB Desc:	Bedrock	***North83:***	4938650
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	5
Date Completed:	1/15/2004	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932959420
Layer:	2
Color:	2
General Color:	GREY
Mat1:	15
Most Common Material:	LIMESTONE
Mat2:	71
Mat2 Desc:	FRACTURED
Mat3:	
Mat3 Desc:	
Formation Top Depth:	2.5
Formation End Depth:	4.3
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	932959419
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0
Formation End Depth:	2.5
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933250109
Layer:	1
Plug From:	0
Plug To:	1
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	963616068
Method Construction Code:	5
Method Construction:	Air Percussion
Other Method Construction:	

Pipe Information

Pipe ID:	11112303
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930839188
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	1.2
Casing Diameter:	50
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	933408114
Layer:	1
Slot:	010
Screen Top Depth:	1.2
Screen End Depth:	4.3
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	50

Water Details

Water ID:	934047756
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	3
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	11112302
Diameter:	
Depth From:	0
Depth To:	
Hole Depth UOM:	m
Hole Diameter UOM:	cm

53	***1 of 1***	***WSW/199.7***	***108.9 / 9.01***	***glidden paint, store 835 7748 kent blvd, #8***	***GEN***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

brockville ON K6V 7J9

Generator No: ON5012928
Status:
Approval Years: 04
Contam. Facility:
MHSW Facility:
SIC Code: 444120
SIC Description: Paint and Wallpaper Stores

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

---

54 1 of 2 WSW/199.6 108.9 / 9.01 GLIDDEN PAINTS
KENT BLVD. RETAIL OUTLET
BROCKVILLE CITY ON SPL

Ref No: 194114
Site No:
Incident Dt: 1/31/2001
Year:
Incident Cause: OTHER CAUSE (N.O.S.)
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Possible
Nature of Impact: Soil contamination
Receiving Medium: Land
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 1/31/2001
Dt Document Closed:
Incident Reason: ERROR
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: GLIDDEN PAINTS:SKID OF PAINT, THINNER,EPOXY FELL OF TRUCK, FD ON SITE
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved: FIRE DEPARTMENT
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 56101
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

54 2 of 2 WSW/199.6 108.9 / 9.01 GLIDDEN PAINTS & WALL PAPER
7748 KENT ROAD BLVD., UNIT 8
BROCKVILLE ON K6V 7J9 GEN

Generator No: ON0003997
Status:
Approval Years: 00,01
Contam. Facility:
MHSW Facility:
SIC Code: 3751
SIC Description: PAINT & VARNISH IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

---

55 1 of 1 SW/16.0 104.9 / 5.02 mile marker 704 Hwy 401 westbound
Augusta ON SPL

Ref No: 2358-BCE9XH
Site No: NA
Incident Dt: 5/22/2019
Year:
Incident Cause:
Incident Event: Collision/Accident
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: 1202
Environment Impact:
Nature of Impact:
Receiving Medium:
Receiving Env: Land
MOE Response: No
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/22/2019
Dt Document Closed:
Incident Reason: Road Conditions
Site Name: Ditch<UNOFFICIAL>
Site County/District: United Counties of Leeds and Grenville
Site Geo Ref Meth:
Incident Summary: Hwy 401 W, Augusta - TT accident, diesel to ditch
Contaminant Qty: 100 L

Discharger Report:
Material Group:
Health/Env Conseq: 2 - Minor Environment
Client Type:
Sector Type: Miscellaneous Industrial
Agency Involved:
Nearest Watercourse:
Site Address: mile marker 704 Hwy 401 westbound
Site District Office: Kingston - District
Site Postal Code:
Site Region: Eastern
Site Municipality: Augusta
Site Lot:
Site Conc:
Northing: 4938466.49
Easting: 444148.77
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Highway Spills (usually highway accidents)
Source Type: Truck - Transport/Hauling

---

56 1 of 1 WSW/151.0 107.8 / 7.97 7777 Kent Boulevard
Brockville ON K6V 6N7 EHS

Order No: 20120213023
Status: C
Report Type: Custom Report
Report Date: 2/17/2012 11:59:25 AM
Date Received: 2/13/2012 11:57:05 AM
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -75.705488
Y: 44.598237

---

57 1 of 1 E/213.0 94.1 / -5.71 P.U.C. BROCKVILLE
MAPLE AVE./PARK ST.
BROCKVILLE CITY ON CA

Certificate #: 7-1076-92-
Application Year: 92
Issue Date: 11/16/1992
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	1 of 57	SSW/243.3	103.3 / 3.45	BLACK & DECKER CANADA INC. 100 CENTRAL AVE. BROCKVILLE CITY ON	CA

Certificate #:	8-4063-86-
Application Year:	86
Issue Date:	11/7/1986
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	ONE BAYCO MODEL BB-78
Contaminants:	Suspended Particulate Matter, Nitrogen Oxides
Emission Control:	No Controls

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	2 of 57	SSW/243.3	103.3 / 3.45	BLACK & DECKER CANADA INC. 100 CENTRAL AVE. *** BROCKVILLE CITY ON	CA

Certificate #:	8-4062-88-
Application Year:	88
Issue Date:	6/22/1988
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	PAINT GENERATOR
Emission Control:	No Controls

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	3 of 57	SSW/243.3	103.3 / 3.45	BLACK & DECKER CANADA INC. 100 CENTRAL AVENUE BROCKVILLE CITY ON	CA

Certificate #:	8-4105-88-
Application Year:	88
Issue Date:	1/27/1989
Approval Type:	Industrial air
Status:	Approved in 1989
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	4 of 57	SSW/243.3	103.3 / 3.45	BLACK & DECKER CANADA INC. 100 CENTRAL AVE. BROCKVILLE CITY ON	CA

Certificate #:	8-4058-87-
Application Year:	87
Issue Date:	8/7/1987

Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	VENTING
Contaminants:	Other Contaminant
Emission Control:	No Controls

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	5 of 57	SSW/243.3	103.3 / 3.45	BLACK & DECKER CANADA INC. 100 CENTRAL AVENUE BROCKVILLE CITY ON	CA

Certificate #:	8-4097-88-
Application Year:	88
Issue Date:	3/15/1989
Approval Type:	Industrial air
Status:	Approved in 1989
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	PLANT REARRANGEMENT
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	6 of 57	SSW/243.3	103.3 / 3.45	BLACK & DECKER CANADA INC. 100 CENTRAL AVE. BROCKVILLE CITY ON	CA

Certificate #:	8-4046-90-
Application Year:	90
Issue Date:	5/18/1990
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	INSTAL FUME HOOD/CABINET IN TEST LAB
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	7 of 57	SSW/243.3	103.3 / 3.45	BLACK & DECKER CANADA INC. 100 CENTRAL AVENUE BROCKVILLE CITY ON	CA

Certificate #:	8-4152-93-
Application Year:	93
Issue Date:	2/2/1994
Approval Type:	Industrial air
Status:	Approved in 1994
Application Type:	
Client Name:	
Client Address:	
Client City:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client Postal Code:
Project Description: PAINT COATING FUME EXHAUST
Contaminants: Ethylene Glycol Butyl Ether (Butyl Cellosolve)
Emission Control: No Controls

---

58 **8 of 57** **SSW/243.3** **103.3 / 3.45** **BLACK AND DECKER CANADA INC** **NPCB**
100 CENTRAL AVE
BROCKVILLE ON K6V 5W6

Company Code: F1450
Industry:
Site Status:
Transaction Date: 1/29/1996
Inspection Date:

---

58 **9 of 57** **SSW/243.3** **103.3 / 3.45** **BLACK & DECKER CANADA INC.** **SCT**
100 CENTRAL AVE W
BROCKVILLE ON K6V 4N8

Established: 1957
Plant Size (ft²): 500000
Employment: 600

--Details--
Description: LAWN AND GARDEN TRACTORS, AND HOME LAWN AND GARDEN EQUIPMENT
SIC/NAICS Code: 3524

Description: POWER-DRIVEN HAND TOOLS
SIC/NAICS Code: 3546

Description: ELECTRIC HOUSEWARES AND FANS
SIC/NAICS Code: 3634

---

58 **10 of 57** **SSW/243.3** **103.3 / 3.45** **BLACK & DECKER CANADA (1989) INC.** **CA**
100 CENTRAL AVENUE
BROCKVILLE CITY ON

Certificate #: 8-4043-97-
Application Year: 97
Issue Date: 5/7/1997
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: VENT FOR MOTOR ARMATURE TRICKLE MACHINE
Contaminants: Styrene
Emission Control:

---

58 **11 of 57** **SSW/243.3** **103.3 / 3.45** **BLACK AND DECKER** **SPL**
100 CENTRAL AVENUE BROCKVILLE PLANT
100 CENTRAL AVENUE
BROCKVILLE CITY ON

Ref No: 150496 **Discharger Report:**
Site No: **Material Group:**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Dt: 12/18/1997
Year:
Incident Cause: OTHER CONTAINER LEAK
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: NOT ANTICIPATED
Nature of Impact:
Receiving Medium: LAND
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 12/18/1997
Dt Document Closed:
Incident Reason: ERROR
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: BLACK & DECKER-25 LITERS HYDRAULIC OIL TO ASPHALT,CONTAINED,CLEANED-UP.
Contaminant Qty:

Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 56101
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

58 **12 of 57** **SSW/243.3** **103.3 / 3.45** **BLACK & DECKER CANADA (1989) INC.** **CA**
100 CENTRAL AVENUE
BROCKVILLE CITY ON

Certificate #: 8-4007-99-
Application Year: 99
Issue Date: 3/12/1999
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: GAS FIRED HEATERS FOR COMFORT HEATING
Contaminants:
Emission Control:

---

58 **13 of 57** **SSW/243.3** **103.3 / 3.45** **BLACK AND DECKER CANADA INC** **NPCB**
100 CENTRAL AVE CENTRAL AVE
BROCKVILLE ON K6V 5W6

Company Code: F1274
Industry:
Site Status:
Transaction Date:
Inspection Date:

--Details--
Label:
Serial No.:
PCB Type/Code:
Location:
Item/State:
No. of Items:
Manufacturer:
Status: In-Storage

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Contents:					

58 | 14 of 57 | SSW/243.3 | 103.3 / 3.45 | CAMOLOR
100 CENTRAL AVENUE
BROCKVILLE CITY ON | SPL

Ref No: 219603
Site No:
Incident Dt: 1/10/2002
Year:
Incident Cause: OTHER CAUSE (N.O.S.)
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: POSSIBLE
Nature of Impact: Soil contamination
Receiving Medium: LAND
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 1/11/2002
Dt Document Closed:
Incident Reason: ERROR
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: CAMOLOR: HALF LITRE OF PAINT DOWN THE DRAIN, CLEANED.
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 56101
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

58 | 15 of 57 | SSW/243.3 | 103.3 / 3.45 | BLACK & DECKER CAN. INC.
100 CENTRAL AVE.
BROCKVILLE CITY ON | CA

Certificate #: 8-4032-85-000
Application Year: 85
Issue Date: 4/2/87
Approval Type: Industrial air
Status: Application Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: RELOCATION OF SILVERSTONING & PAINTING
Contaminants:
Emission Control:

58 | 16 of 57 | SSW/243.3 | 103.3 / 3.45 | BLACK AND DECKER CANADA INC.
100 CENTRAL AVE.
BROCKVILLE CITY ON | CA

Certificate #: 8-4032-85-000
Application Year: 85
Issue Date: 3/22/89
Approval Type: Industrial air
Status: Application Cancelled
Application Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Client Name:					
Client Address:					
Client City:					
Client Postal Code:					
Project Description:					
Contaminants:					
Emission Control:					

58 | 17 of 57 | SSW/243.3 | 103.3 / 3.45 | BLACK & DECKER
100 CENTRAL AVE.
BROCKVILLE CITY ON | CA

Certificate #: 8-4058-85-000
Application Year: 85
Issue Date: 4/2/87
Approval Type: Industrial air
Status: Application Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: MODIFICATION TO EXIT. COMBUSTION FAC.
Contaminants:
Emission Control:

58 | 18 of 57 | SSW/243.3 | 103.3 / 3.45 | BLACK & DECKER
100 CENTRAL AVE.
BROCKVILLE CITY ON | CA

Certificate #: 8-4058-85-000
Application Year: 85
Issue Date: 3/22/89
Approval Type: Industrial air
Status: Application Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

58 | 19 of 57 | SSW/243.3 | 103.3 / 3.45 | 100 Central Avenue, P.O. Box 126
Brockville ON | CA

Certificate #: 8076-4HNMR2
Application Year: 00
Issue Date: 3/23/00
Approval Type: Industrial air
Status: Approved
Application Type: New Certificate of Approval
Client Name: Camalor Mfg. Inc.
Client Address: 100 Central Avenue, P.O. Box 126
Client City: Brockville
Client Postal Code: N6V 5V2
Project Description: This is an application for an air certificate of approval to allow for emissions produced from welding, painting and drying processes to be discharged into the atmosphere via 9 stacks.
Contaminants:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Emission Control:					

58 | 20 of 57 | SSW/243.3 | 103.3 / 3.45 | Black & Decker Canada (1989) Inc.
100 CENTRAL AVENUE, BROCKVILLE CITY
CITY OF BROCKVILLE
ON | EBR

EBR Registry No: IA7E0456
Ministry Ref No: 8404397 19970325
Notice Type: Instrument Decision
Notice Stage: 800471891
Notice Date: May 13, 1997
Proposal Date: April 04, 1997
Year: 1997
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Black & Decker Canada (1989) Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 100 Central Avenue, Brockville Ontario, K6V 5W6
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

100 CENTRAL AVENUE, BROCKVILLE CITY CITY OF BROCKVILLE

58 | 21 of 57 | SSW/243.3 | 103.3 / 3.45 | Camalor Mfg. Inc.
100 Central Avenue, P.O. Box 126 Brockville
Ontario N6V 5V2 CITY OF BROCKVILLE
ON | EBR

EBR Registry No: IA00E0328
Ministry Ref No: 7383-4GDRAM
Notice Type: Instrument Decision
Notice Stage: 800475961
Notice Date: March 28, 2000
Proposal Date: February 11, 2000
Year: 2000
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Camalor Mfg. Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 100 Central Avenue, P.O. Box 126, Brockville Ontario, N6V 5V2
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

100 Central Avenue, P.O. Box 126 Brockville Ontario N6V 5V2 CITY OF BROCKVILLE

58 | 22 of 57 | SSW/243.3 | 103.3 / 3.45 | BLACK AND DECKER CANADA INC.
100 CENTRAL AVE. | REC

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BROCKVILLE ON	

Rec Op Div:
Co Admin:
Phone No Admin:
Rec Div:
Rec Op Name:
Choice of Contact:
Site Bldg:
Site PO Box:
Receiver #: 401-91A005
Facility Type: TRANSFER STATION
Approval Yrs: 90,92,94,95,96,97,98,99,00,01,02,03,04,05,06,07,08

--Details--
Waste Code: 243
Waste Description: PCB'S

58 | 23 of 57 | SSW/243.3 | 103.3 / 3.45 | BLACK AND DECKER CANADA INC
100 CENTRAL AVE
BROCKVILLE ON K6V 5W6 | OPCB

Year: 1999
Site Number: 40191A005
Name Owner:
Additional Site Information:

58 | 24 of 57 | SSW/243.3 | 103.3 / 3.45 | BLACK AND DECKER CANADA INC
100 CENTRAL AVE
BROCKVILLE ON K6V 5W6 | OPCB

Year: 2000
Site Number: 40191A005
Name Owner:
Additional Site Information:

58 | 25 of 57 | SSW/243.3 | 103.3 / 3.45 | BLACK AND DECKER CANADA INC
100 CENTRAL AVE
BROCKVILLE ON K6V 5W6 | OPCB

Year: 2003
Site Number: 40191A005
Name Owner:
Additional Site Information:

58 | 26 of 57 | SSW/243.3 | 103.3 / 3.45 | BLACK AND DECKER CANADA INC
100 CENTRAL AVE
BROCKVILLE ON K6V 5W6 | OPCB

Year: 1998
Site Number: 40191A005
Name Owner:
Additional Site Information:

--Details--
Quantity: 5.00

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Address Site:
Description: Number of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 1000.00
Address Site:
Description: Calculated Weight (Kg) of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 6.00
Address Site:
Description: Number of Capacitors with High Level PCBs (>1000 ppm)

Quantity: 1900.00
Address Site:
Description: Weight of Capacitors with High Level PCBs (>1000 ppm) kg

Quantity: 1.00
Address Site:
Description: Number of Drums of Other Material with High Level PCBs (>1000 ppm)

Quantity: 215.00
Address Site:
Description: Weight of Drums of Other Material with High Level PCBs (>1000 ppm) kg

---

58	27 of 57	SSW/243.3	103.3 / 3.45	BLACK AND DECKER CANADA INC 100 CENTRAL AVE BROCKVILLE ON K6V 5W6	OPCB

Year: 1995
Site Number: 40191A005
Name Owner:
Additional Site Information:

--Details--
Quantity: 5.00
Address Site:
Description: Number of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 1000.00
Address Site:
Description: Weight of Drums of Ballasts with High Level PCBs (>1000 ppm) kg

Quantity: 6.00
Address Site:
Description: Number of Capacitors with High Level PCBs (>1000 ppm)

Quantity: 1900.00
Address Site:
Description: Weight of Capacitors with High Level PCBs (>1000 ppm) kg

Quantity: 1.00
Address Site:
Description: Number of Drums of Other Material with High Level PCBs (>1000 ppm)

Quantity: 215.00
Address Site:
Description: Weight of Drums of Other Material with High Level PCBs (>1000 ppm) kg

---

58	28 of 57	SSW/243.3	103.3 / 3.45	BLACK & DECKER CANADA INC. 100 CENTRAL AVE. W. BROCKVILLE ON K6V 4N8	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON0036000
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 3063
SIC Description: HAND TOOL/IMPLEMENT

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

58	29 of 57	SSW/243.3	103.3 / 3.45	BLACK & DECKER CANADA INC. 05-043 100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	GEN

Generator No: ON0036000
Status:
Approval Years: 92,93,94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 3063
SIC Description: HAND TOOL/IMPLEMENT

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

58	30 of 57	SSW/243.3	103.3 / 3.45	BLACK & DECKER CANADA INC 100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	GEN

Generator No: ON0036000
Status:
Approval Years: 97
Contam. Facility:
MHSW Facility:
SIC Code: 3063
SIC Description: HAND TOOL/IMPLEMENT

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 243
Waste Class Desc: PCB'S

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

58	31 of 57	SSW/243.3	103.3 / 3.45	BLACK & DECKER CANADA INC. 100 CENTRAL AVENUE BROCKVILLE ON K6V 5W6	GEN

Generator No: ON0036000
Status:
Approval Years: 98,99,00,01,02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 3063
SIC Description: HAND TOOL/IMPLEMENT

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 113
Waste Class Desc: ACID WASTE - OTHER METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 148

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

---

58 **32 of 57** **SSW/243.3** **103.3 / 3.45**

CAMALOR MFG. INC.
100 CENTRAL AVENUE
BROCKVILLE ON K6V 5W6

GEN

Generator No: ON2451400
Status:
Approval Years: 99,00,01,02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 3999
SIC Description: OTHER MANU. PROD.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 268
Waste Class Desc: AMINES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

58 **33 of 57** **SSW/243.3** **103.3 / 3.45**

100 Central Avenue
Brockville ON

EHS

Order No: 20040601004
Status: C
Report Type: Site Report
Report Date: 6/2/04
Date Received: 6/1/04
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -75.700282
Y: 44.595872

---

58 **34 of 57** **SSW/243.3** **103.3 / 3.45**

BLACK AND DECKER CANADA INC
100 CENTRAL AVE
BROCKVILLE ON K6V 5W6

OPCB

Year: 2004
Site Number: 40191A005
Name Owner:
Additional Site Information:

---

58 **35 of 57** **SSW/243.3** **103.3 / 3.45**

Camalor Mfg. Inc.
100 Central Ave W
Brockville ON K6V 4N8

SCT

Established: 01-JAN-98
Plant Size (ft²): 43000
Employment:

--Details--
Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
SIC/NAICS Code: 332999

Description: Commercial and Industrial Machinery and Equipment (except Automotive and Electronic) Repair and Maintenance
SIC/NAICS Code: 811310

Description: Paint and Coating Manufacturing
SIC/NAICS Code: 325510

Description: Steel Wire Drawing
SIC/NAICS Code: 331222

Description: All Other Specialty Trade Contractors
SIC/NAICS Code: 238990

Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

---

58 **36 of 57** **SSW/243.3** **103.3 / 3.45**

BLACK AND DECKER CANADA INC
100 CENTRAL AVE W
BROCKVILLE ON K6V 4N8

NPCB

Company Code: F1297
Industry: UNDEFINED
Site Status:
Transaction Date:
Inspection Date:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	37 of 57	SSW/243.3	103.3 / 3.45	Black & Decker Canada Inc. 100 Central Avenue Brockville, United Counties of Leeds and Grenville K6V 5W6 CITY OF BROCKVILLE ON	EBR

EBR Registry No: 011-0343
Ministry Ref No: 0011-867LE2
Notice Type: Instrument Decision
Notice Stage: 803581791
Notice Date: January 31, 2011
Proposal Date: June 21, 2010
Year: 2010
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Black & Decker Canada Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 100 Central avenue, Brockville Ontario, Canada K6V 5W6
Comment Period:
URL:

Site Location Details:

100 Central Avenue Brockville, United Counties of Leeds and Grenville K6V 5W6 CITY OF BROCKVILLE

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	38 of 57	SSW/243.3	103.3 / 3.45	100 Central Ave W Brockville ON K6V 4N8	EHS

Order No: 20100519003
Status: C
Report Type: Custom Report
Report Date: 5/31/2010
Date Received: 5/19/2010
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Title Searches
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -75.7021
Y: 44.596643

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	39 of 57	SSW/243.3	103.3 / 3.45	Black & Decker Canada Inc. 100 Central Ave Brockville ON	CA

Certificate #: 1155-8DAQY6
Application Year: 2011
Issue Date: 1/24/2011
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	40 of 57	SSW/243.3	103.3 / 3.45	BLACK & DECKER CANADA INC. 100 CENTRAL AVENUE BROCKVILLE ON	GEN

Generator No: ON0036000
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 493110
SIC Description: General Warehousing and Storage
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 113
Waste Class Desc: ACID WASTE - OTHER METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
58	41 of 57	SSW/243.3	103.3 / 3.45	CAMALOR MFG. INC. 100 CENTRAL AVENUE BROCKVILLE ON	GEN

Generator No: ON2451400
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 332999
SIC Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

58 **42 of 57** **SSW/243.3** **103.3 / 3.45** **100 Central Avenue Brockville ON** **EHS**

Order No: 20120821022
Status: C
Report Type: Standard Report
Report Date: 29-AUG-12
Date Received: 21-AUG-12
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.700356
Y: 44.596837

---

58 **43 of 57** **SSW/243.3** **103.3 / 3.45** **BLACK & DECKER CANADA INC. 100 CENTRAL AVENUE BROCKVILLE ON** **GEN**

Generator No: ON0036000
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 493110
SIC Description: General Warehousing and Storage

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 113
Waste Class Desc: ACID WASTE - OTHER METALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

---

58 **44 of 57** **SSW/243.3** **103.3 / 3.45** **CAMALOR MFG. INC. 100 CENTRAL AVENUE BROCKVILLE ON** **GEN**

Generator No: ON2451400
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 332999
SIC Description: All Other Miscellaneous Fabricated Metal Product Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

---

58 **45 of 57** **SSW/243.3** **103.3 / 3.45** **CAMALOR MFG. INC. 100 CENTRAL AVENUE BROCKVILLE ON** **GEN**

Generator No: ON2451400
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 332999
SIC Description: All Other Miscellaneous Fabricated Metal Product Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

58 **46 of 57** **SSW/243.3** **103.3 / 3.45** **BLACK & DECKER CANADA INC. 100 CENTRAL AVENUE BROCKVILLE ON** **GEN**

Generator No: ON0036000
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 493110
SIC Description: General Warehousing and Storage

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 113
Waste Class Desc: ACID WASTE - OTHER METALS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

---

58 ***47 of 57*** ***SSW/243.3*** ***103.3 / 3.45*** ***CAMALOR MFG. INC.***
100 CENTRAL AVENUE
BROCKVILLE ON K6V 5W6 ***GEN***

Generator No: ON2451400
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 332999
SIC Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

58 ***48 of 57*** ***SSW/243.3*** ***103.3 / 3.45*** ***BLACK & DECKER CANADA INC.***
100 CENTRAL AVENUE
BROCKVILLE ON K6V 5W6 ***GEN***

Generator No: ON0036000
PO Box No:

Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 493110
SIC Description: General Warehousing and Storage
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 113
Waste Class Desc: ACID WASTE - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

---

58 ***49 of 57*** ***SSW/243.3*** ***103.3 / 3.45*** ***100 Central Ave W***
Brockville ON K6V4N8 ***EHS***

Order No: 20140703072
Status: C
Report Type: Standard Express Report
Report Date: 03-JUL-14
Date Received: 03-JUL-14
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Topographic Maps
Nearest Intersection:
Municipality:
Client Prov/State: FL
Search Radius (km): .25
X: -75.701165
Y: 44.596321

---

58 ***50 of 57*** ***SSW/243.3*** ***103.3 / 3.45*** ***CAMALOR MFG. INC.***
100 CENTRAL AVENUE
BROCKVILLE ON ***GEN***

Generator No: ON2451400
Status:
Approval Years: 2013
Contam. Facility:
PO Box No:
Country:
Choice of Contact:
Co Admin:

MHSW Facility: **Phone No Admin:**
SIC Code: 332999
SIC Description: ALL OTHER MISCELLANEOUS FABRICATED METAL PRODUCT MANUFACTURING

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

---

58 **51 of 57** **SSW/243.3** **103.3 / 3.45** **Black & Decker Canada Inc.**
100 Central Ave
Brockville ON K6V 5W6 **ECA**

Approval No: 1155-8DAQY6
Approval Date: 2011-01-24
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Cataraqui
Approval Type: ECA-AIR
Project Type: AIR
Address: 100 Central Ave
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/0011-867LE2-14.pdf

MOE District: Kingston
City:
Longitude: -75.70206999999999
Latitude: 44.595974
Geometry X:
Geometry Y:

---

58 **52 of 57** **SSW/243.3** **103.3 / 3.45** **Camalor Mfg. Inc.**
100 Central Avenue, P.O. Box 126
Brockville ON N6V 5V2 **ECA**

Approval No: 8076-4HNMR2
Approval Date: 2000-03-23
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Cataraqui
Approval Type: ECA-AIR
Project Type: AIR
Address: 100 Central Avenue, P.O. Box 126
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7383-4GDRAM-14.pdf

MOE District: Kingston
City:
Longitude: -75.70206999999999
Latitude: 44.595974
Geometry X:
Geometry Y:

---

58 **53 of 57** **SSW/243.3** **103.3 / 3.45** **CAMALOR MFG. INC.**
100 CENTRAL AVENUE
BROCKVILLE ON K6V 5W6 **GEN**

Generator No: ON2451400
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 332999
SIC Description: ALL OTHER MISCELLANEOUS FABRICATED METAL PRODUCT MANUFACTURING

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

---

58 **54 of 57** **SSW/243.3** **103.3 / 3.45** **CAMALOR MFG. INC.**
100 CENTRAL AVENUE
BROCKVILLE ON K6V 5W6 **GEN**

Generator No: ON2451400
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 332999
SIC Description: ALL OTHER MISCELLANEOUS FABRICATED METAL PRODUCT MANUFACTURING

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

58 **55 of 57** **SSW/243.3** **103.3 / 3.45** **CAMALOR MFG. INC.**
100 CENTRAL AVENUE
BROCKVILLE ON K6V 5W6 **GEN**

Generator No: ON2451400
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 332999
SIC Description: ALL OTHER MISCELLANEOUS FABRICATED METAL PRODUCT MANUFACTURING

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

58 **56 of 57** **SSW/243.3** **103.3 / 3.45** **CAMALOR MFG. INC.**
100 CENTRAL AVENUE
BROCKVILLE ON K6V 5W6 **GEN**

Generator No: ON2451400
Status: Registered

PO Box No:
Country: Canada

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

---

58 | **57 of 57** | **SSW/243.3** | **103.3 / 3.45** | **CAMALOR MFG. INC.**
100 CENTRAL AVENUE
BROCKVILLE ON K6V 5W6 | **GEN**

Generator No: ON2451400
Status: Registered
Approval Years: As of Apr 2020
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 145 L
Waste Class Desc: Wastes from the use of pigments, coatings and paints

---

59 | **1 of 1** | **ENE/4.2** | **102.8 / 2.90** | **ON** | **BORE**

Borehole ID: 834799
OGF ID: 215586435
Status: Decommissioned
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: 18-AUG-1955
Static Water Level:
Primary Water Use:
Sec. Water Use:
Total Depth m: 7.9
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Core barrel
Orig Ground Elev m:
Elev Reliabil Note:
DEM Ground Elev m: 104
Concession: 1 & 2
Location D: CPR X-ING AT 401 OVERPASS (0.6 MI E OF HWY 29 AT BROCKVILLE) *
Survey D:
Comments:
Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot: 10
Township: Elizabethtown
Latitude DD: 44.605523
Longitude DD: -75.692968
UTM Zone: 18
Easting: 445010
Northing: 4939364
Location Accuracy:
Accuracy: Within 10 metres

Borehole Geology Stratum

Geology Stratum ID: 6019316
Top Depth: 3.3
Bottom Depth: 4.6
Material Color:
Material 1: Limestone
Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:

Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Thin, horizontally bedded limestone **Note: Many records provided by the department have a truncated [Stratum Description] field.**
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6019315
Top Depth: 0
Bottom Depth: 3.3
Material Color:
Material 1:
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: (No data) **Note: Many records provided by the department have a truncated [Stratum Description] field.**
Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6019317
Top Depth: 4.6
Bottom Depth: 7.9
Material Color:
Material 1: Limestone
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Limestone - sound at 5.49m to 5.79m **Note: Many records provided by the department have a truncated [Stratum Description] field.**
Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

---

60 | **1 of 1** | **E/249.9** | **94.9 / -4.93** | **YMCA-YWCA OF BROCKVILLE**
345 PARK ST./MAPLE AVE. (SWM)
BROCKVILLE CITY ON K6V 5Y7 | **CA**

Certificate #: 3-0493-95-
Application Year: 95
Issue Date: 6/30/1995
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

61 | **1 of 1** | **SW/91.8** | **106.8 / 6.95** | **7789 Kent Boulevard**
Brockville ON K6V 6N7 | **EHS**

Order No: 20190806287
Status: C
Report Type: Standard Report
Report Date: 12-AUG-19
Date Received: 06-AUG-19
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.705354
Y: 44.597572

---

62 | **1 of 1** | **SW/91.8** | **106.8 / 6.95** | **W.A. MACKEY FUELS** | **SPL**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

7789 KENT BLVD. TANK TRUCK (CARGO)
BROCKVILLE CITY ON K6V 6N7

Ref No:	83153	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	3/24/1993	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	CONFIRMED	**Site Municipality:**	56101
Nature of Impact:	Soil contamination	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	3/26/1993	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	GASKET/JOINT	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	BACKENTRY-W.A. MACKEY FUELS-25 L DIESEL FUEL TOGROUND, CONTAINED,CLEANED		
Contaminant Qty:			

63 **1 of 1** **ENE/4.7** **102.3 / 2.44** **ON** **BORE**

Borehole ID:	834800	**Inclin FLG:**	No
Status:	Decommissioned	**SP Status:**	Initial Entry
Type:	Borehole	**Surv Elev:**	No
Use:	Geotechnical/Geological Investigation	**Piezometer:**	No
Completion Date:	22-AUG-1955	**Primary Name:**	
Static Water Level:	0.6	**Municipality:**	
Primary Water Use:		**Lot:**	10
Sec. Water Use:		**Township:**	Elizabethtown
Total Depth m:	6.1	**Latitude DD:**	44.60574
Depth Ref:	Ground Surface	**Longitude DD:**	-75.692681
Depth Elev:		**UTM Zone:**	18
Drill Method:	Core barrel	**Easting:**	445033
Orig Ground Elev m:	93.8	**Northing:**	4939388
Elev Reliabil Note:		**Location Accuracy:**	
DEM Ground Elev m:	104	**Accuracy:**	Within 10 metres
Concession:	1 & 2		
Location D:	CPR X-ING AT 401 OVERPASS (0.6 MI E OF HWY 29 AT BROCKVILLE) *		
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	6019320	**Mat Consistency:**	
Top Depth:	3	**Material Moisture:**	
Bottom Depth:	6.1	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Limestone	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	

Gsc Material Description:			
Stratum Description:	Thin horizontally bedded limestone **Note: Many records provided by the department have a truncated [Stratum Description] field.		
Geology Stratum ID:	6019318	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.3	**Material Texture:**	
Material Color:	Black	**Non Geo Mat Type:**	
Material 1:	Topsoil	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	Black topsoil **Note: Many records provided by the department have a truncated [Stratum Description] field.		
Geology Stratum ID:	6019319	**Mat Consistency:**	
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	Sand **Note: Many records provided by the department have a truncated [Stratum Description] field.		

64 **1 of 1** **ENE/63.1** **92.6 / -7.24** **ON** **WWIS**

Well ID:	7101789	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	2/8/2008
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7323
Casing Material:		**Form Version:**	3
Audit No:	Z59954	**Owner:**	
Tag:	A071906	**Street Name:**	
Construction Method:		**County:**	HASTINGS
Elevation (m):		**Municipality:**	BELLEVILLE CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/710\7101789.pdf

Bore Hole Information

Bore Hole ID:	1001494153	**Elevation:**	91.974784
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:		**East83:**	445082
Code OB Desc:		**North83:**	4939341
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	12/14/2007	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1001601083
Layer: 1
Color: 8
General Color: BLACK
Mat1: 11
Most Common Material: GRAVEL
Mat2:
Mat2 Desc:
Mat3: 66
Mat3 Desc: DENSE
Formation Top Depth: 0
Formation End Depth: 1
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1001601084
Layer: 2
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3: 79
Mat3 Desc: PACKED
Formation Top Depth: 1
Formation End Depth:
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1001601085
Layer: 3
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 34
Mat2 Desc: TILL
Mat3: 81
Mat3 Desc: SANDY
Formation Top Depth:
Formation End Depth: 4.67
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1001601087
Layer: 1

Plug From: 0
Plug To: 0.5
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1001601088
Layer: 2
Plug From: 0.5
Plug To: 1
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1001601089
Layer: 3
Plug From: 1
Plug To: 4.75
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1001601093
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1001601082
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1001601091
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 4.67
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1001601092
Layer: 1
Slot: .10
Screen Top Depth: 1.25
Screen End Depth: 4.75
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Water Details

Water ID: 1001601090
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1001601086
Diameter: 8
Depth From: 0
Depth To: 4.75
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

65 ***1 of 1*** ***SSW/248.3*** ***102.7 / 2.88*** ***Brockville ON*** ***WWIS***

Well ID: 7112299
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z63844
Tag: A068528
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 9/29/2008
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 1844
Form Version: 4
Owner:
Street Name: 220 CENTRAL AVE. WEST
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7112299.pdf

Bore Hole Information

Bore Hole ID: 1001820161
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 8/13/2008
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 102.156341
Elevrc:
Zone: 18
East83: 444280
North83: 4938269
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1001820868
Layer: 1
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1001820870
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1001820873
Method Construction Code:
Method Construction:
Other Method Construction:

Pipe Information

Pipe ID: 1001820867
Casing No: 0
Comment:
Alt Name:

Construction Record - Screen

Screen ID: 1001820872
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM:
Screen Diameter UOM:
Screen Diameter:

Water Details

Water ID: 1001820871
Layer: 1
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Hole Diameter

Hole ID: 1001820869
Diameter:
Depth From:
Depth To: 5.2
Hole Depth UOM: m
Hole Diameter UOM: cm

---

66 | ***1 of 1*** | ***ENE/82.3*** | ***94.0 / -5.88*** | ***30 Dewick Drive Brockville ON K6V 1Y4*** | ***EHS***

Order No: 20101119008
Status: C
Report Type: Standard Report
Report Date: 11/22/2010
Date Received: 11/19/2010 10:25:12 AM
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -75.691486
Y: 44.605494

---

67 | ***1 of 2*** | ***SSW/233.9*** | ***102.5 / 2.69*** | ***Brockville ON*** | ***WWIS***

Well ID: 7111990
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: M01057
Tag: A068528
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 9/15/2008
Selected Flag: Yes
Abandonment Rec:
Contractor: 1844
Form Version: 5
Owner:
Street Name: 220 CENTRAL AVE W
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/711\7111990.pdf

Bore Hole Information

Bore Hole ID: 1002677793
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 7/4/2008
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:

Elevation: 102.156341
Elevrc:
Zone: 18
East83: 444280
North83: 4938269
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1002677797
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002677796
Method Construction Code:
Method Construction:
Other Method Construction: HSA

Pipe Information

Pipe ID: 1002677798
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002677800
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: .9
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002677799
Layer:
Slot:
Screen Top Depth: 0.9
Screen End Depth: 5.2
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002677801
Pump Set At:
Static Level: 1.3
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:

Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002677795
Diameter: 20
Depth From:
Depth To: 5.2
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002677802
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 7/4/2008
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation: 102.511451
Elevrc:
Zone: 18
East83: 444254
North83: 4938293
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002677806
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002677805
Method Construction Code:
Method Construction:
Other Method Construction: HSA

Pipe Information

Pipe ID: 1002677807
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002677809
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: .9
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002677808
Layer:
Slot:
Screen Top Depth: 0.9
Screen End Depth: 4.6
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002677810
Pump Set At:
Static Level: 1.4
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002677804
Diameter: 20
Depth From:
Depth To: 4.6
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002677820
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 7/3/2008
Remarks:
Elevation: 102.404579
Elevrc:
Zone: 18
East83: 444248
North83: 4938263
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1002677824
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002677823
Method Construction Code:
Method Construction:
Other Method Construction: HSA

Pipe Information

Pipe ID: 1002677825
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002677827
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: .9
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002677826
Layer:
Slot:
Screen Top Depth: 0.9
Screen End Depth: 4.6
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002677828
Pump Set At:
Static Level: 1.7
Final Level After Pumping:

Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002677822
Diameter: 20
Depth From:
Depth To: 4.6
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1001812406
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole: No
Cluster Kind:
Date Completed: 7/3/2008
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 108.488182
Elevrc:
Zone: 18
East83: 444080
North83: 4938240
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1002677841
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 34
Mat2 Desc: TILL
Mat3: 72
Mat3 Desc: GRAVELLY
Formation Top Depth: 1.7
Formation End Depth: 6.1
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1002677840
Layer: 1

Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 01
Mat2 Desc: FILL
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 1.7
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002677843
Layer: 1
Plug From: 0
Plug To: 1.2
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1002677847
Method Construction Code: F
Method Construction: H.S.A.
Other Method Construction:

Pipe Information

Pipe ID: 1002677838
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002677844
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 1.5
Casing Diameter: 5.1
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002677845
Layer: 1
Slot: 10
Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 5.8

Results of Well Yield Testing

Pump Test ID: 1002677839
Pump Set At:
Static Level: 1.1
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code: 0
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002677842
Diameter: 20
Depth From: 0
Depth To: 6.1
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002677829
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 7/3/2008
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation: 102.694503
Elevrc:
Zone: 18
East83: 444237
North83: 4938246
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002677833
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002677832
Method Construction Code:
Method Construction:
Other Method Construction: HSA

Pipe Information

Pipe ID: 1002677834
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002677836
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 1.5
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002677835
Layer:
Slot:
Screen Top Depth: 1.5
Screen End Depth: 5.9
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002677837
Pump Set At:
Static Level: 1.7
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002677831
Diameter: 20
Depth From:
Depth To: 5.9
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002677811 ***Elevation:*** 102.377601

DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 7/4/2008
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevrc:
Zone: 18
East83: 444250
North83: 4938278
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002677815
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002677814
Method Construction Code:
Method Construction:
Other Method Construction: HSA

Pipe Information

Pipe ID: 1002677816
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002677818
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: .9
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002677817
Layer:
Slot:
Screen Top Depth: 0.9
Screen End Depth: 4.6
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Results of Well Yield Testing

Pump Test ID:	1002677819
Pump Set At:	
Static Level:	1.5
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	m
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1002677813
Diameter:	20
Depth From:	
Depth To:	4.6
Hole Depth UOM:	m
Hole Diameter UOM:	cm

67	***2 of 2***	***SSW/233.9***	***102.5 / 2.69***	***Brockville ON***	***WWIS***

Well ID:	7123681	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	6/3/2009
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Abandoned Monitoring and Test Hole	***Abandonment Rec:***	Yes
Water Type:		***Contractor:***	1844
Casing Material:		***Form Version:***	5
Audit No:	M04457	***Owner:***	
Tag:	A068528	***Street Name:***	220 CENTRAL AVENUE WEST
Construction Method:		***County:***	36
Elevation (m):		***Municipality:***	BROCKVILLE CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7123681.pdf

Bore Hole Information

Bore Hole ID:	1002436160	***Elevation:***	108.488182
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	444080
Code OB Desc:		***North83:***	4938240

Open Hole:	No	***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	3/24/2009	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002765013
Layer:	1
Plug From:	0
Plug To:	6.1
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1002765014
Method Construction Code:	
Method Construction:	
Other Method Construction:	

Bore Hole Information

Bore Hole ID:	1002765008	***Elevation:***	102.694503
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	444237
Code OB Desc:		***North83:***	4938246
Open Hole:		***Org CS:***	UTM83
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3
Date Completed:	3/24/2009	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002765012
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002765011
Method Construction Code:	
Method Construction:	
Other Method Construction:	

Hole Diameter

Hole ID: 1002765010
Diameter: 20
Depth From:
Depth To: 5.9
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002764998
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 3/24/2009
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation: 102.377601
Elevrc:
Zone: 18
East83: 444250
North83: 4938278
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002765002
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002765001
Method Construction Code:
Method Construction:
Other Method Construction:

Hole Diameter

Hole ID: 1002765000
Diameter: 20
Depth From:
Depth To: 4.6
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002765003
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Elevation: 102.404579
Elevrc:
Zone: 18
East83: 444248
North83: 4938263

Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 3/24/2009
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002765007
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002765006
Method Construction Code:
Method Construction:
Other Method Construction:

Hole Diameter

Hole ID: 1002765005
Diameter: 20
Depth From:
Depth To: 4.6
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002764993
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 3/24/2009
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation: 102.511451
Elevrc:
Zone: 18
East83: 444254
North83: 4938293
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002764997
Layer:
Plug From:
Plug To:

Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002764996
Method Construction Code:
Method Construction:
Other Method Construction:

Hole Diameter

Hole ID: 1002764995
Diameter: 20
Depth From:
Depth To: 4.6
Hole Depth UOM: m
Hole Diameter UOM: cm

68 | 1 of 1 | NE/137.9 | 94.8 / -5.08 | Brockville ON | WWIS

Well ID: 7123820
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z81068
Tag: A083165
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 6/8/2009
Selected Flag: Yes
Abandonment Rec:
Contractor: 1844
Form Version: 7
Owner:
Street Name: 2211 PARKDALE AVE.
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7123820.pdf

Bore Hole Information

Bore Hole ID: 1002452867
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 4/30/2009
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 94.484504
Elevrc:
Zone: 18
East83: 445010
North83: 4939554
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1002601224
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2:
Mat2 Desc:
Mat3: 84
Mat3 Desc: SILTY
Formation Top Depth: 0
Formation End Depth: 1.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1002601225
Layer: 2
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3: 75
Mat3 Desc: LIGHT-COLOURED
Formation Top Depth: 1.5
Formation End Depth: 6
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002601231
Layer: 1
Plug From: 0.2
Plug To: 2.8
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1002601236
Method Construction Code: 7
Method Construction: Diamond
Other Method Construction: H.S.A.

Pipe Information

Pipe ID: 1002601223
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002601233
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002601234
Layer: 1
Slot: 10
Screen Top Depth: 3
Screen End Depth: 6
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 5.8

Water Details

Water ID: 1002601232
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1002601226
Diameter: 20
Depth From: 0
Depth To: 1.5
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1002601227
Diameter: 10
Depth From: 1.5
Depth To: 6
Hole Depth UOM: m
Hole Diameter UOM: cm

---

69 | **1 of 1** | **SW/125.8** | **109.9 / 10.09** | **7815 Kent Blvd. Brockville ON** | **EHS**

Order No: 20120705013
Status: C
Report Type: Custom Report
Report Date: 11-JUL-12
Date Received: 05-JUL-12
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.706661
Y: 44.597052

70 | **1 of 1** | **NE/108.4** | **93.8 / -6.02** | **Parkdale Ave And Park Street Brockville ON** | **EHS**

Order No: 20120109057
Status: C
Report Type: Standard Report
Report Date: 1/18/2012 10:13:43 PM
Date Received: 1/9/2012 10:13:43 PM
Previous Site Name:
Lot/Building Size: 7.4 acres
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Title Searches; Topographic Maps

Nearest Intersection:
Municipality: Brockville
Client Prov/State: ON
Search Radius (km): 0.25
X: -75.692612
Y: 44.607128

---

71 | **1 of 5** | **NE/146.1** | **94.0 / -5.82** | **COMMUNITY & PRIMARY HEALTH CARE - LANARK, LEEDS & GRENVILLE 2235 PARKEDALE AVENUE, BROCKVILLE, ON K6V 6B2 Brockville ON** | **RSC**

RSC ID: 212866
RA No:
RSC Type: Phase 1 and 2 RSC
Curr Property Use: Commercial
Ministry District: Kingston District Office
Filing Date: 2014/04/02
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686:
Asmt Roll No: 0802010030464000000
Prop ID No (PIN): 44176-0208 (LT)
Property Municipal Address: 2235 PARKEDALE AVENUE, BROCKVILLE, ON K6V 6B2
Mailing Address:
Latitude & Latitude:
UTM Coordinates:
Consultant:
Legal Desc:
Measurement Method:
Applicable Standards:
RSC PDF: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=33702&fileName=BROWNFIELDS-E.pdf

Cert Date:
Cert Prop Use No:
Intended Prop Use: Residential
Qual Person Name: CARLOS DA SILVA
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N):
Accuracy Estimate:
Telephone:
Fax:
Email:

Document(s) Detail

Document Heading: Supporting Documents
Document Name: PE2606 - Deed Transfer.pdf
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=33701&fileName=PE2606+-+Deed+Transfer.pdf

Document Heading: Supporting Documents
Document Name: Certificate of Corporate Status CPHC.pdf
Document Type: Certificate of Status
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=33706&fileName=Certificate+of+Corporate+Status+CPHC.pdf

Document Heading: Supporting Documents
Document Name: PE2606-CSM Memo.pdf
Document Type: Phase 2 Conceptual Site Model
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

attachmentId=33703&fileName=PE2606-CSM+Memo.pdf

Document Heading: Supporting Documents
Document Name: PE2606 Survey Plan.pdf
Document Type: A Current plan of Survey
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=33700&fileName=PE2606+Survey+Plan.pdf

Document Heading: Supporting Documents
Document Name: LawyersLetter.pdf
Document Type: Lawyer's letter consisting of a legal description of the property
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=34023&fileName=LawyersLetter.pdf

Document Heading: Supporting Documents
Document Name: TableofCandPUses.pdf
Document Type: Table of Current and Past Property Use
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=34018&fileName=TableofCandPUses.pdf

Document Heading: Supporting Documents
Document Name: Table of APECs.pdf
Document Type: Area(s) of Potential Environmental Concern
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=33698&fileName=Table+of+APECs.pdf

---

71 **2 of 5** **NE/146.1** **94.0 / -5.82** **Leeds & Grenville Community Family Health Team**
2235 Parkedale Avenue
Brockville ON K6V 6B2 **GEN**

Generator No: ON7425705
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS

PO Box No:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Jane Fournier
Phone No Admin: 613-342-4076 Ext.2001

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

71 **3 of 5** **NE/146.1** **94.0 / -5.82** **Community & Primary Health Care -**
2235 Parkedale Avenue
Brockville ON K6V 6B2 **GEN**

Generator No: ON7425705
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 621110
SIC Description: OFFICES OF PHYSICIANS

PO Box No:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Jane Fournier
Phone No Admin: 613-342-1313 Ext.2001

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

71 **4 of 5** **NE/146.1** **94.0 / -5.82** **Leeds & Grenville Community Family Health Team Community Family Health Team**
2235 Parkedale Avenue
Brockville ON K6V 6B2 **GEN**

Generator No: ON7425705
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312 P
Waste Class Desc: Pathological wastes

---

71 **5 of 5** **NE/146.1** **94.0 / -5.82** **Leeds & Grenville Community Family Health Team Community Family Health Team**
2235 Parkedale Avenue
Brockville ON K6V 6B2 **GEN**

Generator No: ON7425705
Status: Registered
Approval Years: As of Apr 2020
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312 P
Waste Class Desc: Pathological wastes

---

72 **1 of 1** **ENE/241.6** **94.9 / -4.98** **P.U.C. BROCKVILLE**
ELM AVE./MAPLE AVE./ORMOND ST.
BROCKVILLE CITY ON **CA**

Certificate #: 7-0320-97-
Application Year: 97
Issue Date: 5/15/1997
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

73 **1 of 1** **NE/185.9** **94.9 / -4.98** **Brockville ON** **WWIS**

Well ID: 7177786
Construction Date:
Primary Water Use: Monitoring and Test Hole
Sec. Water Use: 0

Data Entry Status:
Data Src:
Date Received: 3/9/2012
Selected Flag: Yes

Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z145302
Tag: A126547
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
Street Name: 2211 PARKEDALE AVENUE
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7177786.pdf

Bore Hole Information

Bore Hole ID: 1003703217
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 2/10/2012
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 94.966773
Elevrc:
Zone: 18
East83: 445001
North83: 4939613
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004180329
Layer: 2
Color: 1
General Color: WHITE
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3: 73
Mat3 Desc: HARD
Formation Top Depth: 1.22
Formation End Depth: 3.1
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004180328
Layer: 1
Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL

Mat2: 28
Mat2 Desc: SAND
Mat3: 85
Mat3 Desc: SOFT
Formation Top Depth: 0
Formation End Depth: 1.22
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004180340
Layer: 3
Plug From: 1.83
Plug To: 3.1
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004180339
Layer: 2
Plug From: 0.31
Plug To: 1.83
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004180338
Layer: 1
Plug From: 0
Plug To: 0.31
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1004180337
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction: AIR PERCUSSION

Pipe Information

Pipe ID: 1004180327
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004180333
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 1.83
Casing Diameter: 5.02
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004180334
Layer: 1
Slot: 10
Screen Top Depth: 1.83
Screen End Depth: 3.1
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.03

Water Details

Water ID: 1004180332
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1004180331
Diameter: 7.62
Depth From: 1.22
Depth To: 3.1
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1004180330
Diameter: 11.43
Depth From: 0
Depth To: 1.22
Hole Depth UOM: m
Hole Diameter UOM: cm

---

74 **1 of 1** **ENE/122.4** **96.0 / -3.84** **19 BRAMSHOT STREET BROCKVILLE ON** **HINC**

External File Num: FS INC 0811-06761
Fuel Occurrence Type:
Date of Occurrence:
Fuel Type Involved:
Status Desc: Completed - No Action Required
Job Type Desc: Incident/Near-Miss Occurrence (FS)
Oper. Type Involved:
Service Interruptions:
Property Damage:
Fuel Life Cycle Stage:
Root Cause:
Reported Details: Non-mandated. Fuels Safety Inspector Oscar Warrenm has decline dinvestigating the matter since the g
Fuel Category: Gaseous Fuel
Occurrence Type: Near-miss
Affiliation: Emergency Services (Fire, Police,etc)
County Name: Leeds and Grenville
Approx. Quant. Rel:
Nearby body of water:
Enter Drainage Syst.:

Approx. Quant. Unit:
Environmental Impact:

---

75 **1 of 1** **ENE/10.2** **98.2 / -1.65** **ON** **BORE**

Borehole ID: 834809
OGF ID: 215586445
Status: Decommissioned
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: 23-APR-1955
Static Water Level:
Primary Water Use:
Sec. Water Use:
Total Depth m: 4.6
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Not known
Orig Ground Elev m:
Elev Reliabil Note:
DEM Ground Elev m: 97.6
Concession: 1
Location D: ORMOND ST IN BROCKVILLE AND 401 OVERPASS (0.8 MI E OF HWY 29)
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot: 10
Township: Elizabethtown
Latitude DD: 44.606886
Longitude DD: -75.690855
UTM Zone: 18
Easting: 445179
Northing: 4939514
Location Accuracy:
Accuracy: Within 10 metres

Borehole Geology Stratum

Geology Stratum ID: 6019344
Top Depth: 0
Bottom Depth: .1
Material Color: Black
Material 1: Topsoil
Material 2: Clay
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Black clay loam topsoil (wet) **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture: Wet
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6019345
Top Depth: .1
Bottom Depth: 3
Material Color: Brown
Material 1: Clay
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Light brown light medium clay (moderately mottled), moist at 3.05m **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture: Moist
Material Texture: Medium
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6019346
Top Depth: 3
Bottom Depth: 3.7
Material Color: Grey-Brown
Material 1: Clay
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Grey brown light medium clay (moist) **Note: Many records provided by the department have a truncated [Stratum

Mat Consistency:
Material Moisture: Moist
Material Texture: Medium
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Description] field.

Geology Stratum ID: 6019347
Top Depth: 3.7
Bottom Depth: 4.6
Material Color: Vari-colored
Material 1: Clay
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Blue grey light medium clay (moist-wet, slightly plastic) **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture: Moist
Material Texture: Medium
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

---

76 **1 of 1** **ENE/10.3** **97.7 / -2.17** **ON** **BORE**

Borehole ID: 834808
OGF ID: 215586444
Status: Decommissioned
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: 23-APR-1955
Static Water Level: 0.6
Primary Water Use:
Sec. Water Use:
Total Depth m: 3
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Not known
Orig Ground Elev m:
Elev Reliabil Note:
DEM Ground Elev m: 98.3
Concession: 1
Location D: ORMOND ST IN BROCKVILLE AND 401 OVERPASS (0.8 MI E OF HWY 29)
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot: 10
Township: Elizabethtown
Latitude DD: 44.606913
Longitude DD: -75.690817
UTM Zone: 18
Easting: 445182
Northing: 4939517
Location Accuracy:
Accuracy: Within 10 metres

Borehole Geology Stratum

Geology Stratum ID: 6019342
Top Depth: 0
Bottom Depth: .3
Material Color: Black
Material 1: Topsoil
Material 2: Gravel
Material 3: Clay
Material 4:
Gsc Material Description:
Stratum Description: Black clay loam topsoil and gravel mix **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6019343
Top Depth: .3
Bottom Depth: 3
Material Color: Brown
Material 1: Clay
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Light brown light medium clay (slightly mottled-moist-wet) water enter at 0.61m **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture: Moist
Material Texture: Medium
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

77 **1 of 2** **ENE/20.9** **98.7 / -1.20** **ON** **BORE**

Borehole ID: 834802
OGF ID: 215586438
Status: Decommissioned
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: 12-MAY-1955
Static Water Level:
Primary Water Use:
Sec. Water Use:
Total Depth m: 6
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Core barrel
Orig Ground Elev m: 93.1
Elev Reliabil Note:
DEM Ground Elev m: 99.2
Concession: 1
Location D: ORMOND ST IN BROCKVILLE AND 401 OVERPASS (0.8 MI E OF HWY 29)
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot: 10
Township: Elizabethtown
Latitude DD: 44.607137
Longitude DD: -75.69106
UTM Zone: 18
Easting: 445163
Northing: 4939542
Location Accuracy:
Accuracy: Within 10 metres

Borehole Geology Stratum

Geology Stratum ID: 6019325
Top Depth: .2
Bottom Depth: 6
Material Color:
Material 1: Clay
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Clay (medium to stiff) **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency: Stiff
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6019324
Top Depth: 0
Bottom Depth: .2
Material Color: Black
Material 1: Topsoil
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Black topsoil **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

---

77 **2 of 2** **ENE/20.9** **98.7 / -1.20** **ON** **BORE**

Borehole ID: 834810
OGF ID: 215586446
Status: Decommissioned
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: 23-APR-1955
Static Water Level:
Primary Water Use:
Sec. Water Use:
Total Depth m: 4.6
Depth Ref: Ground Surface

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot: 10
Township: Elizabethtown
Latitude DD: 44.607137
Longitude DD: -75.69106
UTM Zone: 18

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Depth Elev:		**Easting:**	445163
Drill Method:	Not known	**Northing:**	4939542
Orig Ground Elev m:		**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Within 10 metres
DEM Ground Elev m:	99.2		
Concession:	1		
Location D:	ORMOND ST IN BROCKVILLE AND 401 OVERPASS (0.8 MI E OF HWY 29)		
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	6019349	**Mat Consistency:**	
Top Depth:	.2	**Material Moisture:**	Moist
Bottom Depth:	2.7	**Material Texture:**	Medium
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	Light brown light medium clay (moist - moderately mottled to 2.44m) **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6019350	**Mat Consistency:**	
Top Depth:	2.7	**Material Moisture:**	Moist
Bottom Depth:	3.7	**Material Texture:**	Medium
Material Color:	Grey-Brown	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	Grey brown light medium clay (moist) **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6019348	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	Moist
Bottom Depth:	.2	**Material Texture:**	
Material Color:	Black	**Non Geo Mat Type:**	
Material 1:	Topsoil	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	Black clay loam topsoil (moist-wet) **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6019351	**Mat Consistency:**	
Top Depth:	3.7	**Material Moisture:**	Moist
Bottom Depth:	4.6	**Material Texture:**	Medium
Material Color:	Vari-colored	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	Blue grey light medium clay (moist-wet, slightly plastic) **Note: Many records provided by the department have a truncated [Stratum Description] field.		

78	1 of 1	ENE/54.8	93.8 / -6.02	ON	BORE

Borehole ID:	834803	**Inclin FLG:**	No

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

OGF ID:	215586439	**SP Status:**	Initial Entry
Status:	Decommissioned	**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	23-APR-1955	**Municipality:**	
Static Water Level:	2.7	**Lot:**	10
Primary Water Use:		**Township:**	Elizabethtown
Sec. Water Use:		**Latitude DD:**	44.606609
Total Depth m:	3.8	**Longitude DD:**	-75.690448
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	445211
Drill Method:	Not known	**Northing:**	4939483
Orig Ground Elev m:		**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Within 10 metres
DEM Ground Elev m:	93.3		
Concession:	1		
Location D:	ORMOND ST IN BROCKVILLE AND 401 OVERPASS (0.8 MI E OF HWY 29)		
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	6019326	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.2	**Material Texture:**	
Material Color:	Black	**Non Geo Mat Type:**	
Material 1:	Topsoil	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	Black clay loam topsoil **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6019329	**Mat Consistency:**	
Top Depth:	3.3	**Material Moisture:**	Wet
Bottom Depth:	5.5	**Material Texture:**	Medium
Material Color:	Vari-colored	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	Blue-grey, light medium clay (wet), plastic **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6019327	**Mat Consistency:**	
Top Depth:	.2	**Material Moisture:**	Moist
Bottom Depth:	2.7	**Material Texture:**	Medium
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	Light brown light-medium clay (slightly loamy) moist-wet **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6019328	**Mat Consistency:**	
Top Depth:	2.7	**Material Moisture:**	Wet
Bottom Depth:	3.3	**Material Texture:**	Medium
Material Color:	Grey-Brown	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	

Material 4:
Gsc Material Description:
Depositional Gen:
Stratum Description: Grey-brown, light medium clay (wet), water enter at 2.74m **Note: Many records provided by the department have a truncated [Stratum Description] field.

---

79 **1 of 1** **ENE/18.6** **99.1 / -0.72** **ON** **BORE**

Borehole ID:	834806	**Inclin FLG:**	No
OGF ID:	215586442	**SP Status:**	Initial Entry
Status:	Decommissioned	**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	23-APR-1955	**Municipality:**	
Static Water Level:		**Lot:**	10
Primary Water Use:		**Township:**	Elizabethtown
Sec. Water Use:		**Latitude DD:**	44.6072
Total Depth m:	4.9	**Longitude DD:**	-75.690934
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	445173
Drill Method:	Not known	**Northing:**	4939549
Orig Ground Elev m:		**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Within 10 metres
DEM Ground Elev m:	99.8		
Concession:	1		
Location D:	ORMOND ST IN BROCKVILLE AND 401 OVERPASS (0.8 MI E OF HWY 29)		
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	6019336	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.5	**Material Texture:**	
Material Color:	Black	**Non Geo Mat Type:**	
Material 1:	Topsoil	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	Black clay loam topsoil and gravel mix **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6019337	**Mat Consistency:**	
Top Depth:	.5	**Material Moisture:**	Moist
Bottom Depth:	3	**Material Texture:**	Medium
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	Light brown light medium clay (moist - slightly mottled) **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6019338	**Mat Consistency:**	
Top Depth:	3	**Material Moisture:**	Moist
Bottom Depth:	4.9	**Material Texture:**	Medium
Material Color:	Vari-colored	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			

Stratum Description: Blue grey light medium clay (moist) **Note: Many records provided by the department have a truncated [Stratum Description] field.

---

80 **1 of 1** **ENE/65.3** **94.4 / -5.44** **ON** **BORE**

Borehole ID:	834807	**Inclin FLG:**	No
OGF ID:	215586443	**SP Status:**	Initial Entry
Status:	Decommissioned	**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	23-APR-1955	**Municipality:**	
Static Water Level:		**Lot:**	10
Primary Water Use:		**Township:**	Elizabethtown
Sec. Water Use:		**Latitude DD:**	44.607522
Total Depth m:	4.6	**Longitude DD:**	-75.691316
Depth Ref:	Ground Surface	**UTM Zone:**	18
Depth Elev:		**Easting:**	445143
Drill Method:	Not known	**Northing:**	4939585
Orig Ground Elev m:		**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Within 10 metres
DEM Ground Elev m:	93.9		
Concession:	1		
Location D:	ORMOND ST IN BROCKVILLE AND 401 OVERPASS (0.8 MI E OF HWY 29)		
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	6019341	**Mat Consistency:**	
Top Depth:	3	**Material Moisture:**	Moist
Bottom Depth:	4.6	**Material Texture:**	Medium
Material Color:	Vari-colored	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	Blue grey light medium clay (moist - wet) **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6019339	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.2	**Material Texture:**	
Material Color:	Black	**Non Geo Mat Type:**	
Material 1:	Topsoil	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	Black clay loam topsoil and gravel mix **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	6019340	**Mat Consistency:**	
Top Depth:	.2	**Material Moisture:**	Moist
Bottom Depth:	3	**Material Texture:**	Medium
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	Light brown light medium clay (moist - slightly mottled), moist-wet from 2.74m to 3.05m **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
81	1 of 23	NE/211.5	94.9 / -4.98	TRIPLE B BAGEL INC. 2211 PARKEDALE AVENUE BROCKVILLE CITY ON	CA

Certificate #: 8-4233-96-
Application Year: 96
Issue Date: 2/4/1997
Approval Type: Industrial air
Status:
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: COMMERCIAL KITCHEN EXHAUST HOOD
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
81	2 of 23	NE/211.5	94.9 / -4.98	ZIPPY PRINT 2211 PARKEDALE AVE W BROCKVILLE ON K6V 6B2	SCT

Established: 1987
Plant Size (ft²): 2000
Employment: 4

--Details--
Description: COMMERCIAL PRINTING, LITHOGRAPHIC
SIC/NAICS Code: 2752

Description: COMMERCIAL PRINTING, N.E.C.
SIC/NAICS Code: 2759

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
81	3 of 23	NE/211.5	94.9 / -4.98	UAP INC. 2211 PARKDALE AVENUE BROCKVILLE ON K6V 6V2	GEN

Generator No: ON0204204
Status:
Approval Years: 86,87,88,89,90,92,93,94
Contam. Facility:
MHSW Facility:
SIC Code: 0000
SIC Description: *** NOT DEFINED ***

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
81	4 of 23	NE/211.5	94.9 / -4.98	JAMES ROSS LTD. 2211 PARKDALE AVE. R.R.# 4,ELIZABETH TOWN IND.PARK, BROCKVILLE ON K6V 5T4	GEN

Generator No: ON1642501
Status:
Approval Years: 93,94
Contam. Facility:
MHSW Facility:
SIC Code: 0000
SIC Description: *** NOT DEFINED ***

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
81	5 of 23	NE/211.5	94.9 / -4.98	ZIPPY PRINT 2211 PARKEDALE AVENUE, UNIT #2 COMMERCE COURT BROCKVILLE ON K6V 1A8	GEN

Generator No: ON1491617
Status:
Approval Years: 94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 2821
SIC Description: PLATEMAKING, ETC.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
81	6 of 23	NE/211.5	94.9 / -4.98	ZIPPY PRINT 2211 PARKEDALE AVENUE, UNIT 2 COMMERCE COURT BROCKVILLE ON K6V 1A8	GEN

Generator No: ON1491617
Status:
Approval Years: 99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 2821
SIC Description: PLATEMAKING, ETC.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
81	7 of 23	NE/211.5	94.9 / -4.98	2211 PARKEDALE AVENUE BROCKVILLE ON K6V 6B2	EHS

Order No: 20070831025
Status: C
Report Type: CAN - Complete Report
Report Date: 9/12/2007
Date Received: 8/31/2007
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection: PAKEDALE AVE. W & ORMOND ST.
Municipality:
Client Prov/State:
Search Radius (km): 0.25
X: -75.692945
Y: 44.608634

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
81	8 of 23	NE/211.5	94.9 / -4.98	LifeLabs LP 2211 Parkedale Ave. Brockville ON K6V 6B2	GEN

Generator No: ON7553380
Status:
Approval Years: 07,08
Contam. Facility:
MHSW Facility:
SIC Code: 621510
SIC Description: Medical and Diagnostic Laboratories

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

81 **9 of 23** **NE/211.5** **94.9 / -4.98** **UPI ENERGY LP***
2211 PARKEDALE AVE W
BROCKVILLE ON **EXP**

Instance No: 10481812
Instance ID: 24043
Instance Type: FS Highway Tank - Gas/Diesel
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

81 **10 of 23** **NE/211.5** **94.9 / -4.98** **UPI ENERGY LP***
2211 PARKEDALE AVE W
BROCKVILLE ON **EXP**

Instance No: 10481769
Instance ID: 22618
Instance Type: FS Highway Tank - Gas/Diesel
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

81 **11 of 23** **NE/211.5** **94.9 / -4.98** **LifeLabs LP**
2211 Parkedale Ave.
Brockville ON K6V 6B2 **GEN**

Generator No: ON7553380
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 621510
SIC Description: Medical and Diagnostic Laboratories

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

81 **12 of 23** **NE/211.5** **94.9 / -4.98** **LifeLabs LP**
2211 Parkedale Ave.
Brockville ON K6V 6B2 **GEN**

Generator No: ON7553380
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 621510

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: Medical and Diagnostic Laboratories

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

81 **13 of 23** **NE/211.5** **94.9 / -4.98** **Dentistry @ Brockville**
2211 Parkedale Ave
Brockville ON **GEN**

Generator No: ON7485798
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 621210
SIC Description: Offices of Dentists

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

---

81 **14 of 23** **NE/211.5** **94.9 / -4.98** **Dentistry @ Brockville**
2211 Parkedale Ave
Brockville ON **GEN**

Generator No: ON7485798
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

81 **15 of 23** **NE/211.5** **94.9 / -4.98** **Drs. K and G Dentistry Professional Corporation**
2211 Parkedale Ave
Brockville ON K6V 6B2 **GEN**

Generator No: ON7485798
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Angie Jobson
Phone No Admin: 613-341-9000 Ext.

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

81 **16 of 23** **NE/211.5** **94.9 / -4.98** **Drs. K and G Dentistry Professional Corporation**
2211 Parkedale Ave
Brockville ON K6V 6B2 **GEN**

Generator No: ON7485798
Status:
Approval Years: 2016

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL

Contam. Facility: No
MHSW Facility: No
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
Co Admin: Angie Jobson
Phone No Admin: 613-341-9000 Ext.

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

81 **17 of 23** **NE/211.5** **94.9 / -4.98**

Dentistry @ Brockville
2211 Parkedale Ave
Brockville ON K6V 6B2

GEN

Generator No: ON7485798
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS
PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Angie Jobson
Phone No Admin: 613-341-9000 Ext.

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

81 **18 of 23** **NE/211.5** **94.9 / -4.98**

Drs. K and G Dentistry Professional Corporation
2211 Parkedale Ave
Brockville ON K6V 6B2

GEN

Generator No: ON7485798
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312 P
Waste Class Desc: Pathological wastes

---

81 **19 of 23** **NE/211.5** **94.9 / -4.98**

LifeLabs LP
2211 Parkedale Ave, Unit 5B
Brockville ON K6V 6B2

GEN

Generator No: ON3006898
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312 P
Waste Class Desc: Pathological wastes

81 **20 of 23** **NE/211.5** **94.9 / -4.98**

2211 Parkedale Avenue
Brockville ON K6V 6M2

EHS

Order No: 20180508062
Status: C
Report Type: Standard Report
Report Date: 15-MAY-18
Date Received: 08-MAY-18
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.692632
Y: 44.608389

---

81 **21 of 23** **NE/211.5** **94.9 / -4.98**

2211 Parkedale Ave Brockville On
Brockville ON K6V6B2

EHS

Order No: 20161115145
Status: C
Report Type: Standard Report
Report Date: 22-NOV-16
Date Received: 15-NOV-16
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: City Directory
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.692668
Y: 44.608416

---

81 **22 of 23** **NE/211.5** **94.9 / -4.98**

Drs. K and G Dentistry Professional Corporation
2211 Parkedale Ave
Brockville ON K6V 6B2

GEN

Generator No: ON7485798
Status: Registered
Approval Years: As of Oct 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312 P
Waste Class Desc: Pathological wastes

---

81 **23 of 23** **NE/211.5** **94.9 / -4.98**

LifeLabs LP
2211 Parkedale Ave, Unit 5B
Brockville ON K6V 6B2

GEN

Generator No: ON3006898
Status: Registered
Approval Years: As of Apr 2020
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312 P
Waste Class Desc: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	1 of 2	ENE/9.6	97.8 / -2.09	ON	BORE

Borehole ID: 834801
OGF ID: 215586437
Status: Decommissioned
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: 11-MAY-1955
Static Water Level:
Primary Water Use:
Sec. Water Use:
Total Depth m: 7.5
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Core barrel
Orig Ground Elev m: 93.1
Elev Reliabil Note:
DEM Ground Elev m: 99.5
Concession: 1
Location D: ORMOND ST IN BROCKVILLE AND 401 OVERPASS (0.8 MI E OF HWY 29)
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot: 10
Township: Elizabethtown
Latitude DD: 44.607013
Longitude DD: -75.690693
UTM Zone: 18
Easting: 445192
Northing: 4939528
Location Accuracy:
Accuracy: Within 10 metres

Borehole Geology Stratum

Geology Stratum ID: 6019321
Top Depth: 0
Bottom Depth: .2
Material Color: Black
Material 1: Topsoil
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Black topsoil **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6019322
Top Depth: .2
Bottom Depth: 5.4
Material Color:
Material 1: Clay
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Clay (medium to stiff) **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency: Stiff
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6019323
Top Depth: 5.4
Bottom Depth: 7.5
Material Color:
Material 1: Rock
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Rock (very hard) **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency: Very Hard
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	2 of 2	ENE/9.6	97.8 / -2.09	ON	BORE

Borehole ID: 834804
OGF ID: 215586440
Status: Decommissioned
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: 23-APR-1955
Static Water Level: 3.0
Primary Water Use:
Sec. Water Use:
Total Depth m: 4.9
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Not known
Orig Ground Elev m:
Elev Reliabil Note:
DEM Ground Elev m: 99.5
Concession: 1
Location D: ORMOND ST IN BROCKVILLE AND 401 OVERPASS (0.8 MI E OF HWY 29)
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot: 10
Township: Elizabethtown
Latitude DD: 44.607013
Longitude DD: -75.690693
UTM Zone: 18
Easting: 445192
Northing: 4939528
Location Accuracy:
Accuracy: Within 10 metres

Borehole Geology Stratum

Geology Stratum ID: 6019330
Top Depth: 0
Bottom Depth: .2
Material Color: Black
Material 1: Topsoil
Material 2: Clay
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Black clay loam topsoil **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6019331
Top Depth: .2
Bottom Depth: 3
Material Color: Brown
Material 1: Clay
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Light brown light medium clay (slightly loamy) moist, wet - slightly mottled **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture: Moist
Material Texture: Medium
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6019332
Top Depth: 3
Bottom Depth: 4.9
Material Color: Vari-colored
Material 1: Clay
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Blue grey, light medium clay (water enter at 3.05m), wet -plastic, hole flooding **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture: Wet
Material Texture: Medium
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
83	1 of 1	ENE/20.1	98.4 / -1.46	ON	BORE

Borehole ID: 834805
OGF ID: 215586441

Inclin FLG: No
SP Status: Initial Entry

Status: Decommissioned
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: 23-APR-1955
Static Water Level:
Primary Water Use:
Sec. Water Use:
Total Depth m: 4.9
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Not known
Orig Ground Elev m:
Elev Reliabil Note:
DEM Ground Elev m: 99.4
Concession: 1
Location D: ORMOND ST IN BROCKVILLE AND 401 OVERPASS (0.8 MI E OF HWY 29)
Survey D:
Comments:

Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot: 10
Township: Elizabethtown
Latitude DD: 44.607273
Longitude DD: -75.69086
UTM Zone: 18
Easting: 445179
Northing: 4939557
Location Accuracy:
Accuracy: Within 10 metres

Borehole Geology Stratum

Geology Stratum ID: 6019333
Top Depth: 0
Bottom Depth: .2
Material Color: Black
Material 1: Topsoil
Material 2: Clay
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Black clay loam topsoil **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6019335
Top Depth: 3
Bottom Depth: 4.9
Material Color: Vari-colored
Material 1: Clay
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Blue grey, light medium clay (moist, slightly indurated) **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture: Moist
Material Texture: Medium
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 6019334
Top Depth: .2
Bottom Depth: 3
Material Color: Brown
Material 1: Clay
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: Light brown light medium clay (moist, slightly mottled) **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture: Moist
Material Texture: Medium
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

---

84 | **1 of 1** | **ENE/45.4** | **96.0 / -3.81** | **44.607487, -75.691013 Brockville ON** | **SPL**

Ref No: 4041-A9GQAZ
Site No: NA
Incident Dt: 2016/04/29
Year:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:

Incident Cause:
Incident Event: Unknown / N/A
Contaminant Code: 98
Contaminant Name: UNKNOWN
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact:
Receiving Medium:
Receiving Env: Surface Water
MOE Response: No
Dt MOE Arvl on Scn:
MOE Reported Dt: 2016/04/29
Dt Document Closed: 2016/05/14
Incident Reason: Unknown / N/A
Site Name: Underpass/Buells Creek<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Brockville: Rainbow Sheen on Buells Creek; cntd.
Contaminant Qty: 0 L

Sector Type: Miscellaneous Communal
Agency Involved:
Nearest Watercourse: Unknown Name
Site Address: 44.607487, -75.691013
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: Brockville
Site Lot:
Site Conc:
Northing: 4939581
Easting: 445167
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Watercourse Spills
Source Type:

---

85 | **1 of 1** | **ENE/249.0** | **95.9 / -3.98** | **95 BRIGHTON CRESCENT BROCKVILLE ON K6V 2P4** | **HINC**

External File Num: FS INC 0811-06980
Fuel Occurrence Type: Pipeline Strike
Date of Occurrence: 11/4/2008
Fuel Type Involved: Natural Gas
Status Desc: Completed - Causal Analysis(End)
Job Type Desc: Incident/Near-Miss Occurrence (FS)
Oper. Type Involved: Other-Specify
Service Interruptions: Yes
Property Damage: Yes
Fuel Life Cycle Stage: Other-specify
Root Cause: Root Cause: Equipment/Material/Component:No Procedures:No Maintenance:No Design:No Training:No Management:Yes Human Factors:Yes

Reported Details:
Fuel Category: Gaseous Fuel
Occurrence Type: Incident
Affiliation: Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
County Name: Leeds and Grenville
Approx. Quant. Rel:
Nearby body of water:
Enter Drainage Syst.:
Approx. Quant. Unit:
Environmental Impact:

---

86 | **1 of 20** | **NE/150.5** | **94.9 / -4.98** | **CP EXPRESS & TRANSPORT 2183 PARKDALE AVE. MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON** | **SPL**

Ref No: 94405
Site No:
Incident Dt: 12/13/1993
Year:
Incident Cause: CONTAINER OVERFLOW
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	56101
Nature of Impact:		**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	WORKS, FIRE
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	12/13/1993	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	ERROR	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	C.P. EXPRESS - 30 L OF DIESEL FUEL TO PAVEMENT WHEN FUELING TRUCK.		
Contaminant Qty:			

86	2 of 20	NE/150.5	94.9 / -4.98	C P EXPRESS & TRANSPORT LTD 2183 PARKDALE AV BROCKVILLE ON	PRT

Location ID:	2257
Type:	private
Expiry Date:	
Capacity (L):	13638.00
Licence #:	0001045323

86	3 of 20	NE/150.5	94.9 / -4.98	TRANSPORT TRUCK 2183 PARKDALE RD. AT MYERS TRANSPORT LOADING DOCK. TRANSPORT TRUCK (CARGO) BROCKVILLE CITY ON	SPL

Ref No:	164580	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	2/12/1999	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	OTHER CONTAINER LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	56101
Nature of Impact:	Soil contamination	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2/12/1999	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	UNKNOWN	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	MYERS TRANSPORT- 90 KG THERMOGUARD(UN 3077) TO GRND AT LOADING DOCK.		
Contaminant Qty:			

86	4 of 20	NE/150.5	94.9 / -4.98	CP EXPRESS (SEE & USE ON1890804) 2183 PARKDALE AVENUE	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

BROCKVILLE ON K6V 5V8

Generator No:	ON0048187	**PO Box No:**	
Status:		**Country:**	
Approval Years:	93,94,95,96,97	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	4561		
SIC Description:	GEN. FREIGHT TRUCK.		

Detail(s)

Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS

86	5 of 20	NE/150.5	94.9 / -4.98	CANADIAN PACIFIC (SEE & USE ON1890804) 2183 PARKDALE AVENUE BROCKVILLE ON K6V 5V8	GEN

Generator No:	ON0048187	**PO Box No:**	
Status:		**Country:**	
Approval Years:	98	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	4561		
SIC Description:	GEN. FREIGHT TRUCK.		

Detail(s)

Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS

86	6 of 20	NE/150.5	94.9 / -4.98	3028241 CANADA LIMITED 2183 PARKDALE AVEUNE BROCKVILLE ON	GEN

Generator No:	ON1890804	**PO Box No:**	
Status:		**Country:**	
Approval Years:	94	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	4561		
SIC Description:	GEN. FREIGHT TRUCK.		

Detail(s)

Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS

86	7 of 20	NE/150.5	94.9 / -4.98	INTERLINK FREIGHT SYSTEMS 2183 PARKDALE AVENUE	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

BROCKVILLE ON

Generator No: ON1890804
Status:
Approval Years: 95,96,97,98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 4561
SIC Description: GEN. FREIGHT TRUCK.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

---

86 | 8 of 20 | NE/150.5 | 94.9 / -4.98 | **Meyers Transport**
2183 Parkedale Ave.
Brockville ON K6V 5W1 | GEN

Generator No: ON4174724
Status:
Approval Years: 04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 488519
SIC Description: Other Freight Transportation Arrangement

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 113
Waste Class Desc: ACID WASTE - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

86 | 9 of 20 | NE/150.5 | 94.9 / -4.98 | **2183 Parkedale Ave,**
Brockville ON | SPL

Ref No: 7330-7FS73Z
Site No:
Incident Dt:
Year:
Incident Cause: Other Discharges
Incident Event:
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Not Anticipated

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Transport Truck
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office: Kingston - District
Site Postal Code:
Site Region:
Site Municipality: Brockville

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Nature of Impact: Soil Contamination
Receiving Medium:
Receiving Env:
MOE Response: No Field Response
Dt MOE Arvl on Scn:
MOE Reported Dt: 6/20/2008
Dt Document Closed:
Incident Reason: Unknown - Reason not determined
Site Name: Meyers Transport<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Myers Transport - 250L DSL to gravel - cleaning
Contaminant Qty: 200 L

Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Land Spills
Source Type:

---

86 | 10 of 20 | NE/150.5 | 94.9 / -4.98 | **INTERLINK FREIGHT SYSTEMS INC**
2183 PARKEDALE AV
BROCKVILLE ON | EXP

Instance No: 10180867
Instance ID: 13364
Instance Type: FS Facility
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

86 | 11 of 20 | NE/150.5 | 94.9 / -4.98 | **C P EXPRESS & TRANSPORT LTD**
2183 PARKEDALE AV
BROCKVILLE ON | EXP

Instance No: 9368160
Instance ID: 380755
Instance Type: FS Facility
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

86 | 12 of 20 | NE/150.5 | 94.9 / -4.98 | **INTERLINK FREIGHT SYSTEMS INC**
2183 PARKEDALE AV
BROCKVILLE ON | EXP

Instance No: 11482858
Instance ID: 86995
Instance Type: FS Liquid Fuel Tank
Description: FS Liquid Fuel Tank
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

86 | 13 of 20 | NE/150.5 | 94.9 / -4.98 | **C P EXPRESS & TRANSPORT LTD**
2183 PARKEDALE AV
BROCKVILLE ON K6V 5V8 | EXP

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance No: 10618441
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 12/29/1990

---

86 **14 of 20** **NE/150.5** **94.9 / -4.98** **INTERLINK FREIGHT SYSTEMS INC**
2183 PARKEDALE AV
BROCKVILLE ON **EXP**

Instance No: 11482878
Instance ID: 86803
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

86 **15 of 20** **NE/150.5** **94.9 / -4.98** **C P EXPRESS & TRANSPORT LTD**
2183 PARKEDALE AV
BROCKVILLE ON **EXP**

Instance No: 10618470
Instance ID: 29775
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

86 **16 of 20** **NE/150.5** **94.9 / -4.98** **Meyers Transport**
2183 Parkedale Ave.
Brockville ON **GEN**

Generator No: ON4174724
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 488519
SIC Description: Other Freight Transportation Arrangement

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 113
Waste Class Desc: ACID WASTE - OTHER METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 145

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

---

86 **17 of 20** **NE/150.5** **94.9 / -4.98** **INTERLINK FREIGHT SYSTEMS INC**
2183 PARKEDALE AV
BROCKVILLE ON K6V 5V8 **EXP**

Instance No: 11482858
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 3/13/1997

---

86 **18 of 20** **NE/150.5** **94.9 / -4.98** **C P EXPRESS & TRANSPORT LTD**
2183 PARKEDALE AV
BROCKVILLE ON K6V 5V8 **EXP**

Instance No: 10618441
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 12/29/1990

---

86 **19 of 20** **NE/150.5** **94.9 / -4.98** **Meyers Transport Limited**
2183 Parkedale Ave
Brockville ON **SPL**

Ref No: 8018-9XWCJN
Site No: NA
Incident Dt: 6/28/2015
Year:
Incident Cause: Leak/Break
Incident Event:
Contaminant Code: 36
Contaminant Name: ARGON (COMPRESSED GAS)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact: Air
Receiving Medium:
Receiving Env:
MOE Response: N
Dt MOE Arvl on Scn:
MOE Reported Dt: 6/28/2015

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address: 2183 Parkedale Ave
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: Brockville
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Dt Document Closed: | **SAC Action Class:** Air Spills - Gases and Vapours
Incident Reason: Equipment Failure | **Source Type:**
Site Name: Meyers Transport Ltd<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Compressed Argon gas leak to atm
Contaminant Qty:

---

86 **20 of 20** **NE/150.5** **94.9 / -4.98** **1310463 Ontario Ltd** **GEN**
2183 Parkdale Ave
Brockville ON K6V 5W1

Generator No: ON8163417 | **PO Box No:**
Status: | **Country:** Canada
Approval Years: 2014 | **Choice of Contact:** CO_OFFICIAL
Contam. Facility: No | **Co Admin:** David Joyce
MHSW Facility: No | **Phone No Admin:** 800-565-3708 Ext.6009
SIC Code: 484110, 484122
SIC Description: GENERAL FREIGHT TRUCKING, LOCAL, 484122

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

---

87 **1 of 1** **NE/179.7** **94.9 / -4.98** **2183 Parkedale Avenue** **EHS**
Brockville ON

Order No: 20141014048 | **Nearest Intersection:**
Status: C | **Municipality:** Brockville
Report Type: Standard Report | **Client Prov/State:** ON
Report Date: 21-OCT-14 | **Search Radius (km):** .25
Date Received: 14-OCT-14 | **X:** -75.69148
Previous Site Name: | **Y:** 44.608877
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

---

88 **1 of 17** **SW/151.1** **105.6 / 5.79** **ESSO PETROLEUM CANADA** **SPL**
220 CENTRAL AVE. STORAGE TANK
BROCKVILLE CITY ON

Ref No: 106704 | **Discharger Report:**
Site No: | **Material Group:**
Incident Dt: 10/26/1994 | **Health/Env Conseq:**
Year: | **Client Type:**
Incident Cause: CONTAINER OVERFLOW | **Sector Type:**
Incident Event: | **Agency Involved:**
Contaminant Code: | **Nearest Watercourse:**
Contaminant Name: | **Site Address:**
Contaminant Limit 1: | **Site District Office:**
Contam Limit Freq 1: | **Site Postal Code:**
Contaminant UN No 1: | **Site Region:**
Environment Impact: NOT ANTICIPATED | **Site Municipality:** 56101
Nature of Impact: | **Site Lot:**
Receiving Medium: LAND | **Site Conc:**
Receiving Env: | **Northing:**
MOE Response: | **Easting:**
Dt MOE Arvl on Scn: | **Site Geo Ref Accu:**
MOE Reported Dt: 10/26/1994 | **Site Map Datum:**
Dt Document Closed: | **SAC Action Class:**
Incident Reason: ERROR | **Source Type:**

Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: QUEENSWAY TANK LINES-3 L DIESEL TO CONCRETE PAD, TANK OVERFILL,CLEANED-UP.
Contaminant Qty:

---

88 **2 of 17** **SW/151.1** **105.6 / 5.79** **QUEENSWAY TANK LINES** **SPL**
220 CENTRAL AVE TANK TRUCK (CARGO)
BROCKVILLE CITY ON

Ref No: 85561 | **Discharger Report:**
Site No: | **Material Group:**
Incident Dt: 5/14/1993 | **Health/Env Conseq:**
Year: | **Client Type:**
Incident Cause: PIPE/HOSE LEAK | **Sector Type:**
Incident Event: | **Agency Involved:**
Contaminant Code: | **Nearest Watercourse:**
Contaminant Name: | **Site Address:**
Contaminant Limit 1: | **Site District Office:**
Contam Limit Freq 1: | **Site Postal Code:**
Contaminant UN No 1: | **Site Region:**
Environment Impact: NOT ANTICIPATED | **Site Municipality:** 56101
Nature of Impact: | **Site Lot:**
Receiving Medium: LAND | **Site Conc:**
Receiving Env: | **Northing:**
MOE Response: | **Easting:**
Dt MOE Arvl on Scn: | **Site Geo Ref Accu:**
MOE Reported Dt: 5/14/1993 | **Site Map Datum:**
Dt Document Closed: | **SAC Action Class:**
Incident Reason: ERROR | **Source Type:**
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: QUEENSWAY TANK LINES - 4 L OF DIESEL FUEL TO ASPHALT
Contaminant Qty:

---

88 **3 of 17** **SW/151.1** **105.6 / 5.79** **Imperial Oil Inc.** **EBR**
220 Central Avenue West Brockville Ontario K6V
5T7 CITY OF BROCKVILLE
ON

EBR Registry No: IT8E0025 | **Decision Posted:**
Ministry Ref No: 98-189 | **Exception Posted:**
Notice Type: Instrument Decision | **Section:**
Notice Stage: 800473428 | **Act 1:**
Notice Date: January 04, 1999 | **Act 2:**
Proposal Date: November 30, 1998 | **Site Location Map:**
Year: 1998
Instrument Type:
Off Instrument Name:
Posted By:
Company Name: Imperial Oil Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 1961 Merivale Road, Nepean Ontario, K2G 5T7
Comment Period:
URL:

Site Location Details:

220 Central Avenue West Brockville Ontario K6V 5T7 CITY OF BROCKVILLE

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

88 **4 of 17** **SW/151.1** **105.6 / 5.79** **220 Central Ave. W. Brockville ON** **EHS**

Order No:	20020808008	**Nearest Intersection:**	Decker Ave.
Status:	C	**Municipality:**	
Report Type:	Basic Report	**Client Prov/State:**	ON
Report Date:	8/16/02	**Search Radius (km):**	0.25
Date Received:	8/8/02	**X:**	-75.70543
Previous Site Name:		**Y:**	44.59282
Lot/Building Size:			
Additional Info Ordered:			

88 **5 of 17** **SW/151.1** **105.6 / 5.79** **ESSO PETROLEUM CANADA 220 CENTRAL AVENUE, BROCKVILLE C/O 1 DUNCAN MILL ROAD DON MILLS ON M3B 1Z2** **GEN**

Generator No:	ON0552398	**PO Box No:**	
Status:		**Country:**	
Approval Years:	88,89	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	0000		
SIC Description:	*** NOT DEFINED ***		

Detail(s)

Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS
Waste Class:	221
Waste Class Desc:	LIGHT FUELS
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS

88 **6 of 17** **SW/151.1** **105.6 / 5.79** **ESSO PETROLEUM CANADA 220 CENTRAL AVENUE BROCKVILLE ON K6V 5T7** **GEN**

Generator No:	ON0552398	**PO Box No:**	
Status:		**Country:**	
Approval Years:	92,93,97	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	5111		
SIC Description:	PETROLEUM PROD., WH.		

Detail(s)

Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS
Waste Class:	221
Waste Class Desc:	LIGHT FUELS

Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS

88 **7 of 17** **SW/151.1** **105.6 / 5.79** **ESSO PETROLEUM CANADA 14-645 220 CENTRAL AVENUE, BROCKVILLE C/O 1 DUNCAN MILL ROAD DON MILLS ON M3B 1Z2** **GEN**

Generator No:	ON0552398	**PO Box No:**	
Status:		**Country:**	
Approval Years:	94,95,96	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	5111		
SIC Description:	PETROLEUM PROD., WH.		

Detail(s)

Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS
Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS
Waste Class:	221
Waste Class Desc:	LIGHT FUELS
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES

88 **8 of 17** **SW/151.1** **105.6 / 5.79** **IMPERIAL OIL LIMITED 220 CENTRAL AVENUE WEST BROCKVILLE ON K6V 5T7** **GEN**

Generator No:	ON0552398	**PO Box No:**	
Status:		**Country:**	
Approval Years:	98,99,00,01	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	5111		
SIC Description:	PETROLEUM PROD., WH.		

Detail(s)

Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS
Waste Class:	221
Waste Class Desc:	LIGHT FUELS
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS

88 **9 of 17** **SW/151.1** **105.6 / 5.79** **IMPERIAL OIL 220 CENTRAL AVENUE WEST** **GEN**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				BROCKVILLE ON K6V 5T7	

Generator No: ON0552398
Status:
Approval Years: 02,03,04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
88	10 of 17	SW/151.1	105.6 / 5.79	220 Central Avenue West Brockville ON K6V 4N8	EHS

Order No: 20080606012
Status: C
Report Type: Complete Report
Report Date: 6/13/2008
Date Received: 6/6/2008
Previous Site Name:
Lot/Building Size: Lot area = 1.303 ha
Additional Info Ordered: Fire Insur. Maps And /or Site Plans

Nearest Intersection: Decker Drive @ Central Avenue West
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -75.70556
Y: 44.593898

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
88	11 of 17	SW/151.1	105.6 / 5.79	Imperial Oil Limited 220 CENTRAL AVE W, BROCKVILLE, ON, K6V 4N8 BROCKVILLE ON K6V 4N8	RSC

RSC ID: 46007
RA No:
RSC Type:
Curr Property Use: Commercial
Ministry District: BROCKVILLE
Filing Date: 13-Feb-09
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686: No

Cert Date: 4-Sep-08
Cert Prop Use No: No CPU
Intended Prop Use: Commercial
Qual Person Name: Charles Normandeau
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N): Yes
Accuracy Estimate: 21 to 100 meters
Telephone: 416-4417387
Fax: 416-4417400
Email: charles.e.normandeau@esso.ca

Asmt Roll No: 08-02-030-070-308-00-0000
Prop ID No (PIN): 44188-0014
Property Municipal Address: 220 CENTRAL AVE W, BROCKVILLE, ON, K6V 4N8
Mailing Address: 90 WYNFORD DR, TORONTO, ON, M3C 1K5
Latitude & Latitude: 44.59388890N 75.70555560W
UTM Coordinates: NAD83 18-444000-4938080 (converted from Latitude & Longitude)
Consultant:
Legal Desc: Part of lots 13 & 14 Registered Plan 4; Part of Lincoln Street Registered Plan 4 closed by LR156141; Part of lot 14 Concession 1, Township of Elizabethtown; Parts 1, 2 & 3, 28R2558; S/T 31E1705, 35E5787; City of Brockville, Ontario
Measurement Method: Digitized from a satellite image
Applicable Standards: Full Depth Site Conditions Standard, with Potable Ground Water, Coarse Textured Soil, for Industrial/Commercial/Community property use
RSC PDF:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
88	12 of 17	SW/151.1	105.6 / 5.79	IMPERIAL OIL LIMITED C/O AUDREY STURGE 220 CENTRAL AV W BROCKVILLE ON	EXP

Instance No: 10244267
Instance ID: 14384
Instance Type: FS Facility
Description: FS Gasoline Station - Card/Keylock
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
88	13 of 17	SW/151.1	105.6 / 5.79	DAVID R BANGS FUELS LTD 220 CENTRAL AV W BROCKVILLE ON	EXP

Instance No: 10466267
Instance ID: 19411
Instance Type: FS Highway Tank - Gas/Diesel
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
88	14 of 17	SW/151.1	105.6 / 5.79	DAVID R BANGS FUELS LTD 220 CENTRAL AV W BROCKVILLE ON	EXP

Instance No: 10483730
Instance ID: 23821
Instance Type: FS Highway Tank - Gas/Diesel
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
88	15 of 17	SW/151.1	105.6 / 5.79	IMPERIAL OIL LIMITED C/O AUDREY STURGE 220 CENTRAL AV W BROCKVILLE ON K6V 5T7	EXP

Instance No: 11569455
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 11/6/1998

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
88	16 of 17	SW/151.1	105.6 / 5.79	IMPERIAL OIL LIMITED C/O AUDREY STURGE 220 CENTRAL AV W BROCKVILLE ON	EXP

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance No: 11569475
Instance ID: 90989
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

88 **17 of 17** **SW/151.1** **105.6 / 5.79** **IMPERIAL OIL LIMITED C/O AUDREY STURGE**
220 CENTRAL AVE W
BROCKVILLE ON K6V 5T7 **EXP**

Instance No: 11569455
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Gasoline Station - Card/Keylock
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 11/6/1998

---

89 **1 of 1** **NE/213.3** **94.9 / -4.98**
ON **WWIS**

Well ID: 7242292
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status:
Water Type:
Casing Material:
Audit No: C22567
Tag: A153941
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

PDF URL (Map):

Data Entry Status: Yes
Data Src:
Date Received: 6/1/2015
Selected Flag: Yes
Abandonment Rec:
Contractor: 1844
Form Version: 8
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1005391902
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11/3/2014
Remarks:

Elevation: 95.42398
Elevrc:
Zone: 18
East83: 445114
North83: 4939766
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

---

90 **1 of 1** **NE/140.5** **94.9 / -4.98** **lot 10 con 1**
BROCKVILLE ON **WWIS**

Well ID: 7299908
Construction Date:
Primary Water Use: Test Hole
Sec. Water Use:
Final Well Status: 0
Water Type:
Casing Material:
Audit No: Z261836
Tag: A228259
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/729\7299908.pdf

Data Entry Status:
Data Src:
Date Received: 11/27/2017
Selected Flag: Yes
Abandonment Rec:
Contractor: 7085
Form Version: 7
Owner:
Street Name: 2183 PARKDALE AVENUE
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 010
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1006828615
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/24/2017
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 93.800666
Elevrc:
Zone: 18
East83: 445184
North83: 4939733
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007054505
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 77
Mat2 Desc: LOOSE
Mat3:

Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 2.44
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007054506
Layer: 2
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 2.44
Formation End Depth: 4.12
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007054516
Layer: 2
Plug From: 0.91
Plug To: 4.12
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007054515
Layer: 1
Plug From: 0
Plug To: 0.91
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1007054514
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1007054503
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007054510
Layer: 1
Material: 1
Open Hole or Material: STEEL

Depth From: -.61
Depth To: .61
Casing Diameter: 10.16
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Casing

Casing ID: 1007054511
Layer: 2
Material: 5
Open Hole or Material: PLASTIC
Depth From: -.61
Depth To: 1.07
Casing Diameter: 5.08
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007054512
Layer: 1
Slot: .10
Screen Top Depth: 1.07
Screen End Depth: 4.12
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.03

Results of Well Yield Testing

Pump Test ID: 1007054504
Pump Set At:
Static Level: 1.37
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code: 0
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1007054509
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 2.44
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1007054507
Diameter: 25.4

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Depth From: 0
Depth To: 0.61
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1007054508
Diameter: 16.51
Depth From: 0.61
Depth To: 4.12
Hole Depth UOM: m
Hole Diameter UOM: cm

---

91 **1 of 1** **NE/103.0** **94.9 / -4.98** **lot 10 con 1 BROCKVILLE ON** **WWIS**

Well ID: 7299907
Construction Date:
Primary Water Use: Test Hole
Sec. Water Use: Monitoring
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z261837
Tag: A228258
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

PDF URL (Map):

Data Entry Status:
Data Src:
Date Received: 11/27/2017
Selected Flag: Yes
Abandonment Rec:
Contractor: 7085
Form Version: 7
Owner:
Street Name: 2183 PARKDALE AVENUE
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 010
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1006828612
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/24/2017
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 94.030876
Elevrc:
Zone: 18
East83: 445214
North83: 4939710
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1007054435

Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3:
Mat3 Desc:
Formation Top Depth: 2.44
Formation End Depth: 4.12
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007054434
Layer: 2
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Mat2 Desc: SILT
Mat3:
Mat3 Desc:
Formation Top Depth: .61
Formation End Depth: 2.44
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007054433
Layer: 1
Color: 2
General Color: GREY
Mat1: 11
Most Common Material: GRAVEL
Mat2: 77
Mat2 Desc: LOOSE
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: .61
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007054445
Layer: 1
Plug From: 0
Plug To: 0.91
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007054446
Layer: 2
Plug From: 0.91

Plug To: 4.12
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1007054444
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1007054431
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007054440
Layer: 2
Material: 1
Open Hole or Material: STEEL
Depth From: -.61
Depth To: .61
Casing Diameter: .16
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Casing

Casing ID: 1007054439
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: -.61
Depth To: 1.07
Casing Diameter: 5.08
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007054441
Layer: 1
Slot: .10
Screen Top Depth: 1.07
Screen End Depth: 4.12
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.03

Results of Well Yield Testing

Pump Test ID: 1007054432
Pump Set At:
Static Level: 1.37
Final Level After Pumping:
Recommended Pump Depth:

Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code: 0
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1007054438
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1007054436
Diameter: 25.4
Depth From: 0
Depth To: 0.61
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1007054437
Diameter: 16.51
Depth From: 0.61
Depth To: 4.12
Hole Depth UOM: m
Hole Diameter UOM: cm

92 | ***1 of 1*** | ***NE/225.3*** | ***94.9 / -4.98*** | ***lot 10 con 1 BROCKVILLE ON*** | ***WWIS***

Well ID: 7299909
Construction Date:
Primary Water Use: Test Hole
Sec. Water Use: Monitoring
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z261835
Tag: A228260
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 11/27/2017
Selected Flag: Yes
Abandonment Rec:
Contractor: 7085
Form Version: 7
Owner:
Street Name: 2183 PARKDALE AVENUE
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 010
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map):

Bore Hole Information

Bore Hole ID:	1006828618	***Elevation:***	95.736793
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	445125
Code OB Desc:		***North83:***	4939794
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	10/24/2017	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007054676
Layer:	3
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	2.44
Formation End Depth:	4.57
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007054674
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	77
Mat2 Desc:	LOOSE
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0
Formation End Depth:	.91
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007054675
Layer:	2
Color:	6
General Color:	BROWN

Mat1:	05
Most Common Material:	CLAY
Mat2:	28
Mat2 Desc:	SAND
Mat3:	
Mat3 Desc:	
Formation Top Depth:	.91
Formation End Depth:	2.44
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007054686
Layer:	1
Plug From:	0
Plug To:	1.37
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007054687
Layer:	2
Plug From:	1.37
Plug To:	4.57
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1007054685
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1007054672
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007054681
Layer:	2
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	1.52
Casing Diameter:	5.08
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Casing

Casing ID:	1007054680
Layer:	1
Material:	7
Open Hole or Material:	OTHER

Depth From: 0
Depth To: .3
Casing Diameter: 7.78
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1007054682
Layer: 1
Slot: .10
Screen Top Depth: 1.52
Screen End Depth: 4.57
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.08

Results of Well Yield Testing

Pump Test ID: 1007054673
Pump Set At:
Static Level: 2.44
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code: 0
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1007054679
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth:
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1007054677
Diameter: 25.4
Depth From: 0
Depth To: 0.3
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1007054678
Diameter: 16.51
Depth From: 0.3
Depth To: 4.57
Hole Depth UOM: m

Hole Diameter UOM: cm

93 **1 of 1** **SW/190.1** **105.2 / 5.35** **Sands Medical Inc.** **SCT**
300 Central Ave W
Brockville ON K6V 5V2

Established: 01-JUL-87
Plant Size (ft²): 4500
Employment:

--Details--
Description: Cut and Sew Clothing Contracting
SIC/NAICS Code: 315210

Description: Medical Equipment and Supplies Manufacturing
SIC/NAICS Code: 339110

Description: Clothing and Clothing Accessories Wholesaler-Distributors
SIC/NAICS Code: 414110

Description: Professional Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417930

Description: All Other Cut and Sew Clothing Manufacturing
SIC/NAICS Code: 315299

Description: New and Used Automobile and Light-Duty Truck Wholesaler-Distributors
SIC/NAICS Code: 415110

Description: Other Women's and Girls' Cut and Sew Clothing Manufacturing
SIC/NAICS Code: 315239

Description: Other Men's and Boys' Cut and Sew Clothing Manufacturing
SIC/NAICS Code: 315229

94 **1 of 1** **NE/134.1** **94.9 / -4.98** **Canarm Limited** **ECA**

Canarm Limited ON K6V5V6

Approval No: 2443-9HUSPX
Approval Date: 7/7/14
Status: Approved
Record Type:
Link Source:
SWP Area Name:
Approval Type:
Project Type: Air/Noise
Address:
Full Address: Canarm Limited, rockville Plant 2157 Parkedale ve Brockville Citynited Counties of Leeds and Grenville K6V5V6
Full PDF Link:

MOE District:
City: Canarm Limited
Longitude: -75.690277777777779988355177920311689 3768310546875
Latitude: 44.609166666666666856144729536026716232 2998046875
Geometry X:
Geometry Y:

95 **1 of 25** **SW/117.0** **106.4 / 6.57** **DOUG SUMMERS FUELS A DIV OF UNIVERSAL TERMINALS** **PRT**
260 CENTRAL AV W
BROCKVILLE ON

Location ID: 4418
Type: retail
Expiry Date: 1995-10-31

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Capacity (L): 231846
Licence #: 0030060001

---

95 **2 of 25** **SW/117.0** **106.4 / 6.57** **REYNOLDS CENTRAL FUELS**
260 CENTRAL AVE. TANK TRUCK (CARGO)
BROCKVILLE CITY ON **SPL**

Ref No: 128660
Site No:
Incident Dt: 7/2/1996
Year:
Incident Cause: OTHER CONTAINER LEAK
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: POSSIBLE
Nature of Impact: Soil contamination
Receiving Medium: LAND
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/2/1996
Dt Document Closed:
Incident Reason: ERROR
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: REYNOLDS CENTRAL FUELS: 45 L FUEL OIL TO GROUND, CONTAINED & CLEANING.
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 56101
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

95 **3 of 25** **SW/117.0** **106.4 / 6.57** **REYNOLDS-CENTRAL FUELS**
260 CENTRAL AVE. W. P.O. BOX 789
BROCKVILLE ON K6V 5W1 **GEN**

Generator No: ON0248900
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 4569
SIC Description: OTHER TRUCK./TRANS.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

95 **4 of 25** **SW/117.0** **106.4 / 6.57** **REYNOLDS-CENTRAL FUELS**
260 CENTRAL AVE. W.
BROCKVILLE ON K6V 5W1 **GEN**

Generator No: ON0248900

PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:
Approval Years: 92,93,97
Contam. Facility:
MHSW Facility:
SIC Code: 4569
SIC Description: OTHER TRUCK./TRANS.

Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

95 **5 of 25** **SW/117.0** **106.4 / 6.57** **REYNOLDS-CENTRAL FUELS 33-162**
260 CENTRAL AVE. W. P.O. BOX 789
BROCKVILLE ON K6V 5W1 **GEN**

Generator No: ON0248900
Status:
Approval Years: 94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 4569
SIC Description: OTHER TRUCK./TRANS.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

95 **6 of 25** **SW/117.0** **106.4 / 6.57** **REYNOLDS-CENTRAL FUELS**
260 CENTRAL AVENUE WEST
BROCKVILLE ON K6V 5W1 **GEN**

Generator No: ON0248900
Status:
Approval Years: 98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 4569
SIC Description: OTHER TRUCK./TRANS.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Desc:		WASTE OILS & LUBRICANTS			

95 **7 of 25** **SW/117.0** **106.4 / 6.57** **Burnbrae Farms** **GEN**
260 Central Avenue
Brockville ON

Generator No: ON7698552
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 311615
SIC Description: POULTRY PROCESSING
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

95 **8 of 25** **SW/117.0** **106.4 / 6.57** **ULTRAMAR CANADA INC** **EXP**
260 CENTRAL AV W
BROCKVILLE ON K6V 5W1

Instance No: 10156574
Instance ID:
Instance Type: FS Facility
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 12/9/1999

95 **9 of 25** **SW/117.0** **106.4 / 6.57** **REYNOLDS CENTRAL FUELS DIV OF** **EXP**
ULTRAMAR LTD ATTN RENE TREMBLAY
260 CENTRAL AV W
BROCKVILLE ON

Instance No: 10452975
Instance ID: 19035
Instance Type: FS Highway Tank - Gas/Diesel
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

95 **10 of 25** **SW/117.0** **106.4 / 6.57** **DOUG SUMMERS FUELS DIV OF UNIVERSAL** **EXP**
TERMINALS INC
260 CENTRAL AV W
BROCKVILLE ON

Instance No: 10472999
Instance ID: 22761
Instance Type: FS Highway Tank - Gas/Diesel
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Facility Type:					
Expired Date:					

95 **11 of 25** **SW/117.0** **106.4 / 6.57** **ULTRAMAR CANADA INC** **EXP**
260 CENTRAL AV W
BROCKVILLE ON K6V 5W1

Instance No: 11440269
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 12/9/1999

95 **12 of 25** **SW/117.0** **106.4 / 6.57** **ULTRAMAR CANADA INC** **EXP**
260 CENTRAL AV W
BROCKVILLE ON K6V 5W1

Instance No: 11440231
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 12/9/1999

95 **13 of 25** **SW/117.0** **106.4 / 6.57** **ULTRAMAR CANADA INC** **EXP**
260 CENTRAL AV W
BROCKVILLE ON K6V 5W1

Instance No: 11440251
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 12/9/1999

95 **14 of 25** **SW/117.0** **106.4 / 6.57** **ULTRAMAR CANADA INC** **EXP**
260 CENTRAL AV W
BROCKVILLE ON K6V 5W1

Instance No: 11440289
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 12/9/1999

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
95	15 of 25	SW/117.0	106.4 / 6.57	ULTRAMAR CANADA INC 260 CENTRAL AV W BROCKVILLE ON K6V 5W1	EXP

Instance No: 11440310
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 12/9/1999

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
95	16 of 25	SW/117.0	106.4 / 6.57	Burnbrae Farms 260 Central Avenue Brockville ON K6V 4N8	GEN

Generator No: ON7698552
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 311615
SIC Description: Poultry Processing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
95	17 of 25	SW/117.0	106.4 / 6.57	Burnbrae Farms 260 Central Avenue Brockville ON K6V 4N8	GEN

Generator No: ON7698552
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 311615
SIC Description: Poultry Processing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
95	18 of 25	SW/117.0	106.4 / 6.57	Burnbrae Farms 260 Central Avenue Brockville ON K6V 4N8	GEN

Generator No: ON7698552
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 311615
SIC Description: Poultry Processing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
95	19 of 25	SW/117.0	106.4 / 6.57	ULTRAMAR CANADA INC 260 CENTRAL AV W BROCKVILLE ON K6V 5W1	EXP

Instance No: 11440231
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Bulk Plant (Small)
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 12/9/1999

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
95	20 of 25	SW/117.0	106.4 / 6.57	ULTRAMAR CANADA INC 260 CENTRAL AV W BROCKVILLE ON K6V 5W1	EXP

Instance No: 11440251
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Bulk Plant (Small)
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 12/9/1999

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
95	21 of 25	SW/117.0	106.4 / 6.57	ULTRAMAR CANADA INC 260 CENTRAL AV W BROCKVILLE ON K6V 5W1	EXP

Instance No: 11440310
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Bulk Plant (Small)
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 12/9/1999

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
95	22 of 25	SW/117.0	106.4 / 6.57	ULTRAMAR CANADA INC 260 CENTRAL AV W BROCKVILLE ON K6V 5W1	EXP

Instance No: 11440289
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Bulk Plant (Small)
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Facility Type: FS Liquid Fuel Tank
Expired Date: 12/9/1999

---

95 | 23 of 25 | SW/117.0 | 106.4 / 6.57 | ULTRAMAR CANADA INC
260 CENTRAL AV W
BROCKVILLE ON K6V 5W1 | EXP

Instance No: 11440269
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Bulk Plant (Small)
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 12/9/1999

---

95 | 24 of 25 | SW/117.0 | 106.4 / 6.57 | Burnbrae Farms Ltd
260 Cetral Ave West
Brockville ON K6V 5V7 | GEN

Generator No: ON8698760
Status: Registered
Approval Years: As of Oct 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

---

95 | 25 of 25 | SW/117.0 | 106.4 / 6.57 | Burnbrae Farms Ltd.
260 Central Avenue
Brockville ON K6V 4N8 | GEN

Generator No: ON7802023
Status: Registered
Approval Years: As of Apr 2020
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 270 L
Waste Class Desc: Other specified organic sludges, slurries or solids

---

96 | 1 of 3 | NE/247.9 | 94.9 / -4.98 | BROCKVILLE CITY
PARKEDALE AVE./CALIFORNIA AVE.
BROCKVILLE CITY ON | CA

Certificate #: 3-0544-94-
Application Year: 94
Issue Date: 6/13/1994
Approval Type: Municipal sewage

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

96 | 2 of 3 | NE/247.9 | 94.9 / -4.98 | P.U.C. BROCKVILLE
PARKEDALE AVE./CALIFORNIA AVE.
BROCKVILLE CITY ON | CA

Certificate #: 7-0534-94-
Application Year: 94
Issue Date: 7/6/1994
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

96 | 3 of 3 | NE/247.9 | 94.9 / -4.98 | NE Corner of California Ave and Parkedale Ave
Brockville ON | EHS

Order No: 20041028014
Status: C
Report Type: Complete Report
Report Date: 11/8/04
Date Received: 10/28/04
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.35
X: -75.690498
Y: 44.611366

---

97 | 1 of 26 | NE/124.0 | 94.9 / -4.98 | CANARM LTD.
2157 PARKEDALE AVE.
BROCKVILLE CITY ON | CA

Certificate #: 8-4046-87-
Application Year: 87
Issue Date: 7/16/1987
Approval Type: Industrial air
Status: Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: EXHAUST SYSTEM
Contaminants: Other Contaminant
Emission Control: No Controls

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	2 of 26	NE/124.0	94.9 / -4.98	Canarm Ltd. 2157 Parkedale Ave W Brockville ON K6V 5V6	SCT

Established: 1965
Plant Size (ft²): 50000
Employment:

--Details--
Description: All Other Plastic Product Manufacturing
SIC/NAICS Code: 326198

Description: Other Ornamental and Architectural Metal Products Manufacturing
SIC/NAICS Code: 332329

Description: Agricultural Implement Manufacturing
SIC/NAICS Code: 333110

Description: Industrial and Commercial Fan and Blower and Air Purification Equipment Manufacturing
SIC/NAICS Code: 333413

Description: Lighting Fixture Manufacturing
SIC/NAICS Code: 335120

Description: Small Electrical Appliance Manufacturing
SIC/NAICS Code: 335210

Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	3 of 26	NE/124.0	94.9 / -4.98	CANARM LIMITED 2157 PARKEDALE AVENUE BROCKVILLE CITY ON	CA

Certificate #: 8-4024-96-
Application Year: 96
Issue Date: 4/1/1996
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: EXHAUST FOR CURING OVEN
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	4 of 26	NE/124.0	94.9 / -4.98	Canarm Limited 2157 Parkdale Avenue Brockville Ontario K6V 5V6 CITY OF BROCKVILLE ON	EBR

EBR Registry No: IA03E0335
Ministry Ref No: 4197-5KCQ67
Notice Type: Instrument Decision
Notice Stage: 800719629
Notice Date: August 09, 2004
Proposal Date: March 12, 2003
Year: 2003
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Posted By:
Company Name: Canarm Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 2157 Parkdale Avenue, Brockville Ontario, K6V 5V6
Comment Period:
URL:

Site Location Details:

2157 Parkdale Avenue Brockville Ontario K6V 5V6 CITY OF BROCKVILLE

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	5 of 26	NE/124.0	94.9 / -4.98	CANARM LTD. 2157 PARKEDALE AVE. W. BROCKVILLE ON K6V 5V6	GEN

Generator No: ON0202500
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 3311
SIC Description: SMALL ELECT. APPL.
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	6 of 26	NE/124.0	94.9 / -4.98	CANARM LTD. 08-027 2157 PARKEDALE AVE. W. BROCKVILLE ON K6V 5V6	GEN

Generator No: ON0202500
Status:
Approval Years: 92,93,94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 3311
SIC Description: SMALL ELECT. APPL.
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

---

97 **7 of 26** **NE/124.0** **94.9 / -4.98** **CANARM LIMITED**
2157 PARKEDALE AVENUE
BROCKVILLE ON K6V 5V6 **GEN**

Generator No: ON0202500
Status:
Approval Years: 97,98,99,00,01,02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 3311
SIC Description: SMALL ELECT. APPL.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

97 **8 of 26** **NE/124.0** **94.9 / -4.98** **CANARM**
2157 PARKEDALE AVENUE NOT AVAILABLE
BROCKVILLE ON K6V5V6 **NPRI**

NPRI ID: 11091
Other ID: Y
No Other ID: 1
Track ID: 32832
Report ID: 92763
Report Type: NPRI
Rpt Type ID: 1
Report Year: 2004
Not-Current Rpt?: No
Yr of Last Filed Rpt: 2004
Fac ID: 156382
Fac Name: CANARM, BROCKVILLE PLANT
Fac Address1: 2157 PARKEDALE AVENUE
Fac Address2: NOT AVAILABLE
Fac Postal Zip: K6V5V6
Facility Lat: 44.6099
Facility Long: -75.6916
DLS (Last Filed Rpt):
Facility DLS:
Datum: 1983
Facility Cmnts: True
URL:
No of Empl.: 120

Org ID: 41207
Submit Date: 1/17/2006
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 164156
Cont Type: MED
Contact Title:
Cont First Name: JEFF
Cont Last Name: SHAVER
Contact Position: PRODUCTION MANAGER
Contact Fax: 6133428437
Contact Ph.: 6133425424
Cont Area Code: 613
Contact Tel.: 33425424
Contact Ext.: 1329
Cont Fax Area Cde: 613
Contact Fax: 33428437
Contact Email: JSHAVER@CANARM.CA
Latitude: 44.6099
Longitude: -75.6916
UTM Zone:
UTM Northing:
UTM Easting:
Waste Streams: False

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Parent Co.: N
No Parent Co.:
Pollut Prev Cmnts: True
Stacks: No
No of Stacks:
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 33
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3335
NAICS 4 Description: Metalworking machinery manufacturing
NAICS Code (6 digit): 333519
NAICS 6 Description: Other metalworking machinery manufacturing

No Streams:
Waste Off Sites: False
No Off Sites:
Shutdown:
No of Shutdown:

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Polymeric diphenylmethane diisocyanate
Chem (fr): Diisocyanate de diphénylméthane (polymérisé)
Quantity: .428
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

---

97 **9 of 26** **NE/124.0** **94.9 / -4.98** **Canarm Ltd.**
2157 Parkedale Ave
Brockville ON K6V 5V6 **SCT**

Established: 01-AUG-60
Plant Size (ft²):
Employment:

--Details--
Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
SIC/NAICS Code: 332999

---

97 **10 of 26** **NE/124.0** **94.9 / -4.98** **Canarm Limited**
2157 Parkdale Avenue
Brockville ON **CA**

Certificate #: 9712-5YNSQB
Application Year: 2004
Issue Date: 7/30/2004
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	11 of 26	NE/124.0	94.9 / -4.98	Canarm Limited 2157 Parkedale Avenue Brockville United Counties of Leeds and Grenville K6V 5V6 CITY OF BROCKVILLE ON	EBR

EBR Registry No: 011-4951
Ministry Ref No: 2055-8LMSYB
Notice Type: Instrument Decision
Notice Stage: 803923403
Notice Date: August 13, 2014
Proposal Date: November 07, 2011
Year: 2011
Instrument Type: (EPA Part II.1-air) - Environmental Compliance Approval (project type: air)
Off Instrument Name:
Posted By:
Company Name: Canarm Limited
Site Address:
Location Other:
Proponent Name:
Proponent Address: 2157 Parkedale avenue, Brockville Ontario, Canada K6V 5V6
Comment Period:
URL:

Site Location Details:

2157 Parkedale Avenue Brockville United Counties of Leeds and Grenville K6V 5V6 CITY OF BROCKVILLE

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	12 of 26	NE/124.0	94.9 / -4.98	CANARM LIMITED 2157 PARKEDALE AVENUE BROCKVILLE ON	GEN

Generator No: ON0202500
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 333519
SIC Description: Other Metalworking Machinery Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	13 of 26	NE/124.0	94.9 / -4.98	CANARM LIMITED	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				2157 PARKEDALE AVENUE BROCKVILLE ON	

Generator No: ON0202500
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 333519
SIC Description: Other Metalworking Machinery Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	14 of 26	NE/124.0	94.9 / -4.98	CANARM LIMITED 2157 PARKEDALE AVENUE BROCKVILLE ON	GEN

Generator No: ON0202500
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 333519
SIC Description: Other Metalworking Machinery Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	15 of 26	NE/124.0	94.9 / -4.98	Canarm Limited 2157 Parkedale Ave Brockville ON	SPL

Ref No:	5100-96FN72	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	04-APR-13	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Leak/Break	**Sector Type:**	Pipeline/Components
Incident Event:		**Agency Involved:**	
Contaminant Code:	35	**Nearest Watercourse:**	
Contaminant Name:	NATURAL GAS (METHANE)	**Site Address:**	2157 Parkedale Ave
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Confirmed	**Site Municipality:**	Brockville
Nature of Impact:	Air Pollution	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	NA
MOE Response:	No Field Response	**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	NA
MOE Reported Dt:	04-APR-13	**Site Map Datum:**	NA
Dt Document Closed:		**SAC Action Class:**	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Incident Reason:	Unknown / N/A	**Source Type:**	
Site Name:	Canarm Limited Brockville Plant		
Site County/District:			
Site Geo Ref Meth:	NA		
Incident Summary:	TSSA: gas line leak; evacuation		
Contaminant Qty:	0 other - see incident description		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	16 of 26	NE/124.0	94.9 / -4.98	CANARM LIMITED 2157 PARKEDALE AVENUE BROCKVILLE ON K6V 5V6	GEN

Generator No:	ON0202500	**PO Box No:**	
Status:		**Country:**	
Approval Years:	2012	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	333519		
SIC Description:	Other Metalworking Machinery Manufacturing		

Detail(s)

Waste Class:	212
Waste Class Desc:	ALIPHATIC SOLVENTS
Waste Class:	131
Waste Class Desc:	NEUTRALIZED WASTES - HEAVY METALS
Waste Class:	211
Waste Class Desc:	AROMATIC SOLVENTS
Waste Class:	241
Waste Class Desc:	HALOGENATED SOLVENTS
Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	17 of 26	NE/124.0	94.9 / -4.98	CANARM LTD. 2157 Parkedale AVE Brockville ON K6V 5V6	EASR

Approval No:	R-003-6410654747	**SWP Area Name:**	
Status:	REGISTERED	**MOE District:**	
Date:	2014-04-08	**Municipality:**	Brockville
Record Type:	EASR	**Latitude:**	44.61
Link Source:	MOFA	**Longitude:**	75.69083333
Project Type:	Heating System	**Geometry X:**	
Full Address:		**Geometry Y:**	
Approval Type:	EASR-Heating System		
Full PDF Link:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=6739		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	18 of 26	NE/124.0	94.9 / -4.98	CANARM LIMITED 2157 PARKEDALE AVENUE BROCKVILLE ON	GEN

Generator No:	ON0202500	**PO Box No:**	
Status:		**Country:**	
Approval Years:	2013	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	333519		
SIC Description:	OTHER METALWORKING MACHINERY MANUFACTURING		

Detail(s)

Waste Class:	212
Waste Class Desc:	ALIPHATIC SOLVENTS
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS
Waste Class:	241
Waste Class Desc:	HALOGENATED SOLVENTS
Waste Class:	131
Waste Class Desc:	NEUTRALIZED WASTES - HEAVY METALS
Waste Class:	213
Waste Class Desc:	PETROLEUM DISTILLATES
Waste Class:	122
Waste Class Desc:	ALKALINE WASTES - OTHER METALS
Waste Class:	211
Waste Class Desc:	AROMATIC SOLVENTS
Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
97	19 of 26	NE/124.0	94.9 / -4.98	2157 PARKEDALE AVENUE, BROCKVILLE ON	INC

Incident No:	1076736		
Incident ID:			
Attribute Category:	FS-Perform L1 Incident Insp		
Status Code:			
Incident Location:	2157 PARKEDALE AVENUE, BROCKVILLE - VAPOUR RELEASE		
Drainage System:			

Sub Surface Contam.:
Aff. Prop. Use Water:
Contam. Migrated:
Contact Natural Env.:
Near Body of Water:
Approx. Quant. Rel.:
Equipment Model:
Serial No:
Residential App. Type:
Commercial App. Type:
Industrial App. Type:
Institutional App. Type:
Venting Type:
Vent Connector Mater:
Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Depth Ground Cover:
Regulator Location:
Regulator Type:
Operation Pressure:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Equipment Type:
Cylinder Capacity:
Cylinder Capac. Units:
Cylinder Material Type:
Tank Capacity:
Fuels Occurence Type: Vapour Release
Fuel Type Involved: Natural Gas
Date of Occurence: 2013/04/04 00:00:00
Time of Occurence: 12:30:00
Occur Insp Start Date: 2013/04/04 00:00:00
Any Health Impact: No
Any Environmental Impact: No
Was Service Interrupted: Yes
Was Property Damaged: Yes
Operation Type Involved: Commercial (e.g. restaurant, business unit, etc)
Enforcement Policy: NULL
Prc Escalation Required: NULL
Task No: 4421134
Notes:
Occurence Narrative: gas line damage inside building
Tank Material Type:
Tank Storage Type:
Tank Location Type:
Pump Flow Rate Capac:
Liquid Prop Notes:

---

97 | 20 of 26 | NE/124.0 | 94.9 / -4.98 | **Canarm Limited**, **2157 Parkedale Ave**, **Brockville ON K6V 5V6** | ECA

Approval No: 2443-9HUSPX
Approval Date: 2014-07-07
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Cataraqui
Approval Type: ECA-AIR
Project Type: AIR
Address: 2157 Parkedale Ave
MOE District: Kingston
City:
Longitude: -75.69032
Latitude: 44.60926
Geometry X:
Geometry Y:

Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2055-8LMSYB-14.pdf

---

97 | 21 of 26 | NE/124.0 | 94.9 / -4.98 | **Canarm Limited**, **2157 Parkdale Avenue**, **Brockville ON K6V 5V6** | ECA

Approval No: 9712-5YNSQB
Approval Date: 2004-07-30
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Cataraqui
Approval Type: ECA-AIR
Project Type: AIR
Address: 2157 Parkdale Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/4197-5KCQ67-14.pdf
MOE District: Kingston
City:
Longitude: -75.69032
Latitude: 44.60926
Geometry X:
Geometry Y:

---

97 | 22 of 26 | NE/124.0 | 94.9 / -4.98 | **CANARM LIMITED**, **2157 PARKEDALE AVENUE**, **BROCKVILLE ON K6V 5V6** | GEN

Generator No: ON0202500
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 333519
SIC Description: OTHER METALWORKING MACHINERY MANUFACTURING
PO Box No:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Art W Chillson
Phone No Admin: 6133425424 Ext.1360

Detail(s)

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

97 | 23 of 26 | NE/124.0 | 94.9 / -4.98 | **CANARM LIMITED**, **2157 PARKEDALE AVENUE**, **BROCKVILLE ON K6V 5V6** | GEN

Generator No: ON0202500
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 333519
SIC Description: OTHER METALWORKING MACHINERY MANUFACTURING

PO Box No:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Art W Chillson
Phone No Admin: 6133425424 Ext.1360

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

97 **24 of 26** **NE/124.0** **94.9 / -4.98** **CANARM LIMITED** **2157 PARKEDALE AVENUE** **BROCKVILLE ON K6V 5V6** **GEN**

Generator No: ON0202500
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 122 C
Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 131 L
Waste Class Desc: Neutralized solutions - containing heavy metals

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 145 L
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 211 H
Waste Class Desc: Aromatic solvents and residues

Waste Class: 212 L
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 213 I
Waste Class Desc: Petroleum distillates

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

97 **25 of 26** **NE/124.0** **94.9 / -4.98** **CANARM LIMITED** **2157 PARKEDALE AVENUE** **BROCKVILLE ON K6V 5V6** **GEN**

Generator No: ON0202500
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 333519
SIC Description: OTHER METALWORKING MACHINERY MANUFACTURING

PO Box No:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Art W Chillson
Phone No Admin: 6133425424 Ext.1360

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

97 **26 of 26** **NE/124.0** **94.9 / -4.98** **CANARM LIMITED** **2157 PARKEDALE AVENUE** **BROCKVILLE ON K6V 5V6** **GEN**

Generator No: ON0202500
Status: Registered
Approval Years: As of Apr 2020
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 122 C
Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 211 H
Waste Class Desc: Aromatic solvents and residues

Waste Class: 213 I
Waste Class Desc: Petroleum distillates

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 145 L
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 131 L
Waste Class Desc: Neutralized solutions - containing heavy metals

Waste Class: 212 L
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

---

98 **1 of 4** **SW/232.8** **101.4 / 1.58** **TOM CARR'S SERVICE CENTRE**
340 CENTRAL W
BROCKVILLE ON K6V 5T3 **RST**

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone: 6133424875
List Name:
Description:

---

98 **2 of 4** **SW/232.8** **101.4 / 1.58** **TOWNVIEW AUTO BODY**
340 CENTRAL AVENUE W C/O PO BOX 884
BROCKVILLE ON K6V 5W1 **GEN**

Generator No: ON0341200
Status:
Approval Years: 86,87,88,89,90,92,93,94
Contam. Facility:
MHSW Facility:
SIC Code: 0000
SIC Description: *** NOT DEFINED ***
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

---

98 **3 of 4** **SW/232.8** **101.4 / 1.58** **R & R SERVICE CENTRE**
340 CENTRAL W
BROCKVILLE ON K6V5V2 **RST**

Headcode: 01186800
Headcode Desc: SERVICE STATIONS-GASOLINE, OIL & NATURAL GAS
Phone:
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

98 **4 of 4** **SW/232.8** **101.4 / 1.58** **R & R SERVICE CENTRE**
340 CENTRAL W
BROCKVILLE ON K6V5V2 **RST**

Headcode: 01186800
Headcode Desc: SERVICE STATIONS GASOLINE OIL & NATURAL
Phone: 6133424875
List Name:
Description:

---

99 **1 of 1** **ENE/131.3** **96.9 / -2.98** **92 SALISBURY AVENUE**
BROCKVILLE ON K6V 2T7 **HINC**

External File Num: FS INC 0707-03963
Fuel Occurrence Type: Pipeline Strike
Date of Occurrence: 7/16/2007
Fuel Type Involved: Natural Gas
Status Desc: Completed - Causal Analysis(End)
Job Type Desc: Incident/Near-Miss Occurrence (FS)
Oper. Type Involved: Construction Site (pipeline strike)
Service Interruptions: Yes
Property Damage: Yes
Fuel Life Cycle Stage: Transmission, Distribution and Transportation
Root Cause: Root Cause: Equipment/Material/Component:No Procedures:Yes Maintenance:No Design:No Training:No Management:Yes Human Factors:Yes

Reported Details:
Fuel Category: Gaseous Fuel
Occurrence Type: Incident
Affiliation: Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
County Name: Leeds and Grenville
Approx. Quant. Rel:
Nearby body of water:
Enter Drainage Syst.:
Approx. Quant. Unit:
Environmental Impact:

---

100 **1 of 1** **ENE/102.9** **96.8 / -3.09** **Brockville ON** **WWIS**

Well ID: 7234038
Construction Date:
Primary Water Use: Test Hole
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z187919
Tag: A145689
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

PDF URL (Map):

Data Entry Status:
Data Src:
Date Received: 12/22/2014
Selected Flag: Yes
Abandonment Rec:
Contractor: 7323
Form Version: 7
Owner:
Street Name: 1879 PARKDALE AVE
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1005263337	***Elevation:***	95.966087
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:		***East83:***	445472
Code OB Desc:		***North83:***	4939677
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	9/18/2014	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005443299
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	01
Mat2 Desc:	FILL
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0
Formation End Depth:	
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005443300
Layer:	2
Color:	2
General Color:	GREY
Mat1:	15
Most Common Material:	LIMESTONE
Mat2:	
Mat2 Desc:	
Mat3:	73
Mat3 Desc:	HARD
Formation Top Depth:	
Formation End Depth:	
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005443308
Layer:	1
Plug From:	0
Plug To:	1
Plug Depth UOM:	ft

Annular Space/Abandonment

Sealing Record

Plug ID:	1005443309
Layer:	2
Plug From:	1
Plug To:	10
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005443310
Layer:	3
Plug From:	10
Plug To:	25
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	1005443307
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	AIR PERCUSSION

Pipe Information

Pipe ID:	1005443298
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005443304
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	13
Casing Diameter:	2
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005443305
Layer:	1
Slot:	.10
Screen Top Depth:	13
Screen End Depth:	23
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Water Details

Water ID:	1005443303
Layer:	
Kind Code:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1005443301
Diameter: 8
Depth From: 0
Depth To: 3
Hole Depth UOM: ft
Hole Diameter UOM: inch

Hole Diameter

Hole ID: 1005443302
Diameter: 4
Depth From: 3
Depth To: 25
Hole Depth UOM: ft
Hole Diameter UOM: inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
101	1 of 4	NE/204.5	94.9 / -4.98	WADE-TECH LIMITED 2117 PARKEDALE AVE W BROCKVILLE ON K6V 5V8	SCT

Established: 1978
Plant Size (ft²): 7000
Employment: 8

--Details--
Description: INDUSTRIAL PROCESS FURNACES AND OVENS
SIC/NAICS Code: 3567

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
101	2 of 4	NE/204.5	94.9 / -4.98	WADE TECH LTD.(SEE&USE ON0733800 H 2117 PARKDALE C/O P.O. BOX 730 BROCKVILLE ON K6V 5V8	GEN

Generator No: ON0767700
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 0000
SIC Description: *** NOT DEFINED ***

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
101	3 of 4	NE/204.5	94.9 / -4.98	WADE TECH LTD.(SEE&USE ON0733800 HEWITT) 2117 PARKDALE C/O P.O. BOX 730 BROCKVILLE ON K6V 5V8	GEN

Generator No: ON0767700
Status:
Approval Years: 92,93,94
Contam. Facility:
MHSW Facility:
SIC Code: 0000
SIC Description: *** NOT DEFINED ***

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
101	4 of 4	NE/204.5	94.9 / -4.98	Hands At Work Stitching Servs 2117 Parkedale Ave Brockville ON K6V 5Y6	SCT

Established: 01-JAN-98
Plant Size (ft²):
Employment:

--Details--
Description: Women's and Girls' Cut and Sew Suit, Coat, Tailored Jacket and Skirt Manufacturing
SIC/NAICS Code: 315234

Description: Cut and Sew Clothing Contracting
SIC/NAICS Code: 315210

Description: Curtain and Linen Mills
SIC/NAICS Code: 314120

Description: Other Building Finishing Contractors
SIC/NAICS Code: 238390

Description: Women's and Girls' Cut and Sew Dress Manufacturing
SIC/NAICS Code: 315233

Description: Other Specialized Design Services
SIC/NAICS Code: 541490

Description: Women's and Girls' Cut and Sew Dress Manufacturing
SIC/NAICS Code: 315233

Description: Other Personal and Household Goods Repair and Maintenance
SIC/NAICS Code: 811490

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
102	1 of 1	NE/143.1	95.1 / -4.78	Daltco Electric & Supply 1 Kesco Ave Brockville ON K6V 5V5	SCT

Established: 01-JAN-77
Plant Size (ft²): 10000
Employment:

--Details--
Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Description: Electrical Wiring and Construction Supplies Wholesaler-Distributors
SIC/NAICS Code: 416110

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
103	1 of 2	ENE/149.2	97.9 / -1.98	101 SALISBURY AVE, BROCKVILLE ON	PINC

Incident ID:
Incident No: 1957052
Type: FS-Pipeline Incident
Status Code: Pipeline Damage Reason Est
Fuel Occurrence Tp:
Fuel Type:
Tank Status: RC Established
Task No: 6376981
Spills Action Centre:
Method Details: E-mail

Health Impact:
Environment Impact:
Property Damage: Yes
Service Interupt:
Enforce Policy: Yes
Public Relation:
Pipeline System:
Depth:
Pipe Material:
PSIG:

Fuel Category:	Natural Gas	**Attribute Category:**	FS-Perform P-line Inc Invest
Date of Occurrence:		**Regulator Location:**	
Occurrence Start Date:	2015/10/13		
Operation Type:			
Pipeline Type:			
Regulator Type:			
Summary:	101 SALISBURY AVE, BROCKVILLE - PIPELINE HIT - 1/2"		
Reported By:	Pierre Potvin - ENBRIDGE		
Affiliation:			
Occurrence Desc:			
Damage Reason:	Excavation practices not sufficient		
Notes:			

103 **2 of 2** **ENE/149.2** **97.9 / -1.98** **Enbridge Gas Distribution Inc.**
101 Salisbury Ave, Brockville
Brockville ON K6V 2T6 **SPL**

Ref No:	7422-AEMPKG	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	10/11/2016	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Miscellaneous Communal
Incident Event:	Leak/Break	**Agency Involved:**	
Contaminant Code:	35	**Nearest Watercourse:**	
Contaminant Name:	NATURAL GAS (METHANE)	**Site Address:**	101 Salisbury Ave, Brockville
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	K6V 2T6
Contaminant UN No 1:		**Site Region:**	
Environment Impact:		**Site Municipality:**	Brockville
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Air	**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	10/11/2016	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Incident Reason:	Operator/Human Error	**Source Type:**	
Site Name:	residential site<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	TSSA - Enbridge, ½" plastic line damaged, made safe		
Contaminant Qty:	0 other - see incident description		

104 **1 of 1** **ENE/205.3** **97.9 / -1.98** **Enbridge Energy Distribution Inc.**
94 Bisely Crst
Brockville ON **SPL**

Ref No:	8888-BF2Q42	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	8/14/2019	**Health/Env Conseq:**	2 - Minor Environment
Year:		**Client Type:**	Corporation
Incident Cause:		**Sector Type:**	Miscellaneous Communal
Incident Event:	Leak/Break	**Agency Involved:**	
Contaminant Code:	35	**Nearest Watercourse:**	
Contaminant Name:	NATURAL GAS (METHANE)	**Site Address:**	94 Bisely Crst
Contaminant Limit 1:		**Site District Office:**	Kingston - District
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:	1075	**Site Region:**	Eastern
Environment Impact:		**Site Municipality:**	Brockville
Nature of Impact:		**Site Lot:**	

Receiving Medium:		**Site Conc:**	
Receiving Env:	Air	**Northing:**	
MOE Response:	No	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	8/14/2019	**Site Map Datum:**	
Dt Document Closed:	9/28/2019	**SAC Action Class:**	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Incident Reason:	Operator/Human Error	**Source Type:**	Pipeline/Components
Site Name:	Residential<UNOFFICIAL>		
Site County/District:	United Counties of Leeds and Grenville		
Site Geo Ref Meth:			
Incident Summary:	TSSA FSB: 1/2" plastic IP service linestrike, made safe		
Contaminant Qty:	0 other - see incident description		

105 **1 of 1** **SW/232.4** **99.4 / -0.50** **CENTRAL AVE AUTO SERVICE AND BROCKVILLE TOWING**
380 CENTRAL AV W
BROCKVILLE ON **EXP**

Instance No:	10113220
Instance ID:	12222
Instance Type:	FS Facility
Description:	FS Propane Vehicle Conv Centre
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	
Expired Date:	

106 **1 of 1** **SW/226.5** **100.6 / 0.75** **380 Central Ave W**
Brockville ON K6V5J9 **EHS**

Order No:	20160126119	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	01-FEB-16	**Search Radius (km):**	.25
Date Received:	26-JAN-16	**X:**	-75.707619
Previous Site Name:		**Y:**	44.591948
Lot/Building Size:			
Additional Info Ordered:			

107 **1 of 11** **NE/218.7** **95.9 / -3.98** **WILLIAM CARTAGE LTD**
2089 PARKDALE AV
BROCKVILLE ON **PRT**

Location ID:	2256
Type:	private
Expiry Date:	
Capacity (L):	50000.00
Licence #:	0001044353

107 **2 of 11** **NE/218.7** **95.9 / -3.98** **COONEY HAULAGE LTD.**
2089 PARKDALE AVE.,
BROCKVILLE ON K8V 5R2 **GEN**

Generator No:	ON0061604	**PO Box No:**	
Status:		**Country:**	
Approval Years:	92,93,97	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility:
SIC Code: 4561
SIC Description: GEN. FREIGHT TRUCK.
Phone No Admin:

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

107 **3 of 11** **NE/218.7** **95.9 / -3.98** **GEN**

COONEY HAULAGE LTD. 42-284
2089 PARKDALE AVE., BROCKVILLE C/O PO BOX 186
TRENTON ON K8V 5R2

Generator No: ON0061604
Status:
Approval Years: 94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 4561
SIC Description: GEN. FREIGHT TRUCK.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

107 **4 of 11** **NE/218.7** **95.9 / -3.98** **GEN**

COONEY HAULAGE LTD.
2089 PARKDALE AVENUE
BROCKVILLE ON K8V 5V7

Generator No: ON0061604
Status:
Approval Years: 98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 4561
SIC Description: GEN. FREIGHT TRUCK.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

107 **5 of 11** **NE/218.7** **95.9 / -3.98** **GEN**

COONEY BULK SALES LIMITED
2089 PARKDALE AVENUE
BROCKVILLE ON K8V 5V7

Generator No: ON0061604
Status:
Approval Years: 02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 254
Waste Class Desc: TRANSFER STATION OILS WASTES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

107 **6 of 11** **NE/218.7** **95.9 / -3.98** **EHS**

2089 Parkdale Ave.
Brockville ON

Order No: 20071101048
Status: C
Report Type: CAN - Complete Report
Report Date: 11/12/2007
Date Received: 11/1/2007
Previous Site Name:
Lot/Building Size: Approx. 1.5 Hectares (3.7 Acres)
Additional Info Ordered: Fire Insur. Maps And /or Site Plans; Topographical Maps

Nearest Intersection: North Augusta Road
Municipality: Brockville
Client Prov/State:
Search Radius (km): 0.25
X: -75.688947
Y: 44.611222

---

107 **7 of 11** **NE/218.7** **95.9 / -3.98** **RSC**

Hilliard Cooney Limited
2089 Parkdale Avenue West, Brockville, Ontario
BROCKVILLE ON

RSC ID: 44922
RA No:
RSC Type:
Curr Property Use: Commercial
Ministry District: BROCKVILLE
Filing Date: 20-May-08
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686: No
Asmt Roll No:
Prop ID No (PIN): 44175 - 0425 LT
Property Municipal Address: 2089 Parkdale Avenue West, Brockville, Ontario

Cert Date: 25-Mar-08
Cert Prop Use No: No CPU
Intended Prop Use: Commercial
Qual Person Name: Mr. Gary T. Cooney
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N): Yes
Accuracy Estimate: 6 to 10 meters
Telephone: 613-9626666
Fax:
Email:

Mailing Address: P.O.Box 186, Trenton, Ontario, K8V5R2
Latitude & Latitude: 44.60884390N 75.68859710W (converted from UTM)
UTM Coordinates: NAD83 18-445360-4939730
Consultant:
Legal Desc: PT BLK A PL 253 AS IN LR32902; S/T LR77387; BROCKVILLE
Measurement Method: Interpolation from a map
Applicable Standards: Full Depth Site Conditions Standard, with Potable Ground Water, Medium/Fine Textured Soil, for Industrial/Commercial/Community property use
RSC PDF:

---

107 | **8 of 11** | **NE/218.7** | **95.9 / -3.98** | **WILLIAM CARTAGE LTD**
2089 PARKDALE AV
BROCKVILLE ON | **FSTH**

License Issue Date: 1/11/1991
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1990
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

---

107 | **9 of 11** | **NE/218.7** | **95.9 / -3.98** | **2089 Parkdale Ave.**
Brockville ON | **SPL**

Ref No: 0372-8TFK2Z
Site No:
Incident Dt: 17-APR-12
Year:
Incident Cause:
Incident Event:
Contaminant Code: 35
Contaminant Name: NATURAL GAS (METHANE)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact:
Receiving Medium: Sewage - Municipal/Private and Commercial
Receiving Env:
MOE Response: No Field Response
Dt MOE Arvl on Scn:
MOE Reported Dt: 17-APR-12
Dt Document Closed:
Incident Reason:
Site Name: 2" gas line severed by construction <UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: TSSAfsb: 2" line severed by construction. still blowing.
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address: 2089 Parkdale Ave.
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: Brockville
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Air Spills - Gases and Vapours
Source Type:

---

107 | **10 of 11** | **NE/218.7** | **95.9 / -3.98** | **WILLIAM CARTAGE LTD**
2089 PARKDALE AV
BROCKVILLE ON K6V 5V7 | **FST**

Instance No: 10618409

Cont Name:
Instance Type: FS Liquid Fuel Tank
Fuel Type: Diesel
Status: Active
Capacity: 50000
Tank Material: Steel
Corrosion Protection: Sacrificial anode
Tank Type: Single Wall UST
Install Year: 1990
Parent Facility Type: Fuels Safety Private Fuel Outlet - Self Serve
Facility Type: FS Liquid Fuel Tank

---

107 | **11 of 11** | **NE/218.7** | **95.9 / -3.98** | **2089 Parkdale Avenue, Brockville ON** | **PINC**

Incident ID:
Incident No: 794602
Type: FS-Pipeline Incident
Status Code: Pipeline Damage Reason Est
Fuel Occurrence Tp:
Fuel Type:
Tank Status: RC Established
Task No: 3800429
Spills Action Centre:
Method Details: E-mail
Fuel Category: Natural Gas
Date of Occurrence:
Occurrence Start Date: 2012/04/17
Operation Type:
Pipeline Type:
Regulator Type:
Summary: 2089 Parkdale Avenue, Brockville - 2" Pipeline Hit
Reported By: Dave McLeod - Brockville FD
Affiliation:
Occurrence Desc:
Damage Reason: Excavation practices not sufficient
Notes:

Health Impact:
Environment Impact:
Property Damage: Yes
Service Interupt:
Enforce Policy: Yes
Public Relation:
Pipeline System:
Depth:
Pipe Material:
PSIG:
Attribute Category: FS-Perform P-line Inc Invest
Regulator Location:

---

108 | **1 of 1** | **NE/135.3** | **96.6 / -3.23** | **BROCKVILLE ON** | **WWIS**

Well ID: 7101787
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z76642
Tag: A053425
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 2/8/2008
Selected Flag: Yes
Abandonment Rec:
Contractor: 7323
Form Version: 4
Owner:
Street Name: 2089 PARKDALE AVE.
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/710\7101787.pdf

Bore Hole Information

Bore Hole ID: 1001494147
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 12/13/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 445398
North83: 4939940
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: gis

Overburden and Bedrock Materials Interval

Formation ID: 1001545863
Layer: 2
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3: 66
Mat3 Desc: DENSE
Formation Top Depth: 2
Formation End Depth: 25
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1001545862
Layer: 1
Color: 2
General Color: GREY
Mat1: 11
Most Common Material: GRAVEL
Mat2: 28
Mat2 Desc: SAND
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 2
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1001545868
Layer: 4
Plug From: 14
Plug To: 25

Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1001545866
Layer: 2
Plug From: 1
Plug To: 12
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1001545865
Layer: 1
Plug From: 0
Plug To: 1
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1001545867
Layer: 3
Plug From: 12
Plug To: 14
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1001545873
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1001545860
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1001545870
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 15
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1001545871
Layer:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Slot:
Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM:
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1001545861
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 0
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing: No

Water Details

Water ID: 1001545869
Layer: 1
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1001545864
Diameter: 8
Depth From:
Depth To: 25
Hole Depth UOM: ft
Hole Diameter UOM: inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
109	1 of 3	NE/113.1	96.8 / -3.02	WILLIAM BROWNLEE CARTAGE LIMITED BOX 520 2089 PARKEDALE AVE. BROCKVILLE ON K6V 5V7	GEN

Generator No: ON0960200
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 0000
SIC Description: *** NOT DEFINED ***

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
109	2 of 3	NE/113.1	96.8 / -3.02	WILLIAM (SEE & USE ON0061604) 42-284 BOX 520 2089 PARKEDALE AVE. BROCKVILLE ON K6V 5V7	GEN

Generator No: ON0960200
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 4561
SIC Description: GEN. FREIGHT TRUCK.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
109	3 of 3	NE/113.1	96.8 / -3.02	WILLIAM CARTAGE LTD 2089 PARKEDALE AV BROCKVILLE ON	FSTH

License Issue Date: 1/11/1991
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1990
Corrosion Protection:
Capacity: 50000
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
110	1 of 1	WSW/199.5	109.0 / 9.15	lot 17 con 2 ON	WWIS

Well ID: 3612722
Construction Date:
Primary Water Use: Municipal
Sec. Water Use:
Final Well Status:
Water Type:
Casing Material:
Audit No: 126218
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 4/16/1993
Selected Flag: Yes
Abandonment Rec:
Contractor: 4006
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 017
Concession: 02
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/361\3612722.pdf

Bore Hole Information

Bore Hole ID:	10226106	***Elevation:***	108.763473
DP2BR:	0	***Elevrc:***	
Spatial Status:	Improved	***Zone:***	18
Code OB:	h	***East83:***	443454
Code OB Desc:	Mixed in a Layer	***North83:***	4938113
Open Hole:		***Org CS:***	N83
Cluster Kind:		***UTMRC:***	3
Date Completed:	3/31/1993	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:	1999-2004 MOE Water Well Data Improvement Project		
Improvement Location Method:	GIS		
Source Revision Comment:	Northing and/or Easting field has been changed. Well in same location as sketch map; conflicts with recorded con/lot.		
Supplier Comment:	Determined to be an improvement rather than a Lot Centroid in December 2009.		

Overburden and Bedrock Materials Interval

Formation ID:	931704002
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	18
Mat2 Desc:	SANDSTONE
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0
Formation End Depth:	16
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931704004
Layer:	3
Color:	1
General Color:	WHITE
Mat1:	18
Most Common Material:	SANDSTONE
Mat2:	78
Mat2 Desc:	MEDIUM-GRAINED
Mat3:	
Mat3 Desc:	
Formation Top Depth:	22
Formation End Depth:	87
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931704003
Layer:	2
Color:	1
General Color:	WHITE
Mat1:	18
Most Common Material:	SANDSTONE
Mat2:	71

Mat2 Desc:	FRACTURED
Mat3:	
Mat3 Desc:	
Formation Top Depth:	16
Formation End Depth:	22
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	933155837
Layer:	2
Plug From:	10
Plug To:	87
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	933155836
Layer:	1
Plug From:	0
Plug To:	10
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	963612722
Method Construction Code:	4
Method Construction:	Rotary (Air)
Other Method Construction:	

Pipe Information

Pipe ID:	10774676
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930381244
Layer:	3
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	87
Casing Diameter:	8
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930381243
Layer:	2
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	3
Casing Diameter:	8

Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930381242
Layer: 1
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 20
Casing Diameter: 10
Casing Diameter UOM: inch
Casing Depth UOM: ft

---

111 **1 of 1** **ENE/133.6** **98.9 / -0.96** **93 SEVENOAKS AVE, BROCKVILLE ON** **INC**

Incident No: 1960942
Incident ID:
Attribute Category: FS-Perform L1 Incident Insp
Status Code:
Incident Location: 93 SEVENOAKS AVE, BROCKVILLE - LEAK
Drainage System:
Sub Surface Contam.:
Aff. Prop. Use Water:
Contam. Migrated:
Contact Natural Env.:
Near Body of Water:
Approx. Quant. Rel.:
Equipment Model:
Serial No:
Residential App. Type:
Commercial App. Type:
Industrial App. Type:
Institutional App. Type:
Venting Type:
Vent Connector Mater:
Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Depth Ground Cover:
Regulator Location:
Regulator Type:
Operation Pressure:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Equipment Type:
Cylinder Capacity:
Cylinder Capac. Units:
Cylinder Material Type:
Tank Capacity:
Fuels Occurence Type: Leak
Fuel Type Involved: Fuel Oil
Date of Occurence: 2016/10/18 00:00:00
Time of Occurence: NULL
Occur Insp Start Date: 2016/10/18 00:00:00
Any Health Impact: No
Any Environmental Impact: Unknown
Was Service Interrupted: Yes
Was Property Damaged: Yes
Operation Type Involved: Private Dwelling

Enforcement Policy: NULL
Prc Escalation Required: NULL
Task No: 6406071
Notes:
Occurence Narrative: NULL
Tank Material Type:
Tank Storage Type:
Tank Location Type:
Pump Flow Rate Capac:
Liquid Prop Notes:

---

112 **1 of 2** **SW/234.0** **98.1 / -1.73** **L.A. Knapp Inc.**
440 Central Avenue West
Brockville ON K6V 4N8 **GEN**

Generator No: ON9830774
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 212 L
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

---

112 **2 of 2** **SW/234.0** **98.1 / -1.73** **L.A. Knapp Inc.**
440 Central Avenue West
Brockville ON K6V 4N8 **GEN**

Generator No: ON9830774
Status: Registered
Approval Years: As of Apr 2020
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 212 L
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

---

113 **1 of 1** **NE/233.1** **97.9 / -1.98** **Loblaw Properties Limited**
NE corner of Parkedale Avenue & Crocker
Brockville ON M4T 2S5 **ECA**

Approval No: 9066-658QKY
Approval Date: 2004-10-07
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Cataraqui
MOE District: Kingston
City:
Longitude: -75.6958
Latitude: 44.6192
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Type: ECA-INDUSTRIAL SEWAGE WORKS
Project Type: INDUSTRIAL SEWAGE WORKS
Address: NE corner of Parkedale Avenue & Crocker
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/4817-5ZRQFA-14.pdf

---

114 **1 of 2** **NE/200.7** **97.9 / -1.98** **MUTTART BUILDER'S SUPPLIES LTD**
2057 PARKEDALE AVE W
BROCKVILLE ON K6V 5V8 **SCT**

Established: 1960
Plant Size (ft²): 8000
Employment: 35

--Details--
Description: STRUCTURAL WOOD MEMBERS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2439

Description: WOOD OFFICE AND STORE FIXTURES, PARTITIONS, SHELVING, AND LOCKERS
SIC/NAICS Code: 2541

---

114 **2 of 2** **NE/200.7** **97.9 / -1.98** **MUTTART BUILDERS' SUPPLIES**
2057 PARKEDALE AVENUE
BROCKVILLE ON K6V5V8 **PES**

Detail Licence No:
Licence No: 10947
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Retail Vendor Class 03
Licence Type Code: 21
Licence Class: 03
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 3451424
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

115 **1 of 5** **SW/236.6** **97.6 / -2.22** **Zigman Metals Ltd.**
700 Central Ave W
Brockville ON K6V 5W1 **SCT**

Established: 01-JUL-12
Plant Size (ft²):
Employment:

--Details--
Description: Iron Foundries
SIC/NAICS Code: 331511

Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
SIC/NAICS Code: 332999

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Metal Service Centres
SIC/NAICS Code: 416210

---

115 **2 of 5** **SW/236.6** **97.6 / -2.22** **ZIGMAN METALS**
700 CENTRAL W
BROCKVILLE ON K6V 5W1 **AUWR**

Headcode: 01169400
Headcode Desc: SCRAP METALS
Phone:
List Name:
Description:

---

115 **3 of 5** **SW/236.6** **97.6 / -2.22** **700 Central Ave. West, Brockville**
Brockville ON **SPL**

Ref No: 0135-7DWKXB
Site No:
Incident Dt:
Year:
Incident Cause:
Incident Event:
Contaminant Code: 44
Contaminant Name: SEWAGE,RAW UNCHLORINATED
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Possible
Nature of Impact: Other Impact(s); Soil Contamination
Receiving Medium:
Receiving Env:
MOE Response: No Field Response
Dt MOE Arvl on Scn:
MOE Reported Dt: 4/21/2008
Dt Document Closed: 11/12/2008
Incident Reason: Error- Operator error
Site Name: Ditch and catchbasin<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Brockville - Sewage spill from broken sewage force main
Contaminant Qty: 151 L

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Sewer
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office: Kingston - District
Site Postal Code:
Site Region:
Site Municipality: Brockville
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Land Spills
Source Type:

---

115 **4 of 5** **SW/236.6** **97.6 / -2.22** **L. ZIGMAN & SONS LIMITED**
700 CENTRAL AVENUE WEST
BROCKVILLE ON K6V 5W1 **EASR**

Approval No: R-004-1335844148
Status: REGISTERED
Date: 2013-05-14
Record Type: EASR
Link Source: MOFA
Project Type: Waste Management System
Full Address:
Approval Type: EASR-Waste Management System
Full PDF Link: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=6199

SWP Area Name:
MOE District:
Municipality: BROCKVILLE
Latitude:
Longitude:
Geometry X:
Geometry Y:

---

115 **5 of 5** **SW/236.6** **97.6 / -2.22** **ZIGMAN METALS**
700 CENTRAL W
BROCKVILLE ON K6V5W1 **AUWR**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Headcode: 01169400
Headcode Desc: SCRAP METALS
Phone: 6133422929
List Name:
Description:

---

118 **1 of 6** **NE/203.2** **98.9 / -0.98** **Michaels Stores, Inc.**
1965 Parkedale Ave
Brockville ON **GEN**

Generator No: ON5851663
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 451130
SIC Description: SEWING, NEEDLEWORK AND PIECE GOODS STORES

Detail(s)

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

---

118 **2 of 6** **NE/203.2** **98.9 / -0.98** **Michaels Stores, Inc.**
1965 Parkedale Ave
Brockville ON K6V 0B4 **GEN**

Generator No: ON5851663
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 451130
SIC Description: SEWING, NEEDLEWORK AND PIECE GOODS STORES

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: James Williams
Phone No Admin: (647)288-3298 Ext.

Detail(s)

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

---

118 **3 of 6** **NE/203.2** **98.9 / -0.98** **Michaels Stores, Inc.**
1965 Parkedale Ave
Brockville ON K6V 0B4 **GEN**

Generator No: ON5851663
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 451130
SIC Description: SEWING, NEEDLEWORK AND PIECE GOODS STORES

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: James Williams
Phone No Admin: (647)288-3298 Ext.

Detail(s)

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

---

118 **4 of 6** **NE/203.2** **98.9 / -0.98** **Michaels Stores, Inc.**
1965 Parkedale Ave
Brockville ON K6V 0B4 **GEN**

Generator No: ON5851663
Status:
Approval Years: 2014

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL

Contam. Facility: No
MHSW Facility: No
SIC Code: 451130
SIC Description: SEWING, NEEDLEWORK AND PIECE GOODS STORES

Co Admin: James Williams
Phone No Admin: (647)288-3298 Ext.

Detail(s)

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

---

118 **5 of 6** **NE/203.2** **98.9 / -0.98** **Michaels Stores, Inc.**
1965 Parkedale Ave
Brockville ON K6V 0B4 **GEN**

Generator No: ON5851663
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 122 C
Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 145 L
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 146 T
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 148 A
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 148 L
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 212 I
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 262 L
Waste Class Desc: Detergents and soaps

Waste Class: 263 A
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 263 L
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 331 L
Waste Class Desc: Waste compressed gases including cylinders

---

118 **6 of 6** **NE/203.2** **98.9 / -0.98** **Michaels Stores, Inc.**
1965 Parkedale Ave
Brockville ON K6V 0B4 **GEN**

Generator No: ON5851663
Status: Registered
Approval Years: As of Apr 2020
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 148 A
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 212 I
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 146 T
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 148 L
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 263 L
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 331 L
Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 145 L
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 262 L
Waste Class Desc: Detergents and soaps

Waste Class: 263 A
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 122 C
Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

---

119 **1 of 9** **NE/218.0** **98.9 / -0.98** **Altima Parkedale Dental Centre**
1981 Parkedale avenue, Unit A
Brockville ON K6V 0B4 **GEN**

Generator No: ON9993485
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 621210
SIC Description: Offices of Dentists

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

119 **2 of 9** **NE/218.0** **98.9 / -0.98** **Altima Parkedale Dental Centre**
1981 Parkedale avenue, Unit A
Brockville ON K6V 0B4 **GEN**

Generator No: ON9993485
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 621210
SIC Description: Offices of Dentists

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

---

119 **3 of 9** **NE/218.0** **98.9 / -0.98** **Altima Parkedale Dental Centre**
1981 Parkedale avenue, Unit A
Brockville ON K6V 0B4 **GEN**

Generator No: ON9993485
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 621210
SIC Description: Offices of Dentists

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

---

119 **4 of 9** **NE/218.0** **98.9 / -0.98** **Altima Parkedale Dental Centre**
1981 Parkedale avenue, Unit A
Brockville ON **GEN**

Generator No: ON9993485
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

---

119 **5 of 9** **NE/218.0** **98.9 / -0.98** **Altima Parkedale Dental Centre**
1981 Parkedale avenue, Unit A
Brockville ON K6V 0B4 **GEN**

Generator No: ON9993485
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

119 **6 of 9** **NE/218.0** **98.9 / -0.98** **Altima Parkedale Dental Centre**
1981 Parkedale avenue, Unit A
Brockville ON K6V 0B4 **GEN**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON9993485
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

---

119 **7 of 9** **NE/218.0** **98.9 / -0.98** **Altima Parkedale Dental Centre**
1981 Parkedale avenue, Unit A
Brockville ON K6V 0B4 **GEN**

Generator No: ON9993485
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 621210
SIC Description: OFFICES OF DENTISTS

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

---

119 **8 of 9** **NE/218.0** **98.9 / -0.98** **Altima Dental Services Ontario Inc.**
1981 Parkedale avenue, Unit A
Brockville ON K6V 0B4 **GEN**

Generator No: ON9993485
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 264 L
Waste Class Desc: Photoprocessing wastes

Waste Class: 312 P
Waste Class Desc: Pathological wastes

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

119 **9 of 9** **NE/218.0** **98.9 / -0.98** **Altima Dental Services Ontario Inc.**
1981 Parkedale avenue, Unit A
Brockville ON K6V 0B4 **GEN**

Generator No: ON9993485
Status: Registered
Approval Years: As of Apr 2020
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 264 L
Waste Class Desc: Photoprocessing wastes

Waste Class: 312 P
Waste Class Desc: Pathological wastes

---

120 **1 of 1** **NE/228.5** **99.4 / -0.42** **The Corporation of the City of Brockville**
Parkedale Avenue & North Augusta Road
Brockville ON **CA**

Certificate #: 8274-5ZTRH8
Application Year: 2004
Issue Date: 6/17/2004
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

121 **1 of 1** **NE/187.1** **100.3 / 0.50** **ON** **WWIS**

Well ID: 3600488
Construction Date:
Primary Water Use: Industrial
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 1/12/1960
Selected Flag: Yes
Abandonment Rec:
Contractor: 3607
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600488.pdf

Bore Hole Information

Bore Hole ID:	10214447	**Elevation:**	101.418258
DP2BR:	31	**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:	r	**East83:**	445572.7
Code OB Desc:	Bedrock	**North83:**	4940189
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	5
Date Completed:	10/16/1959	**UTMRC Desc:**	margin of error : 100 m - 300 m
Remarks:		**Location Method:**	p5
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	931675897
Layer:	3
Color:	
General Color:	
Mat1:	11
Most Common Material:	GRAVEL
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	20
Formation End Depth:	31
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931675896
Layer:	2
Color:	
General Color:	
Mat1:	09
Most Common Material:	MEDIUM SAND
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	10
Formation End Depth:	20
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931675898
Layer:	4
Color:	2
General Color:	GREY

Mat1:	15
Most Common Material:	LIMESTONE
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	31
Formation End Depth:	136
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931675895
Layer:	1
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0
Formation End Depth:	10
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	963600488
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10763017
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930362698
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	37
Casing Diameter:	2
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930362699
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	136

Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600488
Pump Set At:
Static Level: 1
Final Level After Pumping: 5
Recommended Pump Depth: 2
Pumping Rate: 24
Flowing Rate:
Recommended Pump Rate: 10
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 2
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676361
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 136
Water Found Depth UOM: ft

---

122 | 1 of 2 | NE/104.3 | 99.1 / -0.71 | TRANSPORT TRUCK 401 WEST TO BROKVILLE EXIT TO PARKDALE AVE. MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON | SPL

Ref No: 112098
Site No:
Incident Dt: 4/19/1995
Year:
Incident Cause: OTHER CONTAINER LEAK
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: POSSIBLE
Nature of Impact: Soil contamination
Receiving Medium: LAND
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 4/19/1995
Dt Document Closed:
Incident Reason: UNKNOWN
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: INTERLINK/CP EXPRESS-400 L DIESEL TO LOT,SOME TO HWY,FD,MTO.
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 56101
Site Lot:
Site Conc:
Northing:
Easting: FD,OPP,LOCAL PD.
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

122 | 2 of 2 | NE/104.3 | 99.1 / -0.71 | 401 & Parkdale (North Augusta Rd.) Brockville ON K6V 5T1 | SPL

Ref No: 6615-673PAP
Site No:
Incident Dt: 11/25/2004
Year:
Incident Cause:
Incident Event:
Contaminant Code: 13
Contaminant Name: FURNACE OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Possible
Nature of Impact: Soil Contamination
Receiving Medium: Land
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 11/25/2004
Dt Document Closed:
Incident Reason: Spill
Site Name: 2805 2ND CONCESSION<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: 4 L furnace oil spill
Contaminant Qty: 4 L

Discharger Report:
Material Group: Oil
Health/Env Conseq:
Client Type:
Sector Type: Other
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office: Kingston
Site Postal Code:
Site Region: Eastern
Site Municipality: Brockville
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Spill to Land
Source Type:

---

123 | 1 of 1 | NE/183.7 | 98.9 / -0.98 | ON | WWIS

Well ID: 3600522
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 4/20/1965
Selected Flag: Yes
Abandonment Rec:
Contractor: 3607
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600522.pdf

Bore Hole Information

Bore Hole ID: 10214481
DP2BR: 7
Spatial Status:
Code OB: r

Elevation: 98.786605
Elevrc:
Zone: 18
East83: 445660.7

Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 9/21/1964
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

North83: 4940273
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5

Overburden and Bedrock Materials Interval

Formation ID: 931675972
Layer: 2
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 7
Formation End Depth: 105
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931675971
Layer: 1
Color:
General Color:
Mat1: 14
Most Common Material: HARDPAN
Mat2: 13
Mat2 Desc: BOULDERS
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 7
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600522
Method Construction Code: 7
Method Construction: Diamond
Other Method Construction:

Pipe Information

Pipe ID: 10763051
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362766
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 30
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362767
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 105
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600522
Pump Set At:
Static Level: 20
Final Level After Pumping: 25
Recommended Pump Depth: 50
Pumping Rate: 10
Flowing Rate:
Recommended Pump Rate: 10
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 2
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676396
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 105
Water Found Depth UOM: ft

124 | ***1 of 1*** | ***ENE/11.5*** | ***99.9 / 0.02*** | ***Highway 401 Eastbound Brockville ON*** | ***SPL***

Ref No: 1666-B4RCMT
Site No: NA
Incident Dt: 2018/09/19
Year:
Incident Cause:
Incident Event: Collision/Accident
Contaminant Code: 13
Contaminant Name: DIESEL FUEL

Discharger Report:
Material Group:
Health/Env Conseq: 2 - Minor Environment
Client Type:
Sector Type: Miscellaneous Industrial
Agency Involved:
Nearest Watercourse:
Site Address: Highway 401 Eastbound

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminant Limit 1:		**Site District Office:**	Kingston - District
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:	1202	**Site Region:**	Eastern
Environment Impact:		**Site Municipality:**	Brockville
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Land	**Northing:**	4940165.24
MOE Response:	No	**Easting:**	445828.81
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2018/09/19	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Highway Spills (usually highway accidents)
Incident Reason:	Operator/Human Error	**Source Type:**	Truck - Only Saddle Tanks
Site Name:	MM 699 - just East of North Augusta Road<UNOFFICIAL>		
Site County/District:	United Counties of Leeds and Grenville		
Site Geo Ref Meth:			
Incident Summary:	401 Brockville diesel spill to ditch		
Contaminant Qty:	0 other - see incident description		

125 **1 of 23** **NE/249.9** **98.9 / -0.98** **WAL-MART CANADA CORP #3006**
1942 PARKEDALE AVE
BROCKVILLE ON K6V 7N4 **PES**

Detail Licence No:		**Operator Box:**	
Licence No:		**Operator Class:**	
Status:		**Operator No:**	
Approval Date:		**Operator Type:**	
Report Source:		**Oper Area Code:**	
Licence Type:	Limited Vendor	**Oper Phone No:**	
Licence Type Code:	23	**Operator Ext:**	
Licence Class:		**Operator Lot:**	
Licence Control:		**Oper Concession:**	
Latitude:		**Operator Region:**	
Longitude:		**Operator District:**	
Lot:		**Operator County:**	
Concession:		**Op Municipality:**	
Region:		**Post Office Box:**	
District:		**MOE District:**	
County:		**SWP Area Name:**	
Trade Name:			
PDF Link:			

125 **2 of 23** **NE/249.9** **98.9 / -0.98** **Wal-Mart Canada Corp.**
1942 Parkdale Ave.
Brockville ON K6V 9Z1 **GEN**

Generator No:	ON4234091	**PO Box No:**	
Status:		**Country:**	
Approval Years:	05,06,07,08	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	453999		
SIC Description:	All Other Miscellaneous Store Retailers (except Beer and Wine-Making Supplies Stores)		

Detail(s)

Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS
Waste Class:	112
Waste Class Desc:	ACID WASTE - HEAVY METALS

Waste Class:	122
Waste Class Desc:	ALKALINE WASTES - OTHER METALS
Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	147
Waste Class Desc:	CHEMICAL FERTILIZER WASTES
Waste Class:	242
Waste Class Desc:	HALOGENATED PESTICIDES
Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS
Waste Class:	331
Waste Class Desc:	WASTE COMPRESSED GASES
Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	212
Waste Class Desc:	ALIPHATIC SOLVENTS

125 **3 of 23** **NE/249.9** **98.9 / -0.98** **McDonalds Restaurant<UNOFFICIAL>**
1942 Parkdale Avenue MCDONALDS RESTAURANT<UNOFFICIAL>
Brockville ON **SPL**

Ref No:	8188-6RFT32	**Discharger Report:**	
Site No:		**Material Group:**	Oils
Incident Dt:	7/6/2006	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Other Discharges	**Sector Type:**	Other
Incident Event:		**Agency Involved:**	
Contaminant Code:	14	**Nearest Watercourse:**	
Contaminant Name:	GREASE (N.O.S.)	**Site Address:**	1942 PARKDALE AVENUE
Contaminant Limit 1:		**Site District Office:**	Kingston - District
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Possible	**Site Municipality:**	Brockville
Nature of Impact:	Other Impact(s); Soil Contamination	**Site Lot:**	
Receiving Medium:	Land	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	7/6/2006	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	Negligence (Apparent) - Caused by lack of diligence	**Source Type:**	
Site Name:	1942 PARKDALE AVENUE		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Brockville, 5-10 gallons of grease to ground		
Contaminant Qty:	45.45 L		

125 **4 of 23** **NE/249.9** **98.9 / -0.98** **WALMART, 1942 PARKDALE AVE<UNOFFICIAL>**
Brockville ON **SPL**

Ref No:	8614-6PVTVN	**Discharger Report:**	
Site No:		**Material Group:**	Gases/Particulates
Incident Dt:	5/17/2006	**Health/Env Conseq:**	

Year:
Incident Cause:
Incident Event:
Contaminant Code: 38
Contaminant Name: REFRIGERANT GAS, N.O.S.
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Possible
Nature of Impact: Air Pollution
Receiving Medium: Air
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 5/17/2006
Dt Document Closed:
Incident Reason:
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: Walmart: 240 kg R404A to atmosphere
Contaminant Qty: 240 Kg

Client Type:
Sector Type: Other
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office: Kingston - District
Site Postal Code:
Site Region:
Site Municipality: Brockville
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

125 **5 of 23** **NE/249.9** **98.9 / -0.98** **WAL-MART CANADA CORP #3006**
1942 PARKEDALE AVE
BROCKVILLE ON K6V 7N4 **PES**

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

125 **6 of 23** **NE/249.9** **98.9 / -0.98** **Wal-Mart Canada Corp.**
1942 Parkdale Ave. #3006
Brockville ON **GEN**

Generator No: ON4234091
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 453999
SIC Description: All Other Miscellaneous Store Retailers (except Beer and Wine-Making Supplies Stores)

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112

Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 147
Waste Class Desc: CHEMICAL FERTILIZER WASTES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

---

125 **7 of 23** **NE/249.9** **98.9 / -0.98** **Wal-Mart Canada Corp.**
1942 Parkdale Ave. #3006
Brockville ON **GEN**

Generator No: ON4234091
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 453999
SIC Description: All Other Miscellaneous Store Retailers (except Beer and Wine-Making Supplies Stores)

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 147
Waste Class Desc: CHEMICAL FERTILIZER WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

---

125 **8 of 23** **NE/249.9** **98.9 / -0.98** **Wal-Mart Canada Corp.**
1942 Parkdale Ave. #3006
Brockville ON **GEN**

Generator No: ON4234091
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 453999
SIC Description: All Other Miscellaneous Store Retailers (except Beer and Wine-Making Supplies Stores)

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 147
Waste Class Desc: CHEMICAL FERTILIZER WASTES

---

125 **9 of 23** **NE/249.9** **98.9 / -0.98** **Wal-Mart Canada Corp.**
1942 Parkdale Ave. #3006
Brockville ON K6V 9Z1 **GEN**

Generator No: ON4234091
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 453999

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: All Other Miscellaneous Store Retailers (except Beer and Wine-Making Supplies Stores)

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 147
Waste Class Desc: CHEMICAL FERTILIZER WASTES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

---

125 **10 of 23** **NE/249.9** **98.9 / -0.98** **Wal-Mart Canada Corp.**
1942 Parkdale Ave. #3006
Brockville ON **GEN**

Generator No: ON4234091
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 453999
SIC Description: ALL OTHER MISCELLANEOUS STORE RETAILERS (EXCEPT BEER AND WINE-MAKING SUPPLIES STORES)

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 147
Waste Class Desc: CHEMICAL FERTILIZER WASTES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

---

125 **11 of 23** **NE/249.9** **98.9 / -0.98** **1942 PARKDALE AVENUE, BROCKVILLE ON** **INC**

Incident No: 1410716
Incident ID:
Attribute Category: FS-Perform L1 Incident Insp
Status Code:
Incident Location: 1942 PARKDALE AVENUE, BROCKVILLE - VAPOR RELEASE
Drainage System:
Sub Surface Contam.:
Aff. Prop. Use Water:
Contam. Migrated:
Contact Natural Env.:
Near Body of Water:
Approx. Quant. Rel.:
Equipment Model:
Serial No:
Residential App. Type:
Commercial App. Type:
Industrial App. Type:
Institutional App. Type:
Venting Type:
Vent Connector Mater:
Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Depth Ground Cover:
Regulator Location:
Regulator Type:
Operation Pressure:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Equipment Type:
Cylinder Capacity:
Cylinder Capac. Units:
Cylinder Material Type:
Tank Capacity:
Fuels Occurence Type: Vapour Release
Fuel Type Involved: Natural Gas
Date of Occurence: 2014/06/05 00:00:00
Time of Occurence: 15:30:00
Occur Insp Start Date: 2014/06/09 00:00:00
Any Health Impact: No
Any Environmental Impact: No
Was Service Interrupted: Yes
Was Property Damaged: Yes
Operation Type Involved: Commercial (e.g. restaurant, business unit, etc)
Enforcement Policy: NULL

Prc Escalation Required: NULL
Task No: 5055663
Notes:
Occurence Narrative: Gas meter damaged
Tank Material Type:
Tank Storage Type:
Tank Location Type:
Pump Flow Rate Capac:
Liquid Prop Notes:

---

125 **12 of 23** **NE/249.9** **98.9 / -0.98** **Enbridge Gas Distribution Inc.**
1942 Parkdale Ave
Brockville ON **SPL**

Ref No: 5821-9KSUWC
Site No: NA
Incident Dt: 2014/06/05
Year:
Incident Cause: Leak/Break
Incident Event:
Contaminant Code: 35
Contaminant Name: NATURAL GAS (METHANE)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Not Anticipated
Nature of Impact: Air Pollution
Receiving Medium:
Receiving Env:
MOE Response: No Field Response
Dt MOE Arvl on Scn:
MOE Reported Dt: 2014/06/05
Dt Document Closed: 2015/01/28
Incident Reason: Operator/Human Error
Site Name: Walmart<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: TSSA: 3/4 inch line damage, made safe
Contaminant Qty: 0 other - see incident description

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Pipeline/Components
Agency Involved:
Nearest Watercourse:
Site Address: 1942 Parkdale Ave
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: Brockville
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Source Type:

---

125 **13 of 23** **NE/249.9** **98.9 / -0.98** **WAL-MART CANADA CORP/LA COMPAGNIE**
WAL-MART DU CANADA
1942 PARKEDALE AVE
BROCKVILLE ON K6V 7N4 **EASR**

Approval No: R-003-6548052646
Status: REGISTERED
Date: 2015-12-01
Record Type: EASR
Link Source: MOFA
Project Type: Heating System
Full Address:
Approval Type: EASR-Heating System
Full PDF Link: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2018256

SWP Area Name: Cataraqui
MOE District: Kingston
Municipality: BROCKVILLE
Latitude: 44.615
Longitude: -75.68611111
Geometry X:
Geometry Y:

---

125 **14 of 23** **NE/249.9** **98.9 / -0.98** **Wal-Mart Canada Corp.**
1942 Parkdale Ave. #3006
Brockville ON K6V 9Z1 **GEN**

Generator No: ON4234091
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 453999
SIC Description: ALL OTHER MISCELLANEOUS STORE RETAILERS (EXCEPT BEER AND WINE-MAKING SUPPLIES STORES)

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Jason Fries
Phone No Admin: 905-821-2111 Ext.75127

Detail(s)

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 147
Waste Class Desc: CHEMICAL FERTILIZER WASTES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

---

125 **15 of 23** **NE/249.9** **98.9 / -0.98**

Wal-Mart Canada Corp.
1942 Parkdale Ave. #3006
Brockville ON K6V 9Z1

GEN

Generator No: ON4234091
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 453999
SIC Description: ALL OTHER MISCELLANEOUS STORE RETAILERS (EXCEPT BEER AND WINE-MAKING SUPPLIES STORES)

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Vincent Feng
Phone No Admin: 905-821-2111 Ext.75212

Detail(s)

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 147
Waste Class Desc: CHEMICAL FERTILIZER WASTES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

---

125 **16 of 23** **NE/249.9** **98.9 / -0.98**

Wal-Mart Canada Corp.
1942 Parkdale Ave. #3006
Brockville ON K6V 9Z1

GEN

Generator No: ON4234091
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 453999
SIC Description: ALL OTHER MISCELLANEOUS STORE RETAILERS (EXCEPT BEER AND WINE-MAKING SUPPLIES STORES)

PO Box No:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Vincent Feng
Phone No Admin: 905-821-2111 Ext.75212

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 147
Waste Class Desc: CHEMICAL FERTILIZER WASTES

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

125 **17 of 23** **NE/249.9** **98.9 / -0.98**

Wal-Mart Canada Corp.
1942 Parkdale Ave. #3006
Brockville ON K6V 9Z1

GEN

Generator No: ON4234091
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112 C
Waste Class Desc: Acid solutions - containing heavy metals

Waste Class: 122 C
Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 148 C
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 148 I
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 148 T
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 242 A
Waste Class Desc: Halogenated pesticides and herbicides

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 263 I
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 312 P
Waste Class Desc: Pathological wastes

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

---

125 **18 of 23** **NE/249.9** **98.9 / -0.98**

WAL-MART CANADA CORP #3006
1942 PARKEDALE AVE
BROCKVILLE ON K6V9Z1

PES

Detail Licence No:
Licence No: 06320

Operator Box:
Operator Class:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Limited Vendor
Licence Type Code: 23
Licence Class: 01
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 4989912
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

125 **19 of 23** **NE/249.9** **98.9 / -0.98**

1942 Parkedale Ave
Brockville ON K6V 5T2

EHS

Order No: 20180725179
Status: C
Report Type: Standard Report
Report Date: 01-AUG-18
Date Received: 25-JUL-18
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.68735
Y: 44.614852

---

125 **20 of 23** **NE/249.9** **98.9 / -0.98**

WAL-MART CANADA CORP #3006
1942 PARKEDALE AVE
BROCKVILLE ON K6V9Z1

PES

Detail Licence No:
Licence No: 06320
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Retail Vendor Class 03
Licence Type Code: 21
Licence Class: 03
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 4989912
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

125 **21 of 23** **NE/249.9** **98.9 / -0.98**

Wal-Mart Canada Corp.
1942 Parkdale Ave. #3006
Brockville ON K6V 9Z1

GEN

Generator No: ON4234091
Status: Registered
Approval Years: As of Apr 2020
Contam. Facility:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:

MHSW Facility: **Phone No Admin:**
SIC Code:
SIC Description:

Detail(s)

Waste Class: 148 I
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 263 I
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 148 C
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 112 C
Waste Class Desc: Acid solutions - containing heavy metals

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 261 L
Waste Class Desc: Pharmaceuticals

Waste Class: 312 P
Waste Class Desc: Pathological wastes

Waste Class: 148 T
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 242 A
Waste Class Desc: Halogenated pesticides and herbicides

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 122 C
Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 261 A
Waste Class Desc: Pharmaceuticals

---

125 **22 of 23** **NE/249.9** **98.9 / -0.98** **WAL-MART CANADA CORP/LA COMPAGNIE**
WAL-MART DU CANADA
1942 PARKEDALE AVE
BROCKVILLE ON K6V 7N4 **PES**

Detail Licence No:
Licence No: L-232-2068708786
Status: Active
Approval Date: 2019-11-22
Report Source: PEST-Limited Vendor
Licence Type: Limited Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude: 44.615
Longitude: -75.68611111
Lot:
Concession:
Region:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:

District: **MOE District:** Kingston
County: **SWP Area Name:** Cataraqui
Trade Name:
PDF Link: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2194892

---

125 **23 of 23** **NE/249.9** **98.9 / -0.98** **1942 Parkdale Avenue East**
Brockville ON K6V 5T2 **EHS**

Order No: 20200610368
Status: C
Report Type: Standard Report
Report Date: 15-JUN-20
Date Received: 10-JUN-20
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.6865841
Y: 44.6152203

---

126 **1 of 1** **NE/222.4** **98.9 / -0.98** **lot 8 con 2**
ON **WWIS**

Well ID: 3600914
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 11/15/1951
Selected Flag: Yes
Abandonment Rec:
Contractor: 3705
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY (ELIZABETHTOWN)
Site Info:
Lot: 008
Concession: 02
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600914.pdf

Bore Hole Information

Bore Hole ID: 10214871
DP2BR: 5
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 6/14/1951
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 98.973686
Elevrc:
Zone: 18
East83: 445675.7
North83: 4940343
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676862
Layer: 2
Color:
General Color:
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 5
Formation End Depth: 30
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676863
Layer: 3
Color:
General Color:
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 30
Formation End Depth: 42
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676861
Layer: 1
Color:
General Color:
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 5
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600914
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763441

Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930363538
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 5
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930363539
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 42
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600914
Pump Set At:
Static Level: 20
Final Level After Pumping: 30
Recommended Pump Depth:
Pumping Rate: 7
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 2
Water State After Test: CLOUDY
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676882
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 42
Water Found Depth UOM: ft

127 ***1 of 1*** ***WSW/193.6*** ***104.9 / 5.06*** ***lot 17 con 1 ON*** ***WWIS***

Well ID: 3611804
Construction Date:
Primary Water Use: Not Used
Data Entry Status:
Data Src: 1
Date Received: 5/7/1991

Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: 89715
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Selected Flag: Yes
Abandonment Rec:
Contractor: 4877
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot: 017
Concession: 01
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/361\3611804.pdf

Bore Hole Information

Bore Hole ID: 10225191
DP2BR: 18
Spatial Status: Improved
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 2/27/1991
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source: 1999-2004 MOE Water Well Data Improvement Project
Improvement Location Method: GIS
Source Revision Comment: Northing and/or Easting field has been changed. Location estimated from sketch map.
Supplier Comment: Determined to be an improvement rather than a Lot Centroid in December 2009.

Elevation: 105.472251
Elevrc:
Zone: 18
East83: 443053
North83: 4937844
Org CS: N83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method:

Overburden and Bedrock Materials Interval

Formation ID: 931701499
Layer: 1
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 12
Mat2 Desc: STONES
Mat3: 79
Mat3 Desc: PACKED
Formation Top Depth: 0
Formation End Depth: 18
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931701500
Layer: 2
Color: 7
General Color: RED
Mat1: 21

Most Common Material: GRANITE
Mat2: 73
Mat2 Desc: HARD
Mat3:
Mat3 Desc:
Formation Top Depth: 18
Formation End Depth: 81
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933155160
Layer: 1
Plug From: 0
Plug To: 19
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963611804
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10773761
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930379978
Layer: 3
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 81
Casing Diameter: 8
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930379977
Layer: 2
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 19
Casing Diameter: 8
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930379976
Layer: 1

Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 19
Casing Diameter: 12
Casing Diameter UOM: inch
Casing Depth UOM: ft

Water Details

Water ID: 933690232
Layer: 1
Kind Code: 5
Kind: Not stated
Water Found Depth: 18
Water Found Depth UOM: ft

Water Details

Water ID: 933690234
Layer: 3
Kind Code: 5
Kind: Not stated
Water Found Depth: 61
Water Found Depth UOM: ft

Water Details

Water ID: 933690233
Layer: 2
Kind Code: 5
Kind: Not stated
Water Found Depth: 35
Water Found Depth UOM: ft

---

128 | *1 of 1* | *NE/232.7* | *98.9 / -0.98* | *lot 7 con 2 ON* | *WWIS*

Well ID: 3608838
Construction Date:
Primary Water Use: Domestic
Sec. Water Use:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 9/27/1983
Selected Flag: Yes
Abandonment Rec:
Contractor: 4794
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 007
Concession: 02
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3608838.pdf

Bore Hole Information

Bore Hole ID: 10222233
DP2BR: 8
Spatial Status: Improved
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 7/14/1983
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source: 1999-2004 MOE Water Well Data Improvement Project
Improvement Location Method: GIS
Source Revision Comment: Northing and/or Easting field has been changed. Location estimated from sketch map.well conflicts with recorded lot
Supplier Comment: Determined to be an improvement rather than a Lot Centroid in December 2009.

Elevation: 97.972831
Elevrc:
Zone: 18
East83: 445685
North83: 4940367
Org CS: N83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method:

Overburden and Bedrock Materials Interval

Formation ID: 931693861
Layer: 1
Color:
General Color:
Mat1: 02
Most Common Material: TOPSOIL
Mat2: 11
Mat2 Desc: GRAVEL
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 8
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931693862
Layer: 2
Color: 2
General Color: GREY
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 8
Formation End Depth: 98
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933153556
Layer: 1
Plug From: 5
Plug To: 22
Plug Depth UOM: ft

Method of Construction & Well

Use

Method Construction ID: 963608838
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10770803
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930376218
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 22
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930376219
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 98
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993608838
Pump Set At:
Static Level: 20
Final Level After Pumping: 20
Recommended Pump Depth: 85
Pumping Rate: 8
Flowing Rate:
Recommended Pump Rate: 8
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934488583
Test Type: Draw Down
Test Duration: 30

Test Level: 20
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 935001800
Test Type: Draw Down
Test Duration: 60
Test Level: 20
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934742532
Test Type: Draw Down
Test Duration: 45
Test Level: 20
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934201664
Test Type: Draw Down
Test Duration: 15
Test Level: 20
Test Level UOM: ft

Water Details

Water ID: 933685597
Layer: 2
Kind Code: 1
Kind: FRESH
Water Found Depth: 87
Water Found Depth UOM: ft

Water Details

Water ID: 933685596
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 60
Water Found Depth UOM: ft

129 | ***1 of 1*** | ***ENE/43.3*** | ***99.9 / 0.02*** | ***P.U.C. BROCKVILLE WAVERLY DR./FIRST AVE. BROCKVILLE CITY ON*** | ***CA***

Certificate #: 7-0832-93-
Application Year: 93
Issue Date: 10/15/1993
Approval Type: Municipal water
Status: Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Emission Control:

---

130 *1 of 1* *NE/198.7* *99.9 / 0.02* **SPL**

HARMAC TRANSPORTATION
IN FRONT OF 1951 PARKDALE RD. @ BROOM RD. TANK TRUCK (CARGO)
BROCKVILLE CITY ON

Ref No:	154558	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	4/8/1998	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	56101
Nature of Impact:		**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	4/14/1998	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	OTHER	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	HARMAC-<1 L BASEOIL COVERING CAR. CLEANING.		
Contaminant Qty:			

---

131 *1 of 5* *NE/213.0* *99.9 / 0.02* **CA**

P.U.C. BROCKVILLE
PARKEDALE AVE./BROOME RD.
BROCKVILLE CITY ON

Certificate #:	7-0919-94-
Application Year:	94
Issue Date:	9/30/1994
Approval Type:	Municipal water
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

---

131 *2 of 5* *NE/213.0* *99.9 / 0.02* **EHS**

First Ave & Parkedale Ave
Brockville ON

Order No:	20000814007	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Basic Report	**Client Prov/State:**	ON
Report Date:	8/22/00	**Search Radius (km):**	0.25
Date Received:	8/14/00	**X:**	-75.683434
Previous Site Name:		**Y:**	44.615002

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Lot/Building Size:
Additional Info Ordered:

---

131 *3 of 5* *NE/213.0* *99.9 / 0.02* **GEN**

MACGREGOR CRANE SERVICE LIMITED
FIRST AVE. & PARKDALE AVE. BROCKVILLE P.
O.BOX 261
BROCKVILLE ON K6H 5S7

Generator No:	ON1037500	**PO Box No:**	
Status:		**Country:**	
Approval Years:	88,89,90	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	4215		
SIC Description:	EQUIP. RENTAL W. OP.		

Detail(s)

Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES

---

131 *4 of 5* *NE/213.0* *99.9 / 0.02* **GEN**

MACGREGOR CRANE SERVICE LIMITED 26-326
FIRST AVE. & PARKDALE AVE. BROCKVILLE P.
O.BOX 261
BROCKVILLE ON K6H 5S7

Generator No:	ON1037500	**PO Box No:**	
Status:		**Country:**	
Approval Years:	92,93,94,95,96,97,98	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	4215		
SIC Description:	EQUIP. RENTAL W. OP.		

Detail(s)

Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES

---

131 *5 of 5* *NE/213.0* *99.9 / 0.02* **ECA**

Motor Coils Mfg. Ltd.
Broome Road Parkedale Ave
Brockville ON K6V 5T2

Approval No:	6344-4NMM7R	**MOE District:**	Kingston
Approval Date:	2000-08-31	**City:**	
Status:	Approved	**Longitude:**	-75.69200000000001
Record Type:	ECA	**Latitude:**	44.621500000000005
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Cataraqui	**Geometry Y:**	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Address:	Broome Road Parkedale Ave		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/3526-4MDJG2-14.pdf		

---

132 *1 of 1* *NE/213.6* *99.9 / 0.02* **SPL**

Trans Plus <UNOFFICIAL>
North Augusta Rd & Pakedale Ave,
Brockville ON

Ref No:	1102-BDVNFU	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	7/8/2019	**Health/Env Conseq:**	2 - Minor Environment
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Miscellaneous Industrial
Incident Event:	Leak/Break	**Agency Involved:**	
Contaminant Code:	13	**Nearest Watercourse:**	
Contaminant Name:	DIESEL FUEL	**Site Address:**	North Augusta Rd & Pakedale Ave,
Contaminant Limit 1:		**Site District Office:**	Kingston - District
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:	1202	**Site Region:**	Eastern
Environment Impact:		**Site Municipality:**	Brockville
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Land; Surface Water	**Northing:**	4940678
MOE Response:	No	**Easting:**	446056
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	7/8/2019	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Highway Spills (usually highway accidents)
Incident Reason:	Equipment Failure	**Source Type:**	Truck - Only Saddle Tanks
Site Name:	Spill site<UNOFFICIAL>		
Site County/District:	United Counties of Leeds and Grenville		
Site Geo Ref Meth:			
Incident Summary:	saddle rupture, ~ 400 L of diesel to road, cb		
Contaminant Qty:	400 L		

133 | ***1 of 1*** | ***WSW/131.0*** | ***104.6 / 4.74*** | ***lot 17 con 1 ON*** | ***WWIS***

Well ID:	3611808	**Data Entry Status:**	
Construction Date:		**Data Src:**	1
Primary Water Use:	Not Used	**Date Received:**	5/7/1991
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Quality	**Abandonment Rec:**	
Water Type:		**Contractor:**	4877
Casing Material:		**Form Version:**	1
Audit No:	89713	**Owner:**	
Tag:		**Street Name:**	
Construction Method:		**County:**	36
Elevation (m):		**Municipality:**	BROCKVILLE CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	017
Well Depth:		**Concession:**	01
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/361\3611808.pdf

Bore Hole Information

Bore Hole ID:	10225195	**Elevation:**	104.83776
DP2BR:	18	**Elevrc:**	
Spatial Status:	Improved	**Zone:**	18
Code OB:	r	**East83:**	443011
Code OB Desc:	Bedrock	**North83:**	4937742
Open Hole:		**Org CS:**	N83
Cluster Kind:		**UTMRC:**	3
Date Completed:	5/25/1991	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	

Elevrc Desc:	
Location Source Date:	
Improvement Location Source:	1999-2004 MOE Water Well Data Improvement Project
Improvement Location Method:	GIS
Source Revision Comment:	Northing and/or Easting field has been changed. Location estimated from sketch map.
Supplier Comment:	Determined to be an improvement rather than a Lot Centroid in December 2009.

Overburden and Bedrock Materials Interval

Formation ID:	931701506
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	12
Mat2 Desc:	STONES
Mat3:	85
Mat3 Desc:	SOFT
Formation Top Depth:	0
Formation End Depth:	18
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931701507
Layer:	2
Color:	8
General Color:	BLACK
Mat1:	17
Most Common Material:	SHALE
Mat2:	73
Mat2 Desc:	HARD
Mat3:	
Mat3 Desc:	
Formation Top Depth:	18
Formation End Depth:	21
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931701508
Layer:	3
Color:	8
General Color:	BLACK
Mat1:	21
Most Common Material:	GRANITE
Mat2:	73
Mat2 Desc:	HARD
Mat3:	
Mat3 Desc:	
Formation Top Depth:	21
Formation End Depth:	31
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	933155165

Layer: 1
Plug From: 0
Plug To: 31
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963611808
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10773765
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930379989
Layer: 2
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter: 9
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930379988
Layer: 1
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter: 15
Casing Diameter UOM: inch
Casing Depth UOM: ft

Water Details

Water ID: 933690244
Layer: 1
Kind Code: 5
Kind: Not stated
Water Found Depth: 18
Water Found Depth UOM: ft

---

134 | **1 of 1** | **NE/226.9** | **99.9 / 0.02** | **ALEX JOANNIDES HOLDINGS INC.**
2360 Parkdale AVE
Brockville ON K6V 7J5 | **PES**

Detail Licence No:
Licence No: L-232-9056365461
Status: Active
Approval Date: 2019-06-24
Operator Box:
Operator Class:
Operator No:
Operator Type:

Report Source: PEST-Limited Vendor
Licence Type: Limited Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude: 44.60611111
Longitude: -75.69916667
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2161841

Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District: Kingston
SWP Area Name: Cataraqui

---

135 | **1 of 1** | **ENE/122.6** | **99.9 / 0.02** | **ON** | **WWIS**

Well ID: 3600483
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 7/27/1956
Selected Flag: Yes
Abandonment Rec:
Contractor: 3705
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600483.pdf

Bore Hole Information

Bore Hole ID: 10214442
DP2BR: 3
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 6/16/1956
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 99.743377
Elevrc:
Zone: 18
East83: 446025.7
North83: 4940206
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931675885
Layer: 2
Color:
General Color:
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 3
Formation End Depth: 40
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931675884
Layer: 1
Color:
General Color:
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 3
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600483
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763012
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362688
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 10
Casing Diameter: 4
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362689
Layer: 2

Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 40
Casing Diameter: 4
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600483
Pump Set At:
Static Level: 5
Final Level After Pumping: 5
Recommended Pump Depth:
Pumping Rate: 8
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676356
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 38
Water Found Depth UOM: ft

---

136 ***1 of 21*** ***NE/171.9*** ***101.1 / 1.22*** ***DAVID EATON S & D EQUIPMENT RENTALS*** ***PRT***
1917 PARKEDALE AV
BROCKVILLE ON K6V 5T2

Location ID: 2258
Type: private
Expiry Date:
Capacity (L): 13638.00
Licence #: 0001010381

---

136 ***2 of 21*** ***NE/171.9*** ***101.1 / 1.22*** ***DAVID EATON S & D EQUIPMENT RENTALS*** ***FSTH***
1917 PARKEDALE AVE E
BROCKVILLE ON K6V 5T2

License Issue Date: 6/4/1990
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1984
Corrosion Protection:
Capacity: 13638

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

---

136 **3 of 21** **NE/171.9** **101.1 / 1.22** **1207931 Ontario Limited** **GEN**
1917 Parkedale Ave.
Brockville ON

Generator No: ON8101867
Status:
Approval Years: 06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 238299 238910
SIC Description: All Other Building Equipment Contractors, Site Preparation Contractors
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

136 **4 of 21** **NE/171.9** **101.1 / 1.22** **1207931 Ontario Limited** **CA**
1917 Parkedale Avenue
Brockville ON

Certificate #: A860436
Application Year: 2000
Issue Date: 4/17/2000
Approval Type: Waste Management Systems
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

136 **5 of 21** **NE/171.9** **101.1 / 1.22** **1207931 Ontario Limited** **CA**
1917 Parkedale Avenue
Brockville ON

Certificate #: A860436
Application Year: 2006
Issue Date: 3/27/2006
Approval Type: Waste Management Systems
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

136 **6 of 21** **NE/171.9** **101.1 / 1.22** **DAVID EATON S & D EQUIPMENT RENTALS** **EXP**
1917 PARKEDALE AVE E
BROCKVILLE ON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance No: 9243368
Instance ID: 382720
Instance Type: FS Facility
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

136 **7 of 21** **NE/171.9** **101.1 / 1.22** **DAVID EATON S & D EQUIPMENT RENTALS** **EXP**
1917 PARKEDALE AVE E
BROCKVILLE ON K6V 5T2

Instance No: 10618490
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 6/5/1990

---

136 **8 of 21** **NE/171.9** **101.1 / 1.22** **DAVID EATON S & D EQUIPMENT RENTALS** **EXP**
1917 PARKEDALE AVE E
BROCKVILLE ON

Instance No: 10618512
Instance ID: 30007
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

136 **9 of 21** **NE/171.9** **101.1 / 1.22** **1207931 Ontario Limited** **GEN**
1917 Parkedale Ave.
Brockville ON

Generator No: ON8101867
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 238299, 238910
SIC Description: All Other Building Equipment Contractors, Site Preparation Contractors
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

136 **10 of 21** **NE/171.9** **101.1 / 1.22** **1207931 Ontario Limited** **GEN**
1917 Parkedale Ave.
Brockville ON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No: ON8101867
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 238299, 238910
SIC Description: All Other Building Equipment Contractors, Site Preparation Contractors
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

136 ***11 of 21*** ***NE/171.9*** ***101.1 / 1.22*** ***1207931 Ontario Limited***
1917 Parkedale Ave.
Brockville ON ***GEN***

Generator No: ON8101867
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 238299, 238910
SIC Description: All Other Building Equipment Contractors, Site Preparation Contractors
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

136 ***12 of 21*** ***NE/171.9*** ***101.1 / 1.22*** ***1207931 Ontario Limited***
1917 Parkedale Ave.
Brockville ON ***GEN***

Generator No: ON8101867
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 238299, 238910
SIC Description: All Other Building Equipment Contractors, Site Preparation Contractors
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

136 ***13 of 21*** ***NE/171.9*** ***101.1 / 1.22*** ***1207931 Ontario Limited***
1917 Parkedale Ave.
Brockville ON ***GEN***

Generator No: ON8101867
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 238299, 238910
SIC Description: ALL OTHER BUILDING EQUIPMENT CONTRACTORS, SITE PREPARATION CONTRACTORS
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

---

136 ***14 of 21*** ***NE/171.9*** ***101.1 / 1.22*** ***DAVID EATON S & D EQUIPMENT RENTALS***
1917 PARKEDALE AVE E
BROCKVILLE ON K6V 5T2 ***EXP***

Instance No: 10618490
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 6/5/1990

---

136 ***15 of 21*** ***NE/171.9*** ***101.1 / 1.22*** ***1207931 Ontario Limited***
1917 Parkedale Avenue
Brockville ON K6V 5T2 ***ECA***

Approval No: A860436
Approval Date: 2006-03-27
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Cataraqui
Approval Type: ECA-WASTE MANAGEMENT SYSTEMS
Project Type: WASTE MANAGEMENT SYSTEMS
Address: 1917 Parkedale Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/1238-6MVPCM-14.pdf
MOE District: Kingston
City:
Longitude: -75.68229
Latitude: 44.614788
Geometry X:
Geometry Y:

---

136 ***16 of 21*** ***NE/171.9*** ***101.1 / 1.22*** ***1207931 Ontario Limited***
1917 Parkedale Avenue
Brockville ON K6V 5T2 ***ECA***

Approval No: A860436
Approval Date: 2000-04-17
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Cataraqui
Approval Type: ECA-WASTE MANAGEMENT SYSTEMS
Project Type: WASTE MANAGEMENT SYSTEMS
MOE District: Kingston
City:
Longitude: -75.68229
Latitude: 44.614788
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Address: 1917 Parkedale Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7076-4J9GXL-14.pdf

---

136 **17 of 21** **NE/171.9** **101.1 / 1.22** **1207931 Ontario Limited**
1917 Parkedale Ave.
Brockville ON K6V 5T2 **GEN**

Generator No: ON8101867
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 238299, 238910
SIC Description: ALL OTHER BUILDING EQUIPMENT CONTRACTORS, SITE PREPARATION CONTRACTORS

PO Box No:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Ron Eaton
Phone No Admin: 6133422722 Ext.

Detail(s)

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

136 **18 of 21** **NE/171.9** **101.1 / 1.22** **1207931 Ontario Limited**
1917 Parkedale Ave.
Brockville ON K6V 5T2 **GEN**

Generator No: ON8101867
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 238299, 238910
SIC Description: ALL OTHER BUILDING EQUIPMENT CONTRACTORS, SITE PREPARATION CONTRACTORS

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

136 **19 of 21** **NE/171.9** **101.1 / 1.22** **1207931 Ontario Limited**
1917 Parkedale Ave.
Brockville ON K6V 5T2 **GEN**

Generator No: ON8101867
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 238299, 238910
SIC Description: ALL OTHER BUILDING EQUIPMENT CONTRACTORS, SITE PREPARATION CONTRACTORS

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

---

136 **20 of 21** **NE/171.9** **101.1 / 1.22** **1207931 Ontario Limited**
1917 Parkedale Ave.
Brockville ON K6V 5T2 **GEN**

Generator No: ON8101867
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145 L
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 212 L
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 213 L
Waste Class Desc: Petroleum distillates

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 253 L
Waste Class Desc: Emulsified oils

---

136 **21 of 21** **NE/171.9** **101.1 / 1.22** **1207931 Ontario Limited**
1917 Parkedale Ave.
Brockville ON K6V 5T2 **GEN**

Generator No: ON8101867
Status: Registered
Approval Years: As of Apr 2020
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145 L
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 213 L
Waste Class Desc: Petroleum distillates

Waste Class: 212 L
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 253 L
Waste Class Desc: Emulsified oils

---

137 **1 of 1** **NE/214.5** **101.0 / 1.19** **lot 7 con 2**
ON **WWIS**

Well ID: 3600913
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 11/6/1959
Selected Flag: Yes
Abandonment Rec:
Contractor: 3607
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY (ELIZABETHTOWN)
Site Info:
Lot: 007
Concession: 02
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600913.pdf

Bore Hole Information

Bore Hole ID: 10214870
DP2BR: 26
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 8/12/1959
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 102.62442
Elevrc:
Zone: 18
East83: 445809.7
North83: 4940467
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5

Overburden and Bedrock Materials Interval

Formation ID: 931676859
Layer: 1
Color:
General Color:
Mat1: 24
Most Common Material: PREV. DRILLED
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 26
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676860
Layer: 2
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 26
Formation End Depth: 63
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600913
Method Construction Code: 7
Method Construction: Diamond
Other Method Construction:

Pipe Information

Pipe ID: 10763440
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930363537
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 63
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930363536
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 30
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600913
Pump Set At:
Static Level: 26
Final Level After Pumping: 40
Recommended Pump Depth: 35
Pumping Rate: 5
Flowing Rate:
Recommended Pump Rate: 3
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 2
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676881
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 63
Water Found Depth UOM: ft

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
138	1 of 1	NE/182.7	101.9 / 2.01	lot 7 con 1 ON	WWIS

Well ID: 3600636
Construction Date:
Primary Water Use: Commerical
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 10/28/1958
Selected Flag: Yes
Abandonment Rec:
Contractor: 3504
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY (ELIZABETHTOWN)
Site Info:
Lot: 007
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600636.pdf

Bore Hole Information

Bore Hole ID: 10214595
DP2BR: 12
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 6/20/1958
Remarks:
Elevrc:
Zone: 18
East83: 445838.7
North83: 4940451
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 931676234
Layer: 1
Color: 2
General Color: GREY
Mat1: 09
Most Common Material: MEDIUM SAND
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 12
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676235
Layer: 2

Color:
General Color:
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 12
Formation End Depth: 82
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600636
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763165
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362990
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 22
Casing Diameter: 5
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362991
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 82
Casing Diameter: 5
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600636
Pump Set At:
Static Level: 22
Final Level After Pumping: 30
Recommended Pump Depth:
Pumping Rate: 7
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft

Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676545
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 82
Water Found Depth UOM: ft

139 **1 of 1** **NE/209.5** **101.9 / 2.04** **ON** **WWIS**

Well ID: 3600493
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 8/15/1960
Selected Flag: Yes
Abandonment Rec:
Contractor: 3705
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600493.pdf

Bore Hole Information

Bore Hole ID: 10214452
DP2BR: 5
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 8/8/1960
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 103.53804
Elevrc:
Zone: 18
East83: 445828.7
North83: 4940479
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5

Overburden and Bedrock

Materials Interval

Formation ID: 931675907
Layer: 1
Color:
General Color:
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931675908
Layer: 2
Color:
General Color:
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 5
Formation End Depth: 91
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600493
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763022
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362708
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 21
Casing Diameter: 4
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362709
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 91
Casing Diameter: 4
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600493
Pump Set At:
Static Level: 18
Final Level After Pumping: 23
Recommended Pump Depth: 23
Pumping Rate: 5
Flowing Rate:
Recommended Pump Rate: 5
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676366
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 90
Water Found Depth UOM: ft

140 | ***1 of 1*** | ***WSW/209.6*** | ***114.0 / 14.10*** | ***Chemical Rd junkyard*** | ***ANDR***

Brockville ON K6V 5T3

Legal Description: Elizabethtown Con 2 Lot 18S
Location Description: S of Chemical Rd at city limits; adj. trib to Grants Ck
Municipality: Brockville City
Current Municipality: Brockville City
RM: Leeds & Grenville Counties
Facility: Auto junkyard
Date Active: 1974
Date Begun:
Date Complete:
Area (Ha):
Landfill Type:
Group Name: Grants Creek
Operated By: Reynolds [A A]?
Serial: JY LGV5 1974
NTS: 31B12
Diameter (m): 365

Historical Summary:

Chemical Rd junkyard 1976 NTS 1:25,000 MAP 31B12B Shown as an auto wrecker on the 1976 NTS 1:25,000 Map Brockville ON Sheet 31B12B Edition 2 (Air Photos 1974, cultural checks 1975, information 1975, publication 1976).

Waste Type:
UTM X Nad 27: 442850
UTM Y Nad 27: 4937525
UTM Zone: 18

---

141 **1 of 1** **WSW/229.3** **115.2 / 15.30** **ELIZABETHTOWN NEW SITE 1** **AMIS**

ELIZABETHTOWN ON

Site Access Code:
AMIS Distr Code:
Abandoned Mine ID: 00494
Old MDI ID: NOT AVAILABLE
New MDI ID:
Official Nm: ELIZABETHTOWN NEW SITE 1
Mine Status: ABANDONED
Mine Plan/Section: UNDETERMINED
Site Class: D
Clos Reason Code:
Closure Plan: UNDETERMINED
Prim Commod Code:
Prim Commod: UNDETRMINED
Operat Access: ABANDONED ROAD
Date Entered: 01-JUN-2018
Date Last Modified: 04-JUL-2018
Effective Date:
Start Year:
End Year:
Prog Rehab Plan: NO
Evid of Site Contam:
Evid of Sulphide:
Evid Animals Pres:
Revegetation:
Veg Condition:
Veg Descr:
Chemical Doc:
Jurisdiction: MINING ACT
Lot No: 17
Concession: 1
Zone: 18
Northing: 4937748
Easting: 442841
Clos Reason: UNDETRMINED

Hyper Link: http://www.geologyontario.mndm.gov.on.ca/mndmfiles/AMIS/data/records/00494.html
AMIS District: TWEED
District Desc: TWEED
Animal Desc:
Status Type Code:
Mine Features Desc: QUARRY
AMIS Bkgrd Info: ACCESS TO THE SITE:FROM BROCKVILLE - HEAD WEST ON PARKDALE AVENUE (TURNS INTO OLD RED ROAD) FOR 4.41 KMTURN LEFT ONTO SIDE ROAD AND CONTINUE FOR APPROXIMATELY 150 MSITE IS LOCATED APPROXIMATELY 50 M TO THE WEST THROUGH THE BUSHNO CLAIM MAPS AVAILABLE
Alias Name: NOT AVAILABLE

AMIS Features

AMIS Feature ID: 93740
Effective Date:
Date Last Modified: 01-JUN-2018
Dt Entered in AMIS: 01-JUN-2018
Mine Feat Class Desc: FEATURE TO SURFACE
Feature Type Code:
Mine Feat Type Desc: QUARRY
Hazard Status Desc: NOT A HAZARD
Depth or Height: 2
Feature Width: 10
Feature Length: 40
Eval Performed Ind:
Soil Erosion Flag:
Txt Feature ID:
UTM Zone: 18
UTM Northing: 4937748
UTM Easting: 442841
Lat DD Features: 44.59081
Long DD Features: -75.72012
Mine Feature Condition Desc: THIS OBSERVED FEATURE IS A QUARRY THAT IS NOT BENCHED, OR BENCHED >10M AND DRY

---

142 **1 of 1** **NE/188.3** **103.8 / 4.00** **FRANK'S AUTO REPAIR** **RST**
1909 PARKEDALE AVE E
BROCKVILLE ON K6V 5T2

Headcode: 00921430
Headcode Desc: OIL CHANGES & LUBRICATION SERVICE
Phone: 6133421997
List Name:
Description:

143 **1 of 1** **WSW/164.9** **113.0 / 13.14** **lot 19 con 2** **WWIS**
ON

Well ID: 3614462
Construction Date:
Primary Water Use: Municipal
Sec. Water Use:
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: 190627
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Data Entry Status:
Data Src: 1
Date Received: 3/4/1999
Selected Flag: Yes
Abandonment Rec:
Contractor: 4827
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 019
Concession: 02
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/361\3614462.pdf

Bore Hole Information

Bore Hole ID: 10227846
DP2BR: 7
Spatial Status: Improved
Code OB: y
Code OB Desc: Unknown type (bedrock encountered)
Open Hole:
Cluster Kind:
Date Completed: 1/19/1999
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source: 1999-2004 MOE Water Well Data Improvement Project
Improvement Location Method: GIS
Source Revision Comment: Northing and/or Easting field has been changed. Well in same location as sketch map; conflicts with recorded con/lot.
Supplier Comment: Determined to be an improvement rather than a Lot Centroid in December 2009. Discrepancy with MOE Township examined. Wrong lot and/or con in the wwr record.
Elevation: 113.844398
Elevrc:
Zone: 18
East83: 442877
North83: 4937695
Org CS: N83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method:

Overburden and Bedrock Materials Interval

Formation ID: 931708666
Layer: 1
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 85
Mat2 Desc: SOFT
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 7
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931708668
Layer: 3
Color:
General Color:
Mat1: 28
Most Common Material: SAND
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 13
Formation End Depth: 27
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931708673
Layer: 8
Color:
General Color:
Mat1: 28
Most Common Material: SAND
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 58
Formation End Depth: 64
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931708671
Layer: 6
Color:
General Color:
Mat1: 28
Most Common Material: SAND
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 44
Formation End Depth: 53
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931708672
Layer: 7
Color:
General Color:
Mat1: 00
Most Common Material: UNKNOWN TYPE
Mat2:
Mat2 Desc:

Mat3:
Mat3 Desc:
Formation Top Depth: 53
Formation End Depth: 58
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931708667
Layer: 2
Color: 2
General Color: GREY
Mat1: 18
Most Common Material: SANDSTONE
Mat2: 73
Mat2 Desc: HARD
Mat3:
Mat3 Desc:
Formation Top Depth: 7
Formation End Depth: 13
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931708670
Layer: 5
Color:
General Color:
Mat1: 21
Most Common Material: GRANITE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 37
Formation End Depth: 44
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931708676
Layer: 11
Color: 1
General Color: WHITE
Mat1: 20
Most Common Material: QUARTZITE
Mat2: 73
Mat2 Desc: HARD
Mat3:
Mat3 Desc:
Formation Top Depth: 89
Formation End Depth: 101
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931708674
Layer: 9

Color:
General Color:
Mat1: 28
Most Common Material: SAND
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 64
Formation End Depth: 79
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931708675
Layer: 10
Color:
General Color:
Mat1: 21
Most Common Material: GRANITE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 79
Formation End Depth: 89
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931708669
Layer: 4
Color:
General Color:
Mat1: 00
Most Common Material: UNKNOWN TYPE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 27
Formation End Depth: 37
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933157168
Layer: 1
Plug From: 9
Plug To: 0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963614462
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 10776416
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930384485
Layer: 3
Material:
Open Hole or Material:
Depth From:
Depth To: 101
Casing Diameter: 10
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930384484
Layer: 2
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 10
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930384483
Layer: 1
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 9
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 933342018
Layer: 1
Slot: 010
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2

Results of Well Yield Testing

Pump Test ID: 993614462
Pump Set At:
Static Level: 18

Final Level After Pumping: 90
Recommended Pump Depth:
Pumping Rate: 20
Flowing Rate:
Recommended Pump Rate: 20
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 2
Water State After Test: CLOUDY
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934489993
Test Type:
Test Duration: 30
Test Level: 18
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934211982
Test Type:
Test Duration: 15
Test Level: 18
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 935002685
Test Type:
Test Duration: 60
Test Level: 18
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934751499
Test Type:
Test Duration: 45
Test Level: 18
Test Level UOM: ft

Water Details

Water ID: 933694544
Layer: 1
Kind Code: 5
Kind: Not stated
Water Found Depth: 41
Water Found Depth UOM: ft

Water Details

Water ID: 933694545
Layer: 2
Kind Code: 5
Kind: Not stated

Water Found Depth: 82
Water Found Depth UOM: ft

144 **1 of 1** **NE/132.1** **104.9 / 5.02** **ON** **WWIS**

Well ID: 3604633
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 12/16/1968
Selected Flag: Yes
Abandonment Rec:
Contractor: 3607
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3604633.pdf

Bore Hole Information

Bore Hole ID: 10218551
DP2BR: 20
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 10/30/1968
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 104.20156
Elevrc:
Zone: 18
East83: 445930.7
North83: 4940472
Org CS:
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: p4

Overburden and Bedrock Materials Interval

Formation ID: 931685221
Layer: 2
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 20
Formation End Depth: 76
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931685220
Layer: 1
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 13
Mat2 Desc: BOULDERS
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 20
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963604633
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10767121
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930370831
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 25
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930370832
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 76
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993604633
Pump Set At:

Static Level: 17
Final Level After Pumping: 19
Recommended Pump Depth: 35
Pumping Rate: 12
Flowing Rate:
Recommended Pump Rate: 10
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 2
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933681066
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 75
Water Found Depth UOM: ft

145 ***1 of 27*** ***NE/121.0*** ***104.9 / 5.02*** ***MOTOR COILS MFG 1879 PARKDALE AVE. BROCKVILLE CITY ON*** ***CA***

Certificate #: 8-4126-90-
Application Year: 90
Issue Date: 10/4/1990
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: COMBUSTION EQUIPMENT
Contaminants:
Emission Control:

145 ***2 of 27*** ***NE/121.0*** ***104.9 / 5.02*** ***MOTOR COILS MFG. LTD. 1879 PARKDALE AVE E RR 2 BROCKVILLE ON K6V 5T2*** ***SCT***

Established: 1960
Plant Size (ft²): 57000
Employment: 53

--Details--
Description: RAILROAD EQUIPMENT
SIC/NAICS Code: 3743

Description: INDUSTRIAL SUPPLIES
SIC/NAICS Code: 5085

Description: Motor and Generator Manufacturing
SIC/NAICS Code: 335312

Description: Railroad Rolling Stock Manufacturing
SIC/NAICS Code: 336510

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
145	3 of 27	NE/121.0	104.9 / 5.02	MOTOR COILS MFG. LTD. 1879 PARKEDALE AVENUE BROCKVILLE CITY ON	CA

Certificate #: 8-4174-97-
Application Year: 97
Issue Date: 11/12/1997
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: INSTALL PYROLYSIS CLEANING FURNACE
Contaminants: Nitrogen Oxides, Suspended Particulate Matter, Carbon Monoxide
Emission Control: Thermal Incineration

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
145	4 of 27	NE/121.0	104.9 / 5.02	MOTOR COILS MFG. LTD. 1879 PARKEDALE AVE W BROCKVILLE ON K6V 5T2	SCT

Established: 1960
Plant Size (ft²): 57000
Employment: 53

--Details--
Description: RAILROAD EQUIPMENT
SIC/NAICS Code: 3743

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
145	5 of 27	NE/121.0	104.9 / 5.02	Motor Coils Mfg. Co. (1981) Ltd. 1879 Parkdale Avenue Brockville Ontario K6V 5T2 CITY OF BROCKVILLE ON	EBR

EBR Registry No: IA02E0607
Ministry Ref No: 1369-5ATUQB
Notice Type: Instrument Decision
Notice Stage:
Notice Date: August 08, 2003
Proposal Date: June 14, 2002
Year: 2002
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Motor Coils Mfg. Co. (1981) Ltd.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 1879 Parkdale Avenue, Brockville Ontario, K6V 5T2
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

1879 Parkdale Avenue Brockville Ontario K6V 5T2 CITY OF BROCKVILLE

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
145	6 of 27	NE/121.0	104.9 / 5.02	Motor Coils Mfg. Ltd. 1879 Parkedale Ave E RR 2 Brockville ON K6V 5T2	SCT

Established: 01-SEP-60
Plant Size (ft²): 57000
Employment:

--Details--
Description: Motor and Generator Manufacturing
SIC/NAICS Code: 335312

Description: Railroad Rolling Stock Manufacturing
SIC/NAICS Code: 336510

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
145	7 of 27	NE/121.0	104.9 / 5.02	MOTOR COILS MANUFACTURING 1879 PARKDALE AVENUE, BROCKVILLE, ON K6V 5T2	GEN

Generator No: ON0978800
Status:
Approval Years: 86,87,88,89
Contam. Facility:
MHSW Facility:
SIC Code: 0000
SIC Description: *** NOT DEFINED ***

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
145	8 of 27	NE/121.0	104.9 / 5.02	MOTOR COILS MANUFACTURING 1879 PARKDALE AVENUE BROCKVILLE ON K6V 5T2	GEN

Generator No: ON0978800
Status:
Approval Years: 90,99,00,01,02,03,04
Contam. Facility:
MHSW Facility:
SIC Code: 3261
SIC Description: RAILROAD ROLLING ST.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

---

145 | **9 of 27** | **NE/121.0** | **104.9 / 5.02** | **MOTOR COILS MANUFACTURING 27-428**
1879 PARKDALE AVENUE
BROCKVILLE ON K6V 5T2 | **GEN**

Generator No: ON0978800
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 3261
SIC Description: RAILROAD ROLLING ST.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

---

145 | **10 of 27** | **NE/121.0** | **104.9 / 5.02** | **MOTOR COILS MANUFACTURING**
1879 Parkedale Ave.
Brockville ON K6V 5T2 | **GEN**

Generator No: ON0978800
Status:
Approval Years: 05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 336510
SIC Description: Railroad Rolling Stock Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

---

145 | **11 of 27** | **NE/121.0** | **104.9 / 5.02** | **Motor Coils Mfg. Co. (1981) Ltd.**
1879 Parkedale Avenue
Brockville ON | **CA**

Certificate #: 3896-5MDGW4

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Application Year: 2003
Issue Date: 7/31/2003
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

145 **12 of 27** **NE/121.0** **104.9 / 5.02** **MOTOR COILS MANUFACTURING** **GEN**
1879 Parkedale Ave.
Brockville ON

Generator No: ON0978800
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 336510, 336990
SIC Description: Railroad Rolling Stock Manufacturing, Other Transportation Equipment Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

---

145 **13 of 27** **NE/121.0** **104.9 / 5.02** **MOTOR COILS MANUFACTURING** **GEN**
1879 Parkedale Ave.
Brockville ON

Generator No: ON0978800
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 336510, 336990
SIC Description: Railroad Rolling Stock Manufacturing, Other Transportation Equipment Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
145	14 of 27	NE/121.0	104.9 / 5.02	MOTOR COILS MANUFACTURING 1879 Parkedale Ave. Brockville ON	GEN

Generator No: ON0978800
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 336510, 336990
SIC Description: Railroad Rolling Stock Manufacturing, Other Transportation Equipment Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
145	15 of 27	NE/121.0	104.9 / 5.02	MOTOR COILS MANUFACTURING 1879 Parkedale Ave. Brockville ON K6V 5T2	GEN

Generator No: ON0978800
Status:
Approval Years: 2012
Contam. Facility:

PO Box No:
Country:
Choice of Contact:
Co Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility:
Phone No Admin:
SIC Code: 336510, 336990
SIC Description: Railroad Rolling Stock Manufacturing, Other Transportation Equipment Manufacturing

Detail(s)

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
145	16 of 27	NE/121.0	104.9 / 5.02	1879 Parkdale Avenue Brockville ON	EHS

Order No: 20140609029
Status: C
Report Type: Custom Report
Report Date: 12-JUN-14
Date Received: 09-JUN-14
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -75.681784
Y: 44.616206

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
145	17 of 27	NE/121.0	104.9 / 5.02	MOTOR COILS MANUFACTURING 1879 Parkedale Ave.	GEN

Brockville ON

Generator No: ON0978800
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 336510, 336990
SIC Description: RAILROAD ROLLING STOCK MANUFACTURING, OTHER TRANSPORTATION EQUIPMENT MANUFACTURING

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

145 **18 of 27** **NE/121.0** **104.9 / 5.02** **Motor Coils Mfg. Co. (1981) Ltd.**
1879 Parkedale Avenue
Brockville ON K6V 5T2 **ECA**

Approval No: 3896-5MDGW4
Approval Date: 2003-07-31
Status: Approved
Record Type: ECA
Link Source: IDS

MOE District: Kingston
City:
Longitude: -75.681435
Latitude: 44.615482
Geometry X:

SWP Area Name: Cataraqui
Approval Type: ECA-AIR
Project Type: AIR
Address: 1879 Parkedale Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/1369-5ATUQB-14.pdf

Geometry Y:

---

145 **19 of 27** **NE/121.0** **104.9 / 5.02** **MOTOR COILS MANUFACTURING**
1879 Parkedale Ave.
Brockville ON K6V 5T2 **GEN**

Generator No: ON0978800
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 336510, 336990
SIC Description: RAILROAD ROLLING STOCK MANUFACTURING, OTHER TRANSPORTATION EQUIPMENT MANUFACTURING

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Bill Robinson
Phone No Admin: (613) 345-3580 Ext.208

Detail(s)

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

145 | 20 of 27 | NE/121.0 | 104.9 / 5.02 | MOTOR COILS MANUFACTURING
1879 Parkedale Ave.
Brockville ON K6V 5T2 | GEN

Generator No: ON0978800
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 336510, 336990
SIC Description: RAILROAD ROLLING STOCK MANUFACTURING, OTHER TRANSPORTATION EQUIPMENT MANUFACTURING

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Bill Robinson
Phone No Admin: (613) 345-3580 Ext.208

Detail(s)

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

145 | 21 of 27 | NE/121.0 | 104.9 / 5.02 | MOTOR COILS MANUFACTURING
1879 Parkedale Ave.
Brockville ON K6V 5T2 | GEN

Generator No: ON0978800
PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 336510, 336990
SIC Description: RAILROAD ROLLING STOCK MANUFACTURING, OTHER TRANSPORTATION EQUIPMENT MANUFACTURING

Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Bill Robinson
Phone No Admin: (613) 345-3580 Ext.208

Detail(s)

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 131
Waste Class Desc: NEUTRALIZED WASTES - HEAVY METALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

145 | 22 of 27 | NE/121.0 | 104.9 / 5.02 | MOTOR COILS MANUFACTURING
1879 Parkedale Ave.
Brockville ON K6V 5T2 | GEN

Generator No: ON0978800
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 122 C
Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 131 L
Waste Class Desc: Neutralized solutions - containing heavy metals

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 146 L
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 146 T
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 148 C
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 148 T
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 213 I
Waste Class Desc: Petroleum distillates

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 263 A
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 263 I
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 263 L
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 112 C
Waste Class Desc: Acid solutions - containing heavy metals

Waste Class: 112 L
Waste Class Desc: Acid solutions - containing heavy metals

---

145 | ***23 of 27*** | ***NE/121.0*** | ***104.9 / 5.02*** | ***Motor Coils Mfg. Ltd.***
1879 Parkedale Avenue Brockville CITY OF BROCKVILLE
ON | ***EBR***

EBR Registry No: IA7E1508
Ministry Ref No: 8417497 19970930
Notice Type: Instrument Decision
Notice Stage:
Notice Date: November 25, 1997
Proposal Date: October 06, 1997
Year: 1997
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Motor Coils Mfg. Ltd.
Site Address:
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Location Other:
Proponent Name:
Proponent Address: 1879 Parkedale Avenue, Brockvill Ontario, K6V 5T2
Comment Period:
URL:

Site Location Details:

1879 Parkedale Avenue Brockville CITY OF BROCKVILLE

---

145 | ***24 of 27*** | ***NE/121.0*** | ***104.9 / 5.02*** | ***Motor Coils Mfg. Co. (1981) Ltd.***
1879 Parkedale Ave
Brockville ON K6V 5T2 | ***SPL***

Ref No: 5242-AYJHRU
Site No: 8118-79NMQL
Incident Dt: 2018/05/05
Year:
Incident Cause:
Incident Event: Process Upset/Malfunction
Contaminant Code: 28
Contaminant Name: WASHWATER (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: n/a
Environment Impact:
Nature of Impact:
Receiving Medium:
Receiving Env: Land
MOE Response: No
Dt MOE Arvl on Scn:
MOE Reported Dt: 2018/05/07
Dt Document Closed:
Incident Reason: Equipment Failure
Site Name: 1879 Parkedale
Site County/District: United Counties Of Leeds & Grenville
Site Geo Ref Meth: 1-10 metres eg. Good Quality GPS
Incident Summary: Motor Coils: 700L washwater to ashphalt, cntd.
Contaminant Qty: 700 L
Discharger Report:
Material Group:
Health/Env Conseq: 2 - Minor Environment
Client Type: Corporation
Sector Type: Miscellaneous Industrial
Agency Involved:
Nearest Watercourse:
Site Address: 1879 Parkedale Ave
Site District Office: Kingston - District
Site Postal Code: K6V 5T2
Site Region: Eastern
Site Municipality: Brockville
Site Lot:
Site Conc: NA
Northing: 4940570
Easting: 445958
Site Geo Ref Accu: GPS
Site Map Datum: NAD83
SAC Action Class: Land Spills
Source Type: Tank - Above Ground

---

145 | ***25 of 27*** | ***NE/121.0*** | ***104.9 / 5.02*** | ***MOTOR COILS MANUFACTURING***
1879 Parkedale Ave.
Brockville ON K6V 5T2 | ***GEN***

Generator No: ON0978800
Status: Registered
Approval Years: As of Apr 2020
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 148 C
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 146 T
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 211 I
Waste Class Desc: Aromatic solvents and residues

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 263 I
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 131 L
Waste Class Desc: Neutralized solutions - containing heavy metals

Waste Class: 148 T
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 263 A
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 112 C
Waste Class Desc: Acid solutions - containing heavy metals

Waste Class: 112 L
Waste Class Desc: Acid solutions - containing heavy metals

Waste Class: 146 L
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 263 L
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 122 C
Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 213 I
Waste Class Desc: Petroleum distillates

---

145 **26 of 27** **NE/121.0** **104.9 / 5.02** **Motor Coils Mfg. Ltd.**
1879 Parkedale Avenue Brockville, ON Canada
ON **EBR**

EBR Registry No: 019-0241
Ministry Ref No: 2414-BCZSAX
Notice Type: Instrument
Notice Stage: Decision
Updated
Notice Date:
Proposal Date: September 11, 2019
Year: 2019
Instrument Type: Environmental Compliance Approval (air)
Off Instrument Name: Environmental Compliance Approval (air) (EPA s.9)
Posted By: Ministry of the Environment, Conservation and Parks
Company Name:
Site Address: 1879 Parkedale Avenue
Brockville,
ON
Canada
Location Other:
Proponent Name: Motor Coils Mfg. Ltd.
Proponent Address: 1879 Parkedale Avenue

Decision Posted: April 28, 2020
Exception Posted:
Section: Part II.1 (20.3 or 20.5)
Act 1: Environmental Protection Act, R.S.O. 1990
Act 2: Environmental Protection Act
Site Location Map: 44.6157,-75.681105

Brockville,
ON
K6V 5T2
Canada
Comment Period: September 11, 2019 - October 26, 2019 (45 days) Closed
URL: https://ero.ontario.ca/notice/019-0241

Site Location Details:

---

145 **27 of 27** **NE/121.0** **104.9 / 5.02** **Motor Coils Mfg. Ltd.**
1879 Parkedale Ave
Brockville ON K6V 5T2 **ECA**

Approval No: 5597-BEZRX6
Approval Date: 2020-04-27
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Cataraqui
Approval Type: ECA-AIR
Project Type: AIR
Address: 1879 Parkedale Ave
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2414-BCZSAX-14.pdf

MOE District: Kingston
City:
Longitude: -75.68143
Latitude: 44.615482
Geometry X: -8424818.2501
Geometry Y: 5561188.768399998

---

146 **1 of 1** **NE/68.8** **104.9 / 5.02** **lot 7 con 1**
ON **WWIS**

Well ID: 3600635
Construction Date:
Primary Water Use: Commerical
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 10/21/1957
Selected Flag: Yes
Abandonment Rec:
Contractor: 4908
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY (ELIZABETHTOWN)
Site Info:
Lot: 007
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600635.pdf

Bore Hole Information

Bore Hole ID: 10214594
DP2BR: 0
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:

Elevation: 104.572647
Elevrc:
Zone: 18
East83: 446039.7
North83: 4940492
Org CS:
UTMRC: 9

Date Completed: 10/3/1957
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676232
Layer: 3
Color: 2
General Color: GREY
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 30
Formation End Depth: 60
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676230
Layer: 1
Color:
General Color:
Mat1: 17
Most Common Material: SHALE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 4
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676233
Layer: 4
Color: 1
General Color: WHITE
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 60
Formation End Depth: 80
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676231
Layer: 2
Color: 6
General Color: BROWN
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 4
Formation End Depth: 30
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600635
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763164
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362989
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 60
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362988
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 29
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600635
Pump Set At:
Static Level: 36
Final Level After Pumping: 50
Recommended Pump Depth:
Pumping Rate: 28

Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 0
Pumping Duration MIN: 30
Flowing: No

Water Details

Water ID: 933676544
Layer: 2
Kind Code: 1
Kind: FRESH
Water Found Depth: 44
Water Found Depth UOM: ft

Water Details

Water ID: 933676543
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 36
Water Found Depth UOM: ft

---

147 | 1 of 1 | NE/188.3 | 104.9 / 5.02 | ON | WWIS

Well ID: 3600534
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 3/14/1968
Selected Flag: Yes
Abandonment Rec:
Contractor: 3607
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600534.pdf

Bore Hole Information

Bore Hole ID: 10214493
DP2BR: 3
Spatial Status:
Code OB: r
Code OB Desc: Bedrock

Elevation: 104.916481
Elevrc:
Zone: 18
East83: 445954.7
North83: 4940576

Open Hole:
Cluster Kind:
Date Completed: 11/27/1967
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5

Overburden and Bedrock Materials Interval

Formation ID: 931675998
Layer: 1
Color:
General Color:
Mat1: 09
Most Common Material: MEDIUM SAND
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 3
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931675999
Layer: 2
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 3
Formation End Depth: 70
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600534
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763063
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362791
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 70
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362790
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 25
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600534
Pump Set At:
Static Level: 12
Final Level After Pumping: 15
Recommended Pump Depth: 35
Pumping Rate: 10
Flowing Rate:
Recommended Pump Rate: 8
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 2
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676411
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 70
Water Found Depth UOM: ft

148 | 1 of 1 | ENE/149.7 | 101.3 / 1.42 | lot 7 con 1 ON | WWIS

Well ID: 3600631
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Data Entry Status:
Data Src: 1
Date Received: 2/11/1955
Selected Flag: Yes
Abandonment Rec:
Contractor: 3322
Form Version: 1
Owner:
Street Name:

Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
County: 36
Municipality: BROCKVILLE CITY (ELIZABETHTOWN)
Site Info:
Lot: 007
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600631.pdf

Bore Hole Information

Bore Hole ID: 10214590
DP2BR: 46
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 10/2/1954
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation: 101.972183
Elevrc:
Zone: 18
East83: 446198.7
North83: 4940342
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676219
Layer: 1
Color:
General Color:
Mat1: 02
Most Common Material: TOPSOIL
Mat2: 05
Mat2 Desc: CLAY
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 7
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676221
Layer: 3
Color: 2
General Color: GREY
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 46

Formation End Depth: 60
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676220
Layer: 2
Color:
General Color:
Mat1: 14
Most Common Material: HARDPAN
Mat2: 11
Mat2 Desc: GRAVEL
Mat3: 13
Mat3 Desc: BOULDERS
Formation Top Depth: 7
Formation End Depth: 46
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600631
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763160
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362981
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 60
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362980
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 48
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600631
Pump Set At:
Static Level: 6
Final Level After Pumping: 35
Recommended Pump Depth:
Pumping Rate: 8
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 0
Pumping Duration MIN: 30
Flowing: No

Water Details

Water ID: 933676539
Layer: 2
Kind Code: 1
Kind: FRESH
Water Found Depth: 60
Water Found Depth UOM: ft

Water Details

Water ID: 933676538
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 40
Water Found Depth UOM: ft

149 **1 of 1** **ENE/197.9** **100.9 / 1.09** **ON** **WWIS**

Well ID: 3600498
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 10/20/1961
Selected Flag: Yes
Abandonment Rec:
Contractor: 3607
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600498.pdf

Bore Hole Information

Bore Hole ID: 10214457
DP2BR: 5
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 5/16/1961
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 101.941383
Elevrc:
Zone: 18
East83: 446233.8
North83: 4940309
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5

Overburden and Bedrock Materials Interval

Formation ID: 931675918
Layer: 1
Color:
General Color:
Mat1: 02
Most Common Material: TOPSOIL
Mat2: 09
Mat2 Desc: MEDIUM SAND
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931675919
Layer: 2
Color: 7
General Color: RED
Mat1: 21
Most Common Material: GRANITE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 5
Formation End Depth: 70
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600498
Method Construction Code: 7
Method Construction: Diamond
Other Method Construction:

Pipe Information

Pipe ID: 10763027

Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362718
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 22
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362719
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 70
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600498
Pump Set At:
Static Level: 18
Final Level After Pumping: 20
Recommended Pump Depth: 50
Pumping Rate: 12
Flowing Rate:
Recommended Pump Rate: 8
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 2
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676371
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 70
Water Found Depth UOM: ft

150 | ***1 of 1*** | ***WSW/207.6*** | ***111.0 / 11.15*** | ***Chemical Rd Dump 1968*** | ***ANDR***

Brockville ON K6V 5T3

Legal Description: Elizabethtown Con 2 Lots 17-18 pt
Location Description: straddles Brockville City limits

Municipality: Brockville City
Current Municipality: Brockville City
RM: Leeds & Grenville Counties
Facility: Dump
Date Active: 1968
Date Begun:
Date Complete:
Area (Ha): 12
Landfill Type: open dump
Group Name: Grant's Creek
Operated By:
Serial: MOEE 9070 1968
NTS: 31B12
Diameter (m): 600

Historical Summary:

Chemical Rd Dump 1968 1971 NTS Map 31B12 Shown on the 1971 NTS 1:50,000 Map Brockville ON Sheet 31B12 Edition 5 (Produced 1967, information 1968, publication 1971). Chemical Rd Dump DUMP SEEPAGE POLLUTES GRANTS CREEK: Runoff and leachate from Brockville's Chemical Rd dump site is polluting Grant's Creek. Site is closed evenings. Local critics want it opened more in the evenings and that filling of the creek area be controlled. There is an abandoned dump on Grant's Creek which is also thought to be leaking. These claims being made by a residents group (Brockville Recorder Oct 26 1973).

Waste Type:
UTM X Nad 27: 442700
UTM Y Nad 27: 4937425
UTM Zone: 18

---

151 | **1 of 1** | **NE/234.6** | **104.9 / 5.03** | **lot 7 con 11 ON** | **WWIS**

Well ID: 3608778
Construction Date:
Primary Water Use: Domestic
Sec. Water Use:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 5/16/1983
Selected Flag: Yes
Abandonment Rec:
Contractor: 2333
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 007
Concession: 11
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3608778.pdf

Bore Hole Information

Bore Hole ID: 10222174
DP2BR: 6
Spatial Status: Improved
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:

Elevation: 104.575508
Elevrc:
Zone: 18
East83: 445944
North83: 4940631
Org CS: N83
UTMRC: 3

Date Completed: 6/4/1982
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source: 1999-2004 MOE Water Well Data Improvement Project
Improvement Location Method: GIS
Source Revision Comment: Northing and/or Easting field has been changed. Location estimated from sketch map.well conflicts with recorded con, township discrepancy
Supplier Comment: Determined to be an improvement rather than a Lot Centroid in December 2009. Discrepancy with MOE Township examined. Wrong lot and/or con in the wwr record.

UTMRC Desc: margin of error : 10 - 30 m
Location Method:

Overburden and Bedrock Materials Interval

Formation ID: 931693700
Layer: 1
Color: 6
General Color: BROWN
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 6
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931693701
Layer: 2
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 6
Formation End Depth: 92
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933153512
Layer: 1
Plug From: 0
Plug To: 5
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933153513
Layer: 2
Plug From: 5
Plug To: 22
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963608778
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10770744
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930376127
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 22
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930376128
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 92
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993608778
Pump Set At:
Static Level: 16
Final Level After Pumping: 16
Recommended Pump Depth: 80
Pumping Rate: 9
Flowing Rate:
Recommended Pump Rate: 9
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 935001744
Test Type: Draw Down
Test Duration: 60
Test Level: 16
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934201606
Test Type: Draw Down
Test Duration: 15
Test Level: 16
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934488107
Test Type: Draw Down
Test Duration: 30
Test Level: 16
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934742058
Test Type: Draw Down
Test Duration: 45
Test Level: 16
Test Level UOM: ft

Water Details

Water ID: 933685516
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 77
Water Found Depth UOM: ft

Water Details

Water ID: 933685517
Layer: 2
Kind Code: 1
Kind: FRESH
Water Found Depth: 89
Water Found Depth UOM: ft

152 | ***1 of 6*** | ***NE/181.3*** | ***104.9 / 5.02*** | ***CANADA TRANSPORT 1861 PARKDALE TRANSPORT TRUCK (CARGO) BROCKVILLE CITY ON*** | ***SPL***

Ref No: 18025
Site No:
Incident Dt: 5/4/1989
Year:
Incident Cause: OTHER CONTAINER LEAK
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	56101
Nature of Impact:		**Site Lot:**	
Receiving Medium:	AIR	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	FD
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	5/4/1989	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	UNKNOWN	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	CAN.TRANS. - 5 LTR. RESINTO BACK OF TRUCK. VENTINGFUMES.		
Contaminant Qty:			

152	2 of 6	NE/181.3	104.9 / 5.02	**CANADA TRANSPORT GROUP LTD** **1861 PARKDALE AV** **BROCKVILLE ON K6V 5T2**	PRT

Location ID:	2255
Type:	private
Expiry Date:	
Capacity (L):	22700.00
Licence #:	0001057695

152	3 of 6	NE/181.3	104.9 / 5.02	**CANADA TRANSPORT GROUP LTD** **1861 PARKEDALE AVE E** **BROCKVILLE ON**	EXP

Instance No:	9409397
Instance ID:	386739
Instance Type:	FS Facility
Description:	Fuels Safety Private Fuel Outlet - Self Serve
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	
Expired Date:	

152	4 of 6	NE/181.3	104.9 / 5.02	**CANADA TRANSPORT GROUP LTD** **1861 PARKEDALE AVE E** **BROCKVILLE ON K6V 5T2**	EXP

Instance No:	10618365
Instance ID:	
Instance Type:	FS Liquid Fuel Tank
Description:	
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	
Expired Date:	1/23/1991

152	5 of 6	NE/181.3	104.9 / 5.02	**CANADA TRANSPORT GROUP LTD** **1861 PARKEDALE AVE E** **BROCKVILLE ON**	EXP

Instance No:	10618389
Instance ID:	31014
Instance Type:	FS Piping
Description:	FS Piping
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	
Expired Date:	

152	6 of 6	NE/181.3	104.9 / 5.02	**CANADA TRANSPORT GROUP LTD** **1861 PARKEDALE AVE E** **BROCKVILLE ON K6V 5T2**	EXP

Instance No:	10618365
Instance ID:	
Instance Type:	FS Liquid Fuel Tank
Description:	Fuels Safety Private Fuel Outlet - Self Serve
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	FS Liquid Fuel Tank
Expired Date:	1/23/1991

153	1 of 1	WSW/242.2	109.9 / 10.02	**Chemical Rd Dump 1963** **Brockville ON K6V 5T3**	ANDR

Legal Description:	Elizabethtown Con 2 Lots 17-18 pt
Location Description:	on Chemical Rd, straddles City limits
Municipality:	Brockville City
Current Municipality:	Brockville City
RM:	Leeds & Grenville Counties
Facility:	Dump
Date Active:	1962-63
Date Begun:	
Date Complete:	
Area (Ha):	12
Landfill Type:	sanitary landfill
Group Name:	
Operated By:	Brockville C
Serial:	MOEE 9070 1963
NTS:	31B12
Diameter (m):	600

Historical Summary:

Chemical Rd Dump 1963 1968 NTS 1:25,000 Map 31B12B Dump marked, 600m x 200m, irreg,. on Chemical Rd, straddles City limits [1968 NTS 1: 25,000 Map Brockville ON Sheet 31B12B Edition 1 (information 1963, printed 1968)]. Brockville Recorder & Times 8 May 1962 Brockville agrees to purchase sand from Kirkby¿s Cartage for use as dump cover at the sanitary landfill and for covering refuse at the Sandy Hill cemetery on a plot intended to be used for burial purposes in about 15 years time.

Waste Type:	MSW
UTM X Nad 27:	442675
UTM Y Nad 27:	4937450
UTM Zone:	18

154	1 of 1	ENE/35.3	102.8 / 2.98	**lot 7 con 1** **ON**	WWIS

Well ID: 3600630 **Data Entry Status:**

Construction Date:		**Data Src:**	1
Primary Water Use:	Not Used	**Date Received:**	8/24/1955
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Abandoned-Supply	**Abandonment Rec:**	
Water Type:		**Contractor:**	3110
Casing Material:		**Form Version:**	1
Audit No:		**Owner:**	
Tag:		**Street Name:**	
Construction Method:		**County:**	36
Elevation (m):		**Municipality:**	BROCKVILLE CITY (ELIZABETHTOWN)
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	007
Well Depth:		**Concession:**	01
Overburden/Bedrock:		**Concession Name:**	CON
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600630.pdf

Bore Hole Information

Bore Hole ID:	10214589	**Elevation:**	102.992462
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:	o	**East83:**	446146.7
Code OB Desc:	Overburden	**North83:**	4940452
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	9
Date Completed:	9/27/1953	**UTMRC Desc:**	unknown UTM
Remarks:		**Location Method:**	p9
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	931676217
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	02
Most Common Material:	TOPSOIL
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0
Formation End Depth:	1
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931676218
Layer:	2
Color:	2

General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	13
Mat2 Desc:	BOULDERS
Mat3:	
Mat3 Desc:	
Formation Top Depth:	1
Formation End Depth:	27
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	963600630
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10763159
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930362979
Layer:	1
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	6
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Water Details

Water ID:	933676537
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	27
Water Found Depth UOM:	ft

155 | ***1 of 1*** | ***NE/137.9*** | ***104.9 / 5.02*** | ***lot 7 con 1 ON*** | ***WWIS***

Well ID:	3600633	**Data Entry Status:**	
Construction Date:		**Data Src:**	1
Primary Water Use:	Commerical	**Date Received:**	3/4/1957
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Water Supply	**Abandonment Rec:**	
Water Type:		**Contractor:**	1505
Casing Material:		**Form Version:**	1
Audit No:		**Owner:**	
Tag:		**Street Name:**	
Construction Method:		**County:**	36
Elevation (m):		**Municipality:**	BROCKVILLE CITY (ELIZABETHTOWN)
Elevation Reliability:		**Site Info:**	

Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Lot: 007
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600633.pdf

Bore Hole Information

Bore Hole ID: 10214592
DP2BR: 1
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 7/14/1956
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 105.53527
Elevrc:
Zone: 18
East83: 446030.7
North83: 4940581
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676226
Layer: 3
Color:
General Color:
Mat1: 21
Most Common Material: GRANITE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 73
Formation End Depth: 84
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676225
Layer: 2
Color:
General Color:
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 1
Formation End Depth: 73
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676224
Layer: 1
Color:
General Color:
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 1
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600633
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763162
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362984
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 12
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362985
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 84
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600633
Pump Set At:
Static Level: 27

Final Level After Pumping: 45
Recommended Pump Depth:
Pumping Rate: 17
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676541
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 73
Water Found Depth UOM: ft

---

156 | 1 of 1 | NE/141.2 | 104.9 / 5.02 | lot 7 con 1 ON | WWIS

Well ID: 3608487
Construction Date:
Primary Water Use: Commerical
Sec. Water Use:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 9/28/1981
Selected Flag: Yes
Abandonment Rec:
Contractor: 2333
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 007
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3608487.pdf

Bore Hole Information

Bore Hole ID: 10221885
DP2BR: 2
Spatial Status: Improved
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 6/21/1981
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source: 1999-2004 MOE Water Well Data Improvement Project

Elevation: 105.507164
Elevrc:
Zone: 18
East83: 446033
North83: 4940588
Org CS: N83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method:

Improvement Location Method: GIS
Source Revision Comment: Northing and/or Easting field has been changed. Location estimated from sketch map.
Supplier Comment: Determined to be an improvement rather than a Lot Centroid in December 2009.

Overburden and Bedrock Materials Interval

Formation ID: 931692988
Layer: 2
Color: 1
General Color: WHITE
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 2
Formation End Depth: 18
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931692987
Layer: 1
Color: 2
General Color: GREY
Mat1: 11
Most Common Material: GRAVEL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 2
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931692989
Layer: 3
Color: 1
General Color: WHITE
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 18
Formation End Depth: 80
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933153391
Layer: 2
Plug From: 8
Plug To: 22

Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933153390
Layer: 1
Plug From: 0
Plug To: 8
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963608487
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10770455
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930375725
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 22
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930375726
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 80
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993608487
Pump Set At:
Static Level: 18
Final Level After Pumping: 42
Recommended Pump Depth: 60
Pumping Rate: 10
Flowing Rate:
Recommended Pump Rate: 10
Levels UOM: ft

Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934486994
Test Type: Draw Down
Test Duration: 30
Test Level: 35
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934200490
Test Type: Draw Down
Test Duration: 15
Test Level: 25
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934741450
Test Type: Draw Down
Test Duration: 45
Test Level: 42
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 935000720
Test Type: Draw Down
Test Duration: 60
Test Level: 42
Test Level UOM: ft

Water Details

Water ID: 933685128
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 72
Water Found Depth UOM: ft

157 | **1 of 1** | **NE/31.7** | **104.0 / 4.19** | **lot 7 con 1 ON** | **WWIS**

Well ID: 3600629
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:

Data Entry Status:
Data Src: 1
Date Received: 1/19/1954
Selected Flag: Yes
Abandonment Rec:
Contractor: 4227
Form Version: 1
Owner:
Street Name:

Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

County: 36
Municipality: BROCKVILLE CITY (ELIZABETHTOWN)
Site Info:
Lot: 007
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600629.pdf

Bore Hole Information

Bore Hole ID: 10214588
DP2BR: 12
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 7/28/1953
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 104.185958
Elevrc:
Zone: 18
East83: 446119.7
North83: 4940520
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676215
Layer: 1
Color:
General Color:
Mat1: 05
Most Common Material: CLAY
Mat2: 11
Mat2 Desc: GRAVEL
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 12
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676216
Layer: 2
Color:
General Color:
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 12

Formation End Depth: 47
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600629
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763158
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362977
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 15
Casing Diameter: 5
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362978
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 47
Casing Diameter: 5
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600629
Pump Set At:
Static Level: 15
Final Level After Pumping: 15
Recommended Pump Depth:
Pumping Rate: 7
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Water Details

Water ID:	933676536
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	45
Water Found Depth UOM:	ft

---

158 ***1 of 1*** ***NE/91.7*** ***104.9 / 5.02*** ***1000 Oxford Avenue Brockville ON*** ***EHS***

Order No:	20080819027	***Nearest Intersection:***	King St. E.
Status:	C	***Municipality:***	
Report Type:	Complete Report	***Client Prov/State:***	QC
Report Date:	8/27/2008	***Search Radius (km):***	0.25
Date Received:	8/19/2008	***X:***	-75.679622
Previous Site Name:		***Y:***	44.616409
Lot/Building Size:	21,895 sq. ft. bldg.		
Additional Info Ordered:	Fire Insur. Maps And /or Site Plans; Aerials Photos		

---

159 ***1 of 1*** ***ENE/116.5*** ***101.2 / 1.39*** ***PRIVATE RESIDENCE AT MOBILE HOME AT 1871 OXFORD AVE. FURNACE OIL TANK BROCKVILLE CITY ON K6V 7B5*** ***SPL***

Ref No:	167466	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	5/6/1999	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	ABOVE-GROUND TANK LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	56101
Nature of Impact:	Soil contamination	***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	5/6/1999	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	EQUIPMENT FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	RESIDENCE - 25 L OF FURNACE OIL TO GROUND FROM STORAGE TANK.		
Contaminant Qty:			

---

160 ***1 of 1*** ***WSW/94.3*** ***107.2 / 7.32*** ***lot 17 con 2 ON*** ***WWIS***

Well ID:	3613100	***Data Entry Status:***	
Construction Date:		***Data Src:***	1
Primary Water Use:	Municipal	***Date Received:***	3/24/1994
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:		***Abandonment Rec:***	
Water Type:		***Contractor:***	4006

Casing Material:		***Form Version:***	1
Audit No:	126268	***Owner:***	
Tag:		***Street Name:***	
Construction Method:		***County:***	36
Elevation (m):		***Municipality:***	ELIZABETHTOWN TOWNSHIP
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	017
Well Depth:		***Concession:***	02
Overburden/Bedrock:		***Concession Name:***	CON
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/361\3613100.pdf

Bore Hole Information

Bore Hole ID:	10226484	***Elevation:***	107.910217
DP2BR:	0	***Elevrc:***	
Spatial Status:	Improved	***Zone:***	18
Code OB:	h	***East83:***	442747
Code OB Desc:	Mixed in a Layer	***North83:***	4937526
Open Hole:		***Org CS:***	N83
Cluster Kind:		***UTMRC:***	3
Date Completed:	2/28/1994	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:	1999-2004 MOE Water Well Data Improvement Project		
Improvement Location Method:	GIS		
Source Revision Comment:	Northing and/or Easting field has been changed. Well in same location as sketch map; conflicts with recorded con/lot.		
Supplier Comment:	Determined to be an improvement rather than a Lot Centroid in December 2009.		

Overburden and Bedrock Materials Interval

Formation ID:	931704967
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	18
Mat2 Desc:	SANDSTONE
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0
Formation End Depth:	4
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931704968
Layer:	2
Color:	2
General Color:	GREY
Mat1:	18
Most Common Material:	SANDSTONE
Mat2:	

Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 4
Formation End Depth: 60
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933156135
Layer: 1
Plug From: 0
Plug To: 60
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963613100
Method Construction Code: 0
Method Construction: Not Known
Other Method Construction:

Pipe Information

Pipe ID: 10775054
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930381933
Layer: 1
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 4
Casing Diameter: 8
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930381935
Layer: 3
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 60
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930381934
Layer: 2
Material: 1
Open Hole or Material: STEEL

Depth From:
Depth To: 4
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Water Details

Water ID: 933692376
Layer: 1
Kind Code: 5
Kind: Not stated
Water Found Depth: 51
Water Found Depth UOM: ft

Water Details

Water ID: 933692377
Layer: 2
Kind Code: 5
Kind: Not stated
Water Found Depth: 57
Water Found Depth UOM: ft

---

161 | 1 of 8 | NE/162.0 | 104.9 / 5.02 | **GORD'S WEED CONTROL**
1845 PARKDALE AVENUE, R.R. #2
BROCKVILLE ON L0C 1B0 | PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Operator
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

---

161 | 2 of 8 | NE/162.0 | 104.9 / 5.02 | **788636 ONTARIO LIMITED/GARDEN WORLD**
R.R. #2, 1845 PARKEDALE AVENUE
BROCKVILLE ON K6V 6T4 | PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Operator
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:

Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

161 3 of 8 NE/162.0 104.9 / 5.02 GARDENER LANDSCAPING/GARDEN WORLD (C#91392) R.R. #2, 1845 PARKEDALE AVENUE BROCKVILLE ON K6V 1H3 PES

Detail Licence No:
Licence No:
Status:
Approval Date:
Report Source:
Licence Type: Vendor
Licence Type Code:
Licence Class:
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:
Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code:
Oper Phone No:
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

161 4 of 8 NE/162.0 104.9 / 5.02 GARDEN WORLD 17-502 1845 PARKEDALE AVENUE BROCKVILLE ON K6V 5T2 GEN

Generator No: ON1450900
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 0163
SIC Description: NURSERY PRODUCTS
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

161 5 of 8 NE/162.0 104.9 / 5.02 GARDEN WORLD 1845 PARKEDALE AVENUE BROCKVILLE ON K6V 5T2 GEN

Generator No: ON1450900
Status:
Approval Years: 99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 0163
SIC Description: NURSERY PRODUCTS
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

161 6 of 8 NE/162.0 104.9 / 5.02 AUTO PAK 1845 PARKDALE AVE EAST BROCKVILLE ON K6V 5T2 GEN

Generator No: ON9582932
Status:
Approval Years: 04
Contam. Facility:
MHSW Facility:
SIC Code: 416120
SIC Description: Plumbing Heating and Air-Conditioning Equipment and Supplies Wholesaler-Distributors
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

161 7 of 8 NE/162.0 104.9 / 5.02 788636 ONTARIO LIMITED/GARDEN WORLD C/O 1845 PARKEDALE AVENUE BROCKVILLE ON K6V5T1 PES

Detail Licence No:
Licence No: 03753
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Operator
Licence Type Code: 01
Licence Class: 06
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
PDF Link:
Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 3451262
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

161 8 of 8 NE/162.0 104.9 / 5.02 GARDENER LANDSCAPING/GARDEN WORLD (C#91392) R. R. #2, 1845 PARKEDALE AVENUE BROCKVILLE ON K6V5T2 PES

Detail Licence No:
Licence No: 03792
Status:
Approval Date:
Report Source: Legacy Licenses (Excluding TS)
Licence Type: Retail Vendor Class 02
Licence Type Code: 21
Licence Class: 02
Licence Control:
Latitude:
Longitude:
Lot:
Concession:
Region:
District:
County:
Trade Name:
Operator Box:
Operator Class:
Operator No:
Operator Type:
Oper Area Code: 613
Oper Phone No: 3451262
Operator Ext:
Operator Lot:
Oper Concession:
Operator Region:
Operator District:
Operator County:
Op Municipality:
Post Office Box:
MOE District:
SWP Area Name:

PDF Link:

162 | ***1 of 1*** | ***ENE/48.2*** | ***102.9 / 3.08*** | ***lot 6 con 1 ON*** | ***WWIS***

Well ID:	3605369	***Data Entry Status:***	
Construction Date:		***Data Src:***	1
Primary Water Use:	Domestic	***Date Received:***	10/5/1973
Sec. Water Use:	0	***Selected Flag:***	Yes
Final Well Status:	Water Supply	***Abandonment Rec:***	
Water Type:		***Contractor:***	1707
Casing Material:		***Form Version:***	1
Audit No:		***Owner:***	
Tag:		***Street Name:***	
Construction Method:		***County:***	36
Elevation (m):		***Municipality:***	ELIZABETHTOWN TOWNSHIP
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	006
Well Depth:		***Concession:***	01
Overburden/Bedrock:		***Concession Name:***	CON
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3605369.pdf

Bore Hole Information

Bore Hole ID:	10219265	***Elevation:***	102.7238
DP2BR:	54	***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:	r	***East83:***	446202.7
Code OB Desc:	Bedrock	***North83:***	4940492
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	4
Date Completed:	9/20/1973	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	p4
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	931686944
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Mat2 Desc:	GRAVEL
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0
Formation End Depth:	54
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931686945
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	18
Most Common Material:	SANDSTONE
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	54
Formation End Depth:	110
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	963605369
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10767835
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930372093
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	59
Casing Diameter:	5
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pump Test ID:	993605369
Pump Set At:	
Static Level:	15
Final Level After Pumping:	40
Recommended Pump Depth:	
Pumping Rate:	10
Flowing Rate:	
Recommended Pump Rate:	5
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	2
Pumping Duration HR:	1
Pumping Duration MIN:	0

Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934200889
Test Type: Draw Down
Test Duration: 15
Test Level: 30
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934736493
Test Type: Draw Down
Test Duration: 45
Test Level: 40
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 935003297
Test Type: Draw Down
Test Duration: 60
Test Level: 40
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934487366
Test Type: Draw Down
Test Duration: 30
Test Level: 40
Test Level UOM: ft

Water Details

Water ID: 933681926
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 106
Water Found Depth UOM: ft

---

163 | **1 of 1** | **NE/174.1** | **104.9 / 5.02** | **INFRASTRUCTURE ONTARIO**
1804 OXFORD AVE
BROCKVILLE ON | **GEN**

Generator No: ON6727471
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 561210
SIC Description: Facilities Support Services

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

---

164 | **1 of 1** | **NE/28.9** | **103.9 / 4.01** | **lot 6 con 1**
ON | **WWIS**

Well ID: 3600618
Construction Date:

Data Entry Status:
Data Src: 1

Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Date Received: 10/7/1957
Selected Flag: Yes
Abandonment Rec:
Contractor: 3705
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 006
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600618.pdf

Bore Hole Information

Bore Hole ID: 10214577
DP2BR: 60
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 9/11/1957
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 104.204544
Elevrc:
Zone: 18
East83: 446171.7
North83: 4940544
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676192
Layer: 1
Color:
General Color:
Mat1: 23
Most Common Material: PREVIOUSLY DUG
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 60
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676193
Layer: 2
Color: 2
General Color: GREY

Mat1:	18
Most Common Material:	SANDSTONE
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	60
Formation End Depth:	92
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	963600618
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10763147
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930362956
Layer:	2
Material:	4
Open Hole or Material:	OPEN HOLE
Depth From:	
Depth To:	92
Casing Diameter:	4
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Casing

Casing ID:	930362955
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	9
Casing Diameter:	4
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pump Test ID:	993600618
Pump Set At:	
Static Level:	20
Final Level After Pumping:	20
Recommended Pump Depth:	
Pumping Rate:	10
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1

Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933676522
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	90
Water Found Depth UOM:	ft

165 | ***1 of 1*** | ***ENE/152.4*** | ***100.4 / 0.59*** | ***lot 6 con 1 ON*** | ***WWIS***

Well ID:	3604921	**Data Entry Status:**	
Construction Date:		**Data Src:**	1
Primary Water Use:	Domestic	**Date Received:**	6/13/1972
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Water Supply	**Abandonment Rec:**	
Water Type:		**Contractor:**	1707
Casing Material:		**Form Version:**	1
Audit No:		**Owner:**	
Tag:		**Street Name:**	
Construction Method:		**County:**	36
Elevation (m):		**Municipality:**	ELIZABETHTOWN TOWNSHIP
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	006
Well Depth:		**Concession:**	01
Overburden/Bedrock:		**Concession Name:**	CON
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3604921.pdf

Bore Hole Information

Bore Hole ID:	10218831	**Elevation:**	100.678756
DP2BR:	16	**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:	r	**East83:**	446280.7
Code OB Desc:	Bedrock	**North83:**	4940422
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	4
Date Completed:	1/17/1972	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	p4
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID: 931685868
Layer: 2
Color: 6
General Color: BROWN
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 16
Formation End Depth: 69
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931685867
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 16
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963604921
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10767401
Casing No: 1
Comment:
Alt Name:

Results of Well Yield Testing

Pump Test ID: 993604921
Pump Set At:
Static Level: 15
Final Level After Pumping: 20
Recommended Pump Depth:
Pumping Rate: 10
Flowing Rate:
Recommended Pump Rate: 5
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 2
Pumping Duration HR: 1

Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934208041
Test Type: Draw Down
Test Duration: 15
Test Level: 20
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934485662
Test Type: Draw Down
Test Duration: 30
Test Level: 20
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 935002762
Test Type: Draw Down
Test Duration: 60
Test Level: 20
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934735854
Test Type: Draw Down
Test Duration: 45
Test Level: 20
Test Level UOM: ft

Water Details

Water ID: 933681411
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 65
Water Found Depth UOM: ft

166 **1 of 1** **NE/193.5** **104.9 / 5.02** **The Corporation of the City of Brockville**
Parkedale Avenue & North Augusta Rd
Brockville ON K6V 5V1 **ECA**

Approval No: 8274-5ZTRH8
Approval Date: 2004-06-17
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Cataraqui
MOE District: Kingston
City:
Longitude: -75.69200000000001
Latitude: 44.621500000000005
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: Parkedale Avenue & North Augusta Rd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/4238-5YRNU9-14.pdf

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
167	1 of 1	NE/125.6	104.9 / 5.02	lot 6 con 1 ON	WWIS

Well ID: 3600617
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 9/3/1957
Selected Flag: Yes
Abandonment Rec:
Contractor: 4609
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 006
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600617.pdf

Bore Hole Information

Bore Hole ID: 10214576
DP2BR: 22
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 6/17/1957
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 104.821861
Elevrc:
Zone: 18
East83: 446106.7
North83: 4940630
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676190
Layer: 2
Color:
General Color:
Mat1: 09
Most Common Material: MEDIUM SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3:
Mat3 Desc:
Formation Top Depth: 6
Formation End Depth: 22
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676191
Layer: 3
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 22
Formation End Depth: 55
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676189
Layer: 1
Color:
General Color:
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 6
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600617
Method Construction Code: 7
Method Construction: Diamond
Other Method Construction:

Pipe Information

Pipe ID: 10763146
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362954
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 55
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362953
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 22
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600617
Pump Set At:
Static Level: 12
Final Level After Pumping: 16
Recommended Pump Depth:
Pumping Rate: 13
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676521
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 55
Water Found Depth UOM: ft

---

168 | ***1 of 1*** | ***NE/187.4*** | ***104.9 / 5.02*** | ***Parkdale & Oxford Avenues Brockville ON*** | ***CA***

Certificate #: 5816-4PBRUQ
Application Year: 00
Issue Date: 9/22/00
Approval Type: Municipal & Private water
Status: Approved
Application Type: New Certificate of Approval
Client Name: Corporation Of The City Of Brockville
Client Address: One King Street West, P.O. Box 5000
Client City: Brockville
Client Postal Code: K6V 7A5
Project Description: Installation of Watermain on Parkdale & Oxford Avenues.
Contaminants:
Emission Control:

---

169 | ***1 of 1*** | ***NE/158.7*** | ***104.9 / 5.02*** | ***ON*** | ***WWIS***

Well ID: 3600510
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Data Entry Status:
Data Src: 1
Date Received: 10/4/1962
Selected Flag: Yes

Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Abandonment Rec:
Contractor: 3504
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600510.pdf

Bore Hole Information

Bore Hole ID: 10214469
DP2BR: 2
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 5/29/1962
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 104.40242
Elevrc:
Zone: 18
East83: 446086.7
North83: 4940657
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5

Overburden and Bedrock Materials Interval

Formation ID: 931675943
Layer: 1
Color:
General Color:
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 2
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931675944
Layer: 2
Color:
General Color:
Mat1: 18
Most Common Material: SANDSTONE

Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 2
Formation End Depth: 60
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600510
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763039
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362742
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 40
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362743
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 60
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600510
Pump Set At:
Static Level: 20
Final Level After Pumping: 30
Recommended Pump Depth: 50
Pumping Rate: 12
Flowing Rate:
Recommended Pump Rate: 7
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1

Pumping Duration HR: 5
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676383
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 54
Water Found Depth UOM: ft

170 **1 of 1** **NE/61.2** **104.7 / 4.83** **lot 6 con 1 ON** **WWIS**

Well ID: 3600620
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 5/7/1961
Selected Flag: Yes
Abandonment Rec:
Contractor: 3607
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 006
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600620.pdf

Bore Hole Information

Bore Hole ID: 10214579
DP2BR: 20
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 11/11/1960
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 104.268074
Elevrc:
Zone: 18
East83: 446165.7
North83: 4940578
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5

Overburden and Bedrock Materials Interval

Formation ID: 931676197
Layer: 2

Color: 2
General Color: GREY
Mat1: 21
Most Common Material: GRANITE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 20
Formation End Depth: 88
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676196
Layer: 1
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 20
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600620
Method Construction Code: 7
Method Construction: Diamond
Other Method Construction:

Pipe Information

Pipe ID: 10763149
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362959
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 25
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362960
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE

Depth From:
Depth To: 88
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600620
Pump Set At:
Static Level: 12
Final Level After Pumping: 20
Recommended Pump Depth: 35
Pumping Rate: 2
Flowing Rate:
Recommended Pump Rate: 2
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 2
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676524
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 88
Water Found Depth UOM: ft

171 | **1 of 1** | **ENE/150.3** | **100.5 / 0.63** | **lot 6 con 1 Brockville ON** | **WWIS**

Well ID: 7307509
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z253088
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

PDF URL (Map):

Data Entry Status:
Data Src:
Date Received: 3/26/2018
Selected Flag: Yes
Abandonment Rec:
Contractor: 4877
Form Version: 7
Owner:
Street Name: 1871 OXFORD AVE
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 006
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1007001452
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 11/28/2017
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83: 446290
North83: 4940439
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1007225311
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1007225312
Layer: 1
Plug From: 92
Plug To: 0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1007225310
Method Construction Code:
Method Construction:
Other Method Construction:

Pipe Information

Pipe ID: 1007225304
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007225308
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1007225309
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Water Details

Water ID: 1007225307
Layer:
Kind Code:
Kind:
Water Found Depth:
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1007225306
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

173 | **1 of 1** | **NE/128.5** | **104.9 / 5.02** | **lot 6 con 1 ON** | **WWIS**

Well ID: 3600615
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 9/3/1957
Selected Flag: Yes
Abandonment Rec:
Contractor: 3705
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 006
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600615.pdf

Bore Hole Information

Bore Hole ID: 10214574
DP2BR: 32
Spatial Status:
Code OB: r

Elevation: 104.845222
Elevrc:
Zone: 18
East83: 446127.7

Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 5/16/1957
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

North83: 4940641
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676185
Layer: 1
Color:
General Color:
Mat1: 24
Most Common Material: PREV. DRILLED
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 32
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676186
Layer: 2
Color:
General Color:
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 32
Formation End Depth: 69
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600615
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763144
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362950
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 69
Casing Diameter: 4
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362949
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 2
Casing Diameter: 4
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600615
Pump Set At:
Static Level: 25
Final Level After Pumping: 30
Recommended Pump Depth:
Pumping Rate: 4
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676519
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 60
Water Found Depth UOM: ft

174 | ***1 of 1*** | ***NE/194.2*** | ***104.9 / 5.02*** | ***lot 6 con 1 ON*** | ***WWIS***

Well ID: 3600608
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:

Data Entry Status:
Data Src: 1
Date Received: 11/15/1951
Selected Flag: Yes
Abandonment Rec:
Contractor: 3705
Form Version: 1
Owner:

Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 006
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600608.pdf

Bore Hole Information

Bore Hole ID: 10214567
DP2BR: 4
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 6/25/1951
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 104.355758
Elevrc:
Zone: 18
East83: 446081.7
North83: 4940694
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676169
Layer: 2
Color:
General Color:
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 4
Formation End Depth: 20
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676170
Layer: 3
Color:
General Color:
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:

Formation Top Depth: 20
Formation End Depth: 50
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676168
Layer: 1
Color:
General Color:
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 4
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600608
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763137
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362937
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 50
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362936
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 4
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600608
Pump Set At:
Static Level: 25
Final Level After Pumping: 40
Recommended Pump Depth:
Pumping Rate: 3
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676510
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 45
Water Found Depth UOM: ft

---

175 | **1 of 1** | **ENE/230.2** | **97.9 / -1.97** | **lot 6 con 1 ON** | **WWIS**

Well ID: 3600904
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 12/19/1956
Selected Flag: Yes
Abandonment Rec:
Contractor: 3322
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 006
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600904.pdf

Bore Hole Information

Bore Hole ID: 10214861
DP2BR: 3
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 10/31/1956

Elevation: 98.080207
Elevrc:
Zone: 18
East83: 446354.8
North83: 4940392
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM

Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Location Method: p9

Overburden and Bedrock Materials Interval

Formation ID: 931676840
Layer: 2
Color: 2
General Color: GREY
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 3
Formation End Depth: 53
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931676839
Layer: 1
Color:
General Color:
Mat1: 02
Most Common Material: TOPSOIL
Mat2: 05
Mat2 Desc: CLAY
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 3
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600904
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763431
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930363519
Layer: 2
Material: 4

Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 53
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930363518
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 8
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600904
Pump Set At:
Static Level: 25
Final Level After Pumping: 37
Recommended Pump Depth:
Pumping Rate: 10
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 0
Pumping Duration MIN: 30
Flowing: No

Water Details

Water ID: 933676869
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 53
Water Found Depth UOM: ft

---

176 | ***1 of 1*** | ***NE/171.1*** | ***104.9 / 5.02*** | ***ON*** | ***WWIS***

Well ID: 3600509
Construction Date:
Primary Water Use: Commerical
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Data Entry Status:
Data Src: 1
Date Received: 10/4/1962
Selected Flag: Yes
Abandonment Rec:
Contractor: 3504
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: BROCKVILLE CITY
Site Info:

Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3600509.pdf

Bore Hole Information

Bore Hole ID: 10214468
DP2BR: 2
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 5/28/1962
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation: 104.275016
Elevrc:
Zone: 18
East83: 446103.7
North83: 4940678
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5

Overburden and Bedrock Materials Interval

Formation ID: 931675941
Layer: 1
Color:
General Color:
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 2
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931675942
Layer: 2
Color:
General Color:
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 2
Formation End Depth: 60
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963600509
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10763038
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930362741
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 60
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930362740
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 40
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993600509
Pump Set At:
Static Level: 20
Final Level After Pumping: 30
Recommended Pump Depth: 50
Pumping Rate: 12
Flowing Rate:
Recommended Pump Rate: 7
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 2
Pumping Duration MIN: 0
Flowing: No

Water Details

Water ID: 933676382

Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 54
Water Found Depth UOM: ft

177 *1 of 1* *ENE/168.3* *99.3 / -0.55* ***lot 6 con 1 ON*** ***WWIS***

Well ID: 3608305
Construction Date:
Primary Water Use: Domestic
Sec. Water Use: 0
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 10/15/1980
Selected Flag: Yes
Abandonment Rec:
Contractor: 1119
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 006
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/360\3608305.pdf

Bore Hole Information

Bore Hole ID: 10221703
DP2BR: 4
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 7/29/1980
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 100.993598
Elevrc:
Zone: 18
East83: 446329.7
North83: 4940521
Org CS:
UTMRC: 5
UTMRC Desc: margin of error : 100 m - 300 m
Location Method: p5

Overburden and Bedrock Materials Interval

Formation ID: 931692555
Layer: 1
Color:
General Color:
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:

Formation Top Depth: 0
Formation End Depth: 4
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931692556
Layer: 2
Color: 2
General Color: GREY
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 4
Formation End Depth: 84
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963608305
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 10770273
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930375468
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 22
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993608305
Pump Set At:
Static Level: 30
Final Level After Pumping: 50
Recommended Pump Depth: 60
Pumping Rate: 8
Flowing Rate:
Recommended Pump Rate: 8
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR

Pumping Test Method: 1
Pumping Duration HR: 0
Pumping Duration MIN: 30
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934486414
Test Type: Draw Down
Test Duration: 30
Test Level: 50
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934208811
Test Type: Draw Down
Test Duration: 15
Test Level: 50
Test Level UOM: ft

Water Details

Water ID: 933684879
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 80
Water Found Depth UOM: ft

178 | **1 of 2** | **NE/214.4** | **103.9 / 4.02** | **lot 6 con 1 BROCKVILLE ON** | **WWIS**

Well ID: 3616501
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z28399
Tag: A017410
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 7/29/2005
Selected Flag: Yes
Abandonment Rec:
Contractor: 6571
Form Version: 3
Owner:
Street Name: 2805 SECOND CON RD
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info: R PLAN 28 R299
Lot: 006
Concession: 01
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/361\3616501.pdf

Bore Hole Information

Bore Hole ID: 11320936
DP2BR: 5
Spatial Status:
Code OB: r
Elevation: 104.264854
Elevrc:
Zone: 18
East83: 446175

Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 3/23/2005
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

North83: 4940731
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 933013031
Layer: 1
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 1.53
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933013032
Layer: 2
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 1.53
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933273640
Layer: 2
Plug From: 0.921
Plug To: 0
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933273641
Layer: 1
Plug From: 1.53
Plug To: 0.921

Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 963616501
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Pipe ID: 11335791
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930862809
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: .921
Depth To: 0
Casing Diameter: 5.08
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933413824
Layer: 1
Slot: 10
Screen Top Depth: 0.921
Screen End Depth: 1.53
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.28

Hole Diameter

Hole ID: 11539908
Diameter: 10
Depth From: 0
Depth To: 1.53
Hole Depth UOM: m
Hole Diameter UOM: cm

178 **2 of 2** **NE/214.4** **103.9 / 4.02** **lot 6 con 1 BROCKVILLE ON** **WWIS**

Well ID: 7045448
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z58234

Data Entry Status:
Data Src:
Date Received: 6/25/2007
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 6571
Form Version: 3
Owner:

Tag:	A017410	**Street Name:**	2805 SECOND KNIGHT RD
Construction Method:		**County:**	36
Elevation (m):		**Municipality:**	ELIZABETHTOWN TOWNSHIP
Elevation Reliability:		**Site Info:**	R PLAN 28 R299
Depth to Bedrock:		**Lot:**	006
Well Depth:		**Concession:**	01
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/704\7045448.pdf

Bore Hole Information

Bore Hole ID:	11767927	**Elevation:**	104.264854
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:	_	**East83:**	446175
Code OB Desc:	No formation data	**North83:**	4940731
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	4/2/2007	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	933321871
Layer:	1
Plug From:	1.53
Plug To:	0
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	967045448
Method Construction Code:	
Method Construction:	
Other Method Construction:	

Pipe Information

Pipe ID:	11775617
Casing No:	1
Comment:	
Alt Name:	

---

179 | ***1 of 2*** | ***NE/221.1*** | ***103.9 / 4.02*** | ***lot 6 con 1 BROCKVILLE ON*** | ***WWIS***

Well ID:	2410238	**Data Entry Status:**	
Construction Date:		**Data Src:**	

Primary Water Use:		**Date Received:**	7/29/2005
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Observation Wells	**Abandonment Rec:**	
Water Type:		**Contractor:**	6571
Casing Material:		**Form Version:**	3
Audit No:	Z28397	**Owner:**	
Tag:	A017408	**Street Name:**	2805 SECOND CONC RD
Construction Method:		**County:**	36
Elevation (m):		**Municipality:**	ELIZABETHTOWN TOWNSHIP
Elevation Reliability:		**Site Info:**	R PLAN 28 R 299
Depth to Bedrock:		**Lot:**	006
Well Depth:		**Concession:**	01
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/241\2410238.pdf

Bore Hole Information

Bore Hole ID:	11318321	**Elevation:**	104.218765
DP2BR:	6	**Elevrc:**	
Spatial Status:		**Zone:**	18
Code OB:	r	**East83:**	446183
Code OB Desc:	Bedrock	**North83:**	4940737
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	3/23/2005	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	933004527
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0
Formation End Depth:	1.84
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933004528
Layer:	2
Color:	2
General Color:	GREY

Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 1.84
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933273636
Layer: 2
Plug From: 0.921
Plug To: 0
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933273637
Layer: 1
Plug From: 1.84
Plug To: 0.921
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 962410238
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Pipe ID: 11333176
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930858683
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: .921
Depth To: 0
Casing Diameter: 5.08
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933413822
Layer: 1
Slot:
Screen Top Depth: 0.921

Screen End Depth: 1.84
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.28

Hole Diameter

Hole ID: 11536629
Diameter: 10
Depth From: 0
Depth To: 1.84
Hole Depth UOM: m
Hole Diameter UOM: cm

---

179 **2 of 2** **NE/221.1** **103.9 / 4.02** **lot 6 con 1 BROCKVILLE ON** **WWIS**

Well ID: 7045450
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z66865
Tag: A017408
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 6/25/2007
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 6571
Form Version: 3
Owner:
Street Name: 2805 SECOND CONC. RD
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info: R PLAN 28, R299
Lot: 006
Concession: 01
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/704\7045450.pdf

Bore Hole Information

Bore Hole ID: 11767929
DP2BR:
Spatial Status:
Code OB: _
Code OB Desc: No formation data
Open Hole:
Cluster Kind:
Date Completed: 4/2/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 104.218765
Elevrc:
Zone: 18
East83: 446183
North83: 4940737
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 933321873
Layer: 1
Plug From: 1.84
Plug To: 0
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 967045450
Method Construction Code:
Method Construction:
Other Method Construction:

Pipe Information

Pipe ID: 11775619
Casing No: 1
Comment:
Alt Name:

180 **1 of 2** **NE/222.0** **103.9 / 4.02** **lot 6 con 1 BROCKVILLE ON** **WWIS**

Well ID: 3616500
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z28398
Tag: A017409
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 7/29/2005
Selected Flag: Yes
Abandonment Rec:
Contractor: 6571
Form Version: 3
Owner:
Street Name: 2805 SECOND CONC RD
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info: R PLAN 28 R 299
Lot: 006
Concession: 01
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/361\3616500.pdf

Bore Hole Information

Bore Hole ID: 11320935
DP2BR: 9
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 3/23/2005
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:

Elevation: 104.209213
Elevrc:
Zone: 18
East83: 446182
North83: 4940738
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 933013029
Layer: 1
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 2.64
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933013030
Layer: 2
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 2.64
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933273639
Layer: 1
Plug From: 2.64
Plug To: 0.921
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933273638
Layer: 2
Plug From: 0.921
Plug To: 0
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 963616500
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Pipe ID: 11335790
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930862808
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: .921
Depth To: 0
Casing Diameter: 5.08
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933413823
Layer: 1
Slot: 10
Screen Top Depth: 0.921
Screen End Depth: 2.64
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.28

Hole Diameter

Hole ID: 11539907
Diameter: 10
Depth From: 0
Depth To: 2.64
Hole Depth UOM: m
Hole Diameter UOM: cm

180 **2 of 2** **NE/222.0** **103.9 / 4.02** **lot 6 con 1 BROCKVILLE ON** **WWIS**

Well ID: 7045447
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z66864
Tag: A017409
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):

Data Entry Status:
Data Src:
Date Received: 6/25/2007
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 6571
Form Version: 3
Owner:
Street Name: 2805 SECOND CONC. RD
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info: R PLAN 28, R299
Lot: 006
Concession: 01
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:

Flow Rate:
Clear/Cloudy:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/704\7045447.pdf

Bore Hole Information

Bore Hole ID: 11767926
DP2BR:
Spatial Status:
Code OB: _
Code OB Desc: No formation data
Open Hole:
Cluster Kind:
Date Completed: 4/2/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 104.209213
Elevrc:
Zone: 18
East83: 446182
North83: 4940738
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 933321870
Layer: 1
Plug From: 2.6
Plug To: 0
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 967045447
Method Construction Code:
Method Construction:
Other Method Construction:

Pipe Information

Pipe ID: 11775616
Casing No: 1
Comment:
Alt Name:

181 **1 of 1** **NE/243.0** **103.9 / 4.02** ***General Maintenance Contractors Ltd.*** ***2805 2nd Concession Rd.*** ***Brockville ON K6V 5T1*** **GEN**

Generator No: ON1095260
Status:
Approval Years: 04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

182 **1 of 2** **NE/230.8** **103.9 / 4.02** **lot 6 con 1 BROCKVILLE ON** **WWIS**

Well ID: 3616502
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z28460
Tag: A017407
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 7/29/2005
Selected Flag: Yes
Abandonment Rec:
Contractor: 6571
Form Version: 3
Owner:
Street Name: 2805 SECOND CONC RD
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info: R PLAN 28R299
Lot: 006
Concession: 01
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/361\3616502.pdf

Bore Hole Information

Bore Hole ID: 11320937
DP2BR: 5
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 3/23/2005
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 104.130592
Elevrc:
Zone: 18
East83: 446180
North83: 4940747
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 933013033
Layer: 1
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 1.53
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933013034

Layer: 2
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 1.53
Formation End Depth:
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933273710
Layer: 2
Plug From: 0.614
Plug To: 0
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933273711
Layer: 1
Plug From: 1.53
Plug To: 0.614
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 963616502
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Pipe ID: 11335792
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930862810
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: .614
Depth To: 0
Casing Diameter: 5.08
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933413858

Layer: 1
Slot: 10
Screen Top Depth: 0.614
Screen End Depth: 1.53
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.28

Hole Diameter

Hole ID: 11539909
Diameter: 10
Depth From: 0
Depth To: 1.53
Hole Depth UOM: m
Hole Diameter UOM: cm

---

182 **2 of 2** **NE/230.8** **103.9 / 4.02** **lot 6 con 1 BROCKVILLE ON** **WWIS**

Well ID: 7045449
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z58233
Tag: A017407
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 6/25/2007
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 6571
Form Version: 3
Owner:
Street Name: 2805 SECOND CONC RD
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info: R PLAN 28 R299
Lot: 006
Concession: 01
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/704\7045449.pdf

Bore Hole Information

Bore Hole ID: 11767928
DP2BR:
Spatial Status:
Code OB: _
Code OB Desc: No formation data
Open Hole:
Cluster Kind:
Date Completed: 4/2/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 104.130592
Elevrc:
Zone: 18
East83: 446180
North83: 4940747
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 933321872
Layer: 1
Plug From: 1.5
Plug To: 0
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 967045449
Method Construction Code:
Method Construction:
Other Method Construction:

Pipe Information

Pipe ID: 11775618
Casing No: 1
Comment:
Alt Name:

Unplottable Summary

Total: 144 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CA		Lot 6, Concession 1	Elizabethtown-Kitley ON	
CA		Lot 6, Concession 1	Elizabethtown-Kitley ON	
CA		Lot 6, Concession 1	Elizabethtown-Kitley ON	
CA		Lot 6, Concession 1	Elizabethtown ON	
CA	IMPERIAL OIL LIMITED	BELLEVILLE BULK TERMINAL	BELLEVILLE ON	
CA	ROLLINS CONSTRUCTION LTD.	PARK VILLAS PROPERTY N.PARK ST	BELLEVILLE CITY ON	
CA	P.U.C. BROCKVILLE CITY	FIRST AVE.	BROCKVILLE CITY ON	
CA	BROCKVILLE CITY	STEWART BOULEVARD	BROCKVILLE CITY ON	
CA	BROCKVILLE CITY	CENTRE STREET	BROCKVILLE CITY ON	
CA	ESSO PETROLEUM CANADA	P.O. BOX 248	BELLEVILLE CITY ON	
CA	ERNEST H. HARPER	ORMOND PLACE	BROCKVILLE CITY ON	
CA	CITY OF BROCKVILLE	PARK STREET	BROCKVILLE CITY ON	
CA	P.U.C. BROCKVILLE - ORMOND STREET	PARKDALE AVE/ORMOND/PERTH STS.	BROCKVILLE CITY ON	
CA	P.U.C. BROCKVILLE CITY	FIRST AVE.	BROCKVILLE CITY ON	
CA	HIGHLAND GOLF LTD. - PT. LOT 14, CONC. 1	PARKEDALE AVE./STM-WATER DET.	BROCKVILLE CITY ON	
CA	BROCKVILLE CITY	CALIFORNIA AVE.	BROCKVILLE CITY ON	
CA	BROCKVILLE CITY	STEWART BOULEVARD	BROCKVILLE CITY ON	
CA	BROCKVILLE CITY	CENTRE STREET	BROCKVILLE CITY ON	
CA	BROCKVILLE CITY	FIRST AVE.	BROCKVILLE CITY ON	
CA	ERNEST H. HARPER	EASEMENT N. OF ORMOND PLACE	BROCKVILLE CITY ON	
CA	BROOKVILLE CITY	EASEMENT N. OF ORMOND PLACE	BROCKVILLE CITY ON	
CA	Imperial Oil Limited	Designated as Part 1 on Reference Plan 21R-16968	Belleville ON	
CA	Brockville Centre Development Corp.	Centre St	Brockville ON	
CA	Brockville McDowel Ltd.	Centre Street	Brockville ON	
CA	Abbott Laboratories, Limited	North Augusta Rd	Brockville ON	
CA	Imperial Oil Limited		Belleville ON	
CA	Homesite Developments Ltd.	Centre Street	Belleville ON	
CA	Black & Decker Canada (1989) Inc.	Part Lots 8, 9, 11-17, RP #4, Part Lot 14, Conc. 1	Brockville ON	
CA	Imperial Oil Limited	Designated as Part 1 on Reference Plan 21R-16968	Belleville ON	
CA	P.U.C.	ORMOND ST.	BROCKVILLE ON	
CA	ROLLINS CONSTRUCTION LTD.	LT.12,E.OF N.PARK ST	BELLEVILLE ON	
CA		Waverly Drive	Brockville ON	
CA		Part of lot 9, Concession 2	Brockville ON	
CA		Part of lot 9, Concession 2	Brockville ON	
CA		Lot 6, Concession 1	Elizabethtown ON	
CA		Lot 6, Concession 1	Elizabethtown ON	
CA		Lot 6, Concession 1	Elizabethtown ON	
CA		Pt. of Lots 16 & 17, Conc. II , Parkdale Ave.	Brockville ON	
CA		Pt. of Lots 16 & 17, Conc. II , Parkdale Ave.	Brockville ON	
CA	The Corporation of the City of Brockville	Stewart Boulevard	Brockville ON	

CA	1427255 Ontario Inc.	Part of Lot 9, Concession 2	Brockville ON	
CONV	IMPERIAL OIL LIMITED		DON MILLS ON	
CONV	IMPERIAL OIL LIMITED		NORTH YORK ON	
CONV	MEYERS TRANSPORT LIMITED		ON	
CONV	L.A. KNAPP INC.		ON	
EBR	Motor Coils Mfg. Ltd.		City of Brockville ON	
EBR	Imperial Oil Limited, Contact Mr. Chris Atkins	Highway 401 Eastbound @ Mallorytown Mallorytown Ontario CITY OF BROCKVILLE	ON	
EBR	Selkirk Inc.	Part of lot 9, Concession 2 Brockville Ontario CITY OF BROCKVILLE	ON	
EBR	1427255 Ontario Inc.	John G. Broome Industrial Park, City of Brockville Part of Lot 9, Concession 2. CITY OF BROCKVILLE	ON	
EBR	Black & Decker Canada (1989) Inc.	Part Lots 8, 9, 11-17, RP #4, Part Lot 14, Conc. 1 Brockville Ontario CITY OF BROCKVILLE	ON	
EBR	Imperial Oil Limited, Contact Mr. Chris Atkins	Highway 401 Eastbound @ Mallorytown Mallorytown Ontario CITY OF BROCKVILLE	ON	
EBR	Procter & Gamble Inc.	Lot 8, COncession 2 CITY OF BROCKVILLE	ON	
ECA	Brockmoor Developments Corporation Limited and 2159203 Ontario Ltd.	Stewart Blvd Con 2, Lot 15 Elizabethtown	Brockville ON	K6V 3P7
ECA	The Corporation of the City of Brockville	Centre St (30-80 m north of Brock Street)	Brockville ON	K6V 7A5
ECA	Homesite Developments Ltd.	Centre St	Belleville ON	K8N 2Z2
ECA	Donna Lisa Bain	Parkdale Avenue West	Brockville ON	K6V 3G6
ECA	The Corporation of the City of Brockville	Lot 6, Concession 1	Elizabethtown-Kitley ON	K6V 5V1
ECA	Black & Decker Canada (1989) Inc.	Part Lots 8, 9, 11-17, RP #4, Part Lot 14, Conc. 1	Brockville ON	K6V 5W6
ECA	Homesite Developments Ltd.	Centre St	Belleville ON	K8N 2Z2
ECA	The Corporation of the City of Brockville	Lot 6, Concession 1	Elizabethtown-Kitley ON	K6V 5V1
ECA	The Corporation of the City of Brockville	Lot 6, Concession 1	Elizabethtown-Kitley ON	K6V 5V1

ECA	The Corporation of the City of Brockville	Centre Street	Brockville ON	K6V 7A5
ECA	The Corporation of the City of Brockville	Stewart Boulevard	Brockville ON	K6V 5V1
EXP	REYNOLDS CENTRAL FUELS	ADDRESS NOT SPECIFIED	BROCKVILLE ON	
EXP	REYNOLDS CENTRAL FUELS	ADDRESS NOT SPECIFIED	BROCKVILLE ON	
EXP	REYNOLDS CENTRAL FUELS	ADDRESS NOT SPECIFIED	BROCKVILLE ON	
EXP	BROCKVILLE PUBLIC UTILITIES COMMISSION	PARKEDALE AVHENRY LITTLE RESERVO	BROCKVILLE ON	K6V 5R9
EXP	REYNOLDS CENTRAL FUELS	ADDRESS NOT SPECIFIED	BROCKVILLE ON	
EXP	INTERLINK FREIGHT SYSTEMS INC	PARKEDALE AV	BROCKVILLE ON	K7S 3H4
FSTH	BROCKVILLE PUBLIC UTILITIES COMMISSION	PARKEDALE AV HENRY LITTLE RESERVO	BROCKVILLE ON	
FSTH	BROCKVILLE PUBLIC UTILITIES COMMISSION	PARKEDALE AV HENRY LITTLE RESERVO	BROCKVILLE ON	
GEN	MINISTRY OF NATURAL (OUT OF BUSINESS)	DISTRICT OFFICE LOT 6, CONCESSION 1	ELIZABETHTOWN TOWNSHIP ON	
GEN	UPI ENERGY LP	PLAN 67, BLOCK 22 PART LOT 7, PARK STREET	BROCKVILLE ON	K6V 5V5
GEN	BROCKVILLE COUNTRY CLUB	GOLF COURSE WORKSHOP LOT 18 & 19, CONCESSION 1	BROCKVILLE ON	
GEN	UPI INC.	PLAN 67, BLOCK 22 PART LOT 7, PARK STREET	BROCKVILLE ON	K6V 5V5
GEN	UCO PETROLEUM INC. 39-180	PARK ST.,PLAN67,BLOCK 22, PTLOT 7 BROCKVILLE,C/O5600 CANCROSS CT, BOX7030	MISSISSAUGA ON	L5B 2N6
GEN	UPI INC. 39-180	PARK ST., PLAN 67, BLOCK 22, PT.LOT 7	BROCKVILLE ON	K6V 5V5
GEN	ONTARIO HYDRO 29-107	BELLEVILLE TS CENTRE STREET	BELLEVILLE ON	K8N 4W7
GEN	ONTARIO HYDRO	BELLEVILLE TS CENTRE STREET	BELLEVILLE ON	K8N 4W7
GEN	PUROLATOR COURIER LTD (OUT OF BUSINESS)	HWY 29, NORTH GATE PLAZA BAY 5	BROCKVILLE ON	K0E 1T0
GEN	PUROLATOR COURIER LTD.	HWY 29, NORTH GATE PLAZA, BAY 5	BROCKVILLE ON	K0E 1T0
GEN	UNITED CO-OPERATIVES (SEE&USE ON1446912)	PARK STREET PLAN #67 BLOCK 22, PART LOT 7	BROCKVILLE ON	
GEN	UNITED CO(SEE&USE ON1446912) 39-180	PARK ST. PLAN NO.67 BLOCK 22 PT.LOT 7 C/O GEORGE ST. NORTH	BROCKVILLE ON	K6V 5V5

GEN	UNITED CO-OPERATIVES OF ONTARIO	PARK ST. PLAN NO.67 BLOCK 22 PT.LOT 7 C/O GEORGE ST. NORTH	BROCKVILLE ON	K6V 5V5
GEN	UPI ENERGY LP	PLAN 67, BLOCK 22 PART LOT 7, PARK STREET	BROCKVILLE ON	K6V 5V5
GEN	MINISTRY (SEE & USE ON0124151)	OXFORD AVE.	BROCKVILLE ON	K6V 5Y8
PRT	CANADIAN PACIFIC EXPRESS & TRANSPORT LTD	PARKDALE AV	BROCKVILLE ON	
PRT	KI GAS FOOD AND VARIETY SIDDIQUI AFZAL	LOT 16 CON 1	BELLEVILLE ON	
PRT	BROCKVILLE PUBLIC UTILITIES COMMISSION	PARKDALE AV HENRY LITTLE RESERVO	BROCKVILLE ON	
RST	ULTRAMAR		BELLEVILLE ON	
SCT	SANDS MEDICAL		BROCKVILLE ON	K6V 6K8
SPL	The Corporation of the City of Brockville	Brockville Water Pollution Control Center, Lot 6, Concession 1, Elizabethtown	Elizabethtown-Kitley ON	
SPL	S 21(1)(f) of FIPPA	Ormond Street, north of 401	Brockville ON	
SPL	ULTRAMAR CANADA INC.	CONCESSION 1 FUEL TRANSFER DEPOT	AUGUSTA ON	
SPL	TRANSPORT TRUCK	HWY 401, NEAR BELLEVILLE MOTOR VEHICLE (OPERATING FLUID)	BELLEVILLE CITY ON	
SPL	ESSO PETROLEUM CANADA	BULK STATION	BELLEVILLE CITY ON	
SPL	QUEENSWAY TANK LINES	ESSO BULK FARM TANK TRUCK (CARGO)	BROCKVILLE CITY ON	
SPL	ESSO PETROLEUM CANADA	BULK STATION	BELLEVILLE CITY ON	
SPL	TRANSPORT TRUCK	HWY 401 10 KM EAST OF BELLEVILLE, EAST BOUND LANE. MOTOR VEHICLE (OPERATING FLUID)	BELLEVILLE CITY ON	
SPL	UCO PETROLEUM INC.	BROCKVILLE CO-OP PARK STREET BROCKVILLE DEPOT PARK STREET	BROCKVILLE CITY ON	
SPL	MCCOLL-FRONTENAC (TEXACO)	ESSO PETROLEUM SERVICE STATION	BELLEVILLE CITY ON	
SPL	REYNOLDS CENTRAL FUELS	IN THE VILLAGE OF LYN AT THE OLD SCHOOLHOUSE FUEL OIL CO.	ELIZABETHTOWN TWP. ON	
SPL	MEYER'S TRANSPORT CO.	MEYER'S TRANSPORT BELLEVILLE YARD TANK TRUCK (CARGO)	BELLEVILLE CITY ON	
SPL	ESSO PETROLEUM CANADA	BULK STATION	BELLEVILLE CITY ON	

SPL	TRANSPORT TRUCK	HWY 401 WESTBOUND, WEST OF BROCKVILLE MOTOR VEHICLE (OPERATING FLUID)	BROCKVILLE CITY ON
SPL	QUEENSWAY TANK LINES	AT UNITED CO-OP'S BULK PLANT ON PARK ST. TANK TRUCK (CARGO)	BROCKVILLE CITY ON
SPL	ONTARIO HYDRO	CENTRE STREET CAPACITOR STATION TRANSFORMER	BELLEVILLE CITY ON
SPL	TRANSPORT TRUCK	PARKDALE RD IN FRONT OF SOMERVILLE FARMS MOTOR VEHICLE (OPERATING FLUID)	BROCKVILLE CITY ON
SPL	ESSO PETROLEUM CANADA	TANK TRUCK (CARGO)	BELLEVILLE CITY ON
SPL	ONTARIO HYDRO	CENTRE STREET BELLEVILLE T.S. PCB STORAGE SITE (TANK)	BELLEVILLE CITY ON
SPL	ESSO PETROLEUM CANADA	BULK STATION	BELLEVILLE CITY ON
SPL	QUEENSWAY TANK LINES	PARK STREET UNITED CO-OP YARD TANK TRUCK (CARGO)	BROCKVILLE CITY ON
SPL	COLLEGE PRO PAINTERS	PARK ST.	BROCKVILLE CITY ON
SPL	TRANSPORT TRUCK	401 AT BELLEVILLE MOTOR VEHICLE (OPERATING FLUID)	BELLEVILLE CITY ON
SPL	TRANSPORT TRUCK	ALONG THE 401 FROM BROCKVILLE TO LONG SAULT MOTOR VEHICLE (OPERATING FLUID)	BROCKVILLE CITY ON
SPL	ESSO PETROLEUM	CANNIFTON TANK TRUCK (CARGO)	BELLEVILLE CITY ON
SPL	ONTARIO HYDRO	TRANSFORMER STATION - CENTRE ST. TRANSFORMER	BELLEVILLE CITY ON
SPL	ONTARIO HYDRO	TRANSFORMER STATION - CENTRE ST. TRANSPORT TRUCK (CARGO)	BELLEVILLE CITY ON
SPL	ONTARIO HYDRO	CENTRE STREET BELLEVILLE TRANSFORMER STATION TRANSFORMER	BELLEVILLE CITY ON
SPL	ULTRAMAR	SERVICE STATION	BELLEVILLE CITY ON
SPL	CANADA TRANSPORT	TRANSPORT TRUCK (CARGO)	BROCKVILLE CITY ON
SPL	IMPERIAL OIL LTD.	BULK STATION/STORAGE DEPOT	BROCKVILLE CITY ON
SPL	IMPERIAL OIL LTD.	BULK STATION/STORAGE DEPOT	BROCKVILLE CITY ON
SPL	Hydro One Networks Inc.		Elizabethtown-Kitley ON
SPL		Hwy 401 - mile marker 698	Brockville ON
SPL	Greenshield Pest Control Inc.	North Augusta Road	Brockville ON

SPL	HK Travel Centres GP Inc.	HWY 401 MAllorytown	Brockville ON
SPL	Neovia<UNOFFICIAL>	Hwy 401 WB, north side at km marker 696	Brockville ON
SPL	Greyhound Canada Transportation ULC		Belleville ON
SPL	Mortrans Transport<UNOFFICIAL>	Hwy 401 Westbound Lanes (mile marker 698)	Brockville ON
SPL	Loblaws<UNOFFICIAL>		Brockville ON
SPL	John Cherry<UNOFFICIAL>	north end of Crocker Cres.	Brockville ON
SPL	Hydro One Inc.	between Parkdale and Walthon	Brockville ON
SPL	7506180 Canada Inc./J&R Logistics<UNOFFICIAL>	401 Eastbound Mile Marker 698	Elizabethtown-Kitley ON
SPL		ST. LAWRENCE RIVER AT PARK STREET <UNOFFICIAL>	Brockville ON
WDS	Brockville Landfill Site		Brockville ON
WWIS		lot 8 con 1	ON
WWIS		lot 6 con 2	ON
WWIS		lot 6 con 1	ON
WWIS		lot 18 con 1	ON
WWIS		lot 8 con 1	ON
WWIS		lot 6 con 2	ON
WWIS		lot 6 con 1	ON
WWIS		lot 18 con 1	ON

Unplottable Report

Site: ***Database:*** CA

Lot 6, Concession 1 Elizabethtown-Kitley ON

Certificate #: 7583-4LZHX4
Application Year: 01
Issue Date: 9/13/01
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: Notice
Client Name: The Corporation of the City of Brockville
Client Address: 1 King Street West, P.O. Box 5000
Client City: Brockville
Client Postal Code: K6V 3P5
Project Description: Extension of approval for trial operation of supplementary chemical feed system to October 1, 2001
Contaminants:
Emission Control:

Site: ***Database:*** CA

Lot 6, Concession 1 Elizabethtown-Kitley ON

Certificate #: 3-1974-88-917
Application Year: 02
Issue Date: 2/25/02
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: Notice
Client Name: The Corporation of the City of Brockville
Client Address: 1 King Street West, P.O. Box 5000
Client City: Brockville
Client Postal Code: K6V 3P5
Project Description: Permanent relocation of the centrate return discharge to the temporary location.
Contaminants:
Emission Control:

Site: ***Database:*** CA

Lot 6, Concession 1 Elizabethtown-Kitley ON

Certificate #: 3-1974-88-917
Application Year: 01
Issue Date: 9/13/01
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: Notice
Client Name: The Corporation of the City of Brockville
Client Address: 1 King Street West, P.O. Box 5000
Client City: Brockville
Client Postal Code: K6V 3P5
Project Description: Relocation of the coagulation injection point to the primary influent channel
Contaminants:
Emission Control:

Site: ***Database:*** CA

Lot 6, Concession 1 Elizabethtown ON

Certificate #: 7583-4LZHX4

Application Year: 00
Issue Date: 7/7/00
Approval Type: Municipal & Private sewage
Status: Amended
Application Type: New Certificate of Approval
Client Name: Corporation Of The City Of Brockville
Client Address: One King Street West, P.O. Box 5000
Client City: Brockville
Client Postal Code: K6V 7A5
Project Description: This is an application for a pilot plant study at Brockville WPCP. The study would involve chemical feed trials to enhance removal of phosphorus and suspended solids in the plant effluent.
Contaminants:
Emission Control:

Site: ***IMPERIAL OIL LIMITED***
BELLEVILLE BULK TERMINAL BELLEVILLE ON

Database: CA

Certificate #: 4-0050-96-
Application Year: 96
Issue Date: //
Approval Type: Industrial wastewater
Status: RE1
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: GROUNDWATER TREATMENT SYSTEM, ADD. TWO
Contaminants:
Emission Control:

Site: ***ROLLINS CONSTRUCTION LTD.***
PARK VILLAS PROPERTY N.PARK ST BELLEVILLE CITY ON

Database: CA

Certificate #: 7-0234-86-
Application Year: 86
Issue Date: 5/2/1986
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***P.U.C. BROCKVILLE CITY***
FIRST AVE. BROCKVILLE CITY ON

Database: CA

Certificate #: 7-0276-87-
Application Year: 87
Issue Date: 5/26/1987
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BROCKVILLE CITY***
STEWART BOULEVARD BROCKVILLE CITY ON

Database: CA

Certificate #: 7-0829-88-
Application Year: 88
Issue Date: 11/9/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BROCKVILLE CITY***
CENTRE STREET BROCKVILLE CITY ON

Database: CA

Certificate #: 3-1962-88-
Application Year: 88
Issue Date: 12/28/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***ESSO PETROLEUM CANADA***
P.O. BOX 248 BELLEVILLE CITY ON

Database: CA

Certificate #: 4-0009-90-
Application Year: 90
Issue Date: 3/5/1990
Approval Type: Industrial wastewater
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: OIL/WATER SEPARATOR
Contaminants: Grease & Oil (Dissolved Or Suspended), Dissolved And/Or Suspended Solids, Ph
Emission Control: Gravity Oil Separation

Site: ***ERNEST H. HARPER***
ORMOND PLACE BROCKVILLE CITY ON

Database: CA

Certificate #: 7-0844-87-
Application Year: 87
Issue Date: 7/18/1987
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:

Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***CITY OF BROCKVILLE***
PARK STREET BROCKVILLE CITY ON

Database: ***CA***

Certificate #: 7-1301-90-
Application Year: 90
Issue Date: 11/15/1990
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***P.U.C. BROCKVILLE - ORMOND STREET***
PARKDALE AVE/ORMOND/PERTH STS. BROCKVILLE CITY ON

Database: ***CA***

Certificate #: 7-0314-90-
Application Year: 90
Issue Date: 4/26/1990
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***P.U.C. BROCKVILLE CITY***
FIRST AVE. BROCKVILLE CITY ON

Database: ***CA***

Certificate #: 7-0388-88-
Application Year: 88
Issue Date: 6/6/1988
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***HIGHLAND GOLF LTD. - PT. LOT 14, CONC. 1***
PARKEDALE AVE./STM-WATER DET. BROCKVILLE CITY ON

Database: ***CA***

Certificate #: 3-0400-92-

Application Year: 92
Issue Date: 10/2/1992
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BROCKVILLE CITY***
CALIFORNIA AVE. BROCKVILLE CITY ON

Database: ***CA***

Certificate #: 3-0735-89-
Application Year: 89
Issue Date: 6/15/1989
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BROCKVILLE CITY***
STEWART BOULEVARD BROCKVILLE CITY ON

Database: ***CA***

Certificate #: 3-0962-88-
Application Year: 88
Issue Date: 11/8/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BROCKVILLE CITY***
CENTRE STREET BROCKVILLE CITY ON

Database: ***CA***

Certificate #: 3-1185-88-
Application Year: 88
Issue Date: 8/19/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: BROCKVILLE CITY
FIRST AVE. BROCKVILLE CITY ON

Database: CA

Certificate #: 3-0331-87-
Application Year: 87
Issue Date: 5/26/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ERNEST H. HARPER
EASEMENT N. OF ORMOND PLACE BROCKVILLE CITY ON

Database: CA

Certificate #: 3-1003-87-
Application Year: 87
Issue Date: 7/18/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: BROOKVILLE CITY
EASEMENT N. OF ORMOND PLACE BROCKVILLE CITY ON

Database: CA

Certificate #: 3-1004-87-
Application Year: 87
Issue Date: 7/18/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: Imperial Oil Limited
Designated as Part 1 on Reference Plan 21R-16968 Belleville ON

Database: CA

Certificate #: 4291-8JAPY9
Application Year: 2011
Issue Date: 10/26/2011
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:

Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: Brockville Centre Development Corp.
Centre St Brockville ON

Database: CA

Certificate #: 9304-8EBHE7
Application Year: 2011
Issue Date: 2/28/2011
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: Brockville McDowel Ltd.
Centre Street Brockville ON

Database: CA

Certificate #: 8546-5Y4QNN
Application Year: 2004
Issue Date: 4/23/2004
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: Abbott Laboratories, Limited
North Augusta Rd Brockville ON

Database: CA

Certificate #: 7811-7TLK7U
Application Year: 2009
Issue Date: 7/6/2009
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: Imperial Oil Limited
Belleville ON

Database: CA

Certificate #: 6516-7NCRAT
Application Year: 2009

Issue Date: 2/9/2009
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: **Homesite Developments Ltd.**
Centre Street Belleville ON

Database: CA

Certificate #: 5751-5W5PPQ
Application Year: 2004
Issue Date: 2/13/2004
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: **Black & Decker Canada (1989) Inc.**
Part Lots 8, 9, 11-17, RP #4, Part Lot 14, Conc. 1 Brockville ON

Database: CA

Certificate #: 3138-5G9KWB
Application Year: 2003
Issue Date: 1/25/2003
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: **Imperial Oil Limited**
Designated as Part 1 on Reference Plan 21R-16968 Belleville ON

Database: CA

Certificate #: 1991-82BRC5
Application Year: 2010
Issue Date: 2/5/2010
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: **P.U.C.**
ORMOND ST. BROCKVILLE ON

Database: CA

Certificate #: 7-0238-85-006
Application Year: 85
Issue Date: 5/17/85
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: **ROLLINS CONSTRUCTION LTD.**
LT.12,E.OF N.PARK ST BELLEVILLE ON

Database: CA

Certificate #: 8-4025-85-006
Application Year: 85
Issue Date: 8/14/85
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants: Nitrogen Oxides
Emission Control: No Controls

Site:
Waverly Drive Brockville ON

Database: CA

Certificate #: 7287-5ETPJ5
Application Year: 02
Issue Date: 10/11/02
Approval Type: Municipal & Private water
Status: Approved
Application Type: New Certificate of Approval
Client Name: The Corporation of the City of Brockville
Client Address: 1 King Street West, P.O. Box 5000
Client City: Brockville
Client Postal Code: K6V 3P5
Project Description: Approval is sought for the construction (relining) of watermains on Waverly Drive.
Contaminants:
Emission Control:

Site:
Part of lot 9, Concession 2 Brockville ON

Database: CA

Certificate #: 8330-4UYQPW
Application Year: 01
Issue Date: 3/29/01
Approval Type: Industrial air
Status: Approved
Application Type: Amended CofA
Client Name: Selkirk Inc.
Client Address: 1400 California Avenue
Client City: Brockville

Client Postal Code: K6V 5V3
Project Description: This application is to amend the current Air Certificate of Approval to the following additions and modifications: Stack 1- One (1) 91 cm exhaust fan discharging to the atmosphere to ventilate a welding fume control system; an odour control system for two paint touch up areas; and odour and combustion flue gas control system for a Quality Control Lab; a heat control system for a paint drying oven; Stack 2- One (1) exhaust fan discharging to the atmosphere to ventilate a spray booth; Stack 3 and 4- Exhaust fans discharging to the atmosphere to ventilate steam from a metal degreasing system; Stack 5- Type B vent to exhaust combustion gases from a natural gas heater for a metal degreasing system and Stack 6- Type B vent to exhaust combustion gases from a natural gas heater for a paint-drying oven.
Contaminants:
Emission Control:

Site: *Part of lot 9, Concession 2 Brockville ON*
Database: CA

Certificate #: 8-400-005-81-006
Application Year: 01
Issue Date: 4/18/01
Approval Type: Industrial air
Status: Approved
Application Type: Revocation
Client Name: Selkirk Inc.
Client Address: 1400 California Avenue
Client City: Brockville
Client Postal Code: K6V 5V3
Project Description: The proponent, Selkirk Canada, is requesting to revoke their Certificate of Approval # 8-400-005-81-006 for two natural gas-fired Dravo Counter Flow # 85 heating units. These heating units are no longer in use. One unit has been completely removed and the other unit has the burner assembly removed. There is no intention of ever using this equipment.
Contaminants:
Emission Control:

Site: *Lot 6, Concession 1 Elizabethtown ON*
Database: CA

Certificate #: 3-1974-88-917
Application Year: 01
Issue Date: 1/12/01
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: Notice
Client Name: Corporation of the City of Brockville
Client Address: One King Street West, P.O. Box 5000
Client City: Brockville
Client Postal Code: K6V 7A5
Project Description: This application is for a trial diversion of the centrifuge supernatant to a temporary return line leading to the head of the plant, upstream of the main coagulant injection point.
Contaminants:
Emission Control:

Site: *Lot 6, Concession 1 Elizabethtown ON*
Database: CA

Certificate #:
Application Year: 00
Issue Date: 7/7/00
Approval Type: Municipal & Private water
Status: Returned
Application Type: New Certificate of Approval
Client Name: Corporation Of The City Of Brockville
Client Address: One King Street West, P.O. Box 5000
Client City: Brockville
Client Postal Code: K6V 7A5
Project Description:

Contaminants:
Emission Control:

Site: *Lot 6, Concession 1 Elizabethtown ON*
Database: CA

Certificate #:
Application Year: 00
Issue Date: 7/6/00
Approval Type: Municipal & Private water
Status: Cancelled
Application Type: New Certificate of Approval
Client Name: Corporation of the City of Brockville
Client Address: One King Street West, P.O. Box 5000
Client City: Brockville
Client Postal Code: K6V 7A5
Project Description: This is an application for a pilot plant study at Brockville WPCP. The study would involve chemical feed trials to enhance removal of phosphorus and suspended solids in the plant effluent.
Contaminants:
Emission Control:

Site: *Pt. of Lots 16 & 17, Conc. II , Parkdale Ave. Brockville ON*
Database: CA

Certificate #: 2811-4JHPEB
Application Year: 00
Issue Date: 11/24/00
Approval Type: Industrial air
Status: Revoked and/or Replaced
Application Type: New Certificate of Approval
Client Name: Corporation of the City of Brockville
Client Address: One King Street West, P.O. Box 5000
Client City: Brockville
Client Postal Code: K6V 7A5
Project Description: The City of Brockville proposes to install and operate a temporary landfill gas collection and flaring system for odour control purposes at the Brockville municipal landfill. The system will also be used for testing purposes to determine the gas pumping rates and gas reserves for a possible landfill gas collection and utilization system at the site.
Contaminants:
Emission Control:

Site: *Pt. of Lots 16 & 17, Conc. II , Parkdale Ave. Brockville ON*
Database: CA

Certificate #: 5128-4RDRZG
Application Year: 02
Issue Date: 5/14/02
Approval Type: Industrial air
Status: Revoked and/or Replaced
Application Type: Amended CofA
Client Name: Corporation of the City of Brockville
Client Address: One King Street West, P.O. Box 5000
Client City: Brockville
Client Postal Code: K6V 7A5
Project Description: The city is currently operating a temporary landfill gas collection and flaring system for odour control purposes at the Brockville Municipal Landfill. The flare is currently combusting approximately 0.095 cubic metres per second of landfill gas collected from a total of nine wells installed in the waste. The wellfield is being expanded to a total of approximately 20 wells in order to address residual odours resulting from the emission of landfill gas from the waste. It is proposed to increase the flow rate collected from the wellfield and discharged from the flare up to a maximum of 0.23 cubic metres per second at between 40 and 50 % methane by volume.
Contaminants:
Emission Control:

Site: *The Corporation of the City of Brockville*
Stewart Boulevard Brockville ON

Database: CA

Certificate #: 0874-5ZDGBL
Application Year: 2004
Issue Date: 5/28/2004
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: *1427255 Ontario Inc.*
Part of Lot 9, Concession 2 Brockville ON

Database: CA

Certificate #: 2404-4RHQ8P
Application Year: 2000
Issue Date: 12/1/2000
Approval Type: Waste Management Systems
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: *IMPERIAL OIL LIMITED*
DON MILLS ON

Database: CONV

File No:
Crown Brief No:
Court Location:
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description: FAILED TO COMPLY WITH CONDITIONS OF C. OF A.
Background:
URL:

Location:
Region: EASTERN REGION
Ministry District:

Additional Details

Publication Date:
Count: 1
Act: OWRA
Regulation:
Section: 66(3)
Act/Regulation/Section: OWRA- -66(3)
Date of Offence:
Date of Conviction:
Date Charged: 6/4/93
Charge Disposition:

Fine: $6,000
Synopsis:

Site: *IMPERIAL OIL LIMITED*
NORTH YORK ON

Database: CONV

File No:
Crown Brief No:
Court Location:
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description: FAILED TO INSPECT OIL/WATER SEPARATOR WEEKLY & MAINTAIN LOG BOOK AT SITE
Background:
URL:

Location:
Region: EASTERN REGION
Ministry District:

Additional Details

Publication Date:
Count: 1
Act: OWRA
Regulation:
Section: 66(3)
Act/Regulation/Section: OWRA- -66(3)
Date of Offence:
Date of Conviction:
Date Charged: 6/4/93
Charge Disposition:
Fine: $4,000
Synopsis:

Additional Details

Publication Date:
Count: 1
Act: OWRA
Regulation:
Section: 66(3)
Act/Regulation/Section: OWRA- -66(3)
Date of Offence:
Date of Conviction:
Date Charged: 6/4/93
Charge Disposition:
Fine: $1,000
Synopsis:

Site: *MEYERS TRANSPORT LIMITED*
ON

Database: CONV

File No:
Crown Brief No: 98-0000-9004
Court Location:
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:

Location:
Region: EASTERN REGION
Ministry District:

Penalty Imposed:
Description: THIS IS THE EASTERN BRIEF FOR ALL P.O.A. TICKETS
Background:
URL:

Additional Details

Publication Date:
Count: 1
Act: EPA
Regulation:
Section: 186(3)
Act/Regulation/Section: EPA- -186(3)
Date of Offence:
Date of Conviction:
Date Charged: 1/28/02
Charge Disposition: SUSPENDED SENTENCE
Fine: $305.00
Synopsis:

Site: ***L.A. KNAPP INC.***
ON

Database: ***CONV***

File No:
Location:
Crown Brief No: 98-0000-9004
Region: EASTERN REGION
Court Location:
Ministry District:
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description: THIS IS THE EASTERN BRIEF FOR ALL P.O.A. TICKETS
Background:
URL:

Additional Details

Publication Date:
Count: 1
Act: EPA
Regulation:
Section: 40
Act/Regulation/Section: EPA- -40
Date of Offence:
Date of Conviction:
Date Charged: 9/20/01
Charge Disposition: SUSPENDED SENTENCE
Fine: $305.00
Synopsis:

Site: ***Motor Coils Mfg. Ltd.***
City of Brockville ON

Database: ***EBR***

EBR Registry No: IA7E1508.D
Decision Posted:
Ministry Ref No:
Exception Posted:
Notice Type: Instrument
Section:
Notice Stage:
Act 1:
Notice Date:
Act 2:
Proposal Date: 10/6/97
Site Location Map:
Year: 1997
Instrument Type: EPA s. 9 - Approval for discharge into natural environ. (air)
Off Instrument Name:

Posted By:
Company Name:
Site Address:
Location Other:
Proponent Name:
Proponent Address: Motor Coils Mfg. Ltd.,1879 Parkedale Avenue,Brockvill, Ontario,K6V 5T2
Comment Period:
URL:

Site Location Details:

City of Brockville

Site: ***Imperial Oil Limited, Contact Mr. Chris Atkins***
Highway 401 Eastbound @ Mallorytown Mallorytown Ontario CITY OF BROCKVILLE ON

Database: ***EBR***

EBR Registry No: IT06E0001
Decision Posted:
Ministry Ref No: 2005-000279
Exception Posted:
Notice Type: Instrument Decision
Section:
Notice Stage: 803004938
Act 1:
Notice Date: February 17, 2006
Act 2:
Proposal Date: January 16, 2006
Site Location Map:
Year: 2006
Instrument Type:
Off Instrument Name:
Posted By:
Company Name: Imperial Oil Limited, Contact Mr. Chris Atkins
Site Address:
Location Other:
Proponent Name:
Proponent Address: 20-255 Dundas Street East , #504, Waterdown Ontario, L0R 2H6
Comment Period:
URL:

Site Location Details:

Highway 401 Eastbound @ Mallorytown Mallorytown Ontario CITY OF BROCKVILLE

Site: ***Selkirk Inc.***
Part of lot 9, Concession 2 Brockville Ontario CITY OF BROCKVILLE ON

Database: ***EBR***

EBR Registry No: IA01E0135
Decision Posted:
Ministry Ref No: 5636-4TBLJN
Exception Posted:
Notice Type: Instrument Decision
Section:
Notice Stage: 800478555
Act 1:
Notice Date: April 02, 2001
Act 2:
Proposal Date: January 25, 2001
Site Location Map:
Year: 2001
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Selkirk Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 1400 California Avenue, Brockville Ontario, K6V 5V3
Comment Period:
URL:

Site Location Details:

Part of lot 9, Concession 2 Brockville Ontario CITY OF BROCKVILLE

Site: ***1427255 Ontario Inc.***
John G. Broome Industrial Park, City of Brockville Part of Lot 9, Concession 2. CITY OF BROCKVILLE ON

Database: EBR

EBR Registry No:	IA00E1609	***Decision Posted:***	
Ministry Ref No:	3161-4PKRRM	***Exception Posted:***	
Notice Type:	Instrument Decision	***Section:***	
Notice Stage:	800477949	***Act 1:***	
Notice Date:	January 18, 2001	***Act 2:***	
Proposal Date:	October 12, 2000	***Site Location Map:***	
Year:	2000		
Instrument Type:	(EPA s. 27) - Approval for a waste disposal site.		
Off Instrument Name:			
Posted By:			
Company Name:	1427255 Ontario Inc.		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	3354 Navan Road, Gloucester Ontario, K4B 1H9		
Comment Period:			
URL:			

Site Location Details:

John G. Broome Industrial Park, City of Brockville Part of Lot 9, Concession 2. CITY OF BROCKVILLE

Site: ***Black & Decker Canada (1989) Inc.***
Part Lots 8, 9, 11-17, RP #4, Part Lot 14, Conc. 1 Brockville Ontario CITY OF BROCKVILLE ON

Database: EBR

EBR Registry No:	IA02E0728	***Decision Posted:***	
Ministry Ref No:	5477-5BHR6C	***Exception Posted:***	
Notice Type:	Instrument Decision	***Section:***	
Notice Stage:	800720875	***Act 1:***	
Notice Date:	April 25, 2003	***Act 2:***	
Proposal Date:	July 04, 2002	***Site Location Map:***	
Year:	2002		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Off Instrument Name:			
Posted By:			
Company Name:	Black & Decker Canada (1989) Inc.		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	100 Central Avenue, Brockville Ontario, K6V 5W6		
Comment Period:			
URL:			

Site Location Details:

Part Lots 8, 9, 11-17, RP #4, Part Lot 14, Conc. 1 Brockville Ontario CITY OF BROCKVILLE

Site: ***Imperial Oil Limited, Contact Mr. Chris Atkins***
Highway 401 Eastbound @ Mallorytown Mallorytown Ontario CITY OF BROCKVILLE ON

Database: EBR

EBR Registry No:	IT06E0002	***Decision Posted:***	
Ministry Ref No:	2005-000280	***Exception Posted:***	
Notice Type:	Instrument Decision	***Section:***	
Notice Stage:	803004939	***Act 1:***	
Notice Date:	February 17, 2006	***Act 2:***	
Proposal Date:	January 16, 2006	***Site Location Map:***	
Year:	2006		
Instrument Type:			
Off Instrument Name:			
Posted By:			
Company Name:	Imperial Oil Limited, Contact Mr. Chris Atkins		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	20-255 Dundas Street East , #504, Waterdown Ontario, L0R 2H6		
Comment Period:			
URL:			

Site Location Details:

Highway 401 Eastbound @ Mallorytown Mallorytown Ontario CITY OF BROCKVILLE

Site: ***Procter & Gamble Inc.***
Lot 8, COncession 2 CITY OF BROCKVILLE ON

Database: EBR

EBR Registry No:	IA9E1128	***Decision Posted:***	
Ministry Ref No:	8401194992RE1	***Exception Posted:***	
Notice Type:	Instrument Decision	***Section:***	
Notice Stage:	800475753	***Act 1:***	
Notice Date:	February 22, 2000	***Act 2:***	
Proposal Date:	September 22, 1999	***Site Location Map:***	
Year:	1999		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Off Instrument Name:			
Posted By:			
Company Name:	Procter & Gamble Inc.		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	Brockville Division, 1475 California Ave., Brockville Ontario, K6V 6K4		
Comment Period:			
URL:			

Site Location Details:

Lot 8, COncession 2 CITY OF BROCKVILLE

Site: ***Brockmoor Developments Corporation Limited and 2159203 Ontario Ltd.***
Stewart Blvd Con 2, Lot 15 Elizabethtown Brockville ON K6V 3P7

Database: ECA

Approval No:	3459-ANLJAK	***MOE District:***	
Approval Date:	2017-07-05	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Address:	Stewart Blvd Con 2, Lot 15 Elizabethtown		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/5925-ANCQJB-14.pdf		

Site: ***The Corporation of the City of Brockville***
Centre St (30-80 m north of Brock Street) Brockville ON K6V 7A5

Database: ECA

Approval No:	8940-ANJGRY	***MOE District:***	
Approval Date:	2017-06-29	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: Centre St (30-80 m north of Brock Street)
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/4287-ANGNSC-14.pdf

---

Site: ***Homesite Developments Ltd.***
Centre St Belleville ON K8N 2Z2

Database: ECA

Approval No: 2002-5W5PLP
Approval Date: 2004-02-13
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Address: Centre St
Full Address:
Full PDF Link:

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***Donna Lisa Bain***
Parkdale Avenue West Brockville ON K6V 3G6

Database: ECA

Approval No: 0809-667K48
Approval Date: 2004-11-03
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Address: Parkdale Avenue West
Full Address:
Full PDF Link:

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***The Corporation of the City of Brockville***
Lot 6, Concession 1 Elizabethtown-Kitley ON K6V 5V1

Database: ECA

Approval No: 3-1974-88-917
Approval Date: 2001-09-13
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: Lot 6, Concession 1
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7561-4ZET4W-14.pdf

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***Black & Decker Canada (1989) Inc.***
Part Lots 8, 9, 11-17, RP #4, Part Lot 14, Conc. 1 Brockville ON K6V 5W6

Database: ECA

Approval No: 3138-5G9KWB
Approval Date: 2003-01-25
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-AIR
Project Type: AIR

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Address: Part Lots 8, 9, 11-17, RP #4, Part Lot 14, Conc. 1
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5477-5BHR6C-14.pdf

---

Site: ***Homesite Developments Ltd.***
Centre St Belleville ON K8N 2Z2

Database: ECA

Approval No: 5751-5W5PPQ
Approval Date: 2004-02-13
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: Centre St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8100-5UGN2D-14.pdf

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***The Corporation of the City of Brockville***
Lot 6, Concession 1 Elizabethtown-Kitley ON K6V 5V1

Database: ECA

Approval No: 7583-4LZHX4
Approval Date: 2001-09-13
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: Lot 6, Concession 1
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2586-4ZSPVC-14.pdf

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***The Corporation of the City of Brockville***
Lot 6, Concession 1 Elizabethtown-Kitley ON K6V 5V1

Database: ECA

Approval No: 3-1974-88-917
Approval Date: 2002-02-25
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: Lot 6, Concession 1
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7133-55XP9N-14.pdf

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***The Corporation of the City of Brockville***
Centre Street Brockville ON K6V 7A5

Database: ECA

Approval No: 5750-9YHNHF
Approval Date: 2015-07-21
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: Centre Street
Full Address:

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6731-9YDNDY-14.pdf

---

Site: *The Corporation of the City of Brockville*
Stewart Boulevard Brockville ON K6V 5V1

Database: ECA

Approval No: 0874-5ZDGBL
Approval Date: 2004-05-28
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: Stewart Boulevard
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9705-5XSRML-14.pdf

---

Site: *REYNOLDS CENTRAL FUELS*
ADDRESS NOT SPECIFIED BROCKVILLE ON

Database: EXP

Instance No: 10449797
Instance ID: 17814
Instance Type: FS Highway Tank - Gas/Diesel
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

Site: *REYNOLDS CENTRAL FUELS*
ADDRESS NOT SPECIFIED BROCKVILLE ON

Database: EXP

Instance No: 10449788
Instance ID: 17766
Instance Type: FS Highway Tank - Gas/Diesel
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

Site: *REYNOLDS CENTRAL FUELS*
ADDRESS NOT SPECIFIED BROCKVILLE ON

Database: EXP

Instance No: 10449783
Instance ID: 17642
Instance Type: FS Highway Tank - Gas/Diesel
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

Site: *BROCKVILLE PUBLIC UTILITIES COMMISSION*
PARKEDALE AVHENRY LITTLE RESERVO BROCKVILLE ON K6V 5R9

Database: EXP

Instance No: 10545567
Instance ID:

Instance Type: FS Liquid Fuel Tank
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 1/23/1991

Site: *REYNOLDS CENTRAL FUELS*
ADDRESS NOT SPECIFIED BROCKVILLE ON

Database: EXP

Instance No: 10449793
Instance ID: 17471
Instance Type: FS Highway Tank - Gas/Diesel
Description: FS HIGHWAY TANK - GASOLINE/DIESEL
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

Site: *INTERLINK FREIGHT SYSTEMS INC*
PARKEDALE AV BROCKVILLE ON K7S 3H4

Database: EXP

Instance No: 9553366
Instance ID:
Instance Type: FS Facility
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 3/17/1993

Site: *BROCKVILLE PUBLIC UTILITIES COMMISSION*
PARKEDALE AV HENRY LITTLE RESERVO BROCKVILLE ON

Database: FSTH

License Issue Date: 1/22/1991
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1974
Corrosion Protection:
Capacity: 2273
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Site: *BROCKVILLE PUBLIC UTILITIES COMMISSION*
PARKEDALE AV HENRY LITTLE RESERVO BROCKVILLE ON

Database: FSTH

License Issue Date: 1/22/1991
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active

Year of Installation: 1974
Corrosion Protection:
Capacity: 2273
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Site: ***MINISTRY OF NATURAL (OUT OF BUSINESS)***
DISTRICT OFFICE LOT 6, CONCESSION 1 ELIZABETHTOWN TOWNSHIP ON

Database: GEN

Generator No: ON0124151
Status:
Approval Years: 98
Contam. Facility:
MHSW Facility:
SIC Code: 8272
SIC Description: RES. CONS./IND. DEV.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Site: ***UPI ENERGY LP***
PLAN 67, BLOCK 22 PART LOT 7, PARK STREET BROCKVILLE ON K6V 5V5

Database: GEN

Generator No: ON1446912
Status:
Approval Years: 04
Contam. Facility:
MHSW Facility:
SIC Code: 412110
SIC Description: Petroleum Product Wholesaler-Distributors

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Site: ***BROCKVILLE COUNTRY CLUB***
GOLF COURSE WORKSHOP LOT 18 & 19, CONCESSION 1 BROCKVILLE ON

Database: GEN

Generator No: ON1992500
Status:
Approval Years: 99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 9651
SIC Description: GOLF COURSES

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252

Waste Class Desc: WASTE OILS & LUBRICANTS

Site: ***UPI INC.***
PLAN 67, BLOCK 22 PART LOT 7, PARK STREET BROCKVILLE ON K6V 5V5

Database: GEN

Generator No: ON1446912
Status:
Approval Years: 99,00,01,02,03
Contam. Facility:
MHSW Facility:
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Site: ***UCO PETROLEUM INC. 39-180***
PARK ST.,PLAN67,BLOCK 22, PTLOT 7 BROCKVILLE,C/O5600 CANCROSS CT,BOX7030 MISSISSAUGA ON L5B 2N6

Database: GEN

Generator No: ON1446912
Status:
Approval Years: 94,95
Contam. Facility:
MHSW Facility:
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Site: ***UPI INC. 39-180***
PARK ST., PLAN 67, BLOCK 22, PT.LOT 7 BROCKVILLE ON K6V 5V5

Database: GEN

Generator No: ON1446912
Status:
Approval Years: 92,93,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Site: ***ONTARIO HYDRO 29-107***
BELLEVILLE TS CENTRE STREET BELLEVILLE ON K8N 4W7

Database: GEN

Generator No: ON0490316
Status:
Approval Years: 94,95
Contam. Facility:
MHSW Facility:
SIC Code: 4911
SIC Description: ELECT. POWER SYS.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Site: ***ONTARIO HYDRO***
BELLEVILLE TS CENTRE STREET BELLEVILLE ON K8N 4W7

Database: GEN

Generator No: ON0490316
Status:
Approval Years: 86,87,88,89
Contam. Facility:
MHSW Facility:
SIC Code: 4911
SIC Description: ELECT. POWER SYS.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Site: ***PUROLATOR COURIER LTD (OUT OF BUSINESS)***
HWY 29, NORTH GATE PLAZA BAY 5 BROCKVILLE ON K0E 1T0

Database: GEN

Generator No: ON0223841
Status:
Approval Years: 98
Contam. Facility:
MHSW Facility:
SIC Code: 4842
SIC Description: COURIER SERV. IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Site: ***PUROLATOR COURIER LTD.***
HWY 29, NORTH GATE PLAZA, BAY 5 BROCKVILLE ON K0E 1T0

Database: GEN

Generator No: ON0223841
Status:

PO Box No:
Country:

Approval Years: 90
Contam. Facility:
MHSW Facility:
SIC Code: 4842
SIC Description: COURIER SERV. IND.

Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Site: ***UNITED CO-OPERATIVES (SEE&USE ON1446912)***
PARK STREET PLAN #67 BLOCK 22, PART LOT 7 BROCKVILLE ON

Database: GEN

Generator No: ON0178420
Status:
Approval Years: 98
Contam. Facility:
MHSW Facility:
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Site: ***UNITED CO(SEE&USE ON1446912) 39-180***
PARK ST. PLAN NO.67 BLOCK 22 PT.LOT 7 C/O GEORGE ST. NORTH BROCKVILLE ON K6V 5V5

Database: GEN

Generator No: ON0178420
Status:
Approval Years: 92,93,94,95,96,97
Contam. Facility:
MHSW Facility:
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Site: ***UNITED CO-OPERATIVES OF ONTARIO***
PARK ST. PLAN NO.67 BLOCK 22 PT.LOT 7 C/O GEORGE ST. NORTH BROCKVILLE ON K6V 5V5

Database: GEN

Generator No: ON0178420
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Site: ***UPI ENERGY LP***
PLAN 67, BLOCK 22 PART LOT 7, PARK STREET BROCKVILLE ON K6V 5V5

Database: GEN

Generator No: ON1446912
Status:
Approval Years: 05
Contam. Facility:

PO Box No:
Country:
Choice of Contact:
Co Admin:

MHSW Facility: **Phone No Admin:**
SIC Code: 412110
SIC Description: Petroleum Product Wholesaler-Distributors

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Site: ***MINISTRY (SEE & USE ON0124151)*** ***Database:*** ***GEN***
OXFORD AVE. BROCKVILLE ON K6V 5Y8

Generator No: ON0001536 **PO Box No:**
Status: **Country:**
Approval Years: 93,94,95,96,97,98 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No Admin:**
SIC Code: 8273
SIC Description: ENVIRON. ADMIN.

Detail(s)

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Site: ***CANADIAN PACIFIC EXPRESS & TRANSPORT LTD*** ***Database:*** ***PRT***
PARKDALE AV BROCKVILLE ON

Location ID: 2254
Type: retail
Expiry Date: 1993-07-31
Capacity (L): 0
Licence #: 0022692001

Site: ***KI GAS FOOD AND VARIETY SIDDIQUI AFZAL*** ***Database:*** ***PRT***
LOT 16 CON 1 BELLEVILLE ON

Location ID: 1546
Type: retail
Expiry Date: 1995-08-31
Capacity (L): 1300
Licence #: 0033692001

Site: ***BROCKVILLE PUBLIC UTILITIES COMMISSION*** ***Database:*** ***PRT***
PARKDALE AV HENRY LITTLE RESERVO BROCKVILLE ON

Location ID: 1124
Type: private
Expiry Date:
Capacity (L): 2273.00
Licence #: 0001034603

Site: ***ULTRAMAR*** ***Database:*** ***RST***
BELLEVILLE ON

Headcode: 00924800
Headcode Desc: FUEL OIL
Phone: 6139624504
List Name:
Description:

Site: ***SANDS MEDICAL*** ***Database:*** ***SCT***
BROCKVILLE ON K6V 6K8

Established: 1987
Plant Size (ft²): 2500
Employment: 8

--Details--
Description: MEN'S AND BOYS' WORK CLOTHING
SIC/NAICS Code: 2326

Description: APPAREL AND ACCESSORIES, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2389

Description: SURGICAL AND MEDICAL INSTRUMENTS AND APPARATUS
SIC/NAICS Code: 3841

Description: MEDICAL, DENTAL, AND HOSPITAL EQUIPMENT AND SUPPLIES
SIC/NAICS Code: 5047

Site: ***The Corporation of the City of Brockville*** ***Database:*** ***SPL***
Brockville Water Pollution Control Center, Lot 6, Concession 1, Elizabethtown Elizabethtown-Kitley ON

Ref No: 0061-85UKRY **Discharger Report:**
Site No: **Material Group:**
Incident Dt: **Health/Env Conseq:**
Year: **Client Type:**
Incident Cause: **Sector Type:**
Incident Event: **Agency Involved:**
Contaminant Code: 35 **Nearest Watercourse:**
Contaminant Name: METHANE GAS **Site Address:**
Contaminant Limit 1: **Site District Office:**
Contam Limit Freq 1: **Site Postal Code:**
Contaminant UN No 1: **Site Region:**
Environment Impact: Confirmed **Site Municipality:**
Nature of Impact: **Site Lot:**
Receiving Medium: **Site Conc:**
Receiving Env: **Northing:** NA
MOE Response: **Easting:** NA
Dt MOE Arvl on Scn: **Site Geo Ref Accu:**
MOE Reported Dt: 5/27/2010 **Site Map Datum:**
Dt Document Closed: 5/28/2010 **SAC Action Class:** Watercourse Spills
Incident Reason: **Source Type:**
Site Name: Brockville Water Pollution Control Center, Lot 6, Concession 1, Elizabethtown
Site County/District:
Site Geo Ref Meth:
Incident Summary: Brockville WPCP: methane release and no Cl2 to effluent
Contaminant Qty:

Site: ***S 21(1)(f) of FIPPA*** ***Database:*** ***SPL***
Ormond Street, north of 401 Brockville ON

Ref No: 3071-7X8NNS **Discharger Report:**
Site No: **Material Group:**
Incident Dt: **Health/Env Conseq:**
Year: **Client Type:**
Incident Cause: Discharge Or Bypass To A Watercourse **Sector Type:** Other

Incident Event:		***Agency Involved:***	
Contaminant Code:	98	***Nearest Watercourse:***	
Contaminant Name:	UNKNOWN	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	Confirmed	***Site Municipality:***	
Nature of Impact:	Surface Water Pollution	***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:	Planned Field Response	***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	10/27/2009	***Site Map Datum:***	
Dt Document Closed:	1/12/2010	***SAC Action Class:***	Watercourse Spills
Incident Reason:	Unknown - Reason not determined	***Source Type:***	
Site Name:	location<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Brockville: red substance in Buells Crk, investigating.		
Contaminant Qty:			

Site: ***ULTRAMAR CANADA INC.***
CONCESSION 1 FUEL TRANSFER DEPOT AUGUSTA ON

Database: ***SPL***

Ref No:	190483	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	10/10/2000	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	UNKNOWN	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	56601
Nature of Impact:	Soil contamination	***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	10/10/2000	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	UNKNOWN	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	BACKENTRY:ULTRAMAR:LIKELY OFF-PROPERTY CONTAMINATION OF HYDROCARBONS.		
Contaminant Qty:			

Site: ***TRANSPORT TRUCK***
HWY 401, NEAR BELLEVILLE MOTOR VEHICLE (OPERATING FLUID) BELLEVILLE CITY ON

Database: ***SPL***

Ref No:	180578	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	5/10/2000	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	51103
Nature of Impact:		***Site Lot:***	

Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	BELLEVILLE F/D
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	5/10/2000	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	ERROR	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	DUMP TRUCK-91 L DIESEL & MV FLUIDS TO HWY 401.F/D.		
Contaminant Qty:			

Site: ***ESSO PETROLEUM CANADA***
BULK STATION BELLEVILLE CITY ON

Database: ***SPL***

Ref No:	152440	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/15/1998	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	51103
Nature of Impact:	Other	***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	TSSA
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2/15/1998	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	EQUIPMENT FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO PETROLEUM BULK PLANT- 300 L OF FURNACE OIL TO PAVEMENT.		
Contaminant Qty:			

Site: ***QUEENSWAY TANK LINES***
ESSO BULK FARM TANK TRUCK (CARGO) BROCKVILLE CITY ON

Database: ***SPL***

Ref No:	125124	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	4/18/1996	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PIPE/HOSE LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	56101
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	4/18/1996	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	ERROR	***Source Type:***	
Site Name:			

Site County/District:
Site Geo Ref Meth:
Incident Summary: QUEENSWAY TANKLINES-10 L DIESEL TO CONCRETE PAD ATESSO BULK FARM.CLEANED.
Contaminant Qty:

Site: ESSO PETROLEUM CANADA
BULK STATION BELLEVILLE CITY ON

Database: SPL

Ref No:	90258	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	8/23/1993	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	CONFIRMED	Site Municipality:	51103
Nature of Impact:	Soil contamination	Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	8/23/1993	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	EQUIPMENT FAILURE	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO PETROLEUM BULK PLANT- 180 L OF GASOLINE TO PAVEMENT & GROUND.		
Contaminant Qty:			

Site: TRANSPORT TRUCK
HWY 401 10 KM EAST OF BELLEVILLE, EAST BOUND LANE. MOTOR VEHICLE (OPERATING FLUID) BELLEVILLE CITY ON

Database: SPL

Ref No:	89426	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	8/5/1993	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	OTHER TRANSPORTATION ACCIDENT	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	CONFIRMED	Site Municipality:	51103
Nature of Impact:	Soil contamination	Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	8/5/1993	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	ERROR	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	PETERBOROUGH FREIGHTLINES-400 L DIESEL FUEL TO HWYDITCH,CONTAINED.		
Contaminant Qty:			

Site: UCO PETROLEUM INC.
BROCKVILLE CO-OP PARK STREET BROCKVILLE DEPOT PARK STREET BROCKVILLE CITY ON

Database: SPL

Ref No:	89300	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	8/3/1993	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	CONTAINER OVERFLOW	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	POSSIBLE	Site Municipality:	56101
Nature of Impact:	Soil contamination	Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	8/3/1993	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	EQUIPMENT FAILURE	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	UCO PETROLEUM INC. - 90L DIESEL FUEL TO LAND: TRUCK LOADING ARM FAILURE		
Contaminant Qty:			

Site: MCCOLL-FRONTENAC (TEXACO)
ESSO PETROLEUM SERVICE STATION BELLEVILLE CITY ON

Database: SPL

Ref No:	82562	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	3/9/1993	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	OTHER CONTAINER LEAK	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	POSSIBLE	Site Municipality:	51103
Nature of Impact:	Soil contamination	Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	3/9/1993	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	CORROSION	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO PETROLEUM - UNK QTY DIESEL FUEL TO LAND UNDERSNOW DUE TO PUMP LEAK.		
Contaminant Qty:			

Site: REYNOLDS CENTRAL FUELS
IN THE VILLAGE OF LYN AT THE OLD SCHOOLHOUSE FUEL OIL CO. ELIZABETHTOWN TWP. ON

Database: SPL

Ref No:	82275	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	3/1/1993	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	OTHER CONTAINER LEAK	Sector Type:	

Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	56606
Nature of Impact:	Other	***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	3/1/1993	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	EQUIPMENT FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	REYNOLDS FUELS - 10 L OF FURNACE OIL TO GROUND DURING DELIVERY.		
Contaminant Qty:			

Site: ***MEYER'S TRANSPORT CO.***
MEYER'S TRANSPORT BELLEVILLE YARD TANK TRUCK (CARGO) BELLEVILLE CITY ON

Database: ***SPL***

Ref No:	82219	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/27/1993	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	CONTAINER OVERFLOW	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	51103
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2/27/1993	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	ERROR	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	MEYER'S TRANSPORT CO. - 150L DIESEL FUEL TO LAND DUE TO DRIVER OVERFILLING		
Contaminant Qty:			

Site: ***ESSO PETROLEUM CANADA***
BULK STATION BELLEVILLE CITY ON

Database: ***SPL***

Ref No:	80431	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	12/30/1992	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PIPE/HOSE LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	51103
Nature of Impact:		***Site Lot:***	

Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	12/31/1992	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	ERROR	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO-20 LITERS FURNACE OIL TO GRND,CONTAINED ANDCLEANED-UP,PIPE REMOVAL.		
Contaminant Qty:			

Site: ***TRANSPORT TRUCK***
HWY 401 WESTBOUND, WEST OF BROCKVILLE MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON

Database: ***SPL***

Ref No:	77355	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	10/9/1992	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	56101
Nature of Impact:	Soil contamination	***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	OPP, MTO
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	10/9/1992	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	OVERSTRESS/OVERPRESSURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	TRANSPORT TRUCK ACCIDENT:300L DIESEL FUEL LEAK FROM SADDLE TANK		
Contaminant Qty:			

Site: ***QUEENSWAY TANK LINES***
AT UNITED CO-OP'S BULK PLANT ON PARK ST. TANK TRUCK (CARGO) BROCKVILLE CITY ON

Database: ***SPL***

Ref No:	77197	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	10/5/1992	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	CONTAINER OVERFLOW	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	56101
Nature of Impact:	Other	***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	REPORT FAXED TO MCCR
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	10/5/1992	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	ERROR	***Source Type:***	
Site Name:			

Site County/District:
Site Geo Ref Meth:
Incident Summary: QUEENSWAY TANKER TRUCK- 10 L OF GASOLINE TO GRAVEL DURING DELIVERY.
Contaminant Qty:

Site: ONTARIO HYDRO
CENTRE STREET CAPACITOR STATION TRANSFORMER BELLEVILLE CITY ON

Database: SPL

Ref No:	71051	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	5/23/1992	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	COOLING SYSTEM LEAK	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	NOT ANTICIPATED	Site Municipality:	51103
Nature of Impact:		Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	5/23/1992	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	OTHER	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ONTARIO HYDRO - 1 L OF MINERAL OIL TO GROUND FROM CAPACITOR		
Contaminant Qty:			

Site: TRANSPORT TRUCK
PARKDALE RD IN FRONT OF SOMERVILLE FARMS MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON

Database: SPL

Ref No:	69114	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	4/13/1992	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	OTHER CONTAINER LEAK	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	POSSIBLE	Site Municipality:	56101
Nature of Impact:	Soil Contamination	Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	BROCKVILLE FIRE DEPT.,WORKS DEPT.
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	4/13/1992	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	ERROR	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	TRANSPORT TRUCK - 225 L OF DIESEL FUEL TO ROADWAYFROM SADDLE TANK		
Contaminant Qty:			

Site: ESSO PETROLEUM CANADA

Database:

TANK TRUCK (CARGO) BELLEVILLE CITY ON

SPL

Ref No:	59549	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	11/8/1991	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	OTHER CONTAINER LEAK	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	NOT ANTICIPATED	Site Municipality:	51103
Nature of Impact:		Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	11/8/1991	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	WELD/SEAM FAILURE	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO-4 L. GASOLINE TO GRND FROM LEAKING BULK HEAD,CONTAINED & CLEANED.		
Contaminant Qty:			

Site: ONTARIO HYDRO
CENTRE STREET BELLEVILLE T.S. PCB STORAGE SITE (TANK) BELLEVILLE CITY ON

Database: SPL

Ref No:	54662	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	7/25/1991	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	OTHER CONTAINER LEAK	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	CONFIRMED	Site Municipality:	51103
Nature of Impact:	Soil contamination	Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	7/25/1991	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	ERROR	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ONTARIO HYDRO-5 L P.C.B. OIL TO GROUND.		
Contaminant Qty:			

Site: ESSO PETROLEUM CANADA
BULK STATION BELLEVILLE CITY ON

Database: SPL

Ref No:	53131	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	6/27/1991	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	Sector Type:	
Incident Event:		Agency Involved:	

Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	51103
Nature of Impact:		**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	6/27/1991	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	EQUIPMENT FAILURE	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO PETROLEUM BULK PLANT- 50 L. GAS TO GROUND FROM FAULTY VALVE		
Contaminant Qty:			

Site: ***QUEENSWAY TANK LINES***
PARK STREET UNITED CO-OP YARD TANK TRUCK (CARGO) BROCKVILLE CITY ON

Database: *SPL*

Ref No:	52626	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	6/19/1991	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	PIPE/HOSE LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	56101
Nature of Impact:	Soil contamination	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	6/19/1991	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	ERROR	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	QUEENSWAY TANKER TRUCK- 20 L DIESEL FUEL TO GRAVEL		
Contaminant Qty:			

Site: ***COLLEGE PRO PAINTERS***
PARK ST. BROCKVILLE CITY ON

Database: *SPL*

Ref No:	51863	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	6/6/1991	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	OTHER CONTAINER LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	56101
Nature of Impact:		**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	

Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	6/6/1991	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	DAMAGE BY MOVING EQUIPMENT	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	COLLEGE PRO PAINTERS: CANOF LATEX PAINT AND WATER SPILLED TO ROAD		
Contaminant Qty:			

Site: ***TRANSPORT TRUCK***
401 AT BELLEVILLE MOTOR VEHICLE (OPERATING FLUID) BELLEVILLE CITY ON

Database: *SPL*

Ref No:	43107	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	11/7/1990	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	OTHER CONTAINER LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	51103
Nature of Impact:		**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	F.D., MOT
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	11/7/1990	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	OTHER	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	TRANSPORT TRUCK-DIESEL FUEL TO ROAD		
Contaminant Qty:			

Site: ***TRANSPORT TRUCK***
ALONG THE 401 FROM BROCKVILLE TO LONG SAULT MOTOR VEHICLE (OPERATING FLUID) BROCKVILLE CITY ON

Database: *SPL*

Ref No:	42082	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	10/13/1990	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	OTHER TRANSPORTATION ACCIDENT	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	CONFIRMED	**Site Municipality:**	56101
Nature of Impact:	Other	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	O.P.P., MTO
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	10/13/1990	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	ERROR	**Source Type:**	
Site Name:			

Site County/District:
Site Geo Ref Meth:
Incident Summary: 100 L OF DIESEL FUEL TO HWY. 401 FROM LEAKY SADDLE TANK ON TRANSPORT.
Contaminant Qty:

Site: ESSO PETROLEUM
CANNIFTON TANK TRUCK (CARGO) BELLEVILLE CITY ON

Database: SPL

Ref No:	38219	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	7/25/1990	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	CONTAINER OVERFLOW	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	NOT ANTICIPATED	Site Municipality:	51103
Nature of Impact:		Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	7/25/1990	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	ERROR	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: ESSO PETROLEUM - 50L GAS-0LINE TO PAVEMENT WHEN DRIVER OVERFILLED TANKER.
Contaminant Qty:

Site: ONTARIO HYDRO
TRANSFORMER STATION - CENTRE ST. TRANSFORMER BELLEVILLE CITY ON

Database: SPL

Ref No:	24067	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	7/26/1989	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	OTHER CAUSE (N.O.S.)	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	NOT ANTICIPATED	Site Municipality:	51103
Nature of Impact:		Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	7/26/1989	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	UNKNOWN	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: BACKENTRY - 20 LTR. NON- PCB OIL TO GROUND FROM TRANSFORMERS.
Contaminant Qty:

Site: ONTARIO HYDRO

Database:

TRANSFORMER STATION - CENTRE ST. TRANSPORT TRUCK (CARGO) BELLEVILLE CITY ON

SPL

Ref No:	24066	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	7/27/1989	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	NOT ANTICIPATED	Site Municipality:	51103
Nature of Impact:		Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	7/28/1989	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	MATERIAL FAILURE	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: BACKENTRY - 90 LTR. OF HYDRAULIC FLUID TO GROUND.
Contaminant Qty:

Site: ONTARIO HYDRO
CENTRE STREET BELLEVILLE TRANSFORMER STATION TRANSFORMER BELLEVILLE CITY ON

Database: SPL

Ref No:	23514	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	8/12/1989	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	COOLING SYSTEM LEAK	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:		Site Municipality:	51103
Nature of Impact:		Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	8/12/1989	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	FIRE/EXPLOSION	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: ONTARIO HYDRO- 50 LTR OF MINERAL OIL TO GROUND NONPCB CONTAINING.
Contaminant Qty:

Site: ULTRAMAR
SERVICE STATION BELLEVILLE CITY ON

Database: SPL

Ref No:	20445	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	3/10/1989	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	Sector Type:	
Incident Event:		Agency Involved:	

Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	51103
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	3/13/1989	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	UNKNOWN	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	BACKENTRY - ULTRAMAR STN 100L FURNACE OIL FROM LEAKY VALVE		
Contaminant Qty:			

Site: ***CANADA TRANSPORT***
TRANSPORT TRUCK (CARGO) BROCKVILLE CITY ON

Database: ***SPL***

Ref No:	15052	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/21/1989	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	UNKNOWN	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	56101
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	MOE
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2/21/1989	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	UNKNOWN	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	CANADA TRANSPORT- 10L DIESEL SPILLED TO GROUND.		
Contaminant Qty:			

Site: ***IMPERIAL OIL LTD.***
BULK STATION/STORAGE DEPOT BROCKVILLE CITY ON

Database: ***SPL***

Ref No:	104892	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	9/3/1994	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PIPE/HOSE LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	56101
Nature of Impact:	Soil contamination	***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	

Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	9/6/1994	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	NEGLIGENCE (APPARENT)	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO KEY LOCK: 350L DIESEL FUEL TO GROUND DURING FILLING.		
Contaminant Qty:			

Site: ***IMPERIAL OIL LTD.***
BULK STATION/STORAGE DEPOT BROCKVILLE CITY ON

Database: ***SPL***

Ref No:	99754	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	5/11/1994	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PIPE/HOSE LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	56101
Nature of Impact:	Soil contamination	***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	5/11/1994	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	NEGLIGENCE (APPARENT)	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO KEY LOCK: 100L DIESEL FUEL TO GROUND DURING FILLING.		
Contaminant Qty:			

Site: ***Hydro One Networks Inc.***
Elizabethtown-Kitley ON

Database: ***SPL***

Ref No:	6283-BEV4JK	***Discharger Report:***	
Site No:	NA	***Material Group:***	
Incident Dt:	8/8/2019	***Health/Env Conseq:***	2 - Minor Environment
Year:		***Client Type:***	Corporation
Incident Cause:		***Sector Type:***	Miscellaneous Industrial
Incident Event:	Leak/Break	***Agency Involved:***	
Contaminant Code:	15	***Nearest Watercourse:***	
Contaminant Name:	TRANSFORMER OIL (N.O.S.)	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	Kingston - District
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:	n/a	***Site Region:***	Eastern
Environment Impact:		***Site Municipality:***	Elizabethtown-Kitley
Nature of Impact:		***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:	Land	***Northing:***	
MOE Response:	No	***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	8/8/2019	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	Land Spills
Incident Reason:	Weather Conditions	***Source Type:***	Transformer
Site Name:	287 King St East<UNOFFICIAL>		
Site County/District:	United Counties of Leeds and Grenville		

Site Geo Ref Meth:
Incident Summary: Hydro One spill; PCB Mineral oil suspect. Contained, cleaning.
Contaminant Qty: 0 L

Site: **Database:** SPL

Hwy 401 - mile marker 698 Brockville ON

Ref No:	6230-BEKFKU	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	7/30/2019	**Health/Env Conseq:**	2 - Minor Environment
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Miscellaneous Industrial
Incident Event:	Collision/Accident	**Agency Involved:**	
Contaminant Code:	13	**Nearest Watercourse:**	
Contaminant Name:	DIESEL FUEL	**Site Address:**	Hwy 401 - mile marker 698
Contaminant Limit 1:		**Site District Office:**	Kingston - District
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:	1202	**Site Region:**	Eastern
Environment Impact:		**Site Municipality:**	Brockville
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Land	**Northing:**	
MOE Response:	No	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	7/30/2019	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Land Spills
Incident Reason:	Operator/Human Error	**Source Type:**	Motor Vehicle

Site Name: TT Rollover<UNOFFICIAL>
Site County/District: United Counties of Leeds and Grenville
Site Geo Ref Meth:
Incident Summary: TT rollover,Spill to 401 Eastbound at North Augusta Road, Brockville
Contaminant Qty: 10 L

Site: **Database:** SPL

Greenshield Pest Control Inc.
North Augusta Road Brockville ON

Ref No:	2046-BCGHHG	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	5/10/2019	**Health/Env Conseq:**	2 - Minor Environment
Year:		**Client Type:**	Corporation
Incident Cause:		**Sector Type:**	
Incident Event:	Application	**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	North Augusta Road
Contaminant Limit 1:		**Site District Office:**	Kingston - District
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	Eastern
Environment Impact:		**Site Municipality:**	Brockville
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Land	**Northing:**	4939167.06
MOE Response:	Yes	**Easting:**	445935.95
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	5/10/2019	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Pollution Incident Reports (PIRs) and "Other" calls
Incident Reason:	Unknown / N/A	**Source Type:**	

Site Name: Brackenreid Park - Brockville<UNOFFICIAL>
Site County/District: United Counties of Leeds and Grenville
Site Geo Ref Meth:
Incident Summary: Pesticides - Roundup spraying in Brackenreid Park, Brockville
Contaminant Qty:

Site: ***HK Travel Centres GP Inc.*** **Database:** SPL

HWY 401 MAllorytown Brockville ON

Ref No:	6468-A97PYD	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	2016/04/19	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Miscellaneous Industrial
Incident Event:	Fire/Explosion	**Agency Involved:**	
Contaminant Code:	98	**Nearest Watercourse:**	
Contaminant Name:	CONTAMINATED FIRE WATER	**Site Address:**	HWY 401 MAllorytown
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:		**Site Municipality:**	Brockville
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Land	**Northing:**	
MOE Response:	No	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2016/04/20	**Site Map Datum:**	
Dt Document Closed:	2016/06/03	**SAC Action Class:**	Watercourse Spills
Incident Reason:	Unknown / N/A	**Source Type:**	

Site Name: HK ON Route Centre _ Mallorytown<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Truck caught fire _ On Route Service Centre, HWY 401 Mallorytown, ON.
Contaminant Qty: 0 n/a

Site: ***Neovia<UNOFFICIAL>*** **Database:** SPL
Hwy 401 WB, north side at km marker 696 Brockville ON

Ref No:	0525-A7U7QW	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	2016/03/07	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Miscellaneous Communal
Incident Event:	Leak/Break	**Agency Involved:**	
Contaminant Code:	13	**Nearest Watercourse:**	
Contaminant Name:	DIESEL FUEL	**Site Address:**	Hwy 401 WB, north side at km marker 696
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:		**Site Municipality:**	Brockville
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Land	**Northing:**	4938268
MOE Response:	Yes	**Easting:**	443912
Dt MOE Arvl on Scn:	2016/03/08	**Site Geo Ref Accu:**	GPS
MOE Reported Dt:	2016/03/07	**Site Map Datum:**	
Dt Document Closed:	2016/04/16	**SAC Action Class:**	Primary Assessment of Spills
Incident Reason:	Road Conditions	**Source Type:**	

Site Name: Spill site<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Neovia: Brockville: up to 400 L dsl spilled to Hwy 401+shoulder
Contaminant Qty: 400 L

Site: ***Greyhound Canada Transportation ULC*** **Database:** SPL
Belleville ON

Ref No:	4312-8ZFM5E	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	26-OCT-12	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Leak/Break	**Sector Type:**	Motor Vehicle
Incident Event:		**Agency Involved:**	

Contaminant Code:	15	**Nearest Watercourse:**	
Contaminant Name:	MOTOR OIL	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Possible	**Site Municipality:**	Belleville
Nature of Impact:	Soil Contamination	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	No Field Response	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	26-OCT-12	**Site Map Datum:**	
Dt Document Closed:	19-FEB-13	**SAC Action Class:**	Land Spills
Incident Reason:	Equipment Failure	**Source Type:**	
Site Name:	East of 401 and Wallbridge Rd in EB Lane of 401<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Greyhound: 15L of Motor Oil to gravel		
Contaminant Qty:	15 L		

Site: ***Mortrans Transport<UNOFFICIAL>***
Hwy 401 Westbound Lanes (mile marker 698) Brockville ON

Database: SPL

Ref No:	4070-8XEHYF	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	22-AUG-12	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:	13	**Nearest Watercourse:**	
Contaminant Name:	DIESEL FUEL	**Site Address:**	Hwy 401 Westbound Lanes (mile marker 698)
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:		**Site Municipality:**	Brockville
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	No Field Response	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	22-AUG-12	**Site Map Datum:**	
Dt Document Closed:	16-JAN-13	**SAC Action Class:**	Land Spills
Incident Reason:		**Source Type:**	
Site Name:	TT Accident<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Mortrans Transport: 100L Diesel to Grnd, Cln		
Contaminant Qty:	10 L		

Site: ***Loblaws<UNOFFICIAL>***
Brockville ON

Database: SPL

Ref No:	8348-8SLGHC	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	21-MAR-12	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Discharge or Emission to Air	**Sector Type:**	Other
Incident Event:		**Agency Involved:**	
Contaminant Code:	38	**Nearest Watercourse:**	
Contaminant Name:	FREON (CFC)	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Possible	**Site Municipality:**	Brockville
Nature of Impact:	Air Pollution	**Site Lot:**	
Receiving Medium:	Sewage - Municipal/Private and Commercial	**Site Conc:**	

Receiving Env:		**Northing:**	
MOE Response:	No Field Response	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	21-MAR-12	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Air Spills - Gases and Vapours
Incident Reason:	Equipment Failure - Malfunction of system components	**Source Type:**	
Site Name:	1972 Parkdale Ave. - Loblaws Store<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Real CDN Superstore-136 K Freon 507 to Atm.		
Contaminant Qty:			

Site: ***John Cherry<UNOFFICIAL>***
north end of Crocker Cres. Brockville ON

Database: SPL

Ref No:	2144-8N9HXM	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	11/3/2011	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Other Discharges	**Sector Type:**	Other
Incident Event:		**Agency Involved:**	
Contaminant Code:	28	**Nearest Watercourse:**	
Contaminant Name:	WASHWATER (N.O.S.)	**Site Address:**	north end of Crocker Cres.
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Confirmed	**Site Municipality:**	Brockville
Nature of Impact:	Human Health/Safety; Other Impact(s); Soil Contamination	**Site Lot:**	
Receiving Medium:	Sewage - Municipal/Private and Commercial	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	Planned Field Response	**Easting:**	
Dt MOE Arvl on Scn:	11/3/2011	**Site Geo Ref Accu:**	
MOE Reported Dt:	11/3/2011	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Land Spills
Incident Reason:	Spill	**Source Type:**	
Site Name:	Brockville - snow storage site<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Dumping of paint washwater, MOE attending		
Contaminant Qty:	40 L		

Site: ***Hydro One Inc.***
between Parkdale and Walthon Brockville ON

Database: SPL

Ref No:	6174-8GDMVK	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	4/28/2011	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Other Discharges	**Sector Type:**	Transformer
Incident Event:		**Agency Involved:**	
Contaminant Code:	15	**Nearest Watercourse:**	
Contaminant Name:	TRANSMISSION OIL	**Site Address:**	between Parkdale and Walthon
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Confirmed	**Site Municipality:**	Brockville
Nature of Impact:	Surface Water Pollution	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	Priority Field Response	**Easting:**	
Dt MOE Arvl on Scn:	4/29/2011	**Site Geo Ref Accu:**	
MOE Reported Dt:	4/29/2011	**Site Map Datum:**	
Dt Document Closed:	12/22/2011	**SAC Action Class:**	Watercourse Spills
Incident Reason:	Weather	**Source Type:**	

Site Name: Crocker Cres<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Hydro One: xfrmr oil to gnrd and creek, cntd
Contaminant Qty: 40 gal-US

Site: *7506180 Canada Inc./J&R Logistics<UNOFFICIAL>*
401 Eastbound Mile Marker 698 Elizabethtown-Kitley ON

Database: SPL

Ref No:	8426-8ERBB9	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	3/8/2011	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Other Transport Accident	**Sector Type:**	Tank Truck
Incident Event:		**Agency Involved:**	
Contaminant Code:	13	**Nearest Watercourse:**	
Contaminant Name:	DIESEL FUEL	**Site Address:**	401 Eastbound Mile Marker 698
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Confirmed	**Site Municipality:**	Elizabethtown-Kitley
Nature of Impact:	Soil Contamination	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	No Field Response	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	3/8/2011	**Site Map Datum:**	
Dt Document Closed:	12/22/2011	**SAC Action Class:**	Highway Spills (usually highway accidents)
Incident Reason:	Unknown - Reason not determined	**Source Type:**	

Site Name: 401 Eastbound<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: TT Accident 401 Eastbound outside of Elizabethtown-Kitley
Contaminant Qty: 570 L

Site:
ST. LAWRENCE RIVER AT PARK STREET <UNOFFICIAL> Brockville ON

Database: SPL

Ref No:	0427-5ZHFF2	**Discharger Report:**	
Site No:		**Material Group:**	Oil
Incident Dt:	5/31/2004	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:	OIL (PETROLEUM BASED, NOT SPECIFIED)	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Kingston
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	Eastern
Environment Impact:		**Site Municipality:**	Brockville
Nature of Impact:		**Site Lot:**	
Receiving Medium:	Water	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	5/31/2004	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:		**Source Type:**	

Site Name: ST. LAWRENCE RIVER AT PARK STREET <UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Private Auto-Operating Fluids to River
Contaminant Qty:

Site: *Brockville Landfill Site*
Brockville ON

Database: WDS

Approval No:	A440101	**Total Area (ha):**	41.86
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Cancelled	**Transfer Cap (m³):**	
Facility Type:	Landfill	**Transfer Cert No:**	
Record Type:		**Inciner. Area (ha):**	
Link Source:		**Inciner. Cap (t):**	
Project Type:		**Process Area (m³):**	
Application Status:	Notice	**Process Cap (m³/d):**	
Issue Date:	1/9/2002	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	2
Est Closure Date:		**Site Region/County:**	United Counties Of Leeds & Grenville
Mobile Capacity:		**SWP Area Name:**	
Mobile Units:		**MOE District:**	
Mobile Description:		**District Office:**	Kingston - District
Prop City:	Brockville	**Latitude:**	
Prop Postal:	K6V 3P5	**Longitude:**	
Prop Phone:		**Geometry X:**	
Serial Link:	440101	**Geometry Y:**	

Approval Type:
Proponent: The Corporation of the City of Brockville
Prop Address: 1 King Street West, P.O. Box 5000
Proponent County/District: United Counties of Leeds and Grenville
Full Address:
Site Lot: 16, 17
Waste Class Code:
Waste Class:
Waste Type:
Waste Type Other:
Waste Description:
Landfill Monitoring: groundwater
Landfill Ctrl Type: leachate treatment
Site Closing Description:
Project Description: This tender document for Phase 1 Closure submission is in compliance with Condition No. 47 of the existing Certificate of Approval.
Municipalities Served: Leeds and Grenville
Approval Description:
Other Approvals/Permits:
PDF URL:

Site:
lot 8 con 1 ON

Database: WWIS

Well ID:	3609001	**Data Entry Status:**	
Construction Date:		**Data Src:**	1
Primary Water Use:	Domestic	**Date Received:**	10/23/1984
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Water Supply	**Abandonment Rec:**	
Water Type:		**Contractor:**	4794
Casing Material:		**Form Version:**	1
Audit No:		**Owner:**	
Tag:		**Street Name:**	
Construction Method:		**County:**	36
Elevation (m):		**Municipality:**	ELIZABETHTOWN TOWNSHIP
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	008
Well Depth:		**Concession:**	01
Overburden/Bedrock:		**Concession Name:**	CON
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID: 10222395
DP2BR: 5
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 9/26/1984
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931694243
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 01
Mat2 Desc: FILL
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931694245
Layer: 3
Color: 2
General Color: GREY
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 165
Formation End Depth: 240
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931694244
Layer: 2
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:

Mat3 Desc:
Formation Top Depth: 5
Formation End Depth: 165
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933153639
Layer: 1
Plug From: 6
Plug To: 22
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963609001
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10770965
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930376477
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To:
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930376476
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To:
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993609001
Pump Set At:
Static Level: 40
Final Level After Pumping: 40
Recommended Pump Depth:
Pumping Rate: 7
Flowing Rate:
Recommended Pump Rate: 7
Levels UOM: ft

Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934489157
Test Type:
Test Duration: 30
Test Level: 40
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 935002365
Test Type:
Test Duration: 60
Test Level: 40
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934743099
Test Type:
Test Duration: 45
Test Level: 40
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934202238
Test Type:
Test Duration: 15
Test Level: 40
Test Level UOM: ft

Water Details

Water ID: 933685825
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 235
Water Found Depth UOM: ft

Site:

lot 6 con 2 ON

Database: ***WWIS***

Well ID: 3609000
Construction Date:
Primary Water Use: Domestic
Sec. Water Use:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:

Data Entry Status:
Data Src: 1
Date Received: 10/23/1984
Selected Flag: Yes
Abandonment Rec:
Contractor: 4794
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:

Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Lot: 006
Concession: 02
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10222394
DP2BR: 4
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 7/27/1984
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931694241
Layer: 1
Color: 6
General Color: BROWN
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 4
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931694242
Layer: 2
Color: 7
General Color: RED
Mat1: 21
Most Common Material: GRANITE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 4
Formation End Depth: 148
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933153638

Layer: 1
Plug From: 7
Plug To: 22
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963609000
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10770964
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930376474
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To:
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930376475
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To:
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993609000
Pump Set At:
Static Level: 65
Final Level After Pumping: 65
Recommended Pump Depth: 140
Pumping Rate: 6
Flowing Rate:
Recommended Pump Rate: 6
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 935002364
Test Type:
Test Duration: 60
Test Level: 65
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934202237
Test Type:
Test Duration: 15
Test Level: 65
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934489156
Test Type:
Test Duration: 30
Test Level: 65
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934743098
Test Type:
Test Duration: 45
Test Level: 65
Test Level UOM: ft

Water Details

Water ID: 933685824
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 143
Water Found Depth UOM: ft

Site:
lot 6 con 1 ON

Database: ***WWIS***

Well ID: 3615016
Construction Date:
Primary Water Use: Domestic
Sec. Water Use:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 2/14/1984
Selected Flag: Yes
Abandonment Rec:
Contractor: 1119
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 006
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	10228400	***Elevation:***	
DP2BR:	2	***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:	r	***East83:***	
Code OB Desc:	Bedrock	***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	8/23/1983	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	931710288
Layer:	1
Color:	
General Color:	
Mat1:	02
Most Common Material:	TOPSOIL
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0
Formation End Depth:	2
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931710290
Layer:	3
Color:	2
General Color:	GREY
Mat1:	18
Most Common Material:	SANDSTONE
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	30
Formation End Depth:	140
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931710289
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	18
Most Common Material:	SANDSTONE
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	2

Formation End Depth:	30
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	963615016
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	10776970
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930385477
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	
Casing Diameter:	6
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pump Test ID:	993615016
Pump Set At:	
Static Level:	70
Final Level After Pumping:	120
Recommended Pump Depth:	130
Pumping Rate:	6
Flowing Rate:	
Recommended Pump Rate:	6
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	0
Pumping Duration MIN:	30
Flowing:	No

Draw Down & Recovery

Pump Test Detail ID:	934482386
Test Type:	Draw Down
Test Duration:	30
Test Level:	120
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	934214122
Test Type:	Draw Down
Test Duration:	15
Test Level:	120
Test Level UOM:	ft

Water Details

Water ID:	933695385
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	135
Water Found Depth UOM:	ft

Site:

lot 18 con 1 ON

Database: ***WWIS***

Well ID:	3614001	***Data Entry Status:***	
Construction Date:		***Data Src:***	1
Primary Water Use:	Domestic	***Date Received:***	5/1/1997
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Water Supply	***Abandonment Rec:***	
Water Type:		***Contractor:***	6565
Casing Material:		***Form Version:***	1
Audit No:	167756	***Owner:***	
Tag:		***Street Name:***	
Construction Method:		***County:***	36
Elevation (m):		***Municipality:***	ELIZABETHTOWN TOWNSHIP
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	018
Well Depth:		***Concession:***	01
Overburden/Bedrock:		***Concession Name:***	COM E
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	10227385	***Elevation:***	
DP2BR:	8	***Elevrc:***	
Spatial Status:		***Zone:***	18
Code OB:	r	***East83:***	
Code OB Desc:	Bedrock	***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	4/9/1997	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	931707384
Layer:	1
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0
Formation End Depth:	8
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931707386
Layer:	3
Color:	7
General Color:	RED
Mat1:	21
Most Common Material:	GRANITE
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	23
Formation End Depth:	44
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931707385
Layer:	2
Color:	8
General Color:	BLACK
Mat1:	21
Most Common Material:	GRANITE
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	8
Formation End Depth:	23
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	963614001
Method Construction Code:	1
Method Construction:	Cable Tool
Other Method Construction:	

Pipe Information

Pipe ID:	10775955
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930383648
Layer:	1
Material:	1
Open Hole or Material:	STEEL
Depth From:	
Depth To:	23
Casing Diameter:	6
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Results of Well Yield Testing

Pump Test ID:	993614001
Pump Set At:	
Static Level:	10
Final Level After Pumping:	10
Recommended Pump Depth:	34
Pumping Rate:	18
Flowing Rate:	
Recommended Pump Rate:	6
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	2
Water State After Test:	CLOUDY
Pumping Test Method:	2
Pumping Duration HR:	1
Pumping Duration MIN:	0
Flowing:	No

Draw Down & Recovery

Pump Test Detail ID:	934749879
Test Type:	Recovery
Test Duration:	45
Test Level:	10
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	935001486
Test Type:	Recovery
Test Duration:	60
Test Level:	10
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	934488375
Test Type:	Recovery
Test Duration:	30
Test Level:	10
Test Level UOM:	ft

Draw Down & Recovery

Pump Test Detail ID:	934210783
Test Type:	Recovery
Test Duration:	15
Test Level:	10
Test Level UOM:	ft

Water Details

Water ID:	933693839
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	39
Water Found Depth UOM:	ft

Site:
lot 8 con 1 ON

Database: ***WWIS***

Well ID: 3609004 ***Data Entry Status:***

Construction Date:	
Primary Water Use:	Domestic
Sec. Water Use:	
Final Well Status:	Water Supply
Water Type:	
Casing Material:	
Audit No:	
Tag:	
Construction Method:	
Elevation (m):	
Elevation Reliability:	
Depth to Bedrock:	
Well Depth:	
Overburden/Bedrock:	
Pump Rate:	
Static Water Level:	
Flowing (Y/N):	
Flow Rate:	
Clear/Cloudy:	

Data Src:	1
Date Received:	10/23/1984
Selected Flag:	Yes
Abandonment Rec:	
Contractor:	4794
Form Version:	1
Owner:	
Street Name:	
County:	36
Municipality:	ELIZABETHTOWN TOWNSHIP
Site Info:	
Lot:	008
Concession:	01
Concession Name:	CON
Easting NAD83:	
Northing NAD83:	
Zone:	
UTM Reliability:	

Bore Hole Information

Bore Hole ID:	10222398
DP2BR:	4
Spatial Status:	
Code OB:	r
Code OB Desc:	Bedrock
Open Hole:	
Cluster Kind:	
Date Completed:	8/2/1984
Remarks:	
Elevrc Desc:	
Location Source Date:	
Improvement Location Source:	
Improvement Location Method:	
Source Revision Comment:	
Supplier Comment:	

Elevation:	
Elevrc:	
Zone:	18
East83:	
North83:	
Org CS:	
UTMRC:	9
UTMRC Desc:	unknown UTM
Location Method:	na

Overburden and Bedrock Materials Interval

Formation ID:	931694251
Layer:	2
Color:	2
General Color:	GREY
Mat1:	21
Most Common Material:	GRANITE
Mat2:	
Mat2 Desc:	
Mat3:	
Mat3 Desc:	
Formation Top Depth:	4
Formation End Depth:	65
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	931694250
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	02
Most Common Material:	TOPSOIL
Mat2:	
Mat2 Desc:	

Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 4
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933153642
Layer: 1
Plug From: 7
Plug To: 22
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963609004
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10770968
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930376482
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To:
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930376483
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To:
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993609004
Pump Set At:
Static Level: 20
Final Level After Pumping: 20
Recommended Pump Depth: 60
Pumping Rate: 7
Flowing Rate:
Recommended Pump Rate: 7

Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934743102
Test Type: Draw Down
Test Duration: 45
Test Level: 20
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 935002368
Test Type: Draw Down
Test Duration: 60
Test Level: 20
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934489160
Test Type: Draw Down
Test Duration: 30
Test Level: 20
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934202241
Test Type: Draw Down
Test Duration: 15
Test Level: 20
Test Level UOM: ft

Water Details

Water ID: 933685828
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 60
Water Found Depth UOM: ft

Site:
lot 6 con 2 ON

Database: ***WWIS***

Well ID: 3615025
Construction Date:
Primary Water Use: Domestic
Sec. Water Use:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):

Data Entry Status:
Data Src: 1
Date Received: 2/14/1984
Selected Flag: Yes
Abandonment Rec:
Contractor: 1119
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP

Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Site Info:
Lot: 006
Concession: 02
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10228409
DP2BR: 4
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 10/5/1983
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931710313
Layer: 2
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 4
Formation End Depth: 44
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931710312
Layer: 1
Color:
General Color:
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 4
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963615025
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 10776979
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930385485
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To:
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993615025
Pump Set At:
Static Level: 8
Final Level After Pumping: 25
Recommended Pump Depth: 30
Pumping Rate: 10
Flowing Rate:
Recommended Pump Rate: 10
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 1
Pumping Duration HR: 0
Pumping Duration MIN: 30
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934214131
Test Type: Draw Down
Test Duration: 15
Test Level: 25
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934482395
Test Type: Draw Down
Test Duration: 30
Test Level: 25
Test Level UOM: ft

Water Details

Water ID: 933695396
Layer: 1
Kind Code: 1

Kind: FRESH
Water Found Depth: 40
Water Found Depth UOM: ft

Site:

lot 6 con 1 ON

Database: ***WWIS***

Well ID: 3608968
Construction Date:
Primary Water Use: Industrial
Sec. Water Use:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 7/11/1984
Selected Flag: Yes
Abandonment Rec:
Contractor: 4794
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 006
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10222362
DP2BR: 4
Spatial Status:
Code OB: r
Code OB Desc: Bedrock
Open Hole:
Cluster Kind:
Date Completed: 5/18/1984
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931694164
Layer: 2
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 4
Formation End Depth: 25
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931694163
Layer: 1
Color: 6
General Color: BROWN
Mat1: 02
Most Common Material: TOPSOIL
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 4
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931694165
Layer: 3
Color: 2
General Color: GREY
Mat1: 18
Most Common Material: SANDSTONE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 25
Formation End Depth: 120
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933153618
Layer: 1
Plug From: 8
Plug To: 22
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963608968
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10770932
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930376422
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To:
Casing Diameter: 6
Casing Diameter UOM: inch

Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930376423
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To:
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993608968
Pump Set At:
Static Level: 40
Final Level After Pumping: 40
Recommended Pump Depth: 110
Pumping Rate: 24
Flowing Rate:
Recommended Pump Rate: 24
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 935002341
Test Type:
Test Duration: 60
Test Level: 40
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934489125
Test Type:
Test Duration: 30
Test Level: 40
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934743075
Test Type:
Test Duration: 45
Test Level: 40
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934202206
Test Type:
Test Duration: 15
Test Level: 40
Test Level UOM: ft

Water Details

Water ID: 933685782
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 115
Water Found Depth UOM: ft

Site:

lot 18 con 1 ON

Database: ***WWIS***

Well ID: 3608966
Construction Date:
Primary Water Use: Domestic
Sec. Water Use:
Final Well Status: Water Supply
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 7/11/1984
Selected Flag: Yes
Abandonment Rec:
Contractor: 4794
Form Version: 1
Owner:
Street Name:
County: 36
Municipality: ELIZABETHTOWN TOWNSHIP
Site Info:
Lot: 018
Concession: 01
Concession Name: CON
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10222360
DP2BR: 0
Spatial Status:
Code OB: h
Code OB Desc: Mixed in a Layer
Open Hole:
Cluster Kind:
Date Completed: 5/22/1984
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 18
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 931694160
Layer: 2
Color: 7
General Color: RED
Mat1: 21
Most Common Material: GRANITE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 2

Formation End Depth: 148
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 931694159
Layer: 1
Color: 6
General Color: BROWN
Mat1: 02
Most Common Material: TOPSOIL
Mat2: 26
Mat2 Desc: ROCK
Mat3:
Mat3 Desc:
Formation Top Depth: 0
Formation End Depth: 2
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933153616
Layer: 1
Plug From: 6
Plug To: 22
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 963608966
Method Construction Code: 5
Method Construction: Air Percussion
Other Method Construction:

Pipe Information

Pipe ID: 10770930
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930376419
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To:
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930376418
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To:

Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pump Test ID: 993608966
Pump Set At:
Static Level: 18
Final Level After Pumping: 18
Recommended Pump Depth: 140
Pumping Rate: 15
Flowing Rate:
Recommended Pump Rate: 15
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 1
Water State After Test: CLEAR
Pumping Test Method: 1
Pumping Duration HR: 1
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934202204
Test Type:
Test Duration: 15
Test Level: 18
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934743073
Test Type:
Test Duration: 45
Test Level: 18
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 935002339
Test Type:
Test Duration: 60
Test Level: 18
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934489123
Test Type:
Test Duration: 30
Test Level: 18
Test Level UOM: ft

Water Details

Water ID: 933685779
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 130
Water Found Depth UOM: ft

Water Details

Water ID:	933685780
Layer:	2
Kind Code:	1
Kind:	FRESH
Water Found Depth:	142
Water Found Depth UOM:	ft

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

The Ontario Ministry of Natural Resources maintains a database of all active pits and quarries. The database provides information regarding the registered owner/operator, location name, operation type, approval type, and maximum annual tonnage.

Government Publication Date: Up to Sep 2019

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Oct 2018

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks: Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Jan 31, 2020

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.
Environment and Climate Change Canada cites the coronavirus pandemic as an explanation for delays in releasing data pursuant to requests.

Government Publication Date: Jan 2004-Dec 2017

Commercial Fuel Oil Tanks: Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.
Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.
The coronavirus pandemic is cited by the agency responsible for tank regulations and data as an explanation for delays in releasing data pursuant to requests.

Government Publication Date: Feb 28, 2017

Chemical Register: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2020

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 - Jun 2020

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-Dec 2019

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994-Jun 30, 2020

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Sep 2019

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011-Jun 30, 2020

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994-Jun 30, 2020

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011-Jun 30, 2020

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Apr 30, 2020

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Dec 31, 2016

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2019

List of Expired Fuels Safety Facilities: Provincial EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.
The coronavirus pandemic is cited by the agency responsible for tank regulations and data as an explanation for delays in releasing data pursuant to requests.

Government Publication Date: Feb 28, 2017

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

Government Publication Date: Jun 2000-Apr 2020

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2019

Federal Identification Registry for Storage Tank Systems (FIRSTS): Federal FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

Government Publication Date: May 31, 2018

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.
The coronavirus pandemic is cited by the agency responsible for tank regulations and data as an explanation for delays in releasing data pursuant to requests.

Government Publication Date: Feb 28, 2017

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Apr 30, 2020

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Dec 2017

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

Fuel Oil Spills and Leaks: Provincial INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.
The coronavirus pandemic is cited by the agency responsible for tank regulations and data as an explanation for delays in releasing data pursuant to requests.

Government Publication Date: Feb 28, 2017

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the ministry compiles new and updated information. The inventory will include small and large landfills. Additionally, each year the ministry will request operators of the larger landfills complete a landfill data collection form that will be used to update LIMO and will include the following information from the previous operating year. This will include additional information such as estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills will include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Feb 28, 2019

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Jan 2020

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

Government Publication Date: Dec 31, 2018

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Apr 2018

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Mar 31, 2020

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-May 31, 2020

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

Government Publication Date: 1800-Jun 2019

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994-Jun 30, 2020

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: Oct 2011-Jun 30, 2020

Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.
The coronavirus pandemic is cited by the agency responsible for tank regulations and data as an explanation for delays in releasing data pursuant to requests.

Government Publication Date: Feb 28, 2017

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994-Jun 30, 2020

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-2016

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up.
RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09).

Government Publication Date: 1997-Sept 2001, Oct 2004-May 2020

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Jan 31, 2020

Scott's Manufacturing Directory: Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills: Provincial SPL

List of spills and incidents made available the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.
The Ministry of the Environment, Conservation and Parks cites the coronavirus pandemic as an explanation for delays in releasing data pursuant to requests.

Government Publication Date: 1988-Nov 2019

Wastewater Discharger Registration Database: Provincial SRDS

Information under this heading is combination of the following 2 programs. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment maintained a database of all direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation; Mining; Petroleum Refining; Organic Chemicals; Inorganic Chemicals; Pulp & Paper; Metal Casting; Iron & Steel; and Quarries. All sampling information is now collected and stored within the Sample Result Data Store (SRDS).

Government Publication Date: 1990-Dec 31, 2017

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970-Aug 2018

Variances for Abandonment of Underground Storage Tanks: Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness.
The coronavirus pandemic is cited by the agency responsible for tank regulations and data as an explanation for delays in releasing data pursuant to requests.

Government Publication Date: Feb 28, 2017

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011-Jun 30, 2020

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System: Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Apr 30, 2020

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

Appendix C PHOTOGRAPHIC LOG

Photo 1 Auto parts shop north of intersection of Stewart Boulevard and Jefferson Drive, looking north.

Photo 2 Retail gas station (Petro Canada) east of intersection of Stewart Boulevard and Jefferson Drive (325 Stewart Boulevard, **PSOC-3**), looking south.

Photo 3 1000 Island Mall and adjacent strip mall shops including former Sears Canada, north of Highway 401 (**2399 Parkedale Avenue, PSOC-2**), looking south.



Photo 4 Railroad intersecting Parkedale Avenue, between California Avenue and Millwood Avenue, looking north.

Photo 5 North Augusta Road overpass over Highway 401, looking southeast (photo taken from behind Winners Department Store).

Photo 6 Intersection of Parkedale Avenue and North Augusta Road, looking south.

Photo 7 Oil change auto shop north of intersection of Broome Road and Parkedale Avenue (103 Broome Road), looking southeast. Not considered a PSOC based on distance from the Site.

Photo 8 Storage totes with unknown contents at oil change auto shop, to the east of Photo 7, looking southeast.

Photo 9 Heavy equipment yard, southeast of intersection of Broome Road and Parkedale Avenue (1917 Parkedale Avenue, **PSOC-1**), looking south.

Photo 10 Heavy equipment yard, southeast of intersection of Broome Road and Parkedale Avenue (1917 Parkedale Avenue, **PSOC-1**), looking southwest.

Photo 11 Truck repair auto shop at the intersection of Parkedale Avenue and Oxford Avenue (1000 Oxford Avenue, **PSOC-14**), looking south.

Photo 12 Diesel and gas pumps and ASTs for RV/truck camp, northeast of interesction of Parkdale Ave and Broome Road, looking east. Not considered a PSOC based on distance from the Site.

Photo 13 Auto shop west of interesection of Stewart Boulevard and Jefferson Drive (3049 Jefferson Drive, **PSOC-18**) , looking north.

Photo 14 Oil change auto shop north of intersection of Stewart Boulevard and Central Avenue West (125 Stewart Boulevard, **PSOC-5)**, looking north.

Photo 15 Brockville Shopping Centre (strip mall) north of intersection of Stewart Boulevard and Central Avenue West (125 Stewart Boulevard, **PSOC-5)**, looking northeast.

Photo 16 Shipping/storage containers south of Central Avenue West and Decker Drive, looking west.

Photo 17 Diesel and gasoline ASTs northeast of intersection of Central Avenue West and Brockel Trails, looking west. Not considered a PSOC based on distance from the Site.

Photo 18 Heavy equipment lot, northeast of intersection of Central Avenue West and Brockel Trails, looking north. Not considered to represent a PSOC based on the nature of the equipment and distance from the Site.

Photo 19 Large AST and solar panels, northeast of intersection of Central Avenue West and Brockel Trails, looking east. Not considered to represent a PSOC based on distance from the Site.

Photo 20 Towing service and auto shop, northeast of intersection of Central Avenue West and Brockel Trails, looking east. Not considered a PSOC based on distance from the Site and anticipated downgradient location.

Photo 21 Playground south of Highway 401. Highway 401 overpass over Bramshot Avenue can be seen in the background, looking northwest.

Appendix D QUALIFICATIONS OF COS PROJECT TEAM

Romeet Gonsalves B.Sc., G.I.T.

Junior Environmental Site Assesor

Romeet is a geoscientist-in-training and has experience completing Environmental Site Assessments (ESAs - Phase I, II, III), soil monitoring and sampling, soil remediation and groundwater monitoring programs.

Project coordination and implementation of field operations including safety compliance, supervision of jobsite personnel and contractors, soil management, and environmental sampling. Romeet is skilled in site characterization, field work, and technical report writing.

Prior to consulting, Romeet has worked on reservoir characterization projects for oil and gas plays in the Western Canadian Sedimentary Basin and offshore Gulf of Mexico using strong skills in geology, hydrology, mapping, and geological and geophysical data integration.

EDUCATION

B.Sc. (Hons), Geology with a minor in Geophysics, University of Calgary, Calgary, Alberta, 2017

Master's of Environmental Studies, Dalhousie University, Halifax, Nova Scotia, 2019

REGISTRATIONS

Geologist-In-Training #244785 , Association of Professional Engineers and Geoscientists of Alberta

MEMBERSHIPS

Member, Canadian Society of Petroleum Geologists

PROJECT EXPERIENCE

ENVIRONMENTAL SITE ASSESSMENTS

Phase I ESA Telus Telecommunication Tower | Ottawa, Ontario | 2019 | Site Assessor, Report Writer

Successful proposal, assessment and final report for Phase I ESA for a Telecommunications Tower.

Canada Post Annual Groundwater Monitoring | Ottawa, Ontario | 2019 | Field Technician

Maintenance/repair, development and groundwater sampling of 21 monitoring wells on a Canada Post vehicle fleet site. Conducting sampling for contaminated groundwater.

Phase II ESA Telus Telecommunication Tower | Ottawa, Ontario | Site supervisor, and Tield Technician

Oversaw and coordinated drilling of three monitoring well, followed by soil and groundwater sampling of the three wells.

Carlton Place semi-annual groundwater monitoring | Ottawa, Ontario | Field Technician

Groundwater sampling for several flushmount wells, and two potable wells.

Suncor Carling In-Situ Remediation | Ottawa, Ontario | Site Supervisor

Oversaw drilling and in-situ remediation of 32 injections points.

Pendleton Phase II ESA | Curran, Ontario | Field Technician

Dug four test pits, oversaw drilling of two monitoring wells, and sampled five monitoring wells.

Phase I ESA Brandt Developments | Carp, Ontario | Field Assessor, Report Writer

Completed a Phase I ESA site visit and assessment as well as reporting for the Nortrax heavy equipment facility.

Phase I ESA Tesla Brockville | Brockville, Ontario | Site Assessor, Report Writer

Completed a Phase I ESA for a proposed Tesla supercharger station as well as completed reporting for the project.

Casselman Annual Groundwater Monitoring | Casselman, Ontario | Field Technician

Conducted monitoring and sampling for 19 wells in the Village of Casselman.

Casselman Village Landfill Monitoring | Casselman, Ontario | Field Technician

Collected surface water and groundwater samples from across the Casselman landfill.

Castlefrank Well Decommissioning | Kanata, Ontario

Oversaw the decommissioning of nine wells.

Suncor Phase II ESA Groundwater Monitoring | Ottawa, Ontario

Conducted the monitoring and sampling of 29 wells post-remediation as well as supporting the report writing for the project.

Enbridge Gas Distribution Soil Monitoring | Ottawa, Ontario

Ongoing support at various location across Ottawa for soil and vapour monitoring on as as-needed basis.

Campeau Drive Drilling | Kanata, Ontario | Field Technician

Oversaw and supported drilling of three monitoring wells.

PSPC 2019-2020 Annual Potable Water Quality Assessment | Ottawa, Ontario | Report Writer

Completed reports for several buildings.

Site Investigation Services for ATESS | Trenton, Ontario | Field Technician

Winter field work including groundwater monitoring and sampling, well development, and drilling.

OHS Emergency Spills | Ottawa, Ontario | Emergency Responder (phone)

Oversee the emergency response line for the NavCanada spill response phone.

Monthly and Quarterly Effluent Sampling | Ottawa, Ontario | Field Technician

Collect effluent samples (sewer, sanitary) for multiple projects and clients on a monthly or quarterly basis.

Water Well Testing | Ottawa, Ontario | Field Technician

Collected water samples from inlet and outlet valves on either end of heat exchangers and completed reporting for the project.

Phase II ESA Albany Drive | Ottawa, Ontario | Report Writer

Completed a Phase II ESA report for a drilling and well monitoring program for the City of Ottawa.

Grace Ferguson M.Sc., P.Eng.

Senior Hydrogeologist

Grace is a senior hydrogeologist in Stantec's Environmental Services group with 25 years' experience in contaminated site management. She offers clients the benefit of her technical knowledge and experience in solving a variety of environmental challenges. She has managed environmental site assessment, monitoring, and remediation projects for a wide cross-section of service sectors, including road and rail transportation, commercial real estate, the petroleum industry, insurance, land development, municipal, provincial, and federal governments, the Canadian Forces, industry, and waste management. This wide range of experience provides her the vision to see complex projects through from planning to closure.

Grace is a licensed Professional Engineer in the Province of Ontario and is recognized by the Ontario Ministry of the Environment, Conservation and Parks as a Qualified Person for Environmental Site Assessment under Ontario Regulation 153/04. She is also listed as a contaminant/waste specialist with the Ontario Ministry of Transportation.

EDUCATION

M.Sc., University of Waterloo / Hydrogeology, Waterloo, Ontario, 2001

B.A.Sc., University of Waterloo / Geological Engineering, Waterloo, Ontario, 1993

CERTIFICATIONS & TRAINING

eRailSafe Field Contractor Training, CN and CP, Waterloo, Ontario, 2018

40 Hour OSHA Training Safety at Hazardous Materials Sites, New York, New York, 1994

Petroleum Oriented Safety Training - Behaviour Based Safety Level 2, Waterloo, Ontario, 2019

REGISTRATIONS

Professional Engineer #90427949, Professional Engineers Ontario, Feb 9/96

PROJECT EXPERIENCE

ENVIRONMENTAL SITE ASSESSMENTS PHASE I, II, III

Contamination Overview Studies and Phase II Environmental Site Assessment, Peel Watermain Projects | Mississauga, Ontario | 2013-2017 | Environmental Specialist

Completion of contamination overview studies and environmental sampling to assess the potential for generation of contaminated soil during watermain replacement work along three existing and future roadways in Mississauga. Provided fill management options for consideration in construction tendering.

Phase I ESAs Commercial Portfolio | Southern Ontario | 2013 | Project Manager and Senior Reviewer

Oversight of 10 Phase I ESAs as part of a Canada-Wide due diligence portfolio for a large commercial client. Also provided senior review of Phase I ESA reports for several of the portfolio sites.

Phase One and Two Environmental Site Assessments, Commercial Property | Kitchener, Ontario | 2012-2013 | Project Manager

Managed and reviewed ESAs of a used car lot and former industrial site for due diligence in advance of potential purchase and redevelopment of the Kitchener downtown core.

Contamination Overview Study and Environmental Sampling, Windsor-Detroit Tunnel Plaza | Windsor, Ontario | 2011-2012 | Environmental Project Lead

Managed the completion of an assessment of potential environmental concerns that could affect redevelopment of a border crossing facility as part of detailed design.

Phase I ESAs, Commercial and Industrial Properties | Kitchener, Ontario | 2017 | Project Manager

Senior technical support and review for assessments at 10 properties for due diligence purposes.

Environmental Investigation, Industrial Facility | Walkerton, Ontario | 2002-ongoing | Project Manager

Project manager for the assessment, monitoring and development of remedial options for VOC impacts to groundwater at an active industrial facility.

Environmental Investigations, Redevelopment Site | Vaughan, Ontario | 2001-2005 | Project Manager

Project manager for several environmental investigations relating to the redevelopment of Secondary Buffer lands surrounding a recently closed landfill site. These included Phase 1 and Phase 2 environmental site assessments, development of a groundwater monitoring program for a new golf course, and remediation of environmental impacts along a future road realignment. The project involved extensive consultation with MOE and municipal and private stakeholders.

Environmental Site Assessment, Rail Yard | Woodstock, Ontario | 2000-01,2014 | Project Manager

Completion of a hydrogeological assessment of a rail yard facility, including test pit excavation, borehole drilling, monitoring well and drive point piezometer installation, soil and groundwater sampling, and hydraulic conductivity testing. Provided senior technical review of on-going groundwater monitoring activities.

Environmental Review, Proposed Development Site | Kitchener, Ontario | 2013 | Senior Reviewer

Completed a review of historical environmental work done at a property and assessed the level of effort and cost to complete the necessary work to support the filing of a Record of Site Condition with the Ontario Ministry of the Environment. This was done to determine the feasibility of site re-use options.

Environmental Site Assessments, Parkway West Compressor Station | Milton, Ontario | 2012-2013 | Environmental Specialist

Phase One and Phase Two Environmental Site Assessments for development approvals for land being acquired to develop a natural gas compressor station.

Environmental Retainer, Various Sites | Greater Toronto Area, Ontario | 2014-2016 | Project Manager

Managed numerous environmental site assessments and monitoring projects at client-owned properties in advance of site redevelopment for transportation systems as part of a two-year retainer assignment. Managed Phase II ESAs, co-ordinated designated substance surveys and geophysical surveys, and recommended and implemented remedial excavation programs. Also managed on-going monitoring program at a client-owned landfill site.

Environmental Investigation, Rail Yards | Northern Ontario | 2014-ongoing | Project Manager

Senior technical reviewer for quarterly and annual groundwater monitoring at a railyard with petroleum impacts to soil and groundwater. Previously project manager for hydrogeological investigations at the yard from 2000 to 2005. Completed a remedial options/feasibility study and developed a remedial action plan to address both on-site and off-site impacts. Co-ordinated drilling and initial sampling of private domestic wells at several off-site and on-site locations.

Phase I and II Environmental Site Assessment, Commercial/Industrial facility | Mississauga, Ontario | 2016 | Project Manager

Project management and senior technical support for a comprehensive Phase I and II ESA at a former petrochemical research and development facility in an urbanized area. Developed a conceptual site model of subsurface conditions and facilitated an understanding of potential environmental liabilities associated with the property.

Environmental Site Assessment and RSC Filing | Cambridge, Ontario | 2017 | Reviewer, QP_{ESA}

Quality reviewer and QP_{ESA} for assessment of several adjacent properties to be redeveloped into a residential complex. Completed Phase One and Two ESAs and limited remediation and filed an RSC in accordance with O.Reg. 153/04 for one property that had experienced commercial use.

Phase I ESA, Wind Farm Development | Grand Valley, Ontario | 2015-2016 | Senior Technical Reviewer

Provided senior review support to a Phase I ESA of a large network of proposed wind turbines, distribution lines, transformer station, and storage areas forming part of a wind farm that was under development. Identified potential environmental concerns and provided guidance to the client to manage them.

Contamination Overview Study, King and Fountain Street Improvements | Cambridge, Ontario | 2011-2012 | Environmental Specialist

Managed and reviewed a contamination overview study of several roadways in advance of road improvements in an urbanized area.

Contamination Overview Study and Phase I ESAs, Franklin Boulevard | Cambridge, Ontario | 2011-2018 | Project Manager

Project manager and senior reviewer for an assessment of potential sources of contamination along an 8 km roadway and completion of 30 Phase I ESAs adjacent to the roadway, as part of detailed design for road improvements. Provided subsequent environmental expertise for dewatering management during construction phase. Provided subsequent environmental expertise for dewatering management during construction phase.

Phase One Environmental Site Assessment, Former Golf Course, Southern Ontario | Southern Ontario | 2010 | Senior Reviewer

Senior reviewer of a Phase One ESA completed for due diligence in advance of a potential sale of the property. The Phase One ESA was completed to the regulation standards prescribed by O.Reg. 153/04, as amended.

** denotes projects completed with other firms*

** denotes projects completed with other firms*

Phase One and Two ESAs, Risk Assessment and Record of Site Condition | Northern Ontario | 2010-2012 | Senior Reviewer, QP_{ESA}

As a QP_{ESA} , provided senior level review for assessments of two former gasoline service stations. Phase One and Two ESAs were completed to the revised regulatory standards prescribed by O. Reg. 153/04 to support a Risk Assessment (RA) and Record of Site Condition (RSC). She developed a risk management plan for the RA at one site and filed a RSC.

Phase One and Two Environmental Site Assessment, Scrap Metal Facility | Kitchener, Ontario | 2010-2011 | Project Manager

Project Manager and Senior Reviewer for Phase One and Two ESAs of a brownfield site to support potential sale and / or redevelopment. ESAs were completed to the regulatory standards prescribed by O.Reg. 153/04, as amended.

Environmental Assessments, Redevelopment Site | Kitchener, Ontario | 2007-2009 | Project Manager

Phase I Environmental Site Assessment of a construction maintenance yard and surrounding undeveloped land. Development of recommendations for assessment work to support redevelopment approvals. Completion of environmental monitoring following limited removal of impacted soil, and environmental observation and verification sampling during removal of fuel storage facilities.

Contamination Overview Study and Phase I/II Environmental Site Assessment, Weber Street Redevelopment | Kitchener, Ontario | 2009-2011 | Environmental Specialist

Managed and reviewed a contamination overview study and Phase II Environmental Site Assessment to identify and assess potential environmental concerns along a 1.2 km section of Weber Street in Kitchener, as part of preliminary and detailed design for road reconstruction.

Phase I and II Environmental Site Assessments, 104 Retail Service Stations | Southern Ontario | 2009 | Project Manager

Key Project Manager for 25 of 104 retail gasoline service station sites assessed during a 60 day due diligence period. Responsible for project management and senior review of Phase I and Phase II ESAs.

Phase I and II Environmental Site Assessment, Detroit-Windsor Truck Ferry | Windsor, Ontario | 2007-2008 | Project Manager

Completion of Phase I and II ESA and development of waste management options at a truck ferry terminal, in preparation for infrastructure improvements.

Environmental Site Investigation, Proposed HONI Development | Peterborough, Ontario, Canada | 2018-2019 | Senior Environmental Specialist

Provided expertise and senior quality review of a soil and groundwater investigation of existing conditions for a proposed Hydro One Networks Inc. development in Peterborough, Ontario.

Phase I ESA, Industrial Facilities | Ontario | 2004-2007 | Project Manager

Environmental site assessments, including historical review and site reconnaissance, of an industrial plastics manufacturer and a food packaging plant.

Contamination Overview Studies, Proposed Infrastructure Alignments | Hamilton, Sarnia, and Windsor, Ontario, Canada | 2019 | Senior Technical Reviewer

Provided oversight and quality review for three contamination overview studies along proposed alignments ranging in length from approximately 4 km to 60 km in Southern Ontario.

Contamination Overview Studies, Preliminary Site Screenings and Excess Materials Management Plans | Ontario | 2005-present | Environmental Specialist

Completed or reviewed COS, PSS, and/or EMMPs for more than 30 existing and proposed MTO roadways and interchanges to support preliminary and detailed design transportation projects.

Environmental Site Assessment of Fisherman's Pier Lands | Hamilton and Burlington, Ontario | 2002 | Project Hydrogeologist

Completed an Environmental Site Assessment (ESA) as part of a planning study to examine potential redevelopment options for lands known as Fisherman's Pier. Identified current and historical land uses of potential environmental concern.

Environmental Investigation, Petrochemical Terminal Facility | Oakville, Ontario | 2014-present | Senior Technical Reviewer

Senior hydrogeological technical support to an ongoing groundwater investigation at a large petrochemical terminal site. Work was done to fulfill ECA obligations associated with phytoremediation of former landfarm areas and to assess the distribution of impacts across the property.

Environmental Assessment, Redevelopment Site | Milton, Ontario | 2005 | Project Manager

Completed a Phase I/II ESA at a vacant site and filed a Record of Site Condition to support redevelopment as a commercial facility.

Environmental Investigation, International Airport | London, Ontario | 2018 | Senior Reviewer

Provided senior technical review for an assessment of soil, groundwater, sediment, and surface water quality associated with a closed industrial landfill site associated with an airport facility in London, ON.

Phase I and II ESAs, Highway Maintenance Patrol Yards* | Lambton and Simcoe Counties, Ontario | 1995, 1997 | Project Manager

Project manager and primary field personnel for soil and groundwater investigations at 11 maintenance patrol yards, using borehole drilling, well sampling and geophysical methods.

** denotes projects completed with other firms*

Pre-Development ESAs | Kitchener, Ontario | 2017-2020 | Senior Technical Reviewer

Provided senior technical review of Phase 1 and 2 ESAs at two hospital facilities to investigate areas for potential future development. Provided recommendations for future management of excavated soil.

Phase I ESA, Various Properties | Ontario | 2001-present | Project Manager

Historical reviews, site reconnaissance, reporting and senior review of commercial, institutional and vacant properties for financial institutions and land developers.

Phase 1 and 2 ESAs, Former Rail Facility | Cambridge, Ontario | 2016-2017 | Project Manager

Managed a Phase I and II ESA of a former rail facility in an urbanized area, and developed a plan for remedial activities to facilitate future development.

Review of Environmental Conditions | 2019-present | Senior Technical Reviewer

Provided environmental review services and summarized environmental conditions and management implications for a municipality that was planning to rehabilitate an urbanized creek.

Environmental Evaluations, Federally Owned Properties* | Pickering, Ontario | 1996 | Project Manager

Completion of environmental evaluations of more than 70 rural residential, commercial, vacant and agricultural properties within the proposed Pickering Airport lands, Pickering, Ontario. Evaluations included a site reconnaissance, testing of building materials for suspected designated substances, and potable water sampling.

Peer Review Services for Municipal Development Applications | Lanark, Peterborough, Ontario | 2017-Present | Environmental Specialist

Provided environmental peer review services for ESA-related development submissions to two counties. Reports reviewed included Phase One and Two ESAs completed to the Ontario Regulation 153/04 standards, and remediation reports.

Phase I ESAs, Various Properties* | Ontario and Manitoba | 1993-1997 | Project Hydrogeologist

Environmental assessments, including historical review and site reconnaissance of more than 80 residential, institutional, commercial, industrial and vacant properties in Ontario and Manitoba for various financial institutions, developers, individuals and government agencies. Institutional properties included approximately 20 nursing homes and retirement facilities.

Phase One and Two ESAs and RSC Filings | Ottawa, Hamilton, Brantford, Elmira, Ontario | 2017-Present | Project Manager/Senior Technical Specialist

Conducted Phase One and/or Two ESAs of commercial and industrial properties according to Ontario Regulation 153/04 in support of filing a Record of Site Condition (RSC) for eventual site redevelopment to residential land use. Where necessary, provided delineation of soil and/or groundwater impacts, and presented options for management so as to meet the RSC requirements.

Environmental and Historical Review, Mixed Land Use Area | Hamilton, Ontario | 2002 | Project Hydrogeologist

Environmental review of several industrial, commercial and vacant properties in the Hamilton West Harbour area as part of redevelopment planning.

Phase I and II ESAs, Various Facilities* | Toronto and Owen Sound, Ontario | 1994-1996 | Project Hydrogeologist

Assessment of environmental conditions, including potential soil and groundwater impacts, at a former auto repair facility, a commercial property, an inactive industrial site and a former landfill site.

Phase I and II Environmental Site Assessment (ESA), Former Industrial Facility | London, Ontario | 2002 | Project Manager

Project manager for a Phase I/II ESA to assess soil and groundwater conditions prior to purchase of a portion of vacant land formerly used as an industrial facility.

** denotes projects completed with other firms*